



Monitoring Report
OCTOBER
2010

*American Airlines 331
Accident Site and Landfarm*

Submitted to:



Prepared by:



Taking Care of You and Your Environment.

October 2010

**MONITORING REPORT – OCTOBER 2010
AMERICAN AIRLINES 331 ACCIDENT SITE AND
LANDFARM**

Submitted to:
AMERICAN AIRLINES

Prepared by:
CL ENVIRONMENTAL
22 Fort George Heights
Kingston 9

October 2010

Table of Contents

1.0	Introduction	6
2.0	Methodology.....	6
2.1	Meteorological Conditions	6
2.2	Particulates.....	6
2.3	Water Quality	6
2.4	Soil.....	11
3.0	Results.....	13
3.1	Accident Site	13
3.1.1	Water Quality.....	13
3.1.2	General Observations.....	18
3.2	Landfarm.....	20
3.2.1	Meteorological Conditions	20
3.2.2	Particulates	26
3.2.3	Water Quality.....	28
3.2.4	Soil	35
3.2.5	General Observations.....	37
4.0	Discussion	41
5.0	Professional Statement	42
6.0	Appendices.....	43
	Appendix 1 Hydrolab Calibration Certificate	43
	Appendix 2 Detailed water quality and soil data	45
	Appendix 3 Detailed meteorological data.....	100
	Appendix 4 Water quality graphs showing trends from March – October, 2010.....	208

List of Figures

Figure 1 - Location of weather station and dust monitor.....	8
Figure 2 - Locations of the water quality stations at the accident site.....	9
Figure 3 - Location of water quality stations at the landfarm	10
Figure 4 - Diagram showing soil sampling locations.....	11
Figure 5 Graph showing temperature values at accident site.....	13
Figure 6 Graph showing conductivity values at accident site	14
Figure 7 Graph showing salinity values at accident site.....	14
Figure 8 Graph showing pH values at accident site.....	15
Figure 9 Graph showing dissolved oxygen values at accident site.....	15
Figure 10 Graph showing turbidity values at accident site.....	16
Figure 11 Graph showing TDS values at accident site.....	16
Figure 12 Graph showing DRO value at accident site	17
Figure 13 Temperature fluctuations for the month of October, 2010.....	20
Figure 14 Rainfall and rain rate for the month of October, 2010	21
Figure 15 Relative humidity fluctuations for the month of October, 2010.....	21
Figure 16 Wind speeds for the month of October, 2010.....	22
Figure 17 Wind directions for the month of October, 2010	22
Figure 18 High wind speed and direction for the month of October, 2010.....	23
Figure 19 Graph showing PM10 values at landfarm for October.....	27
Figure 20 Graph showing temperature values at landfarm	28
Figure 21 Graph showing conductivity values at landfarm.....	29
Figure 22 Graph showing salinity values at landfarm	29
Figure 23 Graph showing pH values at landfarm	30
Figure 24 Graph showing dissolved oxygen values at landfarm	30
Figure 25 Graph showing turbidity values at landfarm	31
Figure 26 Graph showing TDS values at landfarm	31
Figure 27 Graph showing DRO values at landfarm	32
Figure 28 Graph showing total phosphorus values at landfarm.....	33
Figure 29 Graph showing total nitrogen values at landfarm	33
Figure 30 Graph showing TOC values at landfarm.....	34
Figure 31 Graph showing DRO soil values at the accident site.....	35
Figure 32 Graph showing soil moisture values at the accident site	36

List of Tables

Table 1 - Water quality parameters monitored.....	7
Table 2 - Water quality stations coordinates in JAD 2001	7
Table 3 - Daily summary of temperature, rainfall and wind	23
Table 4 Ambient Air Quality results	27
Table 5 Soil sampling results for impacted grids at accident site	35

List of Plates

Plate 1 Photo showing accident site	18
Plate 2 Photo showing section of accident site	18
Plate 3 Photo showing soil sampling with auger at accident site	19
Plate 4 Photo showing soil sampling with auger at accident site	19
Plate 5 Photo showing flooded treatment area of landfarm.....	37
Plate 6 Photo showing flooded storage area of landfarm	37
Plate 7 Photo flooded treatment area of landfarm	38
Plate 8 Photo showing leachate sample point.....	38
Plate 9 Photo showing sampling from leachate sample point.....	39
Plate 10 Photo showing flooded storage area at landfarm	39
Plate 11 Photo showing ambient air sampler and weather station.....	40

1.0 Introduction

This report outlines the results and interpretation of these results for the monitoring conducted during the month of October 2010 at the American Airlines 331 accident site and the landfarm created for the biodegradation of the impacted material.

2.0 Methodology

2.1 Meteorological Conditions

Temperature, relative humidity, wind speed and direction, rainfall and barometric pressure were recorded at one (1) location at the Landfarm daily by using a Davis Instruments wireless Vantage Pro2 weather system with a data logger and a complete system shelter erected on a tripod. Data was collected every fifteen minutes and stored on the datalogger. This information was downloaded using the WeatherLink 5.8.3 software.

2.2 Particulates

Ambient air quality monitoring involves the measurement of outdoor levels of respirable particles (PM10 - dust with particle size less than 10 microns that can be retained in the lungs). The particles were measured using pre weighed Whatman QMA filters and TISCh Environmental Hi Volume sampler. The TISCh Environmental Hi Volume sampler was placed at approximately 3m above ground level at the Landfarm site. The filters were then taken to the laboratory where the filter papers were stabilised and weighed to determine the levels of particulates. Sampling is conducted on pre defined dates as outlined by the United States Environmental Protection Agency 2010 - 6 day monitoring schedule for PM10.

Sampling was conducted October 5, 11, 17 and 23, 2010, beginning at 0000 hours each day for 24 hours. Sampling was conducted by Carlton Campbell of C.L. Environmental Co. Ltd. The levels were compared with the NEPA ambient air standard.

2.3 Water Quality

Water quality monitoring exercise was conducted at five (5) stations. The parameters monitored are listed in Table 1 and their locations in JAD2001 are listed in Table 2 and depicted in Figure 2 and Figure 3.

Temperature, conductivity, salinity, dissolved oxygen, pH, turbidity and total dissolved solids were collected in situ using a Hydrolab Minisonde (MS5) multi probe meter. The calibration certificate can be seen at Appendix 1.

Whole water samples were collected. Samples were collected in pre-cleaned glass bottles. The samples were stored on ice in a cooler, transported to FedEx for shipment and transported to Test America Pensacola laboratories for laboratory analyses. The water samples were sent under a Chain of Custody.

Sampling was conducted on October 20th, 2010 between the hours of 0815hrs - 1215hrs. Sampling was conducted by Janette Manning of Jamaica Environmental Management Services Ltd.

Table 1 - Water quality parameters monitored

Temperature (°C)	Ethylbenzene (mg/l)
Conductivity (mS/cm)	Total Xylene (mg/l)
Salinity (ppt)	Methyl tert-butyl ether (mg/l)
Dissolved Oxygen (mg/l)	Gasoline Range Organics (mg/l)
pH	Diesel Range Organics (mg/l)
Turbidity (NTU)	Total Phosphorus (mg/l)
Total Dissolved Solids (g/l)	Total Nitrogen (mg/l)
Benzene (mg/l)	Total Organic Carbon (mg/l)
Toluene (mg/l)	

Table 2 - Water quality stations coordinates in JAD 2001

LOCATION	WATER QUALITY STATIONS CODE	JAD2001 GPS Coordinates (WGS84)	
		Easting	Northing
ACCIDENT SITE	WELL 1	773814.957	642358.034
ACCIDENT SITE	WELL 2	773842.010	642386.448
LANDFARM	WELL 3	774302.060	643890.181
ACCIDENT SITE	WELL 4	773808.258	642374.115
LANDFARM	WELL 5	774238.672	643902.798
LANDFARM	LEACHATE	774292.757	643895.843




Figure 1 - Location of weather station and dust monitor




Figure 2 - Locations of the water quality stations at the accident site



Figure 3 - Location of water quality stations at the landfarm

2.4 Soil

A total of 9 cells have been identified in the land farm and storage area for sampling. Each cell will have 10 sampling locations to allow for representative sampling of the cell (Figure 4). Each sample is a composite of 10 equal proportions of samples from the top 150 mm of soil. The samples will each be placed in 250 ml glass jars and sent to Test America Pensacola laboratories for analysis.

Samples will be analysed for:

- Total Organic Carbon, in the leachate on a weekly basis
- Contaminant levels (total petroleum hydrocarbons, benzene, toluene, ethyl-benzene xylenes)
- Nutrient levels (N, P) in the leachate on a weekly basis
- Plate counts for viable bacteria
- Moisture levels; and
- pH levels.




Figure 4 - Diagram showing soil sampling locations

For the October 20th soil sampling, samples were taken from the previously identified impacted areas at the accident site. These are as follows:

- Grid 6-7
- Grid 74
- Grid 98-99
- Grid 126
- Grid 127

Samples were taken using a soil auger, to a depth of 1.5 – 3 feet.

Soil samples were unable to be taken from the landfarm as it was still flooded due to heavy rainfall in the previous month.

3.0 Results

3.1 Accident Site

3.1.1 Water Quality

Temperature

Temperature values for the wells at the accident site ranged from 27.73°C (Well 1) – 30.82°C (Well 4).




Figure 5 Graph showing temperature values at accident site

Conductivity

Conductivity values for the wells at the accident site ranged from 2.053 mS/cm (Well 2) – 3.71 mS/cm (Well 1).




Figure 6 Graph showing conductivity values at accident site

Salinity

Salinity values for the wells at the accident site ranged from 1.11 ppt (Well 2) – 2.07 ppt (Well 1).




Figure 7 Graph showing salinity values at accident site

pH

pH values for the wells at the accident site ranged from 7.86 (Well 2) – 8.06 (Well 4).




Figure 8 Graph showing pH values at accident site

Dissolved Oxygen

D.O. values for the wells at the accident site ranged from 1.56 mg/l (Well 2) – 7.77mg/l (Well 1).




Figure 9 Graph showing dissolved oxygen values at accident site

Turbidity

Turbidity values for the wells at the accident site ranged from 0 NTU (Well 2) - 377.1 NTU (Well 1).




Figure 10 Graph showing turbidity values at accident site

Total Dissolved Solids

TDS values for the wells at the accident site ranged from 1.35g/l (Well 2) - 2.4g/l (Well 1).




Figure 11 Graph showing TDS values at accident site

Gasolene Range Organics (GRO)

No GRO were detected for this month's monitoring exercise.

Diesel Range Organics (DRO)

Only Well 1 had a DRO value of 0.46mg/l.




Figure 12 Graph showing DRO value at accident site

BTEX (Benzene, Toluene, Ethylbenzene, Xylene)

No traces of BTEX were detected in any of the samples taken.

Detailed results of water quality sampling can be found in Appendix 2

3.1.2 General Observations



Plate 1 Photo showing accident site



Plate 2 Photo showing section of accident site



Plate 3 Photo showing soil sampling with auger at accident site



Plate 4 Photo showing soil sampling with auger at accident site

3.2 Landfarm

3.2.1 Meteorological Conditions

Temperature

Average temperature throughout the month of October was 27.6 °C (81.6 °F) and ranged from a low of 23.1 °C (73.5 °F) which occurred on October 1st, 2010 at 3:45pm to a high of 32.4 °C (90.4 °F) which occurred on October 12th, 2010 at 11:45 am.

Figure 13 depicts the temperature fluctuations over the time period measured in October.




Figure 13 Temperature fluctuations for the month of October, 2010

Rainfall

During the period in October, there were 100.3 mm (\approx 3.95") of rainfall over seventeen rain days. Figure 14 depicts the daily rainfall depths and rainfall rate for the time period. The highest rainfall (29.2 mm) occurred on October 9th, 2010.




Figure 14 Rainfall and rain rate for the month of October, 2010

Relative Humidity

Average relative humidity during the period was 82.7% and ranged from a minimum of 54% on October 30th, 2010 at 11:45 am to a maximum of 97% on October 1st, 2010 at 12:15 - 3:30am, 6:45am, October 2nd at 4:15 - 4:30pm, and October 3rd at 4:45-5:15am, 6:30-7:00am. Figure 15 depicts the relative humidity fluctuations over the time period.




Figure 15 Relative humidity fluctuations for the month of October, 2010

Wind Speed and Direction

Average wind speed for the month of October was 1.2 m/s (\approx 2.7 mph) and had a high of 12.5 m/s (\approx 28 mph) which occurred on October 9th, 2010 at 11:45 am. Figure 16 depicts the wind speeds over the time period.

The dominant wind direction was from the North NorthEast (Figure 17).




Figure 16 Wind speeds for the month of October, 2010




Figure 17 Wind directions for the month of October, 2010

High Wind

High winds are the highest wind speeds recorded over the 15 minute archive periods. Figure 18 depicts the high winds and directions over the period monitored in October.




Figure 18 High wind speed and direction for the month of October, 2010

The daily summary, of selected meteorological data are provided in Table 3 and the detailed information in Appendix 3.

Table 3 - Daily summary of temperature, rainfall and wind

OCT 2010	TEMPERATURE (°C)					RAIN (mm)	WIND SPEED (m/s)			DOMINANT WIND DIR
	MEAN	HIGH	TIME	LOW	TIME		AVG.	HIGH	TIME	
1	25.6	29.2	9:15a	23.1	3:45p	23.1	1	11.2	3:15p	ESE
2	25.6	29.2	1:30p	23.7	1:00a	11.4	0.8	5.4	11:45a	NE
3	27.3	30.7	11:30a	24.4	6:30a	1.5	0.9	6.7	6:00p	S
4	27.7	30.5	1:30p	24.8	5:15a	0.3	1.1	4.9	12:30p	NNE
5	28.1	31.3	1:30p	25.1	5:30a	0.5	0.7	4.5	11:00a	S

OCT 2010	TEMPERATURE (°C)					RAIN (mm)	WIND SPEED (m/s)			DOMINANT WIND DIR
	DAY	MEAN	HIGH	TIME	LOW		TIME	AVG.	HIGH	
6	28.1	31.4	3:15p	25.5	6:00a	0.5	0.8	5.4	12:00p	NNE
7	27.8	31.6	10:00a	25.4	5:15a	1.3	1	7.2	12:45p	NW
8	28.3	31.8	12:00p	25.7	5:00a	0	1.1	6.7	7:00p	NW
9	26.4	29.6	8:45a	23.9	7:00a	29.2	1.3	12.5	11:45p	NNE
10	27.4	30.4	11:30a	24.4	12:15a	0.5	1.7	11.2	11:45p	SE
11	28.9	30.9	1:45p	25.9	12:00a	0	3.2	12.1	2:45p	SSE
12	28.6	32.4	11:45a	25.1	6:30a	0	1.5	10.3	1:15p	SSE
13	28.4	31.4	10:15a	25.9	3:00a	0	1.1	9.4	1:45p	SSE
14	28.1	31.8	10:45a	25.3	4:30a	4.3	0.9	10.3	1:15p	NNE
15	28.3	31.1	9:15a	25.7	5:30a	0	1.2	7.2	2:00p	SSE
16	27.7	31.1	10:15a	25.1	4:45a	0.3	0.8	5.8	11:45p	NNE
17	28.1	31.2	11:45a	25.5	6:15a	0	0.8	5.4	1:30p	NNE
18	28	30.8	12:00p	25.5	5:30a	0	1.2	5.8	10:45a	SSE
19	26.8	30.5	12:15p	24.8	7:30p	6.1	1.2	7.2	2:45p	SSE
20	27.4	29.9	11:45a	24.8	12:45a	1.3	1.9	8	3:15a	SE
21	27.6	29.8	10:00a	24.9	3:45a	0	1.6	8	4:45p	ESE
22	27.9	30.8	12:45p	24.8	4:45a	0.3	2.4	10.3	2:30p	SSE
23	27.5	30.9	10:45a	24.2	1:15a	1	0.9	9.8	12:30a	WNW
24	27.4	31.3	10:00a	25.1	3:00a	0.5	1.3	9.8	1:45p	NNE
25	27.4	31	1:30p	24	3:00a	0	1.4	9.4	11:00a	NNE
26	27.8	31.1	10:45a	24.1	5:00a	0	1.5	9.8	2:15p	NNE

OCT 2010	TEMPERATURE (°C)					RAIN (mm)	WIND SPEED (m/s)			DOMINANT WIND DIR	
	DAY	MEAN	HIGH	TIME	LOW		TIME	AVG.	HIGH		TIME
	27	27.8	30.9	12:00p	25.3	4:15a	0	1.2	8.5	1:15p	SSE
	28	26.4	31.3	10:00a	24.3	9:30p	18.3	0.5	6.3	1:00p	NNE
	29	27.1	30.8	11:00a	23.3	3:30a	0	0.7	6.3	5:00p	N
	30	27.9	32.1	11:45a	24	4:00a	0	0.8	6.3	2:45p	NNW
	31	27.4	31.5	10:30a	24.7	6:30a	0	1	8.5	2:30p	NW
		27.6	32.4		23.1		100.3	1.2	12.5		NNE

Meteorological Conditions during Sampling

Sampling Event - October 20th, 2010

Average temperature was 27.4 °C (≈81.3°F) with a low of 24.8 °C (≈76.7°F) and a high of 29.9 °C (≈85.8°F). Average relative humidity was 82.9% and ranged from 68% - 95%. Average wind speed was 1.9 m/s (≈4.3 mph) with maximum wind speeds of 8 m/s (≈18 mph). Dominant wind direction was from Southeast. There was 1.3mm (0.05in) of precipitation during the sampling event.

3.2.2 Particulates

Sampling was conducted on October 5, 11, 17, and 23, 2010, beginning at 0000 hours each day for 24 hours. PM10 results on each sampling day were compliant with NEPA ambient air standards of $150\mu\text{g}/\text{m}^3$ (Table 4, Figure 19).

Table 4 Ambient Air Quality results

Date	Location	Pump Run Time (hrs)	Results (µg/m3)	NEPA Std.(µg/m3)
October 5	Landfarm	24.2	25.87	150
October 11	Landfarm	23.1	28.36	150
October 17	Landfarm	23.8	20.44	150
October 23	Landfarm	23.7	24.23	150




Figure 19

Graph showing PM10 values at landfarm for October

3.2.3 Water Quality

Temperature

Temperature values for the wells at the landfarm ranged from 29.46°C (Well 3) - 31.99°C (leachate).




Figure 20 Graph showing temperature values at landfarm

Conductivity

Conductivity values for the wells at the landfarm ranged from 1.564 mS/cm (leachate) - 10.26 mS/cm (Well 5).




Figure 21 Graph showing conductivity values at landfarm

Salinity

Salinity values for the wells at the landfarm ranged from 0.81 ppt (leachate) - 5.86 ppt (Well 5).




Figure 22 Graph showing salinity values at landfarm

pH

pH values for the wells at the landfarm ranged from 7.24 (Well 3) – 8.9 (leachate).




Figure 23 Graph showing pH values at landfarm

Dissolved Oxygen

D.O. values for the wells at the landfarm ranged from 0.58mg/l (Well 3) – 8.33mg/l (leachate).




Figure 24 Graph showing dissolved oxygen values at landfarm

Turbidity

Turbidity values for the wells at the landfarm ranged from 5.8 NTU (leachate) – 67.5 NTU (Well 3).




Figure 25 Graph showing turbidity values at landfarm

Total Dissolved Solids

TDS values for the wells at the landfarm ranged from 1 g/l (leachate) – 6.719g/l (Well 5).




Figure 26 Graph showing TDS values at landfarm

Gasolene Range Organics (GRO)

No GRO were detected for this month’s monitoring exercise.

Diesel Range Organics (DRO)

Traces of DRO were found in Well 3 (0.16mg/l), the leachate sample (0.13 mg/l), and in Well 5 (0.29mg/l). All were compliant with NEPA DRO standard of 50mg/l.




Figure 27 **Graph showing DRO values at landfarm**

BTEX (Benzene, Toluene, Ethylbenzene, Xylene)

No traces of BTEX were detected in any of the samples taken.

Total Phosphorus

Total Phosphorus values for the wells at the landfarm ranged from 0.14mg/l (Well 5) - 0.36mg/l (Well 3). None was detected in the leachate sample.




Figure 28 Graph showing total phosphorus values at landfarm

Total Nitrogen

Total Nitrogen values for the wells at the landfarm ranged from 1.5mg/l (leachate) - 9mg/l (Well 3).




Figure 29 Graph showing total nitrogen values at landfarm

Total Organic Carbon

TOC values for the wells at the landfarm ranged from 2.2mg/l (leachate) - 24mg/l (Well 5).




Figure 30 Graph showing TOC values at landfarm

Detailed results of water quality sampling can be found in Appendix 2.

3.2.4 Soil

The results for soil samples taken at the following accident site grids were as follows:

Table 5 Soil sampling results for impacted grids at accident site

	DRO (mg/kg)	GRO (mg/kg)	% moisture	BTEX
GRID 6-7	3.8	ND	13	ND
GRID 74	ND	ND	14	ND
GRID 98-99	4.8	ND	7.8	ND
GRID 126	11	ND	10	ND
GRID 127	3.4	ND	9	ND

ND - None Detected

Soil samples were unable to be taken from the landfarm as it was still flooded due to heavy rainfall in the previous month.

Diesel Range Organics (DRO)

DRO traces were detected in all grids sampled excepting for Grid 74. DRO readings ranged from a low of 3.4mg/kg in Grid 127, to a high of 11mg/kg in Grid 126.




Figure 31

Graph showing DRO soil values at the accident site

Gasolene Range Organics (GRO)

No traces of GRO were detected in any of the grids sampled.

Moisture %

Soil moisture ranged from a low of 7.8% in Grid 98-99, to a high of 14% in Grid 74.




Figure 32 **Graph showing soil moisture values at the accident site**

BTEX (Benzene, Toluene, Ethylbenzene, Xylene)

No traces of BTEX were detected in any of the soil samples taken.

3.2.5 General Observations



Plate 5 Photo showing flooded treatment area of landfarm



Plate 6 Photo showing flooded storage area of landfarm



Plate 7 Photo flooded treatment area of landfarm



Plate 8 Photo showing leachate sample point



Plate 9 Photo showing sampling from leachate sample point



Plate 10 Photo showing flooded storage area at landfarm



Plate 11 Photo showing ambient air sampler and weather station

4.0 Discussion

Physicochemical values for water at Wells 1, 2 and 4 at the accident site were all within normal range for groundwater located close to sea. Well 1 had the highest salinity and conductivity value as it is located close to the sea, while Well 2 had the lowest values even though it is located closer to sea than Well 4.

No GRO levels were detected during this month's sampling event, however, minute traces of DRO were detected in Well 1, but still far below the allowable standard.

DRO traces were detected in four out of five of the sampled grid sections at the accident site. These locations coincided with where visible spills of jet fuel were. However, all values were well within the standards.

Physicochemical values for Wells 3 and 5 at the landfarm, are also within normal range, Well 5 displaying an overall higher average salinity than Well 3. Turbidity and TDS values at Well 3 were slightly lower than that of Well 5, however Well 3 D.O. values lower than that of Well 5 due to the nature of the groundwater here, which is usually very turbid and of a foul odour, characteristics usually associated with nearby mangrove swamps.

DRO values were detected in the leachate sample, due to the treatment of the contaminated sand in this section of the landfarm. Water from the sprinkler system and rainfall percolate through the contaminated sand and rocks, and upon reaching the final clay layer, flows toward the leachate containment area where it is stored until it evaporates. DRO values in the leachate sample have also decreased compared to last month's values. There were also minor traces of DRO in monitoring Wells 3 and 5.

Particulate (PM 10) levels were all compliant with NEPA ambient air standards. The lowest particulate values occurred when readings were taken on October 17th and 23rd. Weather data shows that there was no rainfall on any of these days. However, the average wind speed on both these days was very low compared to other days, and high wind will contribute to elevated particulate levels.

5.0 Professional Statement

Treatment of contaminated soil at the landfarm continues to be effective. Minor traces of Diesel Range Organic (DRO) levels were detected at two of the monitoring wells bearing in mind that DRO levels were evident in the wells prior to landfarm construction (baseline data), and as such cannot be attributed to the operations of the landfarm.

6.0 Appendices

Appendix 1 Hydrolab Calibration Certificate

970-962-6710 Hach Labs 15:36:37 28-06-2010 3/4

MiniSonde MS5 Traveler

Order #: 201094541	Cust: CL	S/N: 00500049186	Date: 5.20.10
Verify all options ordered versus current Open Customer Orders report			/ of /

Std Reference ; Chloride-ion ;
NH4-ion ; NO3-ion ; Chlorine ;
Turb ; SC Turb ; Chlorophyll ;
Rhodamine ; Blue-Green FW ;
Blue Green MA

SC Turb
P/N 7280
S/N 97049

D.O. ; Conductivity ; D.O./Cond.
Cond
P/N 4468 S/N 126535

Depth Transducer
Depth plug & screw

100m
P/N 25745033

Temperature Probe
P/N 004165HY

pH ; pH Ref ; pH Orp ;
pH/Orp/Ref ; Std Ref ; Ions
pH / Ions
P/N 7284 S/N 126206

Circulator ; LDO ;
Std Ref (2nd preference)

Cond
P/N 7485
S/N 9923

0.965002
0102

Tip Assembly:	Initials
All o-rings lightly greased on all surfaces	Jm
Seal screw installed on instruments w/o depth or 10m, 25m depth	Jm
DO membrane changed	na

Board Prep/Attachment:	Initials
Check Depth on Hyperterminal: Circle one * 10m 25m 100m 200m	Jm
Main circuit board S/N: 00535983	Jm
All screws installed on ladder and daughter boards	Jm
Probe locking brackets aligned and locked	Jm
MPL Board securely attached to bottom cap	Jm

Software:	Initials
S/N loaded correct? Write S/N displayed on computer screen here: 49186	Jm
Memory: test setup, military time, date, intervals	Jm
Options disabled/enabled to match probe configuration	Jm
TCORP reset	Jm
SDI verifier check ran	Jm

Housing:	Initials
Type of Housing. Write housing type here: NO IBS	Jm
Bulkhead or Cable p/n (circle one, provide p/n if cable)	Jm
Ferrite bead installed	Jm
Desiccant bag installed	Jm
Clean housing with acetone. Install label	Jm

Form # 9130-10-MS5T Rev.B
FSIL:\Operations\Production\Sigma&Hydrolab\OPS\HYDROLAB\Series 5 travelers\MS5.xls

Page 1 of 2

970-962-6710

Hach Labs

15:37:17 28-06-2010

4 / 4

Pressure Tank (142 psi):

	Initials
No Leaks <input checked="" type="checkbox"/> Leaks <input type="checkbox"/> (If leaks, provide comments on RRS form)	JM
Desiccant secure in place	
All screws and connectors secure in place (visual check)	
Tie wrap added around connector on MPL board	
Depth screw removed	

Calibration: Parameter

Parameter	Low Limit	High Limit	Actual	Initials
PH 7.00 buffer calibration verified - (+/- .2 pH)	6.8	7.2	7.02	JM
PH 10.01 buffer calibration verified - (+/- .2 pH) Verify at 4.01 <input checked="" type="checkbox"/>	9.81	10.21	10.02	
Conductivity zero (0.0) calibration verified - (+/- .005mS) in air	-0.005	0.005	0.0	
Conductivity 1.412mS/cm calibration verified - (+/- 0.5% of Reading)	1.4049	1.4191	1.412	
Conductivity verified .500mS/cm calibration verified - (+/- 0.5% of reading)	0.4975	0.5025	0.502	
ORR calibration verified - (423 +/- 20 mV)	403	443		
LDO /DO 100% saturation calibration verified-at 760 mmHg	99.5	100.5	100.0	
LDO /DO 100% saturation calibration verified-at 550 mmHg	99.5	100.5	99.9	
LDO /DO 100% saturation calibration verified- local (+/-5%) BP: 633	99.5	100.5	100.1	
Depth zero (0.0) calibration verified - (.025 meters) in air	-0.025	0.025	0.0	
Std Turbidity calibration verified in DI water 0.1-(+/- .5 NTU)	-0.4	0.6	0.1	
Std Turbidity calibrated at 100NTU - (+/- 10 NTU)	90	110	100	
Std Turbidity calibration verified at 40 NTU -(+/- 5 NTU)	35	45		
Self Cleaning Turb calibrated at 0.1 NTU (+/- 1%)	0.099	0.101	0.0	
Self Cleaning Turb calibrated at 100 NTU (+/- 1%)	99	101	99.8	
Chloride calibration verified (46.2 Lo-cal / 319.3 Hi-cal (1.412 cond. solution))		P / F	(NA)	
NO3 calibration verified (4.62 Lo-cal / 46.2 Hi-cal)		P / F	(NA)	
NH4 calibration verified (4.62 Lo-cal / 46.2 Hi-cal)		P / F	(NA)	
Chlorophyl / Rhodamine/ BG algae (circle one) calibration verified		P / F	(NA)	
TDG calibration verified		P / F	(NA)	

Environmental Chamber:

	Initials
EC test complete	JM
Check S/N, circulator, and no hardware errors or data anomalies	
Internal Battery Voltage: _____ V, (spec, xx-xx) <u>N/A for no IBP</u>	JM

Quality Control Check:

To be performed at pick and pack station:

Criteria:

	Initials
Options on traveler match order detail sheet and built instrument	
Traveler is complete with all columns filled, and values passed	
Kitting on traveler match order detail sheet and items in box.	

Form # 9130-10-MS5T Rev.B

FS1L:\Operations\Production\Sigma&HydroLab\OPSHYDROLAB\Series 5 travelers\MS5.xls

Page 2 of 2

Appendix 2 Detailed water quality and soil data

OCTOBER 20, 2010

STN	Temp (oC)	Cond (mS/cm)	Sal (ppt)	pH	D.O (mg/l)	Turb. (NTU)	TDS	GRO (mg/l)	DRO (mg/l)	Tot Phosphorus (mg/l)	Tot. Nitrogen (mg/l)	Tot. Organic Carbon (mg/l)	Benzene (mg/l)	Toluene (mg/l)	Ethylbenzene (mg/l)	Tot. Xylene (mg/l)	Methyl tert-butyl ether (mg/l)
Well 1	27.73	3.71	2.07	7.9	7.77	377.1	2.4	ND	0.46				ND	ND	ND	ND	ND
Well 2	30.39	2.053	1.11	7.86	1.56	0	1.35	ND	ND				ND	ND	ND	ND	ND
Well 3	29.46	7.55	4.22	7.24	0.58	67.5	4.85	ND	0.16	0.36	9	10	ND	ND	ND	ND	ND
Well 4	30.82	2.204	1.18	8.06	4.54	67.5	1.413	ND	ND				ND	ND	ND	ND	ND
Well 5	29.5	10.26	5.86	7.42	1.41	43.3	6.719	ND	0.29	0.14	4.8	24	ND	ND	ND	ND	ND
Lechate (Landfarm)	31.99	1.564	0.81	8.9	8.33	5.8	1	ND	0.13	ND	1.5	2.2	ND	ND	ND	ND	ND

	DRO (mg/kg)	GRO (mg/kg)	% moisture	BTEX
GRID 6-7	3.8	ND	13	ND
GRID 74	ND	ND	14	ND
GRID 98-99	4.8	ND	7.8	ND
GRID 126	11	ND	10	ND
GRID 127	3.4	ND	9	ND

ND - None Detected

*Submitted to: American Airlines
Prepared by: CL Environmental*



REVIEW OF ANALYTICAL REPORT

JOB NUMBER: 400-51407-1

AA 331 REMEDIATION

International Analytical Group, Inc. (IAG) has conducted an independent, third party review of the above referenced analytical report. The samples were analyzed by Test America Pensacola, a NELAC certified laboratory in Pensacola, Florida.

If you have any questions regarding this analytical report, please contact Maria Jackson at maria@iagenvironmental.com or (954) 894-4023.



5555 HOLLYWOOD BLVD, SUITE 301 HOLLYWOOD, FL 33021

*Submitted to: American Airlines
Prepared by: CL Environmental*

ANALYTICAL REPORT

Job Number: 400-51407-1

Job Description: AA 331 Remediation

For:

CL Environmental
22 Fort George Heights
Stony Hill,
Kingston 8, Jamaica

Attention: Carlton Campbell



Approved for release:
Marty Edwards
Senior Project Manager
11/3/2010 7:39 AM

Marty Edwards
Senior Project Manager
marty.edwards@testamericainc.com
11/03/2010

The test results in this report meet all NELAP requirements for accredited parameters, unless otherwise noted, and relate only to the referenced samples. Pursuant to NELAP, this report may not be reproduced, except in full, without written approval from the laboratory. For questions please contact the Project Manager at the e-mail address listed on this page, or the telephone number at the bottom of the page. TestAmerica Pensacola Certifications and Approvals: Alabama (40150), Arizona (AZ0710), Arkansas (88-0689), Florida (E81010), Illinois (200041), Iowa (367), Kansas (E-10253), Kentucky UST (53), Louisiana (30748), Maryland (233), Massachusetts (M-FL094), Michigan (9912), New Hampshire (250509), New Jersey (FL006), North Carolina (314), Oklahoma (9810), Pennsylvania (68-00467), Rhode Island (LAO00307), South Carolina (96026), Tennessee (TN02907), Texas (T104704286-09-1), Virginia (00008), Washington (C915), West Virginia (136), USDA Foreign Soil Permit (P330-08-00006).

TestAmerica Laboratories, Inc.
TestAmerica Pensacola 3355 McLemore Drive, Pensacola, FL 32514
Tel (850) 474-1001 Fax (850) 478-2671 www.testamericainc.com



METHOD SUMMARY

Client: CL Environmental

Job Number: 400-51407-1

Description	Lab Location	Method	Preparation Method
Matrix Solid			
Volatile Organic Compounds (GC/MS)	TAL PEN	SW846 8260B	
Closed System Purge and Trap	TAL PEN		SW846 5035
GRO by 8015M	TAL PEN	SW846 8015M	
Closed System Purge and Trap	TAL PEN		SW846 5035
Diesel Range Organics (DRO)	TAL PEN	SW846 8015M	
Ultrasonic Extraction	TAL PEN		SW846 3550B
Percent Moisture	TAL PEN	EPA Moisture	
Matrix Water			
BTEX+MTBE	TAL PEN	SW846 8260B	
Purge and Trap	TAL PEN		SW846 5030B
GRO by 8015M	TAL PEN	SW846 8015M	
Purge and Trap	TAL PEN		SW846 5030B
Diesel Range Organics (DRO)	TAL PEN	SW846 8015M	
Liquid-Liquid Extraction (Continuous)	TAL PEN		SW846 3520C
Phosphorus, Total	TAL PEN	EPA 365.4	
Phosphorus, Total	TAL PEN		MCAWW 365.2/365.3/365
Total Organic Carbon	TAL PEN	MCAWW 415.1	
Nitrogen, Total	TAL PEN	EPA Total Nitrogen	

Lab References:

TAL PEN = TestAmerica Pensacola

Method References:

EPA = US Environmental Protection Agency

MCAWW = "Methods For Chemical Analysis Of Water And Wastes", EPA-600/4-79-020, March 1983 And Subsequent Revisions.

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

METHOD / ANALYST SUMMARY

Client: CL Environmental

Job Number: 400-51407-1

Method	Analyst	Analyst ID
SW846 8260B	Drew, Walter	WD
SW846 8260B	Martin, Mary	MM
SW846 8015M	Arbuckle, Mardy	MA
SW846 8015M	Lee, Jefferson	JL
SW846 8015M	Ayers, Kim	KA
EPA 365.4	Gimlin, Wendy	WG
MCAWW 415.1	Rigby, Amy	AR
EPA Moisture	Chea, Vanda	VC
EPA Total Nitrogen	Gimlin, Wendy	WG

SAMPLE SUMMARY

Client: CL Environmental

Job Number: 400-51407-1

Lab Sample ID	Client Sample ID	Client Matrix	Date/Time Sampled	Date/Time Received
400-51407-1	WELL1-GRID9	Water	10/20/2010 0828	10/22/2010 0910
400-51407-2	WELL2-GRID166	Water	10/20/2010 0815	10/22/2010 0910
400-51407-3	WELL4-GRID37	Water	10/20/2010 0823	10/22/2010 0910
400-51407-4	WELL3-MARITIME	Water	10/20/2010 0925	10/22/2010 0910
400-51407-5	GRID 6/7-2.5'	Solid	10/20/2010 1006	10/22/2010 0910
400-51407-6	GRID 74-3'	Solid	10/20/2010 1019	10/22/2010 0910
400-51407-7	GRID 98/99-1.5'	Solid	10/20/2010 1029	10/22/2010 0910
400-51407-8	GRID 126-2'	Solid	10/20/2010 1041	10/22/2010 0910
400-51407-9	GRID 127-3'	Solid	10/20/2010 1057	10/22/2010 0910
400-51407-10	LEACHEATE	Water	10/20/2010 1157	10/22/2010 0910
400-51407-11	LEACHEATE 2	Water	10/20/2010 1215	10/22/2010 0910
400-51407-12	WELL5-LANDFARM	Water	10/20/2010 1250	10/22/2010 0910

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL1-GRID9

Lab Sample ID: 400-51407-1

Date Sampled: 10/20/2010 0828

Client Matrix: Water

Date Received: 10/22/2010 0910

8260B BTEX+MTBE

Method: 8260B

Analysis Batch: 400-119624

Instrument ID: CH_CONAN

Preparation: 5030B

Lab File ID: 102913.D

Dilution: 1.0

Initial Weight/Volume: 5 mL

Date Analyzed: 10/29/2010 1124

Final Weight/Volume: 5 mL

Date Prepared: 10/29/2010 1124

Analyte	Result (mg/L)	Qualifier	RL
Benzene	ND		0.0010
Toluene	ND		0.0050
Ethylbenzene	ND		0.0050
Xylenes, Total	ND		0.010
Methyl tert-butyl ether	ND		0.0050

Surrogate	%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene	91		76 - 114
Dibromofluoromethane	99		80 - 119
Toluene-d8 (Surr)	101		75 - 125

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL2-GRID166

Lab Sample ID: 400-51407-2

Date Sampled: 10/20/2010 0815

Client Matrix: Water

Date Received: 10/22/2010 0910

8260B BTEX+MTBE

Method: 8260B

Analysis Batch: 400-119624

Instrument ID: CH_CONAN

Preparation: 5030B

Lab File ID: 102915.D

Dilution: 1.0

Initial Weight/Volume: 5 mL

Date Analyzed: 10/29/2010 1158

Final Weight/Volume: 5 mL

Date Prepared: 10/29/2010 1158

Analyte	Result (mg/L)	Qualifier	RL
Benzene	ND		0.0010
Toluene	ND		0.0050
Ethylbenzene	ND		0.0050
Xylenes, Total	ND		0.010
Methyl tert-butyl ether	ND		0.0050

Surrogate	%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene	91		76 - 114
Dibromofluoromethane	100		80 - 119
Toluene-d8 (Surr)	100		75 - 125

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL4-GRID37

Lab Sample ID: 400-51407-3

Date Sampled: 10/20/2010 0823

Client Matrix: Water

Date Received: 10/22/2010 0910

8260B BTEX+MTBE

Method: 8260B
Preparation: 5030B
Dilution: 1.0
Date Analyzed: 10/29/2010 1232
Date Prepared: 10/29/2010 1232

Analysis Batch: 400-119624

Instrument ID: CH_CONAN
Lab File ID: 102917.D
Initial Weight/Volume: 5 mL
Final Weight/Volume: 5 mL

Analyte	Result (mg/L)	Qualifier	RL
Benzene	ND		0.0010
Toluene	ND		0.0050
Ethylbenzene	ND		0.0050
Xylenes, Total	ND		0.010
Methyl tert-butyl ether	ND		0.0050
Surrogate	%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene	92		76 - 114
Dibromofluoromethane	102		80 - 119
Toluene-d8 (Surr)	100		75 - 125

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL3-MARITIME

Lab Sample ID: 400-51407-4

Date Sampled: 10/20/2010 0925

Client Matrix: Water

Date Received: 10/22/2010 0910

8260B BTEX+MTBE

Method:	8260B	Analysis Batch:	400-119624	Instrument ID:	CH_CONAN
Preparation:	5030B			Lab File ID:	102919.D
Dilution:	1.0			Initial Weight/Volume:	5 mL
Date Analyzed:	10/29/2010 1306			Final Weight/Volume:	5 mL
Date Prepared:	10/29/2010 1306				

Analyte	Result (mg/L)	Qualifier	RL
Benzene	ND		0.0010
Toluene	ND		0.0050
Ethylbenzene	ND		0.0050
Xylenes, Total	ND		0.010
Methyl tert-butyl ether	ND		0.0050

Surrogate	%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene	93		76 - 114
Dibromofluoromethane	101		80 - 119
Toluene-d8 (Surr)	101		75 - 125

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 6/7-2.5'

Lab Sample ID: 400-51407-5

Date Sampled: 10/20/2010 1006

Client Matrix: Solid

% Moisture: 13.3

Date Received: 10/22/2010 0910

8260B Volatile Organic Compounds (GC/MS)

Method: 8260B

Analysis Batch: 400-119554

Instrument ID: CH_ANNA

Preparation: 5035

Prep Batch: 400-119571

Lab File ID: AS102826.D

Dilution: 1.0

Initial Weight/Volume: 4.69 g

Date Analyzed: 10/28/2010 1742

Final Weight/Volume: 5 g

Date Prepared: 10/25/2010 1500

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Benzene		ND		0.0061
Toluene		ND		0.0061
Ethylbenzene		ND		0.0061
Xylenes, Total		ND		0.012
Methyl tert-butyl ether		ND		0.0061
Surrogate		%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene		100		70 - 132
Dibromofluoromethane		99		74 - 125
Toluene-d8 (Surr)		100		73 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 74-3'

Lab Sample ID: 400-51407-6

Date Sampled: 10/20/2010 1019

Client Matrix: Solid

% Moisture: 13.7

Date Received: 10/22/2010 0910

8260B Volatile Organic Compounds (GC/MS)

Method: 8260B

Analysis Batch: 400-119554

Instrument ID: CH_ANNA

Preparation: 5035

Prep Batch: 400-119571

Lab File ID: AS102827.D

Dilution: 1.0

Initial Weight/Volume: 4.59 g

Date Analyzed: 10/28/2010 1803

Final Weight/Volume: 5 g

Date Prepared: 10/25/2010 1500

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Benzene		ND		0.0063
Toluene		ND		0.0063
Ethylbenzene		ND		0.0063
Xylenes, Total		ND		0.013
Methyl tert-butyl ether		ND		0.0063
Surrogate		%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene		99		70 - 132
Dibromofluoromethane		98		74 - 125
Toluene-d8 (Surr)		100		73 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 98/99-1.5'

Lab Sample ID: 400-51407-7

Date Sampled: 10/20/2010 1029

Client Matrix: Solid

% Moisture: 7.8

Date Received: 10/22/2010 0910

8260B Volatile Organic Compounds (GC/MS)

Method: 8260B

Analysis Batch: 400-119554

Instrument ID: CH_ANNA

Preparation: 5035

Prep Batch: 400-119571

Lab File ID: AS102828.D

Dilution: 1.0

Initial Weight/Volume: 5.15 g

Date Analyzed: 10/28/2010 1823

Final Weight/Volume: 5 g

Date Prepared: 10/25/2010 1500

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Benzene		ND		0.0053
Toluene		ND		0.0053
Ethylbenzene		ND		0.0053
Xylenes, Total		ND		0.011
Methyl tert-butyl ether		ND		0.0053
Surrogate		%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene		99		70 - 132
Dibromofluoromethane		99		74 - 125
Toluene-d8 (Surr)		99		73 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 126-2'

Lab Sample ID: 400-51407-8

Date Sampled: 10/20/2010 1041

Client Matrix: Solid

% Moisture: 10.4

Date Received: 10/22/2010 0910

8260B Volatile Organic Compounds (GC/MS)

Method: 8260B

Analysis Batch: 400-119554

Instrument ID: CH_ANNA

Preparation: 5035

Prep Batch: 400-119571

Lab File ID: AS102829.D

Dilution: 1.0

Initial Weight/Volume: 4.88 g

Date Analyzed: 10/28/2010 1844

Final Weight/Volume: 5 g

Date Prepared: 10/25/2010 1500

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Benzene		ND		0.0057
Toluene		ND		0.0057
Ethylbenzene		ND		0.0057
Xylenes, Total		ND		0.011
Methyl tert-butyl ether		ND		0.0057
Surrogate		%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene		99		70 - 132
Dibromofluoromethane		98		74 - 125
Toluene-d8 (Surr)		99		73 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 127-3'

Lab Sample ID: 400-51407-9

Date Sampled: 10/20/2010 1057

Client Matrix: Solid

% Moisture: 9.0

Date Received: 10/22/2010 0910

8260B Volatile Organic Compounds (GC/MS)

Method: 8260B

Analysis Batch: 400-119554

Instrument ID: CH_ANNA

Preparation: 5035

Prep Batch: 400-119571

Lab File ID: AS102830.D

Dilution: 1.0

Initial Weight/Volume: 4.84 g

Date Analyzed: 10/28/2010 1904

Final Weight/Volume: 5 g

Date Prepared: 10/25/2010 1500

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Benzene		ND		0.0057
Toluene		ND		0.0057
Ethylbenzene		ND		0.0057
Xylenes, Total		ND		0.011
Methyl tert-butyl ether		ND		0.0057
Surrogate		%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene		100		70 - 132
Dibromofluoromethane		99		74 - 125
Toluene-d8 (Surr)		100		73 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: LEACHEATE

Lab Sample ID: 400-51407-10

Client Matrix: Water

Date Sampled: 10/20/2010 1157

Date Received: 10/22/2010 0910

8260B BTEX+MTBE

Method: 8260B
Preparation: 5030B
Dilution: 1.0
Date Analyzed: 10/27/2010 1625
Date Prepared: 10/27/2010 1625

Analysis Batch: 400-119505

Instrument ID: CH_CONAN
Lab File ID: 102711.D
Initial Weight/Volume: 5 mL
Final Weight/Volume: 5 mL

Analyte	Result (mg/L)	Qualifier	RL
Benzene	ND		0.0010
Toluene	ND		0.0050
Ethylbenzene	ND		0.0050
Xylenes, Total	ND		0.010
Methyl tert-butyl ether	ND		0.0050
Surrogate	%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene	90		76 - 114
Dibromofluoromethane	93		80 - 119
Toluene-d8 (Surr)	99		75 - 125

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: LEACHEATE 2

Lab Sample ID: 400-51407-11

Date Sampled: 10/20/2010 1215

Client Matrix: Water

Date Received: 10/22/2010 0910

8260B BTEX+MTBE

Method: 8260B

Analysis Batch: 400-119505

Instrument ID: CH_CONAN

Preparation: 5030B

Lab File ID: 102713.D

Dilution: 1.0

Initial Weight/Volume: 5 mL

Date Analyzed: 10/27/2010 1659

Final Weight/Volume: 5 mL

Date Prepared: 10/27/2010 1659

Analyte	Result (mg/L)	Qualifier	RL
Benzene	ND		0.0010
Toluene	ND		0.0050
Ethylbenzene	ND		0.0050
Xylenes, Total	ND		0.010
Methyl tert-butyl ether	ND		0.0050

Surrogate	%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene	90		76 - 114
Dibromofluoromethane	95		80 - 119
Toluene-d8 (Surr)	100		75 - 125

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL5-LANDFARM

Lab Sample ID: 400-51407-12

Date Sampled: 10/20/2010 1250

Client Matrix: Water

Date Received: 10/22/2010 0910

8260B BTEX+MTBE

Method: 8260B

Analysis Batch: 400-119505

Instrument ID: CH_CONAN

Preparation: 5030B

Lab File ID: 102715.D

Dilution: 1.0

Initial Weight/Volume: 5 mL

Date Analyzed: 10/27/2010 1734

Final Weight/Volume: 5 mL

Date Prepared: 10/27/2010 1734

Analyte	Result (mg/L)	Qualifier	RL
Benzene	ND		0.0010
Toluene	ND		0.0050
Ethylbenzene	ND		0.0050
Xylenes, Total	ND		0.010
Methyl tert-butyl ether	ND		0.0050
Surrogate	%Rec	Qualifier	Acceptance Limits
4-Bromofluorobenzene	92		76 - 114
Dibromofluoromethane	97		80 - 119
Toluene-d8 (Surr)	100		75 - 125

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL1-GRID9

Lab Sample ID: 400-51407-1

Date Sampled: 10/20/2010 0828

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119370

Instrument ID: ETHYL

Preparation: 5030B

Initial Weight/Volume: 5.00 mL

Dilution: 1.0

Final Weight/Volume: 5.00 mL

Date Analyzed: 10/25/2010 2316

Injection Volume:

Date Prepared: 10/25/2010 2316

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10	ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	102		69 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL2-GRID166

Lab Sample ID: 400-51407-2

Date Sampled: 10/20/2010 0815

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119370

Instrument ID: ETHYL

Preparation: 5030B

Initial Weight/Volume: 5.00 mL

Dilution: 1.0

Final Weight/Volume: 5.00 mL

Date Analyzed: 10/26/2010 0016

Injection Volume:

Date Prepared: 10/26/2010 0016

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10	ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	101		69 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL4-GRID37

Lab Sample ID: 400-51407-3

Date Sampled: 10/20/2010 0823

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119370

Instrument ID: ETHYL

Preparation: 5030B

Initial Weight/Volume: 5.00 mL

Dilution: 1.0

Final Weight/Volume: 5.00 mL

Date Analyzed: 10/26/2010 0115

Injection Volume:

Date Prepared: 10/26/2010 0115

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10	ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	103		69 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL3-MARITIME

Lab Sample ID: 400-51407-4

Date Sampled: 10/20/2010 0925

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119471

Instrument ID: ETHYL

Preparation: 5030B

Initial Weight/Volume: 5.00 mL

Dilution: 1.0

Final Weight/Volume: 5.00 mL

Date Analyzed: 10/26/2010 1637

Injection Volume:

Date Prepared: 10/26/2010 1637

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10	ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	102		69 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 6/7-2.5'

Lab Sample ID: 400-51407-5

Date Sampled: 10/20/2010 1006

Client Matrix: Solid

% Moisture: 13.3

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119474

Instrument ID: RITA

Preparation: 5035

Prep Batch: 400-119488

Initial Weight/Volume: 5.14 g

Dilution: 1.0

Final Weight/Volume: 5.00 g

Date Analyzed: 10/26/2010 1946

Injection Volume:

Date Prepared: 10/26/2010 0839

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10		ND		0.11

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	97		67 - 119

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 74-3'

Lab Sample ID: 400-51407-6

Date Sampled: 10/20/2010 1019

Client Matrix: Solid

% Moisture: 13.7

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119474

Instrument ID: RITA

Preparation: 5035

Prep Batch: 400-119488

Initial Weight/Volume: 5.00 g

Dilution: 1.0

Final Weight/Volume: 5.00 g

Date Analyzed: 10/26/2010 2012

Injection Volume:

Date Prepared: 10/26/2010 0839

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10		ND		0.12

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	97		67 - 119

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 98/99-1.5'

Lab Sample ID: 400-51407-7

Date Sampled: 10/20/2010 1029

Client Matrix: Solid

% Moisture: 7.8

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119474

Instrument ID: RITA

Preparation: 5035

Prep Batch: 400-119488

Initial Weight/Volume: 5.30 g

Dilution: 1.0

Final Weight/Volume: 5.00 g

Date Analyzed: 10/26/2010 2038

Injection Volume:

Date Prepared: 10/26/2010 0839

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10		ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	98		67 - 119

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 126-2'

Lab Sample ID: 400-51407-8

Date Sampled: 10/20/2010 1041

Client Matrix: Solid

% Moisture: 10.4

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119474

Instrument ID: RITA

Preparation: 5035

Prep Batch: 400-119488

Initial Weight/Volume: 5.42 g

Dilution: 1.0

Final Weight/Volume: 5.00 g

Date Analyzed: 10/26/2010 2105

Injection Volume:

Date Prepared: 10/26/2010 0839

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10		ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	100		67 - 119

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 127-3'

Lab Sample ID: 400-51407-9

Date Sampled: 10/20/2010 1057

Client Matrix: Solid

% Moisture: 9.0

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119474

Instrument ID: RITA

Preparation: 5035

Prep Batch: 400-119488

Initial Weight/Volume: 5.13 g

Dilution: 1.0

Final Weight/Volume: 5.00 g

Date Analyzed: 10/26/2010 2131

Injection Volume:

Date Prepared: 10/26/2010 0839

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10		ND		0.11

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	99		67 - 119

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: LEACHEATE

Lab Sample ID: 400-51407-10

Client Matrix: Water

Date Sampled: 10/20/2010 1157

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119370

Instrument ID: ETHYL

Preparation: 5030B

Initial Weight/Volume: 5.00 mL

Dilution: 1.0

Final Weight/Volume: 5.00 mL

Date Analyzed: 10/26/2010 0513

Injection Volume:

Date Prepared: 10/26/2010 0513

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10	ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	96		69 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: LEACHEATE 2

Lab Sample ID: 400-51407-11

Date Sampled: 10/20/2010 1215

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119370

Instrument ID: ETHYL

Preparation: 5030B

Initial Weight/Volume: 5.00 mL

Dilution: 1.0

Final Weight/Volume: 5.00 mL

Date Analyzed: 10/26/2010 0612

Injection Volume:

Date Prepared: 10/26/2010 0612

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10	ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	100		69 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL5-LANDFARM

Lab Sample ID: 400-51407-12

Date Sampled: 10/20/2010 1250

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M GRO by 8015M

Method: 8015M

Analysis Batch: 400-119370

Instrument ID: ETHYL

Preparation: 5030B

Initial Weight/Volume: 5.00 mL

Dilution: 1.0

Final Weight/Volume: 5.00 mL

Date Analyzed: 10/26/2010 0712

Injection Volume:

Date Prepared: 10/26/2010 0712

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Gasoline Range Organics (GRO)-C6-C10	ND		0.10

Surrogate	%Rec	Qualifier	Acceptance Limits
a,a,a-Trifluorotoluene (fid)	98		69 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL1-GRID9

Lab Sample ID: 400-51407-1

Date Sampled: 10/20/2010 0828

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M
Preparation: 3520C
Dilution: 1.0
Date Analyzed: 10/27/2010 1727
Date Prepared: 10/25/2010 1422

Analysis Batch: 400-119483
Prep Batch: 400-119292

Instrument ID: ROXY
Initial Weight/Volume: 1020 mL
Final Weight/Volume: 5.0 mL
Injection Volume:
Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Diesel Range Organics [C10-C28]	0.46		0.098

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	113		40 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL2-GRID166

Lab Sample ID: 400-51407-2

Date Sampled: 10/20/2010 0815

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M

Analysis Batch: 400-119483

Instrument ID: ROXY

Preparation: 3520C

Prep Batch: 400-119292

Initial Weight/Volume: 1060 mL

Dilution: 1.0

Final Weight/Volume: 5.0 mL

Date Analyzed: 10/27/2010 1739

Injection Volume:

Date Prepared: 10/25/2010 1422

Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Diesel Range Organics [C10-C28]	ND		0.094

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	107		40 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL4-GRID37

Lab Sample ID: 400-51407-3

Date Sampled: 10/20/2010 0823

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M
Preparation: 3520C
Dilution: 1.0
Date Analyzed: 10/27/2010 1751
Date Prepared: 10/25/2010 1422

Analysis Batch: 400-119483
Prep Batch: 400-119292

Instrument ID: ROXY
Initial Weight/Volume: 1010 mL
Final Weight/Volume: 5.0 mL
Injection Volume:
Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Diesel Range Organics [C10-C28]	ND		0.099

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	103		40 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL3-MARITIME

Lab Sample ID: 400-51407-4

Date Sampled: 10/20/2010 0925

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M
Preparation: 3520C
Dilution: 1.0
Date Analyzed: 10/27/2010 1803
Date Prepared: 10/25/2010 1422

Analysis Batch: 400-119483
Prep Batch: 400-119292

Instrument ID: ROXY
Initial Weight/Volume: 1030 mL
Final Weight/Volume: 5.0 mL
Injection Volume:
Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Diesel Range Organics [C10-C28]	0.16		0.097

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	109		40 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 6/7-2.5'

Lab Sample ID: 400-51407-5

Date Sampled: 10/20/2010 1006

Client Matrix: Solid

% Moisture: 13.3

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M

Analysis Batch: 400-119548

Instrument ID: ROXY

Preparation: 3550B

Prep Batch: 400-119436

Initial Weight/Volume: 30.41 g

Dilution: 1.0

Final Weight/Volume: 5.0 mL

Date Analyzed: 10/28/2010 0156

Injection Volume:

Date Prepared: 10/27/2010 0819

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Diesel Range Organics [C10-C28]		3.8		2.8

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	92		30 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 74-3'

Lab Sample ID: 400-51407-6

Date Sampled: 10/20/2010 1019

Client Matrix: Solid

% Moisture: 13.7

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M

Analysis Batch: 400-119548

Instrument ID: ROXY

Preparation: 3550B

Prep Batch: 400-119436

Initial Weight/Volume: 30.35 g

Dilution: 1.0

Final Weight/Volume: 5.0 mL

Date Analyzed: 10/28/2010 0207

Injection Volume:

Date Prepared: 10/27/2010 0819

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Diesel Range Organics [C10-C28]		ND		2.9
Surrogate		%Rec	Qualifier	Acceptance Limits
o-Terphenyl		89		30 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 98/99-1.5'

Lab Sample ID: 400-51407-7

Date Sampled: 10/20/2010 1029

Client Matrix: Solid

% Moisture: 7.8

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M

Analysis Batch: 400-119548

Instrument ID: ROXY

Preparation: 3550B

Prep Batch: 400-119436

Initial Weight/Volume: 30.43 g

Dilution: 1.0

Final Weight/Volume: 5.0 mL

Date Analyzed: 10/28/2010 0219

Injection Volume:

Date Prepared: 10/27/2010 0819

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Diesel Range Organics [C10-C28]		4.8		2.7

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	91		30 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 126-2'

Lab Sample ID: 400-51407-8

Date Sampled: 10/20/2010 1041

Client Matrix: Solid

% Moisture: 10.4

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M

Analysis Batch: 400-119548

Instrument ID: ROXY

Preparation: 3550B

Prep Batch: 400-119436

Initial Weight/Volume: 30.40 g

Dilution: 1.0

Final Weight/Volume: 5.0 mL

Date Analyzed: 10/28/2010 0231

Injection Volume:

Date Prepared: 10/27/2010 0819

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Diesel Range Organics [C10-C28]		11		2.8

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	86		30 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: GRID 127-3'

Lab Sample ID: 400-51407-9

Date Sampled: 10/20/2010 1057

Client Matrix: Solid

% Moisture: 9.0

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M

Analysis Batch: 400-119548

Instrument ID: ROXY

Preparation: 3550B

Prep Batch: 400-119436

Initial Weight/Volume: 30.26 g

Dilution: 1.0

Final Weight/Volume: 5.0 mL

Date Analyzed: 10/28/2010 0243

Injection Volume:

Date Prepared: 10/27/2010 0819

Result Type: PRIMARY

Analyte	DryWt Corrected: Y	Result (mg/Kg)	Qualifier	RL
Diesel Range Organics [C10-C28]		3.4		2.7

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	95		30 - 118

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: LEACHEATE

Lab Sample ID: 400-51407-10

Client Matrix: Water

Date Sampled: 10/20/2010 1157

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M
Preparation: 3520C
Dilution: 1.0
Date Analyzed: 10/27/2010 1815
Date Prepared: 10/25/2010 1422

Analysis Batch: 400-119483
Prep Batch: 400-119292

Instrument ID: ROXY
Initial Weight/Volume: 1050 mL
Final Weight/Volume: 5.0 mL
Injection Volume:
Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Diesel Range Organics [C10-C28]	0.13		0.095

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	101		40 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: LEACHEATE 2

Lab Sample ID: 400-51407-11

Date Sampled: 10/20/2010 1215

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M
Preparation: 3520C
Dilution: 1.0
Date Analyzed: 10/27/2010 1826
Date Prepared: 10/25/2010 1422

Analysis Batch: 400-119483
Prep Batch: 400-119292

Instrument ID: ROXY
Initial Weight/Volume: 1040 mL
Final Weight/Volume: 5.0 mL
Injection Volume:
Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Diesel Range Organics [C10-C28]	0.096		0.096

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	104		40 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

Client Sample ID: WELL5-LANDFARM

Lab Sample ID: 400-51407-12

Date Sampled: 10/20/2010 1250

Client Matrix: Water

Date Received: 10/22/2010 0910

8015M Diesel Range Organics (DRO)

Method: 8015M
Preparation: 3520C
Dilution: 1.0
Date Analyzed: 10/27/2010 1838
Date Prepared: 10/25/2010 1422

Analysis Batch: 400-119483
Prep Batch: 400-119292

Instrument ID: ROXY
Initial Weight/Volume: 1050 mL
Final Weight/Volume: 5.0 mL
Injection Volume:
Result Type: PRIMARY

Analyte	Result (mg/L)	Qualifier	RL
Diesel Range Organics [C10-C28]	0.29		0.095

Surrogate	%Rec	Qualifier	Acceptance Limits
o-Terphenyl	109		40 - 127

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: WELL3-MARITIME

Lab Sample ID: 400-51407-4

Date Sampled: 10/20/2010 0925

Client Matrix: Water

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Phosphorus, Total	0.36		mg/L	0.10	1.0	365.4
	Analysis Batch: 400-119759		Date Analyzed: 11/01/2010 1029			
	Prep Batch: 400-119532		Date Prepared: 10/27/2010 0930			
Total Organic Carbon	10		mg/L	1.0	1.0	415.1
	Analysis Batch: 400-119398		Date Analyzed: 10/26/2010 1407			
Nitrogen, Total	9.0		mg/L	0.50	1.0	Total Nitrogen
	Analysis Batch: 400-119731		Date Analyzed: 11/02/2010 1605			

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: GRID 6/7-2.5'

Lab Sample ID: 400-51407-5

Client Matrix: Solid

Date Sampled: 10/20/2010 1008

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Percent Moisture	13		%	0.10	1.0	Moisture

Analysis Batch: 400-119469 Date Analyzed: 10/27/2010 1053 DryWt Corrected: N

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: GRID 74-3'

Lab Sample ID: 400-51407-6

Client Matrix: Solid

Date Sampled: 10/20/2010 1019

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Percent Moisture	14		%	0.10	1.0	Moisture

Analysis Batch: 400-119469 Date Analyzed: 10/27/2010 1053 DryWt Corrected: N

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: GRID 98/99-1.5'

Lab Sample ID: 400-51407-7

Client Matrix: Solid

Date Sampled: 10/20/2010 1029

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Percent Moisture	7.8		%	0.10	1.0	Moisture

Analysis Batch: 400-119469 Date Analyzed: 10/27/2010 1053 DryWt Corrected: N

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: GRID 126-2'

Lab Sample ID: 400-51407-8

Client Matrix: Solid

Date Sampled: 10/20/2010 1041

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Percent Moisture	10		%	0.10	1.0	Moisture

Analysis Batch: 400-119469 Date Analyzed: 10/27/2010 1053 DryWt Corrected: N

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: GRID 127-3'

Lab Sample ID: 400-51407-9

Client Matrix: Solid

Date Sampled: 10/20/2010 1057

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Percent Moisture	9.0		%	0.10	1.0	Moisture

Analysis Batch: 400-119469 Date Analyzed: 10/27/2010 1053 DryWt Corrected: N

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: LEACHEATE

Lab Sample ID: 400-51407-10

Client Matrix: Water

Date Sampled: 10/20/2010 1157

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Phosphorus, Total	ND		mg/L	0.10	1.0	365.4
	Analysis Batch: 400-119759		Date Analyzed: 11/01/2010 1029			
	Prep Batch: 400-119532		Date Prepared: 10/27/2010 0930			
Total Organic Carbon	2.2		mg/L	1.0	1.0	415.1
	Analysis Batch: 400-119398		Date Analyzed: 10/26/2010 1428			
Nitrogen, Total	1.5		mg/L	0.50	1.0	Total Nitrogen
	Analysis Batch: 400-119731		Date Analyzed: 11/02/2010 1605			

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: LEACHEATE 2

Lab Sample ID: 400-51407-11

Client Matrix: Water

Date Sampled: 10/20/2010 1215

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Phosphorus, Total	ND		mg/L	0.10	1.0	365.4
	Analysis Batch: 400-119759		Date Analyzed: 11/01/2010 1029			
	Prep Batch: 400-119532		Date Prepared: 10/27/2010 0930			
Total Organic Carbon	1.4		mg/L	1.0	1.0	415.1
	Analysis Batch: 400-119398		Date Analyzed: 10/26/2010 1449			
Nitrogen, Total	1.3		mg/L	0.50	1.0	Total Nitrogen
	Analysis Batch: 400-119731		Date Analyzed: 11/02/2010 1605			

Analytical Data

Client: CL Environmental

Job Number: 400-51407-1

General Chemistry

Client Sample ID: WELL5-LANDFARM

Lab Sample ID: 400-51407-12

Date Sampled: 10/20/2010 1250

Client Matrix: Water

Date Received: 10/22/2010 0910

Analyte	Result	Qual	Units	RL	Dil	Method
Phosphorus, Total	0.14		mg/L	0.10	1.0	365.4
	Analysis Batch: 400-119759		Date Analyzed: 11/01/2010 1029			
	Prep Batch: 400-119532		Date Prepared: 10/27/2010 0930			
Total Organic Carbon	24		mg/L	1.0	1.0	415.1
	Analysis Batch: 400-119398		Date Analyzed: 10/26/2010 1509			
Nitrogen, Total	4.8		mg/L	0.50	1.0	Total Nitrogen
	Analysis Batch: 400-119731		Date Analyzed: 11/02/2010 1605			

<p style="text-align: center;">INTERNATIONAL ANALYTICAL GROUP 400-51407</p> <p style="text-align: center;">CHAIN OF CUSTODY RECORD (DEP 62-770.900 (modified form))</p>			<p>FDEP Facility No. _____</p> <p>Page <u>1</u> of <u>2</u></p> <p>Sampling CompQAP No. _____</p> <p>Approval Date: _____</p>	
<p>5555 HOLLYWOOD BOULEVARD, SUITE 301, HOLLYWOOD, FLORIDA 33021 PHONE: 954-894-4023 • FAX: 954-894-4501 • CELLULAR: 954-494-3272</p>			<p>Print - Sampler Copy</p>	
<p>Original - Return w/ Report</p>			<p>Yellow - Lab Copy</p>	
<p>Report To: CL ENVIRONMENTAL Co LTD.</p> <p>Report To Address: 32 FORT GEORGE HEIGHTS KINGSTON 8</p>			<p>Report To Address: P.O. BOX 814407, HOLLYWOOD, FLORIDA 33081-4407</p>	
<p>Bill To: INTERNATIONAL ANALYTICAL GROUP (IAG)</p>			<p>Billing Address: P.O. BOX 814407, HOLLYWOOD, FLORIDA 33081-4407</p>	
<p>Project Number/Name: AA 331 Remediation</p>			<p>Site Location: AA 331 INCIDENT SITE</p>	
<p>Project Contact: CARLTON CAMPBELL</p>			<p>Phone: 876-371-2267</p>	
<p>Alternate Contact: JARLETTE MANNING</p>			<p>FAX: 876-422-3661</p>	
<p>Sampled By (print): JARLETTE MANNING</p>			<p>FAX: _____</p>	
<p>Sampler's Signature _____</p>			<p>Sampler's Signature _____</p>	

ITEM #	SAMPLE ID	DATE COLLECTED	TIME COLLECTED	PH	TEMP °C	CONC	MATRIX	SAMPLE LOCATION/ JOB DESCRIPTION (optional if needed when samples are from different site locations)	# CONTAINERS	ANALYSIS REQUIRED			Sample Condition as Received: Temp _____ C Sealed Yes No
										PLATE NAME OR METHOD NUMBER OF TESTS NEEDED IN LARGE BOXES BELOW. (✓) CHECK OFF WHICH SAMPLE ITEMS NEED EACH TEST PERFORMED	Lot Number of Sampling Containers Used	Lot Number of Sampling Containers Used	
1	Well 11-Grid 9	10-20-10	08:28				GW		5	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	1
2	Well 12-Grid 166	10-20-10	08:15				GW		5	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	2
3	Well 14-Grid 37	10-20-10	09:23				GW		5	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	3
4	Well 13- Machine	10-20-10	09:25				GW		9	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	4
5	Grid 67-2-5'	10-20-10	10:06				S		1	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	5
6	Grid 74-3'	10-20-10	10:14				S		1	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	6
7	Grid 98/99-15	10-20-10	10:29				S		1	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	7
8	Grid 126-2'	10-20-10	10:41				S		1	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	8
9	Grid 127-3'	10-20-10	10:57				S		1	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	9
10	Leachate	10-20-10	11:57				SW		9	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	<input checked="" type="checkbox"/> TRM-Geo (GeoS)	6
<p>Special Comments: Email results to: c.lenniv@clenviro.com + jenservices1@gmail.com</p>										<p>QA/QC Report Needed? Yes No (See price guide for applicable fees)</p> <p>Report Format: Standard Other (specify)</p>			
<p>(1) Relinquished by Signature: _____ Date: 20 Oct 2010</p>										<p>Relinquished by Signature: _____ Date: 20 Oct 2010</p>			
<p>Company: CL/ JEMS</p>										<p>Company: _____ Date: 13:30</p>			
<p>(1) Received by Signature: _____ Date: _____</p>										<p>Received by Signature: _____ Date: 10/20/10</p>			
<p>Company: _____</p>										<p>Company: _____ Date: _____</p>			
<p>(1) Relinquished by Signature: _____ Date: _____</p>										<p>Relinquished by Signature: _____ Date: _____</p>			
<p>Company: _____</p>										<p>Company: _____ Date: _____</p>			
<p>Special Comments: _____</p>										<p>Special Comments: _____</p>			

Submitted to: American Airlines
Prepared by: CL Environmental

INTERNATIONAL ANALYTICAL GROUP 400-51407
CHAIN OF CUSTODY RECORD (DEP 62-770.900 (modified form))

Submission Code: _____ Page 2 of 2
Orders: 5555 HOLLYWOOD BOULEVARD, SUITE 301, HOLLYWOOD, FLORIDA 33021 Sampling CompQAP No. _____
Entered to IIRMS: PHONE: 954-894-4023 • FAX: 954-894-4501 • CELLULAR: 954-494-3272 Approval Date: _____

Original - Return w/ Report Yellow - Lab Copy Pink - Sampler Copy

Report To: **CL ENVIRONMENTAL Co LTD** Report To Address: **22 FOOT GEORGE HEIGHTS KINGSTON B**
Bill To: **INTERNATIONAL ANALYTICAL GROUP (IAG)** Billing Address: **P.O. BOX 814407, HOLLYWOOD, FLORIDA 33081-4407**
Project Number/Name: **AA 331 Remediation** Site Location: **AA 331 INCIDENT SITE**
Project Contact: **CARLTON CAMPBELL** Phone: **876-371-2267** FAX: _____
Alternate Contact: **JANETTE MANNING** Phone: **876-422-3661** FAX: _____
Sampled By (print): **JANETTE MANNING** Sampler's Signature: _____

I T E M #	S A M P L E I D	D A T E C O L L E C T E D	T I M E C O L L E C T E D	P H	T E M P ° C	M A T R I X	S A M P L E L O C A T I O N / J O B D E S C R I P T (optional if needed when samples are from different site locations)	# C O N T A I N E R S	A N A L Y S I S R E Q U I R E D		S a m p l e C o n d i t i o n a s R e c e 	L o t N u m b e r o f S a m p l i n g C o n t a i n e r s U s e d	
									PLATE NAME OR METHOD NUMBER OF TESTS NEEDED IN LARGE BOXES BELOW. (✓) CHECK OFF WHICH SAMPLE ITEMS NEED EACH TEST PERFORMED	Other (specify)			
04	Leachate 2	10-20-10	12:15			SW		9	X	X	X	X	
05	Wells-Landfarm	10-20-10				GW		9	X	X	X	X	
3													
4													
5													
6													
7													
8													
9													
10													

Special Comments: **Final results: clenviro@worldnet.att.net**
 (1) Relinquished by Signatory: **CL ENVIRONMENTAL Co LTD** Date: **20 Oct 2010** Time: **13:30**
 (2) Relinquished by Signatory: _____ Date: _____ Time: _____
 Company: **CL ENVIRONMENTAL Co LTD**
 (1) Received by Signatory: _____ Date: **10/22/10** Time: **9:10**
 Company: _____
 (2) Received by Signatory: _____ Date: _____ Time: _____
 Company: _____

QA/QC Report Needed: Yes No (See price guide for applicable fees)
 Report Format: Standard Other (specify)

DUE DATE REQUESTED: _____
 Confirmation # _____
 Coating Code: _____
 Misc. Charges: _____
 SHADED AREAS ARE FOR LAB USE ONLY

Login Sample Receipt Check List

Client: CL Environmental

Job Number: 400-51407-1

Login Number: 51407
Creator: Hor, Koma
List Number: 1

List Source: TestAmerica Pensacola

Question	T / F / NA	Comment
Radioactivity either was not measured or, if measured, is at or below background	N/A	
The cooler's custody seal, if present, is intact.	N/A	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	4.8°C
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the sample IDs on the containers and the COC.	True	
Samples are received within Holding Time.	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified	False	LEACHEATE, LEACHEATE 2, WELL5-LANDFARM, all vials were received unpreserved.
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
VOA sample vials do not have headspace or bubble is <6mm (1/4") in diameter.	True	
If necessary, staff have been informed of any short hold time or quick TAT needs	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	

Appendix 3 Detailed meteorological data

		Temp	Hi	Low	Out	Dew	Wind	Wind	Hi	Hi			Rain
Date	Time	Out	Temp	Temp	Hum	Pt.	Speed	Dir	Speed	Dir	Bar	Rain	Rate
10/1/2010	12:15 AM	24.8	24.8	24.8	97	24.3	0	ESE	0.4	ESE	1009.2	0	0
10/1/2010	12:30 AM	24.8	24.8	24.8	97	24.3	0	---	0.4	ESE	1009	0	0
10/1/2010	12:45 AM	24.9	24.9	24.8	97	24.4	0	ESE	0.4	ESE	1008.7	0	0
10/1/2010	1:00 AM	24.8	24.9	24.8	97	24.3	0	ESE	0.4	ESE	1008.4	0	0
10/1/2010	1:15 AM	24.7	24.8	24.7	97	24.2	0	---	0	---	1008.3	0	0
10/1/2010	1:30 AM	24.6	24.7	24.6	97	24.1	0	ESE	0.4	ESE	1008.3	0	0
10/1/2010	1:45 AM	24.6	24.6	24.6	97	24	0	ESE	0.4	ESE	1008.2	0	0
10/1/2010	2:00 AM	24.6	24.6	24.5	97	24	0	ESE	0.4	ESE	1008.1	0	0
10/1/2010	2:15 AM	24.6	24.6	24.5	97	24	0	---	0	---	1007.9	0	0
10/1/2010	2:30 AM	24.4	24.6	24.4	97	23.9	0	ESE	0.4	ESE	1007.8	0	0
10/1/2010	2:45 AM	24.3	24.4	24.2	97	23.8	0	ESE	0.9	ESE	1008	0	0
10/1/2010	3:00 AM	24.4	24.4	24.3	97	23.9	0	ESE	0.4	ESE	1007.9	0	0
10/1/2010	3:15 AM	24.4	24.4	24.4	97	23.9	0	ESE	0.9	ESE	1007.9	0	0
10/1/2010	3:30 AM	24.4	24.4	24.4	97	23.9	0.4	ESE	1.8	ESE	1008	0	0
10/1/2010	3:45 AM	24.5	24.6	24.4	96	23.8	0.4	ESE	2.2	ESE	1008.1	0	0
10/1/2010	4:00 AM	24.6	24.6	24.4	96	23.9	0	ESE	0.9	ESE	1008.1	0	0
10/1/2010	4:15 AM	24.4	24.6	24.4	96	23.8	0	ESE	0.9	ESE	1008.2	0	0
10/1/2010	4:30 AM	24.4	24.4	24.4	96	23.7	0	ESE	0.9	ESE	1008.3	0	0
10/1/2010	4:45 AM	24.3	24.4	24.3	96	23.7	0	ESE	0.9	ESE	1008.4	0	0
10/1/2010	5:00 AM	24.3	24.3	24.3	96	23.7	0	ESE	0.4	ESE	1008.3	0	0
10/1/2010	5:15 AM	24.1	24.3	24.1	95	23.2	0	ESE	0.4	ESE	1008.4	0	0
10/1/2010	5:30 AM	23.9	24.1	23.9	95	23.1	0	---	0	---	1008.5	0	0
10/1/2010	5:45 AM	23.9	23.9	23.9	96	23.3	0	---	0	---	1008.6	0	0
10/1/2010	6:00 AM	24.1	24.1	23.9	96	23.4	0	ESE	0.4	ESE	1008.8	0	0
10/1/2010	6:15 AM	24.2	24.2	24	96	23.5	0	---	0	---	1008.9	0	0
10/1/2010	6:30 AM	24.4	24.4	24.2	96	23.7	0	---	0	---	1008.8	0	0
10/1/2010	6:45 AM	24.8	24.8	24.4	97	24.3	0	---	0	---	1008.9	0	0
10/1/2010	7:00 AM	25.3	25.3	24.8	95	24.5	0	ESE	0.4	ESE	1008.8	0	0
10/1/2010	7:15 AM	26.3	26.3	25.3	92	24.9	0	---	0	---	1008.8	0	0
10/1/2010	7:30 AM	27.7	27.7	26.4	87	25.3	0	---	0	---	1008.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/1/2010	7:45 AM	27.9	28.2	27.7	85	25.2	0	---	0	---	1009.4	0	0
10/1/2010	8:00 AM	27.9	28.3	27.9	84	24.9	0.9	SSE	2.7	SSE	1009.7	0	0
10/1/2010	8:15 AM	27.9	27.9	27.7	83	24.7	0.4	SSE	2.2	SSE	1009.9	0	0
10/1/2010	8:30 AM	28.1	28.1	27.8	83	24.9	0	SE	1.8	SE	1010	0	0
10/1/2010	8:45 AM	28.3	28.3	27.9	83	25.1	1.3	ESE	3.1	ENE	1009.8	0	0
10/1/2010	9:00 AM	28.9	28.9	28.3	78	24.7	1.3	ENE	2.2	ENE	1009.9	0	0
10/1/2010	9:15 AM	29.1	29.2	28.9	77	24.7	1.3	ENE	3.1	SSE	1010.1	0	0
10/1/2010	9:30 AM	28.6	29.1	28.6	78	24.3	1.3	SE	3.1	SSE	1010.2	0	0
10/1/2010	9:45 AM	28.3	28.7	28.3	82	24.9	2.2	S	4	S	1010.2	0	0
10/1/2010	10:00 AM	28.2	28.4	28.2	84	25.3	1.3	SW	3.1	WSW	1010.5	0	0
10/1/2010	10:15 AM	27.7	28.3	27.7	85	25	0.9	S	2.7	S	1010.3	0	0
10/1/2010	10:30 AM	27.6	27.8	27.6	86	25	1.3	S	4	SSE	1010.1	0	0
10/1/2010	10:45 AM	27.6	27.6	27.4	85	24.9	1.3	S	2.7	S	1009.9	0	0
10/1/2010	11:00 AM	28.3	28.3	27.6	84	25.3	1.3	S	3.1	SW	1009.7	0	0
10/1/2010	11:15 AM	28.7	28.7	28.2	85	25.9	1.3	S	3.1	SSE	1009.4	0	0
10/1/2010	11:30 AM	28.7	28.9	28.7	82	25.3	1.3	S	3.1	SSE	1009.1	0	0
10/1/2010	11:45 AM	28.1	28.7	28.1	83	24.9	1.8	SE	3.6	S	1008.7	0	0
10/1/2010	12:00 PM	28.3	28.3	28.1	81	24.7	1.8	SSE	3.6	SE	1008.6	0	0
10/1/2010	12:15 PM	28.6	28.6	28.3	81	25	2.7	S	4.9	S	1008.6	0	0
10/1/2010	12:30 PM	28.7	28.9	28.6	81	25.1	2.2	S	4.9	S	1008.3	0	0
10/1/2010	12:45 PM	28.6	28.7	28.6	81	25	2.7	S	4	S	1008.2	0	0
10/1/2010	1:00 PM	28.7	28.7	28.6	81	25.1	2.7	S	4	S	1008	0	0
10/1/2010	1:15 PM	28.5	28.8	28.5	82	25.1	2.2	SSE	4.5	SSE	1007.7	0	0
10/1/2010	1:30 PM	28.3	28.5	28.3	82	24.9	1.8	SSE	3.6	SSE	1007.7	0	0
10/1/2010	1:45 PM	28.2	28.3	28.2	83	25.1	1.8	S	3.1	SSE	1007.6	0	0
10/1/2010	2:00 PM	28.3	28.3	28.2	83	25.2	1.3	S	3.1	SSW	1007.6	0	0
10/1/2010	2:15 PM	28.2	28.4	28.2	83	25.1	1.8	S	3.6	SSE	1007.6	0	0
10/1/2010	2:30 PM	27.9	28.2	27.9	84	25	1.8	S	3.1	SSE	1007.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/1/2010	2:45 PM	28	28	27.9	84	25	1.8	SSE	3.1	S	1007.7	0	0
10/1/2010	3:00 PM	27.8	27.9	27.8	85	25.1	1.8	S	3.6	S	1007.7	0	0
10/1/2010	3:15 PM	24.2	27.8	24.2	93	23	5.4	WSW	11.2	WSW	1007.7	8.38	96.3
10/1/2010	3:30 PM	23.4	24.2	23.4	95	22.6	4.5	WNW	8.5	WSW	1008.5	9.4	111.8
10/1/2010	3:45 PM	23.1	23.5	23.1	95	22.2	2.2	NW	5.4	NW	1008.9	2.54	24.9
10/1/2010	4:00 PM	23.1	23.2	23.1	95	22.2	4	NNE	6.3	NNE	1008.6	0.76	5.1
10/1/2010	4:15 PM	23.4	23.4	23.1	92	22	4	NNE	6.7	NNE	1008.4	0	0
10/1/2010	4:30 PM	23.7	23.7	23.4	92	22.3	0.9	NE	3.6	NNE	1008.3	0	0
10/1/2010	4:45 PM	23.8	23.9	23.7	92	22.5	0.4	NE	3.1	ENE	1008.2	0	0
10/1/2010	5:00 PM	23.8	23.9	23.8	94	22.8	0	NE	0.4	NE	1008.4	0	0
10/1/2010	5:15 PM	23.6	23.8	23.5	95	22.7	0	---	0	---	1008.2	0	0
10/1/2010	5:30 PM	23.4	23.6	23.4	95	22.6	0	---	0	---	1008.4	0	0
10/1/2010	5:45 PM	23.4	23.4	23.4	95	22.5	0	---	0	---	1008.6	0	0
10/1/2010	6:00 PM	23.4	23.4	23.4	95	22.5	0	---	0	---	1008.6	0	0
10/1/2010	6:15 PM	23.4	23.4	23.3	95	22.5	0	---	0	---	1008.6	0	0
10/1/2010	6:30 PM	23.7	23.8	23.3	96	23	0	---	0	---	1008.7	0	0
10/1/2010	6:45 PM	23.6	23.6	23.5	96	22.9	0	---	0	---	1008.9	0	0
10/1/2010	7:00 PM	23.9	23.9	23.6	96	23.2	0	---	0	---	1008.9	0.25	0
10/1/2010	7:15 PM	24	24	23.9	95	23.1	0	NE	0.9	NE	1008.9	0	0
10/1/2010	7:30 PM	24.2	24.2	23.9	93	23	0.9	E	2.2	NE	1008.9	0	0
10/1/2010	7:45 PM	24.3	24.3	24.2	93	23.1	0.4	E	1.3	E	1009	0	0
10/1/2010	8:00 PM	24.3	24.3	24.2	93	23.1	0	E	0.9	E	1009.2	0	0
10/1/2010	8:15 PM	24.4	24.4	24.3	92	23.1	0	E	1.3	E	1009.5	0	0
10/1/2010	8:30 PM	24.4	24.5	24.4	91	22.9	0	E	1.8	E	1009.5	0	0
10/1/2010	8:45 PM	24.4	24.5	24.3	92	23.1	0	E	1.3	E	1009.7	0	0
10/1/2010	9:00 PM	24.4	24.4	24.4	90	22.6	0.9	E	3.1	ESE	1009.7	0	0
10/1/2010	9:15 PM	24.7	24.7	24.4	89	22.7	1.8	ESE	3.1	E	1009.8	0	0
10/1/2010	9:30 PM	24.9	24.9	24.7	89	22.9	1.8	ESE	3.1	ESE	1009.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/1/2010	9:45 PM	24.8	24.9	24.8	89	22.9	1.8	ESE	2.7	ESE	1010	0	0
10/1/2010	10:00 PM	24.8	24.8	24.8	89	22.8	1.8	ESE	3.1	ESE	1009.9	0	0
10/1/2010	10:15 PM	24.9	24.9	24.8	89	22.9	1.8	ESE	3.1	ESE	1009.8	0	0
10/1/2010	10:30 PM	24.9	25	24.9	89	23	2.2	ESE	3.6	ESE	1009.8	0	0
10/1/2010	10:45 PM	25.1	25.1	24.9	89	23.1	2.7	ESE	4	ESE	1009.5	0	0
10/1/2010	11:00 PM	25.2	25.2	25.1	89	23.2	2.2	ESE	4	ESE	1009.3	0	0
10/1/2010	11:15 PM	25.3	25.3	25.2	90	23.6	2.2	ESE	3.6	ESE	1009.2	0	0
10/1/2010	11:30 PM	24.8	25.4	24.8	92	23.4	1.3	SW	4	SW	1009.5	0	0
10/1/2010	11:45 PM	24.7	24.8	24.7	95	23.8	0.9	SW	3.6	SW	1009.4	1.27	9.9
10/2/2010	12:00 AM	24.4	24.7	24.4	95	23.5	1.3	W	3.6	WNW	1009.5	0.51	3.6
10/2/2010	12:15 AM	24	24.4	24	95	23.1	1.8	W	4	WNW	1009.4	0	0
10/2/2010	12:30 AM	23.8	24	23.8	96	23.2	0	WNW	2.2	W	1009.3	0	0
10/2/2010	12:45 AM	23.9	23.9	23.8	96	23.2	1.8	NNE	4.5	NNE	1009.2	0	0
10/2/2010	1:00 AM	23.7	23.9	23.7	95	22.9	1.8	NNE	3.6	NE	1009	0	0
10/2/2010	1:15 AM	23.8	23.8	23.7	94	22.8	0.9	NNE	2.7	NNE	1008.6	0	0
10/2/2010	1:30 AM	24.2	24.2	23.8	93	23	1.3	NNE	3.1	NNE	1008.4	0	0
10/2/2010	1:45 AM	24.4	24.4	24.2	91	22.8	1.3	NNE	3.1	NE	1008.1	0	0
10/2/2010	2:00 AM	24.6	24.6	24.4	92	23.2	0.9	NNE	3.1	N	1008	0	0
10/2/2010	2:15 AM	24.5	24.6	24.5	91	22.9	0	NNE	0.9	NNE	1007.9	0	0
10/2/2010	2:30 AM	24.3	24.6	24.3	92	22.9	0	NNE	0.4	NNE	1007.7	0	0
10/2/2010	2:45 AM	24.3	24.3	24.2	94	23.2	0	---	0	---	1007.6	0	0
10/2/2010	3:00 AM	24.6	24.6	24.1	94	23.6	0.9	NNE	2.7	NE	1007.4	0	0
10/2/2010	3:15 AM	24.6	24.7	24.5	93	23.3	0	NE	1.8	NE	1007.4	0	0
10/2/2010	3:30 AM	24.6	24.6	24.6	94	23.6	0	NE	0.9	NE	1007.4	0	0
10/2/2010	3:45 AM	24.6	24.7	24.6	94	23.5	0	NE	0.4	NE	1007.5	0	0
10/2/2010	4:00 AM	24.6	24.6	24.5	94	23.5	0	NE	0.4	NE	1007.7	0	0
10/2/2010	4:15 AM	24.9	24.9	24.6	93	23.7	0	NE	0.9	NE	1007.7	0	0
10/2/2010	4:30 AM	25.4	25.4	24.9	90	23.7	1.3	NE	2.7	NE	1007.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/2/2010	4:45 AM	25.7	25.8	25.5	89	23.8	1.3	NE	2.7	NE	1007.4	0	0
10/2/2010	5:00 AM	25.8	25.8	25.7	88	23.6	0.4	NE	1.8	NE	1007.4	0	0
10/2/2010	5:15 AM	25.7	25.8	25.7	89	23.7	0	NE	0.4	NE	1007.5	0	0
10/2/2010	5:30 AM	25.6	25.7	25.6	89	23.6	0	NE	0.9	NE	1007.7	0	0
10/2/2010	5:45 AM	25.5	25.6	25.4	91	23.9	0	NE	0.4	NE	1007.7	0	0
10/2/2010	6:00 AM	25.4	25.5	25.4	92	24	0	NW	1.3	NW	1008	0	0
10/2/2010	6:15 AM	25.3	25.4	25.3	93	24.1	0	NW	0.4	NW	1008.1	0	0
10/2/2010	6:30 AM	25.3	25.3	25.3	93	24.1	0.9	WNW	4	W	1008.3	0.51	50
10/2/2010	6:45 AM	24.9	25.3	24.9	94	23.9	0	WNW	3.1	WSW	1008.2	0.76	50
10/2/2010	7:00 AM	24.9	25	24.9	94	23.9	0	---	0	---	1008.4	0	0
10/2/2010	7:15 AM	25	25.1	24.9	95	24.1	0.4	NE	2.7	ENE	1008.3	0	0
10/2/2010	7:30 AM	25.2	25.3	25	94	24.2	0	NE	1.8	NE	1008.4	0	0
10/2/2010	7:45 AM	25.6	25.6	25.2	94	24.5	0	---	0	---	1008.4	0	0
10/2/2010	8:00 AM	26.1	26.1	25.6	91	24.5	0	NE	0.9	NE	1008.3	0	0
10/2/2010	8:15 AM	27.3	27.3	26.1	85	24.6	0	NE	0.9	NE	1008.4	0	0
10/2/2010	8:30 AM	26.2	27.7	26.2	88	24.1	1.3	SW	4.5	SW	1008.7	0.25	0
10/2/2010	8:45 AM	25.2	26.2	25.2	94	24.1	0.9	S	3.1	S	1008.9	0.76	6.1
10/2/2010	9:00 AM	25.2	25.2	25.1	94	24.1	0.4	SSE	2.2	SSE	1009	0	0
10/2/2010	9:15 AM	25	25.2	24.9	94	24	0.9	S	2.2	S	1009.2	0	0
10/2/2010	9:30 AM	25.4	25.4	25	94	24.4	1.3	SE	2.7	E	1009.4	0	0
10/2/2010	9:45 AM	25.6	25.6	25.3	93	24.4	0.9	SE	2.7	SSE	1009.5	0	0
10/2/2010	10:00 AM	26.4	26.4	25.6	92	25	1.3	ESE	3.6	ENE	1009.4	0	0
10/2/2010	10:15 AM	26.8	26.8	26.4	89	24.9	1.8	ESE	3.1	ENE	1009.3	0	0
10/2/2010	10:30 AM	26.8	26.9	26.8	88	24.7	2.2	SE	3.1	ESE	1009.1	0	0
10/2/2010	10:45 AM	27	27	26.8	87	24.6	2.2	SE	3.1	ESE	1009	0	0
10/2/2010	11:00 AM	27.2	27.2	26.9	87	24.8	2.2	SE	4	SE	1008.7	0	0
10/2/2010	11:15 AM	27.4	27.4	27.2	85	24.7	2.7	SE	4.5	SSE	1008.6	0	0
10/2/2010	11:30 AM	27.5	27.7	27.4	87	25.1	3.1	SSE	4.5	SE	1008.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/2/2010	11:45 AM	27.3	27.6	27.3	86	24.8	3.1	SSE	5.4	SE	1008.5	0	0
10/2/2010	12:00 PM	27.6	27.6	27.3	86	25	3.1	SE	4.5	SSE	1008.1	0	0
10/2/2010	12:15 PM	27.7	27.7	27.4	86	25.1	3.1	SE	4.9	SSE	1007.6	0	0
10/2/2010	12:30 PM	27.9	28	27.7	85	25.2	3.1	SE	4.5	SE	1007.3	0	0
10/2/2010	12:45 PM	27.9	27.9	27.8	86	25.4	3.1	SE	4.5	SE	1007.1	0	0
10/2/2010	1:00 PM	28.4	28.4	27.9	86	25.9	2.7	SSE	4.9	S	1006.9	0	0
10/2/2010	1:15 PM	28.8	28.8	28.4	79	24.8	1.8	S	4	S	1006.7	0	0
10/2/2010	1:30 PM	28.7	29.2	28.7	80	24.9	2.2	S	4	SSE	1006.5	0	0
10/2/2010	1:45 PM	28.6	28.9	28.6	80	24.8	1.8	SSE	4	SSE	1006.3	0	0
10/2/2010	2:00 PM	27.9	28.6	27.9	84	25	1.8	S	4	S	1006.2	0	0
10/2/2010	2:15 PM	27.6	27.9	27.6	85	24.8	1.3	S	4	S	1006.3	0	0
10/2/2010	2:30 PM	26.7	27.6	26.7	90	24.9	1.3	W	4.5	W	1006.3	1.27	15.5
10/2/2010	2:45 PM	25.5	26.7	25.5	94	24.5	2.7	WNW	4.9	WNW	1006.6	2.29	16.8
10/2/2010	3:00 PM	24.6	25.5	24.6	94	23.5	2.7	WNW	5.4	W	1006.6	1.02	9.1
10/2/2010	3:15 PM	24.4	24.6	24.4	95	23.5	1.3	WNW	4	WNW	1006.5	3.56	20.1
10/2/2010	3:30 PM	24.3	24.4	24.3	96	23.6	0.4	NW	2.2	N	1006.6	0.76	17
10/2/2010	3:45 PM	24.3	24.3	24.2	96	23.6	0	NNE	1.8	NNE	1006.6	0.25	1.8
10/2/2010	4:00 PM	24.4	24.4	24.3	96	23.7	0	NNE	0.4	NNE	1006.5	0	0
10/2/2010	4:15 PM	24.8	24.8	24.4	97	24.3	0	NNE	0.4	NNE	1006.6	0	0
10/2/2010	4:30 PM	24.8	24.8	24.7	97	24.3	0	---	0	---	1006.6	0	0
10/2/2010	4:45 PM	24.9	24.9	24.8	96	24.3	0	---	0	---	1006.7	0	0
10/2/2010	5:00 PM	25	25	24.9	96	24.3	0	NNE	0.4	NNE	1006.9	0	0
10/2/2010	5:15 PM	25.1	25.1	25	96	24.4	0	NNE	1.3	NNE	1006.9	0	0
10/2/2010	5:30 PM	25.3	25.4	25.1	96	24.6	0.4	W	2.2	WSW	1007.1	0	0
10/2/2010	5:45 PM	25.2	25.4	25.2	96	24.5	0.4	WSW	1.8	WSW	1007.1	0	0
10/2/2010	6:00 PM	25.2	25.2	25.2	96	24.5	0.4	W	2.2	WNW	1007.2	0	0
10/2/2010	6:15 PM	25.5	25.5	25.2	95	24.6	0.9	WNW	3.1	WNW	1007.3	0	0
10/2/2010	6:30 PM	25.5	25.6	25.4	95	24.6	0.9	NW	2.7	WNW	1007.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/2/2010	6:45 PM	25.3	25.5	25.3	96	24.6	0.4	WNW	2.2	NW	1007.4	0	0
10/2/2010	7:00 PM	25.2	25.3	25.2	95	24.3	0.4	NW	2.2	NNW	1007.5	0	0
10/2/2010	7:15 PM	25.1	25.2	25.1	95	24.3	0.4	NW	2.2	NNW	1007.6	0	0
10/2/2010	7:30 PM	25.1	25.2	25.1	95	24.3	0.4	NW	2.2	WNW	1007.7	0	0
10/2/2010	7:45 PM	25.2	25.2	25.2	95	24.3	0.4	WNW	2.2	WNW	1008	0	0
10/2/2010	8:00 PM	25.2	25.2	25.2	95	24.4	0	WNW	1.3	WNW	1007.9	0	0
10/2/2010	8:15 PM	25.2	25.2	25.2	94	24.2	0	WNW	0.9	WNW	1008.2	0	0
10/2/2010	8:30 PM	25.1	25.2	25.1	94	24.1	0.4	WNW	2.2	W	1008.4	0	0
10/2/2010	8:45 PM	25.3	25.3	25.1	94	24.2	0.4	W	2.2	WNW	1008.6	0	0
10/2/2010	9:00 PM	25.2	25.3	25.2	94	24.2	0	W	1.8	WNW	1008.9	0	0
10/2/2010	9:15 PM	25.3	25.4	25.2	95	24.5	0	W	0.4	W	1009.2	0	0
10/2/2010	9:30 PM	25.3	25.4	25.3	95	24.5	0	---	0	---	1009.4	0	0
10/2/2010	9:45 PM	25.3	25.3	25.3	95	24.5	0	---	0	---	1009.4	0	0
10/2/2010	10:00 PM	25.2	25.3	25.2	95	24.3	0	---	0	---	1009.5	0	0
10/2/2010	10:15 PM	24.9	25.2	24.9	95	24.1	0	---	0	---	1009.5	0	0
10/2/2010	10:30 PM	24.9	25	24.9	95	24.1	0	---	0	---	1009.5	0	0
10/2/2010	10:45 PM	24.9	25	24.9	95	24.1	0	---	0	---	1009.5	0	0
10/2/2010	11:00 PM	25.1	25.1	24.9	95	24.2	0	---	0	---	1009.3	0	0
10/2/2010	11:15 PM	25.3	25.3	25.1	95	24.4	0	---	0	---	1009.2	0	0
10/2/2010	11:30 PM	25.3	25.3	25.3	95	24.5	0	W	0.4	W	1009.2	0	0
10/2/2010	11:45 PM	25.3	25.3	25.3	95	24.4	0	---	0	---	1009.1	0	0
10/3/2010	12:00 AM	25.2	25.3	25.2	95	24.4	0	---	0	---	1008.9	0	0
10/3/2010	12:15 AM	25.2	25.2	25.2	95	24.3	0	W	0.4	W	1008.7	0	0
10/3/2010	12:30 AM	25.2	25.2	25.1	95	24.3	0	---	0	---	1008.6	0	0
10/3/2010	12:45 AM	25.2	25.3	25.1	96	24.5	0	---	0	---	1008.5	0	0
10/3/2010	1:00 AM	25.1	25.2	25	95	24.2	0	---	0	---	1008.3	0	0
10/3/2010	1:15 AM	25.2	25.2	25.1	95	24.4	0	W	0.9	W	1008.3	0	0
10/3/2010	1:30 AM	25.3	25.4	25.2	93	24.1	0.4	NW	1.8	WNW	1008.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/3/2010	1:45 AM	25.3	25.4	25.3	93	24.1	0	NW	0.4	NW	1008	0	0
10/3/2010	2:00 AM	25.3	25.4	25.3	93	24.1	0	---	0	---	1008	0	0
10/3/2010	2:15 AM	25.3	25.3	25.2	95	24.5	0	NW	0.9	NW	1007.9	0	0
10/3/2010	2:30 AM	25.4	25.5	25.3	94	24.4	0	NW	0.9	NW	1008	0	0
10/3/2010	2:45 AM	25.3	25.4	25.3	94	24.3	0	NW	0.4	NW	1007.9	0.25	0
10/3/2010	3:00 AM	25.4	25.5	25.3	95	24.6	0	---	0	---	1007.9	0.25	1.3
10/3/2010	3:15 AM	25.3	25.4	25.3	95	24.4	0	NW	0.9	NW	1008.1	0.51	2.3
10/3/2010	3:30 AM	25.2	25.3	25.2	96	24.5	0	S	1.8	SSW	1008.1	0	1
10/3/2010	3:45 AM	25.1	25.2	25.1	96	24.4	0	SSW	1.8	SSW	1008.1	0	0
10/3/2010	4:00 AM	25.1	25.1	25	96	24.4	0	---	0	---	1008.2	0	0
10/3/2010	4:15 AM	25	25.1	25	96	24.3	0	---	0	---	1008.1	0.25	0
10/3/2010	4:30 AM	25	25.1	25	96	24.3	0	SSW	0.4	SSW	1007.9	0	0
10/3/2010	4:45 AM	25	25	24.9	97	24.5	0	SSW	0.4	SSW	1008	0	0
10/3/2010	5:00 AM	25.2	25.2	25	97	24.7	0	SSW	0.4	SSW	1007.9	0	0
10/3/2010	5:15 AM	25.2	25.2	25.2	97	24.7	0	SSW	0.4	SSW	1007.8	0	0
10/3/2010	5:30 AM	24.9	25.2	24.9	96	24.3	0	WSW	0.4	WSW	1007.9	0.25	0
10/3/2010	5:45 AM	24.6	24.9	24.6	96	23.9	0	WSW	0.4	WSW	1008	0	0
10/3/2010	6:00 AM	24.7	24.7	24.6	97	24.2	0	---	0	---	1008.2	0	0
10/3/2010	6:15 AM	24.5	24.7	24.5	96	23.8	0	---	0	---	1008.5	0	0
10/3/2010	6:30 AM	24.7	24.7	24.4	97	24.2	0	---	0	---	1008.8	0	0
10/3/2010	6:45 AM	25.3	25.3	24.7	97	24.8	0	---	0	---	1009.1	0	0
10/3/2010	7:00 AM	25.8	25.8	25.3	97	25.3	0	---	0	---	1009.2	0	0
10/3/2010	7:15 AM	26.7	26.7	25.8	95	25.8	0	WSW	1.3	WSW	1009.4	0	0
10/3/2010	7:30 AM	27	27	26.7	93	25.8	1.3	SSW	2.7	SSW	1009.5	0	0
10/3/2010	7:45 AM	27.3	27.3	26.9	91	25.7	0.4	S	1.8	S	1009.8	0	0
10/3/2010	8:00 AM	27.7	27.7	27.3	90	25.9	0.4	WSW	1.8	S	1010	0	0
10/3/2010	8:15 AM	27.8	27.8	27.6	89	25.8	0.4	W	1.8	W	1010.1	0	0
10/3/2010	8:30 AM	27.7	27.9	27.7	89	25.7	0.4	WNW	2.2	WNW	1010.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/3/2010	8:45 AM	27.6	27.8	27.6	88	25.4	0.4	WNW	1.8	WNW	1010.4	0	0
10/3/2010	9:00 AM	27.8	27.8	27.6	88	25.6	0.9	WNW	2.2	WNW	1010.3	0	0
10/3/2010	9:15 AM	28.2	28.2	27.8	87	25.8	1.3	WNW	2.2	WNW	1010.2	0	0
10/3/2010	9:30 AM	28.4	28.4	28.2	86	25.9	1.3	WNW	2.2	WNW	1010.2	0	0
10/3/2010	9:45 AM	28.9	28.9	28.4	83	25.7	1.3	WNW	2.7	WNW	1010.3	0	0
10/3/2010	10:00 AM	29.6	29.6	28.9	77	25.1	0.9	WNW	2.2	WNW	1010.3	0	0
10/3/2010	10:15 AM	29.9	29.9	29.6	76	25.2	0.9	WNW	2.2	W	1010.3	0	0
10/3/2010	10:30 AM	30.2	30.2	29.9	76	25.5	1.3	WNW	2.7	WNW	1010.3	0	0
10/3/2010	10:45 AM	30.4	30.4	30.2	73	25	1.3	WSW	3.1	WSW	1010.2	0	0
10/3/2010	11:00 AM	30.4	30.4	30.3	75	25.5	1.3	WSW	3.1	WSW	1010	0	0
10/3/2010	11:15 AM	30.6	30.6	30.4	73	25.2	0.9	WSW	2.7	SSW	1009.8	0	0
10/3/2010	11:30 AM	30	30.7	30	75	25.1	1.3	SSW	2.7	SSW	1009.6	0	0
10/3/2010	11:45 AM	29.7	30	29.7	78	25.4	1.3	SW	3.6	S	1009.4	0	0
10/3/2010	12:00 PM	29.8	29.9	29.7	77	25.4	0.9	SW	3.6	S	1009.2	0	0
10/3/2010	12:15 PM	29.6	29.8	29.5	78	25.3	1.3	SW	3.6	SW	1009.1	0	0
10/3/2010	12:30 PM	29.4	29.7	29.3	80	25.6	1.8	S	4	SSE	1009	0	0
10/3/2010	12:45 PM	28.9	29.4	28.9	83	25.8	1.8	SSE	3.6	SSW	1008.9	0	0
10/3/2010	1:00 PM	29.2	29.2	28.9	81	25.6	2.2	S	4	SE	1008.7	0	0
10/3/2010	1:15 PM	29.3	29.3	29	81	25.7	2.2	SSE	4.5	SSE	1008.5	0	0
10/3/2010	1:30 PM	29.5	29.6	29.3	79	25.5	1.3	S	4	S	1008.3	0	0
10/3/2010	1:45 PM	29.5	29.5	29.3	80	25.7	1.8	S	4.5	SSE	1008.2	0	0
10/3/2010	2:00 PM	29.4	29.9	29.4	81	25.8	2.2	S	4.5	SSE	1008	0	0
10/3/2010	2:15 PM	29.3	29.4	29.2	80	25.5	2.2	S	4.5	SSE	1007.9	0	0
10/3/2010	2:30 PM	29.3	29.4	29.2	79	25.3	1.8	S	4.5	S	1007.9	0	0
10/3/2010	2:45 PM	29.6	29.7	29.3	78	25.4	2.2	S	4	S	1007.5	0	0
10/3/2010	3:00 PM	29.8	29.8	29.6	77	25.3	2.2	S	4.5	SSE	1007.4	0	0
10/3/2010	3:15 PM	29.6	29.8	29.6	77	25.1	2.7	S	4.9	S	1007.4	0	0
10/3/2010	3:30 PM	29.7	29.8	29.6	76	25	2.2	S	4.5	SSE	1007.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/3/2010	3:45 PM	29.9	30	29.7	76	25.3	1.8	SSE	4	SSE	1007.5	0	0
10/3/2010	4:00 PM	29.8	29.9	29.8	75	24.9	0.9	S	3.1	S	1007.7	0	0
10/3/2010	4:15 PM	29.6	29.8	29.6	76	24.9	0.9	WSW	3.1	SW	1007.8	0	0
10/3/2010	4:30 PM	29.3	29.7	29.3	76	24.6	0.9	S	2.7	S	1007.9	0	0
10/3/2010	4:45 PM	29.1	29.3	29.1	76	24.4	0.9	SW	2.7	SW	1008.1	0	0
10/3/2010	5:00 PM	29.2	29.3	29.1	75	24.3	0.4	SSW	2.7	S	1008.1	0	0
10/3/2010	5:15 PM	28.9	29.2	28.8	79	24.9	0.9	W	3.1	SW	1008.4	0	0
10/3/2010	5:30 PM	28.3	28.8	28.3	83	25.2	0.9	W	3.1	WNW	1008.5	0	0
10/3/2010	5:45 PM	27.6	28.3	27.6	80	23.8	1.8	WNW	5.8	NNE	1008.6	0	0
10/3/2010	6:00 PM	26.9	27.6	26.9	83	23.8	4	NNE	6.7	NNE	1008.7	0	0
10/3/2010	6:15 PM	26.6	26.9	26.6	85	23.9	3.1	NNE	5.8	N	1008.9	0	0
10/3/2010	6:30 PM	26.8	26.8	26.6	82	23.4	2.7	NNE	4.9	NNE	1008.9	0	0
10/3/2010	6:45 PM	26.8	26.8	26.7	82	23.4	2.7	NNE	6.3	NE	1009	0	0
10/3/2010	7:00 PM	26.7	26.8	26.7	83	23.6	0.9	NNE	3.6	NNE	1009.2	0	0
10/3/2010	7:15 PM	26.7	26.7	26.7	85	24	1.3	NNW	3.1	NNW	1009.4	0	0
10/3/2010	7:30 PM	26.8	26.8	26.7	85	24	1.3	NW	3.1	NW	1009.5	0	0
10/3/2010	7:45 PM	26.8	26.8	26.7	85	24	1.8	NNW	3.6	NW	1009.8	0	0
10/3/2010	8:00 PM	26.9	26.9	26.7	83	23.8	1.8	NNW	3.6	NW	1010.1	0	0
10/3/2010	8:15 PM	26.9	27	26.9	84	24	0.9	WNW	3.1	NW	1010.4	0	0
10/3/2010	8:30 PM	26.7	26.9	26.7	84	23.8	0.9	WNW	2.2	NNW	1010.5	0	0
10/3/2010	8:45 PM	26.7	26.7	26.6	84	23.7	0.9	NW	3.1	NNW	1010.6	0	0
10/3/2010	9:00 PM	26.8	26.8	26.7	83	23.6	0.9	NNW	3.1	NW	1010.5	0	0
10/3/2010	9:15 PM	26.9	27	26.8	80	23.2	1.3	NW	3.6	NNW	1010.5	0	0
10/3/2010	9:30 PM	26.9	27	26.9	81	23.4	1.3	NNW	2.7	NNW	1010.5	0	0
10/3/2010	9:45 PM	26.7	26.9	26.7	82	23.4	0.9	NW	3.1	NNE	1010.5	0	0
10/3/2010	10:00 PM	26.6	26.7	26.6	82	23.2	1.3	NNE	4	NNE	1010.5	0	0
10/3/2010	10:15 PM	26.7	26.7	26.6	79	22.7	1.3	NNE	4.5	NNE	1010.5	0	0
10/3/2010	10:30 PM	26.8	26.8	26.7	78	22.6	0.4	NNE	2.7	NNE	1010.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/3/2010	10:45 PM	27.1	27.1	26.8	76	22.5	0.9	NW	4	NW	1010.6	0	0
10/3/2010	11:00 PM	27	27.1	27	76	22.4	0.9	NW	3.1	NW	1010.4	0	0
10/3/2010	11:15 PM	26.8	27	26.8	77	22.5	0.4	NNW	2.2	NW	1010.3	0	0
10/3/2010	11:30 PM	26.7	26.8	26.7	79	22.7	0.4	NNE	2.7	NNE	1010.1	0	0
10/3/2010	11:45 PM	26.7	26.7	26.6	80	23	0.9	NNE	2.7	NNE	1010	0	0
10/4/2010	12:00 AM	26.6	26.7	26.6	80	22.9	0.4	NNE	2.2	NNE	1009.9	0	0
10/4/2010	12:15 AM	26.6	26.6	26.6	80	22.8	0	NNE	0.9	NNE	1009.7	0	0
10/4/2010	12:30 AM	26.3	26.6	26.3	82	23	0	NNE	1.8	NNE	1009.5	0	0
10/4/2010	12:45 AM	26.3	26.4	26.3	83	23.2	0.4	NNE	1.8	NNE	1009.4	0	0
10/4/2010	1:00 AM	26.2	26.3	26.2	84	23.3	0	NNE	0.9	NNE	1009.2	0	0
10/4/2010	1:15 AM	26.2	26.2	26.2	83	23	0.4	NNE	2.7	NNE	1009.1	0	0
10/4/2010	1:30 AM	26.6	26.6	26.2	81	23	0.9	NNE	3.1	NNE	1009	0	0
10/4/2010	1:45 AM	26.8	26.8	26.6	80	23	0.9	NNE	3.6	NNE	1008.9	0	0
10/4/2010	2:00 AM	26.7	26.8	26.7	80	23	0.4	N	2.7	N	1008.9	0	0
10/4/2010	2:15 AM	26.6	26.7	26.5	81	23	0	NNE	1.8	N	1008.6	0	0
10/4/2010	2:30 AM	26.3	26.5	26.3	82	23	0	NNE	1.3	NNE	1008.4	0	0
10/4/2010	2:45 AM	26.2	26.3	26.2	82	22.8	0	NNE	0.9	NNE	1008.3	0	0
10/4/2010	3:00 AM	25.9	26.2	25.9	84	23	0	NNE	0.4	NNE	1008.2	0	0
10/4/2010	3:15 AM	25.7	25.9	25.7	86	23.2	0	NNE	1.8	NNE	1008.3	0	0
10/4/2010	3:30 AM	25.8	25.8	25.7	86	23.3	0	NNE	0.4	NNE	1008.2	0	0
10/4/2010	3:45 AM	25.9	25.9	25.8	85	23.2	0	NNE	0.4	NNE	1008.2	0	0
10/4/2010	4:00 AM	25.7	25.9	25.7	86	23.1	0	---	0	---	1008.4	0	0
10/4/2010	4:15 AM	25.3	25.7	25.3	85	22.6	0	---	0	---	1008.4	0	0
10/4/2010	4:30 AM	25.7	25.7	25.3	86	23.1	0	NNE	0.4	NNE	1008.5	0	0
10/4/2010	4:45 AM	25.5	25.7	25.5	88	23.4	0	NNE	0.4	NNE	1008.6	0	0
10/4/2010	5:00 AM	25.1	25.4	25.1	90	23.3	0	---	0	---	1008.7	0	0
10/4/2010	5:15 AM	24.9	25.1	24.8	90	23.2	0	NNE	0.4	NNE	1009	0	0
10/4/2010	5:30 AM	25.3	25.3	24.9	88	23.1	0	NNE	0.9	NNE	1009.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/4/2010	5:45 AM	25.6	25.6	25.3	86	23	0	NNE	0.9	NNE	1009.4	0	0
10/4/2010	6:00 AM	25.7	25.7	25.6	87	23.3	0	NNE	0.4	NNE	1009.5	0	0
10/4/2010	6:15 AM	25.6	25.6	25.4	88	23.4	0	NNE	0.4	NNE	1009.6	0	0
10/4/2010	6:30 AM	25.8	25.8	25.6	89	23.9	0	---	0	---	1009.7	0	0
10/4/2010	6:45 AM	26.3	26.3	25.8	83	23.2	0	NNE	0.4	NNE	1009.8	0	0
10/4/2010	7:00 AM	26.8	26.8	26.3	81	23.3	0	NNE	0.9	NNE	1009.8	0	0
10/4/2010	7:15 AM	27.2	27.2	26.8	80	23.5	0	NNE	1.8	NNE	1010	0	0
10/4/2010	7:30 AM	27.5	27.5	27.2	82	24.2	0.9	NNE	2.7	NNE	1010.2	0	0
10/4/2010	7:45 AM	28.3	28.3	27.5	81	24.7	0.4	NNE	1.8	NNE	1010.4	0	0
10/4/2010	8:00 AM	28.8	28.8	28.3	80	25	0.4	NNE	1.8	NNE	1010.5	0	0
10/4/2010	8:15 AM	28.9	29	28.8	79	24.9	0.9	NNE	2.2	NNE	1010.5	0	0
10/4/2010	8:30 AM	29.1	29.1	28.8	79	25	0.9	NNE	2.2	NNE	1010.5	0	0
10/4/2010	8:45 AM	29.3	29.4	29.1	77	24.8	0.9	NNE	2.2	NNE	1010.6	0	0
10/4/2010	9:00 AM	29.3	29.3	29.1	78	25	0.9	NNE	2.2	NNE	1010.6	0	0
10/4/2010	9:15 AM	29.3	29.4	29.3	73	24	1.3	NE	3.1	ESE	1010.5	0	0
10/4/2010	9:30 AM	29.4	29.4	29.3	71	23.6	1.3	SE	3.6	SE	1010.6	0	0
10/4/2010	9:45 AM	29.6	29.6	29.3	70	23.5	2.2	ESE	3.6	SSE	1010.6	0	0
10/4/2010	10:00 AM	29.7	29.7	29.5	72	24.1	2.2	SE	3.6	ESE	1010.5	0	0
10/4/2010	10:15 AM	29.6	29.7	29.6	73	24.3	2.2	SE	4	SSE	1010.5	0	0
10/4/2010	10:30 AM	29.7	29.8	29.7	72	24.1	2.2	S	4	S	1010.4	0	0
10/4/2010	10:45 AM	29.6	29.7	29.4	74	24.4	2.7	SSE	4.5	S	1010.4	0	0
10/4/2010	11:00 AM	29.4	29.6	29.4	76	24.8	2.2	S	4.5	S	1010.3	0	0
10/4/2010	11:15 AM	29.4	29.7	29.4	76	24.8	2.7	S	4.5	S	1010.2	0	0
10/4/2010	11:30 AM	29.9	30.1	29.5	70	23.9	2.2	S	3.6	S	1010	0	0
10/4/2010	11:45 AM	30.1	30.3	29.9	72	24.5	2.2	S	4.5	SSE	1009.8	0	0
10/4/2010	12:00 PM	30.1	30.1	29.9	70	24	2.7	SSE	4	SSE	1009.6	0	0
10/4/2010	12:15 PM	30.2	30.3	30.1	71	24.4	2.7	SE	4.5	SE	1009.4	0	0
10/4/2010	12:30 PM	30.2	30.3	30.1	72	24.6	3.1	SSE	4.9	SSE	1009.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/4/2010	12:45 PM	30.2	30.2	30	72	24.6	3.1	SSE	4.9	SSE	1009.1	0	0
10/4/2010	1:00 PM	30.4	30.4	30.2	73	25	3.1	SSE	4.9	S	1008.9	0	0
10/4/2010	1:15 PM	30.4	30.4	30.3	71	24.6	2.7	SSE	4.9	SSE	1008.8	0	0
10/4/2010	1:30 PM	30.2	30.5	30.1	70	24.1	2.7	SSE	4.5	SE	1008.8	0	0
10/4/2010	1:45 PM	30.1	30.2	30.1	72	24.5	3.1	SSE	4.9	SSE	1008.7	0	0
10/4/2010	2:00 PM	30.2	30.3	30.1	71	24.4	2.7	SSE	4	SSE	1008.6	0	0
10/4/2010	2:15 PM	30.2	30.2	29.9	72	24.6	2.7	SSE	4.9	SSE	1008.3	0	0
10/4/2010	2:30 PM	29.9	30.3	29.9	73	24.5	2.2	SE	4	ESE	1008.2	0	0
10/4/2010	2:45 PM	29.7	29.9	29.7	73	24.4	1.8	SE	3.1	SSE	1008.2	0	0
10/4/2010	3:00 PM	29.5	29.8	29.4	75	24.6	1.3	SSE	2.7	SSE	1008.2	0	0
10/4/2010	3:15 PM	29.5	29.6	29.5	75	24.6	1.8	SSE	3.1	SSE	1008.1	0	0
10/4/2010	3:30 PM	29.5	29.5	29.4	76	24.8	0.9	SSE	2.7	SSE	1008.2	0	0
10/4/2010	3:45 PM	29.6	29.6	29.4	76	24.9	0	SSW	0.9	SSW	1008.4	0	0
10/4/2010	4:00 PM	29.6	29.6	29.6	74	24.4	0	SW	2.2	SSW	1008.4	0	0
10/4/2010	4:15 PM	29.6	29.6	29.6	76	24.9	0.4	WNW	1.8	W	1008.2	0	0
10/4/2010	4:30 PM	29.4	29.6	29.4	76	24.7	0.4	W	2.2	WNW	1008.4	0	0
10/4/2010	4:45 PM	29.2	29.4	29.2	80	25.4	0.9	WNW	3.1	WNW	1008.5	0	0
10/4/2010	5:00 PM	28.3	29.2	28.3	84	25.4	2.2	WNW	3.6	WNW	1008.7	0	0
10/4/2010	5:15 PM	28	28.3	28	84	25	1.8	WNW	3.6	W	1008.9	0	0
10/4/2010	5:30 PM	27.9	28	27.9	83	24.8	1.8	WNW	3.6	W	1009.1	0	0
10/4/2010	5:45 PM	27.8	28.1	27.8	84	24.9	1.8	WNW	3.6	NW	1009.2	0	0
10/4/2010	6:00 PM	27.7	27.8	27.7	85	25	2.7	WNW	4	WNW	1009.3	0	0
10/4/2010	6:15 PM	27.6	27.7	27.6	85	24.8	2.2	WNW	4	WNW	1009.3	0	0
10/4/2010	6:30 PM	27.3	27.6	27.3	85	24.5	1.3	WNW	2.7	WNW	1009.5	0	0
10/4/2010	6:45 PM	27.4	27.4	27.3	84	24.4	1.8	WNW	3.6	WNW	1009.9	0	0
10/4/2010	7:00 PM	27.4	27.5	27.4	85	24.6	1.3	WNW	3.6	WNW	1010.1	0	0
10/4/2010	7:15 PM	27.2	27.4	27.2	86	24.6	1.8	WNW	4	WNW	1010.2	0	0
10/4/2010	7:30 PM	27.1	27.2	27.1	86	24.6	1.8	WNW	3.6	WNW	1010.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/4/2010	7:45 PM	27.1	27.2	27.1	86	24.6	1.3	WNW	2.7	W	1010.6	0	0
10/4/2010	8:00 PM	26.9	27.2	26.9	87	24.5	1.8	WNW	3.6	WNW	1010.7	0.25	0
10/4/2010	8:15 PM	26.7	26.8	26.7	88	24.6	1.3	WNW	2.7	WNW	1010.8	0	0
10/4/2010	8:30 PM	26.7	26.8	26.7	88	24.5	1.3	WNW	3.1	WNW	1010.8	0	0
10/4/2010	8:45 PM	26.7	26.7	26.7	88	24.5	0.9	W	2.7	WNW	1010.7	0	0
10/4/2010	9:00 PM	26.4	26.7	26.4	88	24.3	0.4	W	2.2	W	1010.6	0	0
10/4/2010	9:15 PM	26.4	26.4	26.3	89	24.4	0.4	WSW	2.2	WSW	1010.7	0	0
10/4/2010	9:30 PM	26.7	26.7	26.4	87	24.4	1.3	WNW	3.6	W	1010.6	0	0
10/4/2010	9:45 PM	26.9	26.9	26.7	86	24.4	0.9	WNW	3.1	NNW	1010.6	0	0
10/4/2010	10:00 PM	26.9	26.9	26.9	85	24.2	0.4	NW	2.2	NW	1010.6	0	0
10/4/2010	10:15 PM	26.9	26.9	26.9	86	24.3	0	NW	1.8	W	1010.5	0	0
10/4/2010	10:30 PM	26.6	26.9	26.6	87	24.2	0	W	0.4	W	1010.4	0	0
10/4/2010	10:45 PM	26.6	26.6	26.5	88	24.4	0	W	1.3	WNW	1010.1	0	0
10/4/2010	11:00 PM	26.4	26.6	26.4	88	24.3	0	WNW	1.3	WNW	1009.9	0	0
10/4/2010	11:15 PM	26.4	26.4	26.3	87	24	0.4	WNW	2.2	NW	1010	0	0
10/4/2010	11:30 PM	26.5	26.5	26.4	86	24	0.9	NW	2.2	NNW	1009.7	0	0
10/4/2010	11:45 PM	26.6	26.6	26.5	86	24.1	1.3	NNW	4	NW	1009.3	0	0
10/5/2010	12:00 AM	26.5	26.6	26.5	86	24	0.9	NW	3.6	NW	1009.2	0	0
10/5/2010	12:15 AM	26.4	26.5	26.4	87	24	0.9	NW	2.7	W	1009	0	0
10/5/2010	12:30 AM	26.4	26.4	26.3	88	24.2	0.4	WNW	2.2	WNW	1008.9	0	0
10/5/2010	12:45 AM	26.3	26.4	26.3	89	24.4	0.9	NW	2.2	WNW	1008.8	0	0
10/5/2010	1:00 AM	26.2	26.3	26.2	89	24.2	0.9	WNW	2.7	W	1008.4	0	0
10/5/2010	1:15 AM	26.3	26.3	26.2	86	23.8	0.9	NW	2.2	WNW	1008.3	0	0
10/5/2010	1:30 AM	26.4	26.4	26.3	85	23.7	1.3	NW	3.6	NNW	1008.2	0	0
10/5/2010	1:45 AM	26.4	26.4	26.4	82	23.1	1.3	NW	3.6	NNW	1008	0	0
10/5/2010	2:00 AM	26.2	26.4	26.2	82	22.9	0.9	N	2.2	NNW	1008.1	0	0
10/5/2010	2:15 AM	26.1	26.2	26.1	84	23.1	0	N	0.9	N	1007.9	0	0
10/5/2010	2:30 AM	25.7	26.1	25.7	87	23.4	0	---	0	---	1007.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/5/2010	2:45 AM	25.8	25.8	25.7	90	24.1	0	N	0.9	N	1007.8	0	0
10/5/2010	3:00 AM	25.6	25.8	25.6	90	23.8	0	---	0	---	1007.7	0	0
10/5/2010	3:15 AM	25.4	25.6	25.3	91	23.8	0	---	0	---	1007.7	0	0
10/5/2010	3:30 AM	25.6	25.6	25.4	90	23.8	0	N	0.4	N	1007.8	0	0
10/5/2010	3:45 AM	25.7	25.7	25.6	90	23.9	0	---	0	---	1007.8	0	0
10/5/2010	4:00 AM	25.6	25.7	25.6	91	24	0	---	0	---	1007.8	0	0
10/5/2010	4:15 AM	25.4	25.6	25.4	91	23.9	0	---	0	---	1007.8	0	0
10/5/2010	4:30 AM	25.4	25.4	25.3	92	24	0	N	1.3	N	1007.9	0	0
10/5/2010	4:45 AM	25.6	25.6	25.4	91	24	0	N	0.4	N	1007.9	0	0
10/5/2010	5:00 AM	25.5	25.6	25.4	91	23.9	0	---	0	---	1008.1	0	0
10/5/2010	5:15 AM	25.4	25.6	25.4	92	24	0	---	0	---	1008.1	0	0
10/5/2010	5:30 AM	25.1	25.3	25.1	93	23.9	0	---	0	---	1008.2	0	0
10/5/2010	5:45 AM	25.2	25.3	25.1	93	24	0	N	1.3	N	1008.4	0	0
10/5/2010	6:00 AM	25.2	25.2	25.1	91	23.6	0.4	N	2.2	N	1008.5	0	0
10/5/2010	6:15 AM	25.4	25.4	25.2	90	23.6	0	N	0.4	N	1008.7	0	0
10/5/2010	6:30 AM	25.7	25.7	25.3	91	24.1	0	---	0	---	1008.7	0	0
10/5/2010	6:45 AM	26.3	26.3	25.7	91	24.7	0	---	0	---	1008.9	0	0
10/5/2010	7:00 AM	26.8	26.8	26.3	87	24.4	0	N	0.4	N	1009.1	0	0
10/5/2010	7:15 AM	27.2	27.2	26.8	84	24.2	0	N	0.9	N	1009.3	0	0
10/5/2010	7:30 AM	27.9	27.9	27.2	82	24.5	0	N	0.9	N	1009.4	0	0
10/5/2010	7:45 AM	28.2	28.2	27.9	81	24.6	0	N	0.9	N	1009.4	0.25	0
10/5/2010	8:00 AM	28.5	28.5	28.2	82	25.1	0	N	0.9	N	1009.7	0	0
10/5/2010	8:15 AM	28.4	28.6	28.4	83	25.3	0.9	WNW	2.2	WNW	1010	0	0
10/5/2010	8:30 AM	28.6	28.6	28.4	82	25.2	0.4	NW	1.8	NW	1010	0	0
10/5/2010	8:45 AM	28.9	28.9	28.6	81	25.3	0.4	WNW	1.8	WNW	1009.9	0	0
10/5/2010	9:00 AM	29.1	29.1	28.9	81	25.5	0.4	WNW	1.8	WNW	1010	0	0
10/5/2010	9:15 AM	29.9	29.9	29	75	25	0	WNW	0.9	NW	1009.9	0	0
10/5/2010	9:30 AM	30.6	30.7	29.9	71	24.7	0	NW	1.3	NW	1010	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/5/2010	9:45 AM	30.8	30.8	30.7	69	24.5	0	NW	2.2	WSW	1009.8	0	0
10/5/2010	10:00 AM	31.1	31.1	30.8	68	24.5	0.4	WSW	2.2	WSW	1009.8	0	0
10/5/2010	10:15 AM	31.1	31.1	30.9	70	25	0.4	NE	2.2	E	1009.7	0	0
10/5/2010	10:30 AM	30.9	31.1	30.8	65	23.5	1.3	S	3.6	SSE	1009.7	0	0
10/5/2010	10:45 AM	30.5	30.9	30.5	70	24.4	2.2	S	4	SE	1009.7	0	0
10/5/2010	11:00 AM	30.5	30.5	30.2	72	24.9	2.2	S	4.5	SSE	1009.6	0	0
10/5/2010	11:15 AM	31	31	30.6	72	25.4	1.8	S	4	SW	1009.5	0	0
10/5/2010	11:30 AM	31.1	31.1	31.1	70	24.9	1.8	S	4.5	SSE	1009.2	0	0
10/5/2010	11:45 AM	30.6	31.2	30.4	73	25.2	2.2	S	4	S	1009	0	0
10/5/2010	12:00 PM	30.6	30.6	30.4	69	24.2	2.2	S	4	S	1008.9	0	0
10/5/2010	12:15 PM	30.7	30.7	30.4	70	24.6	1.8	SSE	4	SSE	1008.5	0	0
10/5/2010	12:30 PM	30.9	30.9	30.6	74	25.8	2.2	S	3.6	SSE	1008.3	0	0
10/5/2010	12:45 PM	31.3	31.3	30.9	73	25.9	2.2	S	4.5	S	1008	0	0
10/5/2010	1:00 PM	31.1	31.3	31.1	68	24.5	2.2	S	4	SSE	1007.8	0	0
10/5/2010	1:15 PM	31.1	31.2	30.9	71	25.2	1.8	S	4.5	S	1007.7	0	0
10/5/2010	1:30 PM	30.9	31.3	30.8	70	24.8	2.2	S	4.5	SSE	1007.5	0	0
10/5/2010	1:45 PM	30.8	31.3	30.8	70	24.7	1.8	S	3.6	S	1007.2	0	0
10/5/2010	2:00 PM	30.8	30.8	30.6	73	25.4	2.2	S	4.5	SSE	1007.1	0	0
10/5/2010	2:15 PM	30.9	31.1	30.7	70	24.8	1.8	S	3.6	S	1007	0	0
10/5/2010	2:30 PM	30.2	30.9	30.2	73	24.8	2.7	S	4	SSW	1007.1	0	0
10/5/2010	2:45 PM	30.2	30.2	30.2	71	24.3	1.8	SSE	3.6	SSE	1007.1	0	0
10/5/2010	3:00 PM	30.3	30.3	30.2	72	24.7	1.3	S	3.1	SSW	1007.1	0	0
10/5/2010	3:15 PM	30.4	30.4	30.3	70	24.3	1.8	S	3.6	S	1007	0	0
10/5/2010	3:30 PM	30.2	30.4	30.1	69	23.9	2.2	SSE	4	SSE	1007	0	0
10/5/2010	3:45 PM	30.4	30.4	30.1	70	24.4	1.8	SSE	3.6	S	1006.9	0	0
10/5/2010	4:00 PM	30.3	30.6	30.3	72	24.7	2.2	SSE	3.1	S	1007.2	0	0
10/5/2010	4:15 PM	30.1	30.2	30	73	24.7	1.8	SSE	3.6	S	1007.3	0	0
10/5/2010	4:30 PM	29.8	30.1	29.8	73	24.5	1.8	SSE	3.1	SSE	1007.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/5/2010	4:45 PM	29.7	29.8	29.7	71	23.9	1.3	SSE	2.7	S	1007.4	0	0
10/5/2010	5:00 PM	29.7	29.7	29.7	73	24.3	0.9	SSE	2.2	SSE	1007.5	0	0
10/5/2010	5:15 PM	29.6	29.7	29.6	71	23.7	0.9	S	2.2	SSE	1007.5	0	0
10/5/2010	5:30 PM	29.6	29.6	29.6	71	23.7	0.4	S	1.8	S	1007.7	0	0
10/5/2010	5:45 PM	29.4	29.6	29.4	72	23.9	0.4	S	2.2	S	1008	0	0
10/5/2010	6:00 PM	29.3	29.4	29.3	74	24.2	0	S	0.4	S	1008.2	0	0
10/5/2010	6:15 PM	29.2	29.3	29.2	73	23.9	0	S	0.4	S	1008.3	0	0
10/5/2010	6:30 PM	28.7	29.2	28.7	77	24.2	0.9	NNE	3.6	NNE	1008.1	0	0
10/5/2010	6:45 PM	28.1	28.7	28.1	81	24.5	0.9	NNE	3.6	NE	1008.1	0	0
10/5/2010	7:00 PM	27.7	28.1	27.7	84	24.7	0.9	NNE	3.6	N	1008.3	0	0
10/5/2010	7:15 PM	27.3	27.7	27.3	85	24.5	0	N	3.6	N	1008.4	0.25	0
10/5/2010	7:30 PM	26.9	27.3	26.9	86	24.3	0	WNW	0.9	WNW	1008.5	0	0
10/5/2010	7:45 PM	26.9	26.9	26.8	86	24.3	0	WNW	0.9	NW	1008.7	0	0
10/5/2010	8:00 PM	27	27	26.9	86	24.5	0	---	0	---	1008.8	0	0
10/5/2010	8:15 PM	27.1	27.1	26.9	86	24.5	0	NW	0.9	NW	1008.9	0	0
10/5/2010	8:30 PM	27.2	27.2	27.1	86	24.7	0.4	NNE	2.2	NNE	1009	0	0
10/5/2010	8:45 PM	27.3	27.3	27.2	85	24.5	0	NNE	1.8	NNE	1009	0	0
10/5/2010	9:00 PM	27.4	27.4	27.2	85	24.6	0	NNE	1.8	NNE	1009	0	0
10/5/2010	9:15 PM	27.5	27.5	27.4	85	24.8	0	NNE	1.8	NNE	1008.9	0	0
10/5/2010	9:30 PM	27.3	27.5	27.3	85	24.5	0	NNE	0.4	NNE	1008.8	0	0
10/5/2010	9:45 PM	27.3	27.4	27.3	88	25.1	0	---	0	---	1008.7	0	0
10/5/2010	10:00 PM	26.8	27.3	26.8	89	24.9	0	---	0	---	1008.7	0	0
10/5/2010	10:15 PM	26.6	26.8	26.6	88	24.5	0	---	0	---	1008.7	0	0
10/5/2010	10:30 PM	26.7	26.8	26.6	88	24.6	0	---	0	---	1008.6	0	0
10/5/2010	10:45 PM	26.7	26.9	26.7	90	24.9	0	---	0	---	1008.6	0	0
10/5/2010	11:00 PM	26.3	26.7	26.3	90	24.6	0	---	0	---	1008.4	0	0
10/5/2010	11:15 PM	26.2	26.3	26.1	89	24.3	0	---	0	---	1008.3	0	0
10/5/2010	11:30 PM	26.3	26.3	26.2	90	24.6	0	---	0	---	1008.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/5/2010	11:45 PM	26.5	26.5	26.3	87	24.2	0	NNE	0.4	NNE	1008.6	0	0
10/6/2010	12:00 AM	26.8	26.8	26.5	86	24.3	0	NNE	0.4	NNE	1008.5	0	0
10/6/2010	12:15 AM	26.8	26.8	26.7	85	24.1	0	NNE	0.4	NNE	1008.4	0	0
10/6/2010	12:30 AM	26.9	26.9	26.8	84	24	0	NNE	0.4	NNE	1008.4	0	0
10/6/2010	12:45 AM	27	27	26.9	84	24.1	0	---	0	---	1008.2	0	0
10/6/2010	1:00 AM	26.9	27	26.9	84	24	0	---	0	---	1008	0	0
10/6/2010	1:15 AM	26.7	26.9	26.7	83	23.6	0	NNE	0.9	NNE	1007.8	0	0
10/6/2010	1:30 AM	26.7	26.7	26.7	83	23.5	0	NNE	0.4	NNE	1007.9	0	0
10/6/2010	1:45 AM	26.7	26.7	26.7	83	23.5	0	---	0	---	1007.5	0	0
10/6/2010	2:00 AM	26.6	26.7	26.6	84	23.6	0	NNE	0.4	NNE	1007.3	0	0
10/6/2010	2:15 AM	26.4	26.6	26.4	86	23.9	0	---	0	---	1007.2	0	0
10/6/2010	2:30 AM	26.3	26.5	26.3	88	24.2	0	---	0	---	1007.1	0	0
10/6/2010	2:45 AM	26	26.3	26	89	24	0	NNE	0.4	NNE	1006.9	0	0
10/6/2010	3:00 AM	26.2	26.2	25.9	87	23.9	0	NNE	0.9	NNE	1006.8	0	0
10/6/2010	3:15 AM	26.4	26.5	26.2	84	23.5	0	NNE	0.4	NNE	1006.7	0	0
10/6/2010	3:30 AM	26.5	26.6	26.4	83	23.4	0	NNE	0.4	NNE	1006.7	0	0
10/6/2010	3:45 AM	26.4	26.5	26.4	84	23.5	0	---	0	---	1006.6	0	0
10/6/2010	4:00 AM	26.2	26.4	26.2	86	23.6	0	---	0	---	1006.6	0	0
10/6/2010	4:15 AM	26	26.2	26	87	23.7	0	---	0	---	1006.8	0	0
10/6/2010	4:30 AM	25.9	26	25.9	86	23.4	0	---	0	---	1006.9	0	0
10/6/2010	4:45 AM	26.2	26.2	25.9	85	23.5	0	NNE	0.4	NNE	1007	0	0
10/6/2010	5:00 AM	26.3	26.3	26.2	85	23.6	0	NNE	0.4	NNE	1007	0	0
10/6/2010	5:15 AM	26.2	26.3	26.2	88	24	0	---	0	---	1007	0	0
10/6/2010	5:30 AM	25.8	26.2	25.8	89	23.8	0	---	0	---	1007	0	0
10/6/2010	5:45 AM	25.6	25.8	25.6	90	23.8	0	---	0	---	1006.8	0	0
10/6/2010	6:00 AM	25.6	25.6	25.5	90	23.8	0	---	0	---	1006.8	0	0
10/6/2010	6:15 AM	25.8	25.8	25.6	89	23.8	0	NNE	0.4	NNE	1006.9	0	0
10/6/2010	6:30 AM	26.2	26.2	25.8	88	24.1	0	NNE	0.4	NNE	1007	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/6/2010	6:45 AM	26.3	26.4	26.2	84	23.4	0	NNE	0.9	NNE	1007.1	0	0
10/6/2010	7:00 AM	27.1	27.1	26.4	81	23.5	0	NNE	1.8	NNE	1007.4	0	0
10/6/2010	7:15 AM	27.8	27.8	27.1	78	23.6	0	NNE	0.9	NNE	1007.7	0	0
10/6/2010	7:30 AM	28.2	28.2	27.8	77	23.8	0.4	NNE	1.8	NNE	1007.9	0	0
10/6/2010	7:45 AM	28.8	28.8	28.2	76	24.2	0	NNE	0.9	NNE	1008.1	0.25	0
10/6/2010	8:00 AM	29.2	29.3	28.8	79	25.1	0.4	NNE	2.2	NNE	1008.3	0	0
10/6/2010	8:15 AM	29.3	29.3	29.1	78	25.1	0.4	NNE	2.2	NNE	1008.3	0	0
10/6/2010	8:30 AM	29.3	29.4	29.3	76	24.6	0.9	NNE	3.1	NE	1008.5	0	0
10/6/2010	8:45 AM	29.4	29.4	29.3	77	25	1.3	E	2.7	E	1008.5	0	0
10/6/2010	9:00 AM	29.7	29.7	29.4	74	24.6	0.9	E	2.7	E	1008.6	0	0
10/6/2010	9:15 AM	30.1	30.1	29.7	76	25.4	0.9	E	2.2	E	1008.6	0	0
10/6/2010	9:30 AM	29.7	30.2	29.7	76	25	1.8	SSE	3.6	SE	1008.5	0	0
10/6/2010	9:45 AM	29.5	29.7	29.4	78	25.3	2.2	SSE	3.6	SE	1008.4	0	0
10/6/2010	10:00 AM	29.5	29.6	29.4	78	25.3	2.2	SSE	4	SSE	1008.4	0	0
10/6/2010	10:15 AM	29.8	29.8	29.5	77	25.4	2.7	SE	4	SE	1008.4	0	0
10/6/2010	10:30 AM	29.7	29.9	29.7	77	25.3	2.7	SSE	4.5	SSE	1008.3	0	0
10/6/2010	10:45 AM	29.9	29.9	29.7	75	25	2.7	SSE	4.5	S	1008.4	0	0
10/6/2010	11:00 AM	30.1	30.1	29.9	75	25.1	2.7	S	4.9	S	1008.3	0	0
10/6/2010	11:15 AM	30.1	30.2	29.9	76	25.4	3.1	SSE	4.9	SSE	1008.3	0	0
10/6/2010	11:30 AM	30.3	30.3	30	77	25.8	3.1	SSE	4.9	SSE	1008.2	0	0
10/6/2010	11:45 AM	30.3	30.4	30.3	75	25.3	3.1	S	4.5	SSW	1008.3	0	0
10/6/2010	12:00 PM	30.3	30.5	30.3	73	24.9	2.7	S	5.4	SSE	1008.1	0	0
10/6/2010	12:15 PM	30.4	30.4	30.1	75	25.5	2.7	S	4.5	SSE	1007.9	0	0
10/6/2010	12:30 PM	30.1	30.3	30.1	77	25.6	3.1	SSE	4.9	SE	1007.7	0	0
10/6/2010	12:45 PM	30.3	30.3	30	76	25.6	2.2	SSE	4.5	SSE	1007.3	0	0
10/6/2010	1:00 PM	30.1	30.4	30.1	73	24.7	2.7	SSE	4	S	1007.1	0	0
10/6/2010	1:15 PM	30.5	30.5	30.1	72	24.9	2.2	SSE	4	SE	1006.7	0	0
10/6/2010	1:30 PM	30.4	30.4	30.3	74	25.2	2.7	SE	4.5	S	1006.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/6/2010	1:45 PM	30.4	30.4	30.2	71	24.5	2.7	SSE	4.5	S	1005.9	0	0
10/6/2010	2:00 PM	30.4	30.6	30.3	74	25.3	2.7	S	4.5	SSE	1006	0	0
10/6/2010	2:15 PM	30.9	31	30.4	71	25.1	2.2	S	4.9	S	1006	0	0
10/6/2010	2:30 PM	30.6	30.9	30.6	75	25.6	2.7	S	4.5	S	1005.7	0	0
10/6/2010	2:45 PM	30.7	30.8	30.6	75	25.7	2.2	S	4	S	1005.6	0	0
10/6/2010	3:00 PM	31.3	31.3	30.7	73	25.9	1.3	S	4	S	1005.7	0	0
10/6/2010	3:15 PM	30.7	31.4	30.7	75	25.7	1.8	S	4.9	SSE	1005.7	0	0
10/6/2010	3:30 PM	30.2	30.7	30.2	78	26	0.9	S	3.1	SSE	1006	0	0
10/6/2010	3:45 PM	30.3	30.6	30.3	77	25.8	1.8	S	3.6	S	1006.1	0	0
10/6/2010	4:00 PM	30.3	30.4	30.2	77	25.8	1.8	S	3.6	SSE	1006	0	0
10/6/2010	4:15 PM	30	30.3	30	79	26	1.3	SSE	3.1	SSE	1006	0	0
10/6/2010	4:30 PM	29.3	30	29.3	81	25.7	0.9	SE	2.2	SSE	1005.9	0	0
10/6/2010	4:45 PM	28.8	29.3	28.8	85	26	0.4	SE	1.8	SE	1005.7	0.25	0
10/6/2010	5:00 PM	28.4	28.8	28.4	86	25.9	0.4	SE	2.2	SE	1005.6	0	0
10/6/2010	5:15 PM	28.2	28.5	28.2	86	25.7	0	SE	2.2	SW	1005.9	0	0
10/6/2010	5:30 PM	27.7	28.2	27.7	86	25.1	0.9	WNW	2.7	NW	1005.9	0	0
10/6/2010	5:45 PM	27.7	27.7	27.7	87	25.3	0.4	NW	2.2	NE	1005.8	0	0
10/6/2010	6:00 PM	27.6	27.7	27.6	87	25.3	0.4	NNE	2.7	N	1006.1	0	0
10/6/2010	6:15 PM	27.5	27.6	27.5	87	25.1	0.4	NNW	3.1	NNW	1006.3	0	0
10/6/2010	6:30 PM	27.4	27.5	27.4	87	25.1	0	NNW	1.8	NNW	1006.4	0	0
10/6/2010	6:45 PM	27.4	27.4	27.4	86	24.8	0.4	N	2.2	NNW	1006.6	0	0
10/6/2010	7:00 PM	27.7	27.7	27.4	86	25.1	0	NNE	1.3	NNE	1007	0	0
10/6/2010	7:15 PM	27.7	27.8	27.6	86	25.2	0	NNE	0.9	NNE	1007.2	0	0
10/6/2010	7:30 PM	27.6	27.7	27.6	85	24.8	0	NNE	0.4	NNE	1007.4	0	0
10/6/2010	7:45 PM	27.6	27.6	27.5	84	24.6	0	NNE	0.9	NNE	1007.6	0	0
10/6/2010	8:00 PM	27.7	27.7	27.6	83	24.5	0	NNE	0.9	NNE	1007.7	0	0
10/6/2010	8:15 PM	27.7	27.7	27.7	84	24.7	0	NNW	0.9	NNW	1007.8	0	0
10/6/2010	8:30 PM	27.6	27.7	27.6	82	24.2	0	NNW	0.9	NNW	1008	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/6/2010	8:45 PM	27.5	27.6	27.5	84	24.6	0.4	WNW	1.8	NNW	1007.8	0	0
10/6/2010	9:00 PM	27.5	27.6	27.5	85	24.8	0	NW	0.9	NW	1007.7	0	0
10/6/2010	9:15 PM	27.3	27.6	27.3	87	25	0	NW	0.9	NW	1007.8	0	0
10/6/2010	9:30 PM	27.2	27.3	27.2	87	24.9	0	WNW	2.2	WNW	1007.5	0	0
10/6/2010	9:45 PM	27.2	27.2	27.2	88	25	0	WNW	0.9	NW	1007.3	0	0
10/6/2010	10:00 PM	27.1	27.2	27.1	86	24.6	0	NW	0.9	NW	1006.7	0	0
10/6/2010	10:15 PM	27	27.1	27	86	24.5	0	NW	0.9	NW	1006.3	0	0
10/6/2010	10:30 PM	26.9	27	26.9	86	24.4	0	NW	0.9	NW	1006.3	0	0
10/6/2010	10:45 PM	26.9	26.9	26.9	87	24.6	0	NW	0.4	NW	1006.4	0	0
10/6/2010	11:00 PM	27	27	26.9	87	24.6	0	NW	1.8	N	1006.6	0	0
10/6/2010	11:15 PM	27.1	27.1	27	88	25	0	NW	0.9	NW	1006.6	0	0
10/6/2010	11:30 PM	27.1	27.2	27.1	87	24.7	0	NW	0.9	NW	1006.6	0	0
10/6/2010	11:45 PM	26.9	27.1	26.9	84	24	0.4	NW	2.2	WNW	1006.6	0	0
10/7/2010	12:00 AM	27.1	27.1	26.9	83	24	0.4	NNW	1.8	NNW	1006.6	0	0
10/7/2010	12:15 AM	27	27.1	27	84	24.1	0.4	W	2.2	W	1006.8	0	0
10/7/2010	12:30 AM	26.8	26.9	26.8	86	24.3	0.9	WNW	2.2	WNW	1006.8	0	0
10/7/2010	12:45 AM	26.7	26.8	26.7	84	23.7	0	WNW	0.9	WNW	1006.7	0	0
10/7/2010	1:00 AM	26.5	26.7	26.5	85	23.8	0	NW	0.4	NW	1006.8	0	0
10/7/2010	1:15 AM	26.4	26.5	26.4	85	23.7	0	---	0	---	1006.5	0	0
10/7/2010	1:30 AM	26.3	26.4	26.3	86	23.7	0	NW	0.4	NW	1006.5	0	0
10/7/2010	1:45 AM	26.3	26.3	26.2	87	23.9	0	NW	0.4	NW	1006.2	0	0
10/7/2010	2:00 AM	26.3	26.4	26.3	86	23.8	0	NW	0.9	NW	1006.1	0	0
10/7/2010	2:15 AM	26.3	26.4	26.3	87	24	0	---	0	---	1006.2	0	0
10/7/2010	2:30 AM	26.1	26.3	26.1	89	24.2	0	NW	0.4	NW	1005.9	0	0
10/7/2010	2:45 AM	25.9	26.1	25.9	90	24.1	0	---	0	---	1006	0	0
10/7/2010	3:00 AM	25.8	25.9	25.8	90	24.1	0	---	0	---	1006.2	0	0
10/7/2010	3:15 AM	26.2	26.2	25.8	91	24.6	0	NW	1.8	WNW	1006.2	0	0
10/7/2010	3:30 AM	26.1	26.2	26.1	89	24.2	0.4	WNW	1.8	WNW	1006	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/7/2010	3:45 AM	26.1	26.2	26.1	89	24.2	0	NW	0.4	NW	1006	0	0
10/7/2010	4:00 AM	26.1	26.2	26.1	90	24.3	0	---	0	---	1005.8	0	0
10/7/2010	4:15 AM	25.8	26.1	25.8	91	24.2	0	---	0	---	1006	0	0
10/7/2010	4:30 AM	25.5	25.8	25.5	92	24.1	0	NW	0.4	NW	1006.2	0	0
10/7/2010	4:45 AM	25.6	25.6	25.5	93	24.3	0	---	0	---	1006.3	0	0
10/7/2010	5:00 AM	25.7	25.8	25.6	93	24.4	0	---	0	---	1006.5	0	0
10/7/2010	5:15 AM	25.5	25.7	25.4	93	24.3	0	WNW	1.8	WNW	1006.5	0	0
10/7/2010	5:30 AM	25.6	25.6	25.5	92	24.2	0	WNW	1.8	WNW	1006.6	0	0
10/7/2010	5:45 AM	25.6	25.6	25.6	90	23.8	0	WNW	1.8	WNW	1006.7	0	0
10/7/2010	6:00 AM	25.5	25.6	25.5	91	23.9	0	WNW	0.9	WNW	1006.8	0	0
10/7/2010	6:15 AM	25.6	25.6	25.5	91	24	0	---	0	---	1006.9	0	0
10/7/2010	6:30 AM	25.7	25.7	25.5	92	24.3	0	WNW	0.4	WNW	1007	0	0
10/7/2010	6:45 AM	26.3	26.3	25.7	91	24.7	0	WNW	0.9	WNW	1007.1	0	0
10/7/2010	7:00 AM	26.9	26.9	26.3	88	24.8	0	WNW	0.4	WNW	1007.3	0	0
10/7/2010	7:15 AM	27.3	27.3	26.9	87	25	0	WNW	1.3	WNW	1007.6	0	0
10/7/2010	7:30 AM	27.8	27.8	27.3	85	25	0.4	WNW	2.7	WNW	1008	0	0
10/7/2010	7:45 AM	28.2	28.2	27.7	83	25.1	0.4	NW	1.8	NW	1008.2	0	0
10/7/2010	8:00 AM	28.7	28.7	28.2	82	25.3	0.4	NNW	1.8	N	1008.2	0	0
10/7/2010	8:15 AM	29.2	29.2	28.7	79	25.2	0.4	NNW	0.9	NNW	1008.1	0	0
10/7/2010	8:30 AM	29.7	29.7	29.2	78	25.4	0.4	NNW	1.8	WNW	1008.2	0	0
10/7/2010	8:45 AM	29.9	29.9	29.6	76	25.2	0.4	NNW	1.8	NW	1008.3	0	0
10/7/2010	9:00 AM	30.3	30.3	29.9	74	25.1	0.4	WSW	2.7	WSW	1008.4	0	0
10/7/2010	9:15 AM	30.9	30.9	30.3	72	25.3	0.4	W	2.2	W	1008.4	0	0
10/7/2010	9:30 AM	31	31	30.8	71	25.1	0.4	WNW	2.2	WNW	1008.3	0	0
10/7/2010	9:45 AM	31.4	31.4	31.1	69	25.1	0.4	WNW	2.2	WNW	1008.4	0	0
10/7/2010	10:00 AM	31	31.6	31	67	24.2	1.3	S	3.6	S	1008.5	0	0
10/7/2010	10:15 AM	30.5	31	30.4	70	24.4	2.2	S	3.6	S	1008.5	0	0
10/7/2010	10:30 AM	30.4	30.6	30.4	71	24.6	2.2	S	4.5	S	1008.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/7/2010	10:45 AM	30.3	30.6	30.1	73	24.9	2.2	SSE	4.5	SSE	1008.3	0	0
10/7/2010	11:00 AM	30.4	30.6	30.3	73	25	2.7	SSE	4	SE	1008.3	0	0
10/7/2010	11:15 AM	30.3	30.5	30.3	76	25.6	3.1	SSE	4.5	S	1008.2	0	0
10/7/2010	11:30 AM	30.2	30.3	30.1	75	25.2	3.1	SSE	4.9	SE	1008	0	0
10/7/2010	11:45 AM	30.3	30.4	30.2	77	25.8	3.6	SE	5.4	SE	1007.9	0	0
10/7/2010	12:00 PM	30.4	30.4	30.3	76	25.7	3.6	SE	4.9	SE	1007.7	0	0
10/7/2010	12:15 PM	30.4	30.5	30.3	76	25.7	3.6	SE	6.3	SE	1007.3	0	0
10/7/2010	12:30 PM	30.6	30.7	30.4	77	26.1	3.6	SE	5.4	S	1007.1	0	0
10/7/2010	12:45 PM	30.7	30.7	30.6	77	26.2	4	SE	7.2	SSE	1006.9	0	0
10/7/2010	1:00 PM	30.9	31.1	30.7	76	26.2	3.6	SE	6.3	SSE	1006.9	0	0
10/7/2010	1:15 PM	30.8	31.2	30.8	74	25.7	4	SSE	5.8	SSE	1006.8	0	0
10/7/2010	1:30 PM	30.8	31.1	30.8	73	25.4	3.6	SSE	6.3	SE	1006.6	0	0
10/7/2010	1:45 PM	30.6	30.8	30.4	75	25.6	3.6	SSE	5.8	S	1006.4	0	0
10/7/2010	2:00 PM	30.8	30.8	30.6	75	25.8	3.6	SSE	5.4	S	1006.4	0	0
10/7/2010	2:15 PM	30.4	30.8	30.4	77	26	3.6	S	5.8	S	1006.5	0	0
10/7/2010	2:30 PM	30.2	30.4	30.2	78	25.9	3.6	SSE	5.4	SE	1006.3	0	0
10/7/2010	2:45 PM	29.9	30.2	29.9	80	26.1	2.7	SSE	4.5	SSE	1006.4	0	0
10/7/2010	3:00 PM	29.9	30.1	29.9	77	25.4	2.7	SSE	5.8	NE	1006.5	0	0
10/7/2010	3:15 PM	28.4	29.8	28.4	80	24.7	3.6	ENE	5.8	ENE	1006.6	0	0
10/7/2010	3:30 PM	27.9	28.4	27.9	85	25.2	3.1	NNE	6.3	NNE	1006.5	0	0
10/7/2010	3:45 PM	27.1	27.9	27.1	89	25.1	2.7	NNE	6.3	NE	1006.7	0.25	0
10/7/2010	4:00 PM	26.8	27.1	26.8	91	25.2	0.4	NNW	2.2	NNE	1006.8	0	0
10/7/2010	4:15 PM	27.1	27.3	26.8	93	25.8	0.4	NNW	3.1	WNW	1006.7	1.02	11.7
10/7/2010	4:30 PM	27.2	27.2	26.9	93	25.9	0.4	W	1.8	N	1006.8	0	0
10/7/2010	4:45 PM	27.2	27.3	27.1	91	25.6	0.9	SE	4	SE	1007	0	0
10/7/2010	5:00 PM	27.1	27.2	27.1	90	25.3	2.2	SE	4.5	SE	1007	0	0
10/7/2010	5:15 PM	26.9	27.1	26.9	89	24.9	2.2	SE	3.6	SE	1007.1	0	0
10/7/2010	5:30 PM	27	27.1	26.9	89	25	0.4	SE	2.2	SE	1007.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/7/2010	5:45 PM	27.1	27.1	26.9	90	25.3	0	SE	0.4	SE	1007.4	0	0
10/7/2010	6:00 PM	26.8	27.1	26.8	91	25.2	0	---	0	---	1007.5	0	0
10/7/2010	6:15 PM	26.8	26.8	26.8	92	25.4	0	SE	0.4	SE	1007.8	0	0
10/7/2010	6:30 PM	26.9	26.9	26.8	92	25.5	0	SE	0.4	SE	1008	0	0
10/7/2010	6:45 PM	27.1	27.1	26.9	92	25.7	0	SE	0.4	SE	1008.2	0	0
10/7/2010	7:00 PM	27.1	27.2	27.1	92	25.7	0	SE	0.9	SW	1008.2	0	0
10/7/2010	7:15 PM	27.1	27.2	27.1	92	25.7	0	SW	0.9	SW	1008.2	0	0
10/7/2010	7:30 PM	27	27.2	27	92	25.6	0	SW	0.4	SW	1008.4	0	0
10/7/2010	7:45 PM	27.1	27.1	27	92	25.7	0	W	0.9	W	1008.7	0	0
10/7/2010	8:00 PM	27	27.1	26.9	92	25.6	0.4	W	1.8	W	1008.9	0	0
10/7/2010	8:15 PM	27	27	26.9	93	25.8	0.4	W	1.8	W	1009	0	0
10/7/2010	8:30 PM	27.2	27.2	27	92	25.8	0.4	WNW	2.2	WNW	1009.1	0	0
10/7/2010	8:45 PM	27.2	27.3	27.2	92	25.8	0.4	NW	2.7	NW	1009.1	0	0
10/7/2010	9:00 PM	27.2	27.2	27.2	92	25.8	0	NW	1.8	NNW	1009.2	0	0
10/7/2010	9:15 PM	27.1	27.2	27.1	92	25.7	0.4	NW	1.8	NW	1009.4	0	0
10/7/2010	9:30 PM	27.2	27.2	27.1	92	25.8	0.4	NW	1.8	NW	1009.5	0	0
10/7/2010	9:45 PM	26.9	27.2	26.9	92	25.5	0.4	WNW	2.7	WNW	1009.5	0	0
10/7/2010	10:00 PM	26.8	26.9	26.8	92	25.4	0.4	NW	1.3	NNW	1009.5	0	0
10/7/2010	10:15 PM	26.8	26.8	26.7	92	25.4	0	NW	2.2	NNW	1009.7	0	0
10/7/2010	10:30 PM	26.8	26.8	26.7	91	25.2	0.9	NW	2.7	NNW	1009.7	0	0
10/7/2010	10:45 PM	26.9	26.9	26.8	90	25.1	0.9	WNW	2.7	NW	1009.9	0	0
10/7/2010	11:00 PM	27.1	27.1	26.9	89	25.1	1.3	NW	2.7	WNW	1009.7	0	0
10/7/2010	11:15 PM	27	27.1	27	89	25	0.4	NW	2.2	NNW	1009.7	0	0
10/7/2010	11:30 PM	26.9	27	26.9	89	24.9	0.4	NW	2.2	NNW	1009.6	0	0
10/7/2010	11:45 PM	26.9	26.9	26.8	90	25.1	0.4	NNW	2.2	NNW	1009.4	0	0
10/8/2010	12:00 AM	26.9	26.9	26.9	89	24.9	0.4	WNW	2.7	WNW	1009.5	0	0
10/8/2010	12:15 AM	26.8	26.9	26.8	89	24.8	0	WNW	0.9	WNW	1009.7	0	0
10/8/2010	12:30 AM	26.6	26.8	26.6	89	24.6	0	WNW	0.4	WNW	1009.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/8/2010	12:45 AM	26.6	26.7	26.6	88	24.4	0	WNW	0.4	WNW	1009.4	0	0
10/8/2010	1:00 AM	26.4	26.6	26.4	90	24.7	0	---	0	---	1009.2	0	0
10/8/2010	1:15 AM	26.1	26.4	26.1	91	24.5	0	---	0	---	1009.1	0	0
10/8/2010	1:30 AM	26	26.1	25.9	92	24.6	0	---	0	---	1009	0	0
10/8/2010	1:45 AM	25.9	26	25.9	92	24.5	0	---	0	---	1008.6	0	0
10/8/2010	2:00 AM	26.2	26.2	25.9	91	24.6	0	NW	1.8	NW	1008.6	0	0
10/8/2010	2:15 AM	26.2	26.2	26.2	90	24.4	0	NW	0.4	NW	1008.4	0	0
10/8/2010	2:30 AM	26.2	26.2	26.2	89	24.2	0	---	0	---	1008.5	0	0
10/8/2010	2:45 AM	26.2	26.3	26.2	89	24.3	0	NW	0.4	NW	1008.4	0	0
10/8/2010	3:00 AM	26.2	26.2	26.2	90	24.4	0	NW	1.8	NW	1008.3	0	0
10/8/2010	3:15 AM	26.2	26.2	26.2	90	24.4	0.4	NNW	1.8	N	1008.1	0	0
10/8/2010	3:30 AM	26.4	26.4	26.2	90	24.6	0.9	NNW	2.7	NE	1008.1	0	0
10/8/2010	3:45 AM	26.5	26.5	26.3	90	24.7	0.9	NE	2.2	NE	1008.1	0	0
10/8/2010	4:00 AM	26.4	26.5	26.4	90	24.7	0	NE	0.9	NE	1008	0	0
10/8/2010	4:15 AM	26.4	26.4	26.3	90	24.6	0.4	NE	1.3	NE	1008.2	0	0
10/8/2010	4:30 AM	26.1	26.4	26.1	90	24.3	0	NE	0.9	NE	1008.3	0	0
10/8/2010	4:45 AM	25.7	26.1	25.7	90	24	0	NE	1.8	NE	1008.2	0	0
10/8/2010	5:00 AM	25.7	25.7	25.7	89	23.8	0	NE	1.8	NE	1008.3	0	0
10/8/2010	5:15 AM	25.9	25.9	25.7	88	23.8	0.4	N	2.7	NE	1008.5	0	0
10/8/2010	5:30 AM	26.1	26.2	25.9	87	23.8	0.9	NNE	3.1	NNE	1008.6	0	0
10/8/2010	5:45 AM	26.1	26.2	26.1	87	23.7	0	NNE	1.3	NNE	1008.8	0	0
10/8/2010	6:00 AM	26	26.1	26	87	23.7	0	NNE	1.3	W	1009	0	0
10/8/2010	6:15 AM	26.1	26.1	26	87	23.8	0	NW	0.9	NW	1009.1	0	0
10/8/2010	6:30 AM	26.4	26.4	26.1	87	24.1	0	NW	0.4	NW	1009.5	0	0
10/8/2010	6:45 AM	27.3	27.3	26.4	88	25.1	0	---	0	---	1009.6	0	0
10/8/2010	7:00 AM	27.9	27.9	27.7	84	25	0	NW	0.4	NW	1009.8	0	0
10/8/2010	7:15 AM	28.1	28.1	27.9	85	25.3	0	NW	0.4	NW	1009.9	0	0
10/8/2010	7:30 AM	28.3	28.3	28.1	84	25.3	0	NW	0.9	NW	1010.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/8/2010	7:45 AM	28.5	28.6	28.3	82	25.1	0	NW	0.9	NW	1010.2	0	0
10/8/2010	8:00 AM	28.7	28.7	28.4	82	25.3	0	NW	0.9	NW	1010.3	0	0
10/8/2010	8:15 AM	29.5	29.5	28.7	82	26.1	0	NW	0.9	NW	1010.6	0	0
10/8/2010	8:30 AM	29.7	29.7	29.4	82	26.3	0.4	NW	1.8	NNE	1010.8	0	0
10/8/2010	8:45 AM	29.8	29.8	29.7	80	26	0.4	NNE	1.3	NNE	1010.9	0	0
10/8/2010	9:00 AM	30	30	29.7	75	25.1	0.4	NNE	0.9	NNE	1010.9	0	0
10/8/2010	9:15 AM	30.1	30.2	30	78	25.8	0.9	WNW	2.2	WNW	1011.1	0	0
10/8/2010	9:30 AM	30.3	30.3	30.1	74	25.2	0.4	WNW	1.8	WNW	1011.2	0	0
10/8/2010	9:45 AM	30.8	30.8	30.3	74	25.7	0.9	WNW	2.2	WNW	1011.1	0	0
10/8/2010	10:00 AM	31.1	31.1	30.8	72	25.4	0.4	NW	1.8	NW	1011.2	0	0
10/8/2010	10:15 AM	30.9	31.1	30.9	73	25.5	0.9	S	4	SSE	1011.2	0	0
10/8/2010	10:30 AM	30.5	30.9	30.5	72	24.9	1.8	S	3.6	S	1011.2	0	0
10/8/2010	10:45 AM	31.2	31.2	30.4	73	25.8	0.9	SW	3.1	WNW	1011	0	0
10/8/2010	11:00 AM	31.3	31.4	31.2	73	25.9	1.3	WNW	3.1	WNW	1010.7	0	0
10/8/2010	11:15 AM	31.2	31.4	31.2	70	25.1	1.3	SW	3.6	WSW	1010.7	0	0
10/8/2010	11:30 AM	31.7	31.8	31.2	70	25.6	1.3	W	3.1	WSW	1010.5	0	0
10/8/2010	11:45 AM	31.7	31.8	31.6	73	26.3	1.3	W	3.1	NW	1010.2	0	0
10/8/2010	12:00 PM	31.6	31.8	31.6	70	25.5	1.3	WSW	3.1	WSW	1010.1	0	0
10/8/2010	12:15 PM	31.2	31.8	31.2	72	25.5	1.8	S	4	S	1009.9	0	0
10/8/2010	12:30 PM	30.8	31.4	30.8	72	25.2	1.8	S	4	SSE	1009.8	0	0
10/8/2010	12:45 PM	31.2	31.2	30.6	75	26.2	1.8	S	4.5	SSW	1009.6	0	0
10/8/2010	1:00 PM	30.7	31.2	30.7	75	25.7	2.2	S	4	SSE	1009.5	0	0
10/8/2010	1:15 PM	30.7	30.8	30.6	74	25.5	3.1	S	4.9	S	1009.4	0	0
10/8/2010	1:30 PM	30.8	30.9	30.6	75	25.8	3.1	SSE	4.9	SE	1009.1	0	0
10/8/2010	1:45 PM	30.6	30.8	30.5	72	24.9	3.6	SSE	5.4	S	1008.9	0	0
10/8/2010	2:00 PM	30.8	30.8	30.6	72	25.1	3.1	SSE	4.9	SSE	1008.8	0	0
10/8/2010	2:15 PM	30.8	30.9	30.8	74	25.7	3.1	SSE	5.4	S	1008.7	0	0
10/8/2010	2:30 PM	30.6	30.9	30.6	77	26.1	3.6	SE	5.8	SE	1008.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/8/2010	2:45 PM	30.5	30.8	30.5	76	25.8	3.1	SE	4.9	SSE	1008.3	0	0
10/8/2010	3:00 PM	30.8	30.8	30.4	78	26.5	3.6	SE	5.4	ESE	1008.2	0	0
10/8/2010	3:15 PM	30.6	31	30.6	75	25.6	3.6	SSE	5.8	SE	1008.3	0	0
10/8/2010	3:30 PM	30.4	30.5	30.3	76	25.7	3.6	SE	5.8	ESE	1008.2	0	0
10/8/2010	3:45 PM	30.3	30.4	30.2	76	25.6	3.1	SE	5.4	ESE	1008.3	0	0
10/8/2010	4:00 PM	30.3	30.5	30.3	75	25.3	3.1	SE	4.9	SSE	1008.4	0	0
10/8/2010	4:15 PM	30.3	30.4	30.3	76	25.6	2.7	SSE	4.5	SE	1008.5	0	0
10/8/2010	4:30 PM	30.4	30.4	30.3	76	25.7	2.7	SE	4.5	SSE	1008.7	0	0
10/8/2010	4:45 PM	30.4	30.4	30.4	76	25.7	3.1	SSE	5.4	S	1008.8	0	0
10/8/2010	5:00 PM	30.1	30.4	30.1	78	25.8	3.1	SSE	4.9	SSE	1009.1	0	0
10/8/2010	5:15 PM	29.8	30.2	29.8	78	25.6	3.1	SSE	5.4	SSE	1009.2	0	0
10/8/2010	5:30 PM	29.6	29.8	29.6	80	25.8	3.1	SSE	5.4	SSE	1009.5	0	0
10/8/2010	5:45 PM	29.4	29.6	29.4	82	26	3.1	SSE	5.4	SSE	1009.4	0	0
10/8/2010	6:00 PM	29.3	29.4	29.3	82	25.9	3.6	SSE	5.8	S	1009.9	0	0
10/8/2010	6:15 PM	29.4	29.4	29.3	83	26.3	3.1	SSE	5.8	SSE	1010.2	0	0
10/8/2010	6:30 PM	27.7	29.4	27.7	83	24.5	1.3	NNE	5.4	N	1010.5	0	0
10/8/2010	6:45 PM	27.1	27.7	27.1	85	24.3	1.8	NNE	5.4	N	1010.6	0	0
10/8/2010	7:00 PM	26.3	27.1	26.3	87	23.9	3.6	NNE	6.7	NNE	1010.8	0	0
10/8/2010	7:15 PM	26	26.3	26	86	23.5	1.8	NNE	5.4	NNE	1010.9	0	0
10/8/2010	7:30 PM	25.9	26	25.8	86	23.4	1.3	NNW	3.1	NNW	1010.8	0	0
10/8/2010	7:45 PM	26.3	26.3	25.9	88	24.2	0.4	NNW	2.2	NNW	1010.9	0	0
10/8/2010	8:00 PM	26.6	26.6	26.3	88	24.4	0	NNW	2.2	NE	1011.1	0	0
10/8/2010	8:15 PM	26.8	26.8	26.6	87	24.5	0.4	NNW	2.2	NNW	1011.5	0	0
10/8/2010	8:30 PM	27.1	27.1	26.8	85	24.4	0.4	NNW	2.2	NNW	1011.7	0	0
10/8/2010	8:45 PM	27.3	27.3	27.1	86	24.7	0.4	WNW	1.8	WNW	1012	0	0
10/8/2010	9:00 PM	27	27.3	27	86	24.5	0.4	NW	3.1	NNW	1012.2	0	0
10/8/2010	9:15 PM	27.1	27.1	27	86	24.5	0	NNW	1.8	NNW	1012.3	0	0
10/8/2010	9:30 PM	27.2	27.2	27.1	86	24.6	0	NNW	0.4	NNW	1012.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/8/2010	9:45 PM	27.2	27.2	27.1	86	24.6	0	NNW	0.9	NNW	1012.3	0	0
10/8/2010	10:00 PM	27.1	27.2	27.1	87	24.7	0	NNW	0.4	NNW	1012	0	0
10/8/2010	10:15 PM	26.8	27.1	26.8	87	24.5	0	NNW	0.4	NNW	1012	0	0
10/8/2010	10:30 PM	26.9	26.9	26.8	89	24.9	0	NNW	0.9	NNW	1012	0	0
10/8/2010	10:45 PM	26.7	26.9	26.7	90	24.9	0	NW	0.9	NW	1011.9	0	0
10/8/2010	11:00 PM	26.7	26.7	26.7	90	24.9	0	---	0	---	1011.7	0	0
10/8/2010	11:15 PM	26.7	26.7	26.6	90	24.9	0	NW	0.9	NW	1011.6	0	0
10/8/2010	11:30 PM	26.8	26.8	26.7	89	24.8	0	NW	0.4	NW	1011.4	0	0
10/8/2010	11:45 PM	26.8	26.9	26.8	88	24.7	0	NW	0.9	NW	1011.4	0	0
10/9/2010	12:00 AM	26.9	26.9	26.8	88	24.7	0	NW	0.9	NW	1011.3	0	0
10/9/2010	12:15 AM	27.1	27.1	26.9	87	24.8	0.4	NNE	2.2	NNE	1011.2	0	0
10/9/2010	12:30 AM	27.1	27.1	27.1	87	24.7	0	NNE	0.9	NNE	1011	0	0
10/9/2010	12:45 AM	26.9	27.1	26.9	86	24.3	0	NNE	0.9	NNE	1010.9	0	0
10/9/2010	1:00 AM	26.8	26.9	26.8	86	24.2	0	NNE	0.9	NNE	1010.6	0	0
10/9/2010	1:15 AM	26.7	26.8	26.7	86	24.2	0	NNE	0.9	NNE	1010.4	0	0
10/9/2010	1:30 AM	26.8	26.8	26.7	85	24	0	NNE	0.4	NNE	1010.3	0	0
10/9/2010	1:45 AM	26.8	26.8	26.8	85	24	0	NNE	0.4	NNE	1010.1	0	0
10/9/2010	2:00 AM	26.8	26.8	26.7	86	24.2	0	---	0	---	1010	0	0
10/9/2010	2:15 AM	26.6	26.8	26.6	87	24.2	0	---	0	---	1009.8	0	0
10/9/2010	2:30 AM	26.6	26.7	26.6	87	24.3	0	---	0	---	1009.9	0	0
10/9/2010	2:45 AM	26.5	26.7	26.5	87	24.2	0	---	0	---	1009.8	0	0
10/9/2010	3:00 AM	26.6	26.6	26.4	89	24.6	0	NNE	0.4	NNE	1010	0	0
10/9/2010	3:15 AM	26.6	26.7	26.6	88	24.4	0	NNE	0.9	NNE	1010	0	0
10/9/2010	3:30 AM	26.5	26.6	26.5	88	24.3	0	NNE	0.4	NNE	1009.8	0	0
10/9/2010	3:45 AM	26.4	26.6	26.4	87	24	0	NNE	0.9	NNE	1009.7	0	0
10/9/2010	4:00 AM	26.2	26.4	26.2	86	23.7	0	NNE	0.4	NNE	1009.7	0	0
10/9/2010	4:15 AM	26.4	26.4	26.2	85	23.7	0	NNE	0.9	NNE	1009.7	0	0
10/9/2010	4:30 AM	26.5	26.6	26.4	83	23.4	0	NNE	0.9	NNE	1009.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/9/2010	4:45 AM	26.4	26.6	26.4	83	23.3	0.4	NNW	2.7	NNE	1009.8	0	0
10/9/2010	5:00 AM	26.5	26.6	26.4	83	23.4	0	NNW	2.2	NNW	1009.7	0	0
10/9/2010	5:15 AM	26.6	26.6	26.5	83	23.4	0.4	NNW	1.8	NW	1010	0	0
10/9/2010	5:30 AM	26.5	26.6	26.5	81	23	0.4	NNW	1.8	NNW	1010.2	0	0
10/9/2010	5:45 AM	26.4	26.5	26.4	82	23.1	0.4	NNW	1.8	NW	1010.2	0	0
10/9/2010	6:00 AM	26.3	26.4	26.3	83	23.2	0.4	NNE	3.6	NE	1010.3	0	0
10/9/2010	6:15 AM	26.3	26.3	26.3	84	23.4	0.9	NNE	3.6	NNE	1010.6	0	0
10/9/2010	6:30 AM	26.6	26.6	26.3	83	23.5	1.3	NNE	3.6	NNE	1010.6	0	0
10/9/2010	6:45 AM	27	27	26.7	81	23.5	2.2	NNE	4.9	NNE	1010.5	0	0
10/9/2010	7:00 AM	27.3	27.3	27	81	23.8	1.3	NNE	2.7	NNE	1010.8	0	0
10/9/2010	7:15 AM	27.8	27.8	27.4	81	24.3	0.4	NNE	2.2	NNE	1011.1	0	0
10/9/2010	7:30 AM	28.7	28.7	27.8	80	24.9	0	NNE	0.4	NNE	1011.1	0	0
10/9/2010	7:45 AM	29.3	29.3	28.7	77	24.9	0	NNE	0.9	NNE	1011.2	0	0
10/9/2010	8:00 AM	29.1	29.3	29.1	80	25.3	0.9	NNE	2.2	NNE	1011.2	0	0
10/9/2010	8:15 AM	29	29.1	28.9	79	25	0.9	NNE	2.2	NNE	1011.4	0	0
10/9/2010	8:30 AM	29.4	29.4	29	78	25.2	0.9	NNE	2.2	NNE	1011.7	0	0
10/9/2010	8:45 AM	29.2	29.6	29.2	76	24.6	0.9	S	2.7	S	1012	0	0
10/9/2010	9:00 AM	28.9	29.2	28.9	76	24.3	0.9	S	2.7	S	1012	0	0
10/9/2010	9:15 AM	28.9	28.9	28.9	77	24.5	0.4	S	2.2	S	1012.3	0	0
10/9/2010	9:30 AM	29.1	29.1	28.9	78	24.8	0	SSE	1.3	SSE	1012.4	0	0
10/9/2010	9:45 AM	29.3	29.3	29.1	79	25.3	0	SE	1.8	NE	1012.6	0	0
10/9/2010	10:00 AM	28.9	29.3	28.9	80	25.1	0.9	NE	2.7	NE	1012.5	0	0
10/9/2010	10:15 AM	29	29	28.9	80	25.2	0.4	NE	2.7	NNE	1012.4	0	0
10/9/2010	10:30 AM	29.1	29.1	28.9	78	24.9	3.1	SE	6.3	SSE	1012.4	0	0
10/9/2010	10:45 AM	29	29.2	29	81	25.4	4	SE	6.7	SE	1012.5	0	0
10/9/2010	11:00 AM	28.9	29	28.8	80	25.1	3.1	SE	5.4	ESE	1012.4	0	0
10/9/2010	11:15 AM	26.9	29	26.9	87	24.6	4.5	S	9.4	SSW	1012.5	0	0
10/9/2010	11:30 AM	25.4	26.9	25.4	93	24.2	5.8	S	9.8	S	1012.6	0.51	12.7

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/9/2010	11:45 AM	25.1	25.4	25	94	24	5.4	SE	12.5	SE	1012.6	5.33	43.4
10/9/2010	12:00 PM	25.1	25.1	25	94	24	2.2	ESE	4.5	ESE	1012.3	0.76	16.3
10/9/2010	12:15 PM	25.2	25.3	25.1	95	24.4	1.3	ESE	3.6	ENE	1012	0.25	2.3
10/9/2010	12:30 PM	25.2	25.3	25.2	94	24.2	1.3	E	3.1	ENE	1011.6	0	0
10/9/2010	12:45 PM	25.5	25.5	25.2	94	24.5	0.4	SE	2.2	SE	1011.3	0	0
10/9/2010	1:00 PM	25.7	25.7	25.5	94	24.7	0	SE	1.3	SE	1011.2	0.25	0
10/9/2010	1:15 PM	26.3	26.3	25.8	93	25.1	0.9	SE	2.7	SSE	1010.7	0.25	1.8
10/9/2010	1:30 PM	26.8	26.8	26.3	91	25.2	1.8	SE	4.9	SSE	1010.4	0	0
10/9/2010	1:45 PM	27.1	27.1	26.8	90	25.3	2.2	SE	5.4	SE	1010.4	0.25	0
10/9/2010	2:00 PM	27.1	27.1	27.1	90	25.3	3.1	SE	5.8	SE	1010.3	0	0
10/9/2010	2:15 PM	27.2	27.2	27.1	91	25.6	2.7	SE	4.9	SE	1010.3	0	0
10/9/2010	2:30 PM	27.4	27.4	27.2	88	25.3	3.1	SE	5.8	ESE	1010.2	0	0
10/9/2010	2:45 PM	26.7	27.6	26.7	89	24.8	3.6	SE	5.8	ESE	1010.1	1.02	56.9
10/9/2010	3:00 PM	26.7	26.7	26.5	91	25.1	2.2	ESE	5.4	ESE	1010	0	0
10/9/2010	3:15 PM	26.9	26.9	26.7	88	24.8	1.8	ESE	4.5	SE	1010	0.25	0
10/9/2010	3:30 PM	26.4	27	26.4	91	24.8	3.1	SSE	6.3	SSE	1010.2	2.03	47.5
10/9/2010	3:45 PM	26.7	26.7	26.3	90	24.9	3.1	SSE	6.3	SE	1010.4	0.51	20.6
10/9/2010	4:00 PM	26.1	26.7	26	92	24.7	1.8	S	6.3	S	1010.5	2.03	72.4
10/9/2010	4:15 PM	26.2	26.3	26.1	92	24.8	1.8	S	4.5	S	1010.4	0.51	9.1
10/9/2010	4:30 PM	26.1	26.2	25.9	93	24.8	1.8	S	3.1	S	1010.3	0.25	8.1
10/9/2010	4:45 PM	26.2	26.2	26.1	92	24.8	0.4	S	3.1	S	1010.5	0	0
10/9/2010	5:00 PM	26.2	26.3	26.2	91	24.6	0.9	S	3.6	S	1010.7	0.25	0
10/9/2010	5:15 PM	25.6	26.2	25.6	90	23.8	1.8	S	5.8	SSE	1011	0	0
10/9/2010	5:30 PM	25.4	25.7	25.4	91	23.8	2.2	E	4.5	ESE	1011.1	0	0
10/9/2010	5:45 PM	25.5	25.5	25.4	91	23.9	0.9	ESE	2.7	E	1011.4	0	0
10/9/2010	6:00 PM	25.2	25.5	25.2	93	24	1.8	SSE	6.3	S	1011.9	1.02	20.1
10/9/2010	6:15 PM	24.7	25.2	24.7	94	23.6	2.2	ESE	5.8	ESE	1012.1	1.52	20.1
10/9/2010	6:30 PM	24.5	24.7	24.4	95	23.6	4.9	ESE	8.9	SE	1012.4	1.02	7.4

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/9/2010	6:45 PM	23.9	24.5	23.9	95	23.1	4.5	ESE	9.8	SE	1012.3	6.35	57.7
10/9/2010	7:00 PM	23.9	24	23.9	95	23.1	4	ESE	5.8	E	1012.1	1.02	11.2
10/9/2010	7:15 PM	24.3	24.3	23.9	95	23.4	3.6	ESE	6.3	ESE	1012.2	1.02	5.3
10/9/2010	7:30 PM	24.6	24.6	24.3	93	23.3	4.5	ESE	7.2	ESE	1012.4	0.76	4.6
10/9/2010	7:45 PM	24.8	24.8	24.6	92	23.4	4	ESE	6.3	ESE	1012.5	0.25	1.8
10/9/2010	8:00 PM	24.8	24.8	24.8	92	23.4	3.6	ESE	5.4	ESE	1012.2	0.76	4.3
10/9/2010	8:15 PM	24.8	24.8	24.7	90	23	3.1	E	4.9	E	1011.9	0.76	4.1
10/9/2010	8:30 PM	25.1	25.1	24.8	88	22.9	2.2	E	4	E	1011.7	0.25	3
10/9/2010	8:45 PM	25.2	25.2	25.1	87	22.9	0.9	ENE	3.1	E	1011.5	0	0
10/9/2010	9:00 PM	25.3	25.4	25.2	88	23.2	0.4	ENE	2.2	ENE	1011.5	0	0
10/9/2010	9:15 PM	25.1	25.4	25.1	90	23.3	0	NNE	0.9	NNE	1011.7	0	0
10/9/2010	9:30 PM	24.8	25.1	24.8	92	23.4	0	---	0	---	1011.6	0	0
10/9/2010	9:45 PM	24.8	24.8	24.8	93	23.6	0	NNE	0.4	NNE	1011.7	0	0
10/9/2010	10:00 PM	24.8	24.8	24.7	93	23.6	0	NNE	0.4	NNE	1011.5	0	0
10/9/2010	10:15 PM	24.7	24.8	24.7	93	23.5	0	NNE	0.4	NNE	1011.5	0	0
10/9/2010	10:30 PM	24.7	24.8	24.6	92	23.3	0	NNE	0.9	NNE	1011.4	0	0
10/9/2010	10:45 PM	24.7	24.8	24.7	92	23.3	0	---	0	---	1011.4	0	0
10/9/2010	11:00 PM	24.5	24.7	24.5	93	23.3	0	---	0	---	1011.4	0	0
10/9/2010	11:15 PM	24.6	24.8	24.5	94	23.5	0	---	0	---	1011.4	0	0
10/9/2010	11:30 PM	24.4	24.6	24.4	94	23.4	0	---	0	---	1011.2	0	0
10/9/2010	11:45 PM	24.4	24.4	24.4	95	23.6	0	---	0	---	1011.2	0	0
10/10/2010	12:00 AM	24.4	24.5	24.4	95	23.6	0	NNE	0.4	NNE	1011.2	0	0
10/10/2010	12:15 AM	24.6	24.6	24.4	95	23.7	0	NNE	0.9	NNE	1011.1	0	0
10/10/2010	12:30 AM	24.7	24.7	24.6	95	23.8	0	NNE	1.8	NNE	1010.9	0	0
10/10/2010	12:45 AM	24.8	24.8	24.6	95	23.9	0	NNE	1.8	NNE	1010.8	0	0
10/10/2010	1:00 AM	24.7	24.8	24.7	94	23.7	0	NNE	0.4	NNE	1010.9	0	0
10/10/2010	1:15 AM	24.8	24.8	24.7	94	23.7	0	---	0	---	1010.6	0	0
10/10/2010	1:30 AM	24.8	24.8	24.8	93	23.6	0	NNE	0.9	NNE	1010.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/10/2010	1:45 AM	24.9	24.9	24.8	92	23.5	0	NNE	0.9	NNE	1010.5	0	0
10/10/2010	2:00 AM	24.9	24.9	24.9	92	23.6	0	NNE	0.4	NNE	1010.1	0	0
10/10/2010	2:15 AM	25	25.1	24.9	91	23.4	0	NNE	0.4	NNE	1009.9	0	0
10/10/2010	2:30 AM	25.1	25.1	25	91	23.5	0	NNE	1.3	NNE	1009.6	0	0
10/10/2010	2:45 AM	25.1	25.1	25	90	23.3	0	E	2.2	ENE	1009.5	0	0
10/10/2010	3:00 AM	24.9	25.1	24.9	90	23.2	0.4	W	2.2	SW	1009.5	0	0
10/10/2010	3:15 AM	25.1	25.1	24.9	90	23.3	0.4	WNW	2.7	NW	1009.4	0	0
10/10/2010	3:30 AM	25.1	25.2	25	90	23.4	0.4	WNW	2.2	WNW	1009.6	0	0
10/10/2010	3:45 AM	25.2	25.2	25.1	89	23.3	0.9	WNW	3.1	WNW	1009.6	0.25	0
10/10/2010	4:00 AM	25.1	25.2	25.1	90	23.3	0	NW	1.3	NW	1009.7	0	0
10/10/2010	4:15 AM	25	25.1	25	91	23.4	0	NW	2.2	NNW	1009.8	0	0
10/10/2010	4:30 AM	25	25.1	25	91	23.4	0.4	NW	2.2	NW	1010.1	0	0
10/10/2010	4:45 AM	25	25	24.9	91	23.4	0.4	NW	2.2	NNW	1010.3	0	0
10/10/2010	5:00 AM	25.1	25.1	25	91	23.5	0.4	NNW	2.2	NNW	1010.5	0	0
10/10/2010	5:15 AM	25.2	25.2	25.1	90	23.5	0.4	NNE	2.2	N	1010.3	0	0
10/10/2010	5:30 AM	25.3	25.3	25.2	90	23.5	0	NNE	0.9	NNE	1010.2	0	0
10/10/2010	5:45 AM	25.4	25.4	25.3	89	23.4	0	NNE	1.3	NNE	1010.3	0.25	0
10/10/2010	6:00 AM	25.4	25.4	25.4	91	23.8	0	---	0	---	1010.2	0	0
10/10/2010	6:15 AM	25	25.4	25	92	23.6	0	---	0	---	1010.4	0	0
10/10/2010	6:30 AM	25	25.1	24.9	93	23.8	0	NNE	0.4	NNE	1010.6	0	0
10/10/2010	6:45 AM	25.4	25.4	25	92	24	0.4	NNE	0.9	NNE	1010.9	0	0
10/10/2010	7:00 AM	25.8	25.8	25.4	91	24.2	0.4	NNE	1.8	NNW	1011.2	0	0
10/10/2010	7:15 AM	25.9	25.9	25.7	91	24.3	0	NNW	0.4	NNW	1011.3	0	0
10/10/2010	7:30 AM	26.2	26.2	25.9	90	24.4	0	NNW	0.9	NNW	1011.3	0	0
10/10/2010	7:45 AM	26.6	26.6	26.2	89	24.6	0	NNW	0.9	NNW	1011.5	0	0
10/10/2010	8:00 AM	27.1	27.1	26.6	87	24.7	0	NNW	1.3	NNW	1011.7	0	0
10/10/2010	8:15 AM	27.6	27.6	27.1	85	24.9	0	NNW	0.9	NNW	1011.9	0	0
10/10/2010	8:30 AM	28.1	28.1	27.6	83	24.9	0.4	NE	2.7	N	1011.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/10/2010	8:45 AM	28.4	28.5	28.1	82	25.1	2.2	ESE	4.9	E	1011.9	0	0
10/10/2010	9:00 AM	28.7	28.7	28.5	82	25.3	2.2	ESE	4.9	ESE	1011.9	0	0
10/10/2010	9:15 AM	29.2	29.2	28.7	79	25.2	2.7	ESE	4.5	ESE	1011.7	0	0
10/10/2010	9:30 AM	29.5	29.5	29.2	78	25.3	2.7	ESE	4.9	ESE	1011.7	0	0
10/10/2010	9:45 AM	29.7	29.7	29.5	77	25.3	2.7	SE	4.9	SSE	1011.7	0	0
10/10/2010	10:00 AM	29.6	29.7	29.6	77	25.1	3.1	SE	5.8	SSE	1011.5	0	0
10/10/2010	10:15 AM	29.5	29.5	29.4	77	25	4	SE	6.3	ESE	1011.4	0	0
10/10/2010	10:30 AM	29.6	29.6	29.4	77	25.1	4	SE	6.7	ESE	1011.4	0	0
10/10/2010	10:45 AM	29.8	29.8	29.6	78	25.5	3.6	SE	6.7	ESE	1011.2	0	0
10/10/2010	11:00 AM	30.2	30.2	29.8	77	25.7	3.6	SE	5.8	SSE	1010.8	0	0
10/10/2010	11:15 AM	30.3	30.3	30.2	78	26	3.6	SE	6.3	ESE	1010.8	0	0
10/10/2010	11:30 AM	30.2	30.4	30.2	80	26.4	4	SE	6.7	S	1010.7	0	0
10/10/2010	11:45 AM	26.9	30.2	26.9	89	25	6.7	SE	11.2	SSE	1010.8	0	0
10/10/2010	12:00 PM	27.1	27.1	26.8	88	24.9	5.4	ESE	9.4	ESE	1010.9	0	0
10/10/2010	12:15 PM	28.1	28.1	27.1	82	24.7	3.6	ESE	6.3	ESE	1010.6	0	0
10/10/2010	12:30 PM	28.8	28.8	28.2	80	25	3.1	ESE	4.9	ESE	1010	0	0
10/10/2010	12:45 PM	29.1	29.1	28.8	79	25	4	ESE	6.7	SE	1009.8	0	0
10/10/2010	1:00 PM	29.2	29.3	29.1	80	25.4	3.6	ESE	5.8	SE	1009.7	0	0
10/10/2010	1:15 PM	29.4	29.4	29.2	80	25.6	4	SE	8	ESE	1009.5	0	0
10/10/2010	1:30 PM	29.7	29.7	29.4	80	25.9	4.5	SE	7.2	SE	1009.4	0	0
10/10/2010	1:45 PM	29.2	29.7	29.2	82	25.8	4.9	SE	8	ESE	1009.3	0	0
10/10/2010	2:00 PM	29.3	29.3	29.1	80	25.5	4	SE	7.2	SE	1009.5	0	0
10/10/2010	2:15 PM	29.4	29.4	29.3	80	25.6	4	SE	6.3	ESE	1009.4	0	0
10/10/2010	2:30 PM	29.4	29.5	29.4	81	25.8	4	SE	6.7	SE	1009.3	0	0
10/10/2010	2:45 PM	28.6	29.4	28.6	85	25.8	3.6	SE	6.3	SE	1009.1	0	0
10/10/2010	3:00 PM	28.9	28.9	28.6	81	25.4	3.6	SE	5.8	SE	1008.8	0	0
10/10/2010	3:15 PM	29.1	29.1	28.9	81	25.5	3.1	SE	4.9	SE	1008.7	0	0
10/10/2010	3:30 PM	29.1	29.1	29.1	80	25.3	3.6	SE	5.8	SE	1008.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/10/2010	3:45 PM	29.2	29.2	29.1	82	25.8	3.1	SE	5.8	ESE	1008.7	0	0
10/10/2010	4:00 PM	29.2	29.2	29.1	81	25.6	3.1	SE	5.4	ESE	1009	0	0
10/10/2010	4:15 PM	29.2	29.2	29.2	80	25.4	3.1	ESE	5.4	SE	1009.2	0	0
10/10/2010	4:30 PM	29.2	29.2	29.2	81	25.6	2.7	SE	4.9	ESE	1009.3	0	0
10/10/2010	4:45 PM	29.1	29.2	29.1	80	25.3	2.2	SE	4	SE	1009.4	0	0
10/10/2010	5:00 PM	29.1	29.2	29.1	80	25.3	2.2	SE	3.6	ESE	1009.4	0	0
10/10/2010	5:15 PM	29.2	29.2	29.1	78	24.9	2.7	SE	4.9	SE	1009.6	0	0
10/10/2010	5:30 PM	29.1	29.2	29.1	79	25.1	2.7	SE	4.9	SE	1009.7	0	0
10/10/2010	5:45 PM	28.8	29.1	28.8	80	25	1.8	ESE	3.6	ESE	1009.9	0	0
10/10/2010	6:00 PM	28.8	28.9	28.7	81	25.2	1.8	SE	3.6	ESE	1010.2	0	0
10/10/2010	6:15 PM	28.8	28.9	28.8	82	25.4	0.9	ESE	3.6	ESE	1010.3	0	0
10/10/2010	6:30 PM	28.6	28.8	28.6	81	25	0.4	SE	2.2	SE	1010.5	0	0
10/10/2010	6:45 PM	28.2	28.6	28.2	84	25.2	0.4	ESE	1.8	E	1010.6	0	0
10/10/2010	7:00 PM	27.9	28.2	27.9	84	24.9	0	---	0	---	1010.8	0	0
10/10/2010	7:15 PM	27.7	27.9	27.7	85	24.9	0	E	0.9	E	1011.1	0	0
10/10/2010	7:30 PM	27.5	27.7	27.4	85	24.8	0.4	NNE	2.2	NE	1011.1	0	0
10/10/2010	7:45 PM	27.5	27.5	27.4	84	24.6	0.4	NNE	0.9	NNE	1011.3	0	0
10/10/2010	8:00 PM	27.3	27.5	27.3	85	24.5	0	NNE	0.4	NNE	1011.5	0	0
10/10/2010	8:15 PM	27.2	27.3	27.2	85	24.5	0	NNE	0.9	NNE	1011.7	0	0
10/10/2010	8:30 PM	27.3	27.3	27.2	85	24.5	0	NNE	1.3	NNE	1012	0	0
10/10/2010	8:45 PM	27.1	27.3	27.1	86	24.5	0	NNE	0.9	NNE	1012.1	0	0
10/10/2010	9:00 PM	27.2	27.2	27	85	24.5	0.4	NNE	1.8	NNE	1012.2	0	0
10/10/2010	9:15 PM	27.1	27.2	27.1	84	24.2	0	NNE	0.9	NNE	1012.2	0	0
10/10/2010	9:30 PM	27.2	27.3	27.1	83	24.1	0	NNE	0.9	NNE	1012.2	0	0
10/10/2010	9:45 PM	27.2	27.3	27.2	83	24.1	0	NNE	0.9	NNE	1012	0	0
10/10/2010	10:00 PM	27	27.2	27	84	24.1	0	NNE	0.9	NNE	1011.9	0	0
10/10/2010	10:15 PM	26.9	27.1	26.9	86	24.3	0	NNE	0.9	NNE	1011.8	0	0
10/10/2010	10:30 PM	26.7	26.9	26.6	88	24.5	0	NNE	0.4	NNE	1011.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/10/2010	10:45 PM	28	28	26.7	86	25.4	1.8	SE	4.9	SE	1011.7	0	0
10/10/2010	11:00 PM	28.1	28.2	28	85	25.3	3.6	SE	6.7	SE	1011.7	0	0
10/10/2010	11:15 PM	28.2	28.2	28	83	25	4	SE	6.7	ESE	1011.5	0	0
10/10/2010	11:30 PM	28.1	28.2	28.1	84	25.1	3.6	SSE	5.4	SE	1011.5	0	0
10/10/2010	11:45 PM	28	28.1	27.9	85	25.2	3.1	SE	4.9	SSE	1011.5	0	0
10/11/2010	12:00 AM	28	28	27.9	84	25	3.1	SE	5.8	SSE	1011.5	0	0
10/11/2010	12:15 AM	28.2	28.2	28	83	25	2.7	SE	4	ESE	1011.5	0	0
10/11/2010	12:30 AM	27.9	28.2	27.8	80	24.1	2.2	E	4.9	ESE	1011.3	0	0
10/11/2010	12:45 AM	28.2	28.2	27.9	79	24.2	2.7	ESE	4.9	E	1011.1	0	0
10/11/2010	1:00 AM	28.4	28.4	28.2	78	24.2	3.6	ESE	5.8	E	1010.7	0	0
10/11/2010	1:15 AM	28.4	28.4	28.3	79	24.4	3.6	ESE	5.8	ESE	1010.4	0	0
10/11/2010	1:30 AM	28.4	28.5	28.4	81	24.9	3.6	ESE	5.8	ESE	1010.3	0	0
10/11/2010	1:45 AM	28.4	28.4	28.4	82	25	4	SE	6.3	ESE	1010.1	0	0
10/11/2010	2:00 AM	28.4	28.4	28.3	82	25	4	ESE	7.2	ESE	1009.9	0	0
10/11/2010	2:15 AM	28.3	28.4	28.3	82	25	3.6	ESE	5.8	SE	1009.6	0	0
10/11/2010	2:30 AM	28.5	28.5	28.3	81	24.9	3.6	SE	5.8	SE	1009.6	0	0
10/11/2010	2:45 AM	28.6	28.6	28.4	80	24.8	3.6	SE	6.7	SSE	1009.5	0	0
10/11/2010	3:00 AM	28.6	28.7	28.6	81	25	4	SE	6.7	ESE	1009.5	0	0
10/11/2010	3:15 AM	28.6	28.6	28.6	81	25	3.6	SE	5.8	ESE	1009.5	0	0
10/11/2010	3:30 AM	28.4	28.6	28.4	83	25.3	3.6	SE	5.4	SE	1009.6	0	0
10/11/2010	3:45 AM	28.5	28.5	28.4	82	25.1	4	SE	8.5	SE	1009.7	0	0
10/11/2010	4:00 AM	28.3	28.5	28.3	83	25.2	4	SE	6.3	SE	1009.6	0	0
10/11/2010	4:15 AM	28.3	28.3	28.3	83	25.2	4	SE	6.7	SE	1009.7	0	0
10/11/2010	4:30 AM	28.3	28.3	28.3	83	25.2	3.6	SE	6.7	SE	1009.7	0	0
10/11/2010	4:45 AM	28.3	28.3	28.2	82	24.9	3.6	ESE	6.3	ESE	1009.9	0	0
10/11/2010	5:00 AM	28.2	28.3	28.2	81	24.6	2.7	ESE	4.9	ESE	1010	0	0
10/11/2010	5:15 AM	27.6	28.2	27.6	81	24	1.3	ENE	5.8	SE	1010.2	0	0
10/11/2010	5:30 AM	27	27.6	27	82	23.7	0.4	ENE	3.6	NNE	1010.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/11/2010	5:45 AM	27	27.1	26.9	82	23.7	1.3	NNE	4.5	NNE	1010.7	0	0
10/11/2010	6:00 AM	27	27.2	27	81	23.5	0.9	NNE	3.1	NE	1010.9	0	0
10/11/2010	6:15 AM	26.9	27	26.9	82	23.6	0.4	N	2.7	NNE	1010.9	0	0
10/11/2010	6:30 AM	27.1	27.1	26.9	83	23.9	0	N	0.4	N	1011.2	0	0
10/11/2010	6:45 AM	27.5	27.5	27.1	83	24.4	0	N	0.4	N	1011.4	0	0
10/11/2010	7:00 AM	28.2	28.2	27.5	81	24.6	0.4	NNE	1.8	NNE	1011.4	0	0
10/11/2010	7:15 AM	28.8	28.8	28.2	79	24.8	0.4	NNE	2.2	ENE	1011.6	0	0
10/11/2010	7:30 AM	29.2	29.2	28.8	78	24.9	2.7	SE	4.5	SE	1011.8	0	0
10/11/2010	7:45 AM	29.2	29.3	29.2	78	25	2.7	SE	4.9	ESE	1012	0	0
10/11/2010	8:00 AM	29.3	29.3	29.1	78	25.1	3.6	SE	5.8	SE	1012.1	0	0
10/11/2010	8:15 AM	29.5	29.6	29.3	77	25	3.6	SE	5.8	SE	1012.1	0	0
10/11/2010	8:30 AM	29.7	29.7	29.4	77	25.3	3.6	SE	5.4	SE	1012.2	0	0
10/11/2010	8:45 AM	29.9	29.9	29.7	76	25.2	3.6	SE	5.8	SSE	1012.3	0	0
10/11/2010	9:00 AM	29.9	29.9	29.8	77	25.5	3.6	SE	5.8	SSE	1012.6	0	0
10/11/2010	9:15 AM	30.2	30.2	29.9	76	25.5	4	SE	7.2	SE	1012.7	0	0
10/11/2010	9:30 AM	30.3	30.3	30.2	75	25.4	4	SE	6.3	SSE	1012.6	0	0
10/11/2010	9:45 AM	30.6	30.6	30.3	74	25.4	4	SE	6.7	SSE	1012.6	0	0
10/11/2010	10:00 AM	30.7	30.7	30.6	74	25.6	4	SSE	6.3	SE	1012.7	0	0
10/11/2010	10:15 AM	30.6	30.8	30.6	78	26.3	4.5	SSE	6.7	SSE	1012.4	0	0
10/11/2010	10:30 AM	30.4	30.6	30.4	78	26.2	4.9	SSE	7.2	SE	1012.4	0	0
10/11/2010	10:45 AM	30.8	30.8	30.4	79	26.7	4.9	SSE	8	SE	1012.3	0	0
10/11/2010	11:00 AM	30.7	30.8	30.6	78	26.4	5.4	SSE	8.5	SSE	1012.1	0	0
10/11/2010	11:15 AM	30.7	30.8	30.6	79	26.6	5.4	SSE	8.9	SE	1012	0	0
10/11/2010	11:30 AM	30.6	30.7	30.6	79	26.6	5.4	SSE	8.5	SSE	1011.6	0	0
10/11/2010	11:45 AM	30.6	30.7	30.5	79	26.6	5.8	SSE	9.8	SSE	1011.5	0	0
10/11/2010	12:00 PM	30.7	30.7	30.6	79	26.6	5.8	SSE	9.8	SSE	1011.3	0	0
10/11/2010	12:15 PM	30.6	30.7	30.6	78	26.3	6.3	SSE	9.8	SE	1011.1	0	0
10/11/2010	12:30 PM	30.7	30.7	30.6	75	25.7	6.3	SSE	9.8	SSE	1010.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/11/2010	12:45 PM	30.7	30.8	30.7	74	25.5	5.8	SSE	9.8	SE	1010.7	0	0
10/11/2010	1:00 PM	30.6	30.7	30.6	77	26.1	6.3	SSE	9.8	S	1010.4	0	0
10/11/2010	1:15 PM	30.6	30.7	30.6	77	26.1	5.8	SSE	9.4	S	1010.3	0	0
10/11/2010	1:30 PM	30.8	30.8	30.7	76	26.1	5.4	SSE	9.8	SSE	1010.2	0	0
10/11/2010	1:45 PM	30.7	30.9	30.7	76	26	5.8	SSE	9.8	SE	1010.1	0	0
10/11/2010	2:00 PM	30.6	30.7	30.5	77	26.1	6.3	SSE	9.8	SSE	1010	0	0
10/11/2010	2:15 PM	30.6	30.7	30.6	77	26.1	5.8	SSE	8.9	SSE	1009.7	0	0
10/11/2010	2:30 PM	30.8	30.8	30.6	75	25.8	5.8	SSE	9.4	SSE	1009.7	0	0
10/11/2010	2:45 PM	30.8	30.8	30.7	74	25.6	6.3	SSE	12.1	SSE	1009.6	0	0
10/11/2010	3:00 PM	30.7	30.8	30.7	74	25.6	5.8	SSE	9.8	SSE	1009.5	0	0
10/11/2010	3:15 PM	30.7	30.7	30.7	75	25.7	5.4	SSE	8.9	SSE	1009.4	0	0
10/11/2010	3:30 PM	30.6	30.7	30.5	76	25.8	5.4	SSE	8.5	SE	1009.4	0	0
10/11/2010	3:45 PM	30.4	30.6	30.4	77	25.9	4.9	SSE	8	SE	1009.4	0	0
10/11/2010	4:00 PM	30.2	30.4	30.2	80	26.4	4.9	SSE	8	SSE	1009.5	0	0
10/11/2010	4:15 PM	30.2	30.3	30.2	81	26.6	4.9	SSE	8	SE	1009.4	0	0
10/11/2010	4:30 PM	29.9	30.2	29.9	82	26.5	5.8	SSE	8.9	S	1009.7	0	0
10/11/2010	4:45 PM	29.9	29.9	29.9	81	26.3	5.4	SSE	9.4	SSE	1009.9	0	0
10/11/2010	5:00 PM	29.7	29.9	29.7	81	26.1	5.4	SSE	9.4	SSE	1010	0	0
10/11/2010	5:15 PM	29.6	29.7	29.6	81	26	5.4	SE	8.9	SE	1010.2	0	0
10/11/2010	5:30 PM	29.6	29.6	29.5	79	25.5	5.4	SE	9.4	SSE	1010.4	0	0
10/11/2010	5:45 PM	29.4	29.5	29.4	79	25.4	4.9	SE	8	ESE	1010.6	0	0
10/11/2010	6:00 PM	29.2	29.4	29.2	79	25.2	4	SE	6.7	SE	1010.7	0	0
10/11/2010	6:15 PM	29.2	29.2	29.1	78	24.9	4	SE	6.3	SSE	1011	0	0
10/11/2010	6:30 PM	29.2	29.2	29.1	77	24.7	3.6	SE	5.8	SE	1011.1	0	0
10/11/2010	6:45 PM	29.1	29.2	29.1	76	24.4	2.7	SE	4.9	ESE	1011.2	0	0
10/11/2010	7:00 PM	28.9	29.1	28.9	75	24.1	2.2	SE	4	SE	1011.3	0	0
10/11/2010	7:15 PM	28.7	29	28.7	75	23.8	1.8	ESE	4	SE	1011.5	0	0
10/11/2010	7:30 PM	28.6	28.8	28.6	79	24.6	0.9	ENE	2.2	ENE	1011.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/11/2010	7:45 PM	28.6	28.7	28.6	76	23.9	0.9	SSE	2.7	N	1012	0	0
10/11/2010	8:00 PM	28.7	28.8	28.6	79	24.7	0	SSE	1.3	SSE	1012	0	0
10/11/2010	8:15 PM	28.1	28.7	28.1	78	23.9	0	---	0	---	1012.3	0	0
10/11/2010	8:30 PM	27.4	28.1	27.4	81	23.9	0	SSE	0.4	SSE	1012.4	0	0
10/11/2010	8:45 PM	27.3	27.4	27.3	79	23.3	0.4	SSE	1.8	SSE	1012.4	0	0
10/11/2010	9:00 PM	27.3	27.4	27.3	80	23.6	0	SSE	0.9	SSE	1012.5	0	0
10/11/2010	9:15 PM	27.3	27.4	27.3	82	24	0	SSE	0.4	SSE	1012.6	0	0
10/11/2010	9:30 PM	27.2	27.3	27.2	85	24.5	0	SSE	0.4	SSE	1012.7	0	0
10/11/2010	9:45 PM	27.3	27.3	27.2	85	24.6	0	NW	1.8	NW	1012.7	0	0
10/11/2010	10:00 PM	27.6	27.6	27.3	83	24.4	0	WNW	0.9	WNW	1012.7	0	0
10/11/2010	10:15 PM	27.4	27.6	27.4	84	24.4	0.4	WSW	2.2	WSW	1012.6	0	0
10/11/2010	10:30 PM	27.2	27.4	27.2	84	24.3	0	SW	1.8	SW	1012.6	0	0
10/11/2010	10:45 PM	27.1	27.2	27.1	85	24.3	0	SW	0.9	SW	1012.6	0	0
10/11/2010	11:00 PM	26.8	27.1	26.8	87	24.5	0	WSW	0.4	WSW	1012.6	0	0
10/11/2010	11:15 PM	26.5	26.9	26.4	86	24	0	---	0	---	1012.4	0	0
10/11/2010	11:30 PM	26.3	26.5	26.3	88	24.1	0	WSW	0.9	WSW	1012.3	0	0
10/11/2010	11:45 PM	26.2	26.3	26.1	89	24.2	0	WSW	0.9	WSW	1012.3	0	0
10/12/2010	12:00 AM	25.9	26.2	25.9	89	23.9	0	WSW	0.4	WSW	1012.5	0	0
10/12/2010	12:15 AM	25.8	25.9	25.8	89	23.9	0	WSW	0.4	WSW	1012.3	0	0
10/12/2010	12:30 AM	25.7	25.8	25.7	89	23.7	0	WSW	0.4	WSW	1012.2	0	0
10/12/2010	12:45 AM	25.6	25.7	25.6	87	23.3	0	WSW	0.4	WSW	1011.9	0	0
10/12/2010	1:00 AM	25.7	25.8	25.6	87	23.4	0	WSW	0.4	WSW	1011.7	0	0
10/12/2010	1:15 AM	25.4	25.7	25.4	88	23.3	0	WSW	0.9	WSW	1011.6	0	0
10/12/2010	1:30 AM	25.6	25.6	25.4	87	23.3	0	WSW	0.9	WSW	1011.3	0	0
10/12/2010	1:45 AM	25.6	25.7	25.6	86	23.1	0	WSW	1.8	WNW	1011.2	0	0
10/12/2010	2:00 AM	25.6	25.6	25.6	85	22.9	0	N	2.2	NNW	1011.1	0	0
10/12/2010	2:15 AM	25.6	25.6	25.6	84	22.7	0	N	0.4	N	1010.9	0	0
10/12/2010	2:30 AM	25.6	25.7	25.6	82	22.3	0	N	0.9	N	1010.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/12/2010	2:45 AM	25.7	25.7	25.6	82	22.4	0	N	0.9	N	1010.8	0	0
10/12/2010	3:00 AM	25.7	25.8	25.7	82	22.4	0	N	0.9	N	1010.7	0	0
10/12/2010	3:15 AM	25.7	25.7	25.7	81	22.2	0	NW	0.9	N	1010.6	0	0
10/12/2010	3:30 AM	25.7	25.7	25.7	80	22	0	NW	1.8	NW	1010.6	0	0
10/12/2010	3:45 AM	25.7	25.7	25.7	81	22.2	0	NW	0.9	NW	1010.6	0	0
10/12/2010	4:00 AM	25.7	25.7	25.6	80	22	0	NW	0.9	NW	1010.5	0	0
10/12/2010	4:15 AM	25.7	25.7	25.7	79	21.8	0	NW	0.4	NW	1010.5	0	0
10/12/2010	4:30 AM	25.7	25.7	25.7	79	21.8	0	NW	0.9	NW	1010.4	0	0
10/12/2010	4:45 AM	25.6	25.7	25.6	78	21.4	0	NW	0.9	NW	1010.5	0	0
10/12/2010	5:00 AM	25.4	25.6	25.4	79	21.5	0	NW	0.4	NW	1010.5	0	0
10/12/2010	5:15 AM	25.4	25.5	25.4	79	21.5	0	NNW	0.9	NW	1010.7	0	0
10/12/2010	5:30 AM	25.2	25.4	25.2	78	21.1	0	NNW	0.4	NNW	1010.8	0	0
10/12/2010	5:45 AM	25.4	25.4	25.2	80	21.7	0	NNW	0.4	NNW	1011.1	0	0
10/12/2010	6:00 AM	25.3	25.5	25.3	82	22	0	---	0	---	1011.2	0	0
10/12/2010	6:15 AM	25.2	25.4	25.2	84	22.3	0	---	0	---	1011.4	0	0
10/12/2010	6:30 AM	25.2	25.2	25.1	85	22.5	0	NNW	0.4	NNW	1011.6	0	0
10/12/2010	6:45 AM	26.1	26.1	25.2	83	22.9	0	NNW	0.4	NNW	1011.7	0	0
10/12/2010	7:00 AM	27.4	27.4	26.1	81	23.8	0	---	0	---	1011.8	0	0
10/12/2010	7:15 AM	27.7	28.1	27.4	78	23.5	0.4	NNW	0.9	NNW	1011.9	0	0
10/12/2010	7:30 AM	28.1	28.1	27.5	79	24.1	0	NNW	0.9	NNW	1012.1	0	0
10/12/2010	7:45 AM	28.6	28.6	28.1	78	24.4	0	NNW	0.9	NNW	1012.1	0	0
10/12/2010	8:00 AM	28.5	28.6	28.3	78	24.3	0	NNW	0.9	NNW	1012.3	0	0
10/12/2010	8:15 AM	28.9	28.9	28.3	75	24	0.4	NW	1.8	NW	1012.4	0	0
10/12/2010	8:30 AM	28.8	29.3	28.8	71	23	0.4	NW	1.8	NW	1012.6	0	0
10/12/2010	8:45 AM	29.3	29.3	28.8	70	23.3	0.4	NW	1.8	NW	1012.8	0	0
10/12/2010	9:00 AM	30	30	29.3	67	23.2	0.4	NW	1.3	NW	1012.8	0	0
10/12/2010	9:15 AM	30.2	30.2	30	72	24.6	0.4	WNW	1.8	WNW	1012.8	0	0
10/12/2010	9:30 AM	30.3	30.3	30.1	73	24.9	0.9	WNW	2.2	NW	1012.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/12/2010	9:45 AM	30.3	30.3	30.2	71	24.4	1.3	WNW	2.7	W	1012.9	0	0
10/12/2010	10:00 AM	30.7	30.7	30.3	67	23.8	1.3	WNW	2.7	NW	1012.9	0	0
10/12/2010	10:15 AM	30.7	30.8	30.7	65	23.4	1.3	WNW	2.2	WNW	1012.8	0	0
10/12/2010	10:30 AM	31.3	31.3	30.7	66	24.2	0.9	NW	2.2	NNW	1012.7	0	0
10/12/2010	10:45 AM	31.7	31.7	31.3	64	24	0.9	WNW	2.2	WNW	1012.6	0	0
10/12/2010	11:00 AM	31.9	31.9	31.7	64	24.3	1.3	WNW	2.7	WNW	1012.5	0	0
10/12/2010	11:15 AM	31.9	32	31.9	65	24.5	1.3	WNW	2.2	WNW	1012.4	0	0
10/12/2010	11:30 AM	32.1	32.1	31.9	64	24.4	1.3	WNW	2.7	WNW	1012.3	0	0
10/12/2010	11:45 AM	32.4	32.4	32.1	66	25.3	0.9	WNW	3.6	SW	1012	0	0
10/12/2010	12:00 PM	31.7	32.4	31.7	71	25.8	3.1	SE	6.3	ESE	1011.8	0	0
10/12/2010	12:15 PM	32.1	32.1	31.7	72	26.4	2.7	ESE	5.4	E	1011.6	0	0
10/12/2010	12:30 PM	31.6	32.1	31.6	75	26.6	4.5	SSE	8	SE	1011.2	0	0
10/12/2010	12:45 PM	31.6	31.7	31.6	77	27	4.9	SSE	8	SSE	1011.1	0	0
10/12/2010	1:00 PM	31.7	31.7	31.4	76	26.9	5.4	SSE	9.8	SE	1011.1	0	0
10/12/2010	1:15 PM	31.1	31.7	31.1	78	26.8	5.8	SSE	10.3	S	1010.7	0	0
10/12/2010	1:30 PM	31.3	31.4	31.1	78	27	5.8	SSE	9.4	SSE	1010.5	0	0
10/12/2010	1:45 PM	31.1	31.3	31.1	78	26.8	6.3	SSE	10.3	SSE	1010.4	0	0
10/12/2010	2:00 PM	31.2	31.3	31.1	76	26.5	5.8	SSE	8.9	SE	1010.3	0	0
10/12/2010	2:15 PM	31.1	31.3	30.9	77	26.5	5.8	SSE	8.9	SSE	1010.4	0	0
10/12/2010	2:30 PM	31.1	31.1	30.9	79	27	5.4	SSE	9.4	SE	1010.3	0	0
10/12/2010	2:45 PM	31.1	31.2	31	78	26.8	4.9	SSE	8.5	SE	1010.1	0	0
10/12/2010	3:00 PM	31.4	31.5	31.1	77	26.9	4.9	SSE	9.4	SE	1010.2	0	0
10/12/2010	3:15 PM	31.1	31.4	31	79	27	4.9	SSE	8.5	SSE	1010	0	0
10/12/2010	3:30 PM	30.9	31.2	30.9	80	27.1	4.9	SSE	8	SE	1010.1	0	0
10/12/2010	3:45 PM	31.4	31.4	30.9	72	25.8	4.5	SE	8.5	SE	1010.2	0	0
10/12/2010	4:00 PM	31.1	31.4	31.1	77	26.6	3.6	SSE	6.7	SE	1010.1	0	0
10/12/2010	4:15 PM	31.2	31.2	31.1	74	26	3.6	SE	6.7	SSE	1010.4	0	0
10/12/2010	4:30 PM	30	31.2	30	80	26.2	5.4	SSE	9.8	SE	1010.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/12/2010	4:45 PM	29.4	30	29.4	84	26.5	5.4	SSE	8.9	S	1010.5	0	0
10/12/2010	5:00 PM	29.3	29.6	29.3	84	26.3	5.4	SE	9.8	SE	1010.6	0	0
10/12/2010	5:15 PM	29.6	29.6	29.3	83	26.4	4.9	SE	8.5	SSE	1010.6	0	0
10/12/2010	5:30 PM	29.4	29.6	29.4	83	26.3	4.5	SE	8.9	SSE	1010.7	0	0
10/12/2010	5:45 PM	29.5	29.5	29.4	79	25.5	4.5	SE	8	ESE	1010.8	0	0
10/12/2010	6:00 PM	29.3	29.6	29.3	80	25.5	4	SE	6.7	SE	1010.8	0	0
10/12/2010	6:15 PM	29.2	29.3	29.2	80	25.4	3.1	SE	5.4	SE	1011	0	0
10/12/2010	6:30 PM	29.3	29.6	29.3	81	25.7	1.3	ENE	4	SE	1011.4	0	0
10/12/2010	6:45 PM	29.2	29.3	29.2	81	25.6	2.7	NNE	5.4	NE	1011.6	0	0
10/12/2010	7:00 PM	29.2	29.2	29.2	82	25.8	2.2	NNE	4.5	NNE	1011.9	0	0
10/12/2010	7:15 PM	28.9	29.2	28.9	82	25.6	0.9	NE	2.7	NE	1012.2	0	0
10/12/2010	7:30 PM	28.9	28.9	28.8	82	25.5	0	NNE	2.2	NNE	1012.4	0	0
10/12/2010	7:45 PM	28.7	28.9	28.7	83	25.5	0	NNE	0.9	NNE	1012.4	0	0
10/12/2010	8:00 PM	28.6	28.7	28.6	83	25.4	0	NNE	0.4	NNE	1012.4	0	0
10/12/2010	8:15 PM	28.4	28.6	28.4	85	25.6	0	NNE	0.9	NNE	1012.5	0	0
10/12/2010	8:30 PM	28.2	28.4	28.2	86	25.7	0	---	0	---	1012.4	0	0
10/12/2010	8:45 PM	28.1	28.3	28.1	87	25.7	0	NNE	0.4	NNE	1012.6	0	0
10/12/2010	9:00 PM	27.9	28.1	27.8	86	25.3	0	NNE	0.9	NNE	1012.6	0	0
10/12/2010	9:15 PM	28	28	27.9	86	25.4	0	NNE	1.3	WNW	1012.7	0	0
10/12/2010	9:30 PM	28	28.1	27.9	85	25.2	0.4	W	1.3	W	1012.8	0	0
10/12/2010	9:45 PM	28	28	27.9	86	25.4	0	W	1.3	W	1012.8	0	0
10/12/2010	10:00 PM	28.1	28.1	28	85	25.3	0	WNW	1.3	WNW	1012.8	0	0
10/12/2010	10:15 PM	27.9	28.1	27.9	84	24.9	0	WNW	0.9	WNW	1012.8	0	0
10/12/2010	10:30 PM	27.8	27.9	27.8	84	24.8	0	WNW	0.4	WNW	1012.8	0	0
10/12/2010	10:45 PM	27.6	27.8	27.6	84	24.7	0	WNW	0.4	WNW	1012.8	0	0
10/12/2010	11:00 PM	27.5	27.6	27.5	84	24.6	0	WNW	1.8	NNW	1012.8	0	0
10/12/2010	11:15 PM	27.5	27.5	27.4	84	24.6	0	N	1.3	N	1012.7	0	0
10/12/2010	11:30 PM	27.4	27.5	27.4	84	24.4	0	N	0.9	N	1012.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/12/2010	11:45 PM	27.4	27.4	27.3	84	24.4	0	N	1.8	N	1012.3	0	0
10/13/2010	12:00 AM	27.4	27.4	27.3	83	24.2	0	N	0.9	N	1012.3	0	0
10/13/2010	12:15 AM	27.4	27.4	27.3	84	24.4	0	N	0.9	N	1012.3	0	0
10/13/2010	12:30 AM	27.3	27.4	27.3	83	24.1	0	N	0.4	N	1012.1	0	0
10/13/2010	12:45 AM	27.2	27.3	27.2	85	24.4	0	N	0.4	N	1011.9	0	0
10/13/2010	1:00 AM	26.9	27.2	26.9	87	24.5	0	---	0	---	1011.7	0	0
10/13/2010	1:15 AM	26.7	26.9	26.7	86	24.2	0	N	0.4	N	1011.4	0	0
10/13/2010	1:30 AM	26.8	26.9	26.7	85	24.1	0	---	0	---	1011.2	0	0
10/13/2010	1:45 AM	26.8	26.8	26.7	87	24.4	0	---	0	---	1011	0	0
10/13/2010	2:00 AM	26.4	26.8	26.4	88	24.3	0	---	0	---	1010.8	0	0
10/13/2010	2:15 AM	26.2	26.6	26.2	90	24.4	0	---	0	---	1010.8	0	0
10/13/2010	2:30 AM	26.1	26.2	25.9	91	24.5	0	---	0	---	1011	0	0
10/13/2010	2:45 AM	26	26.1	25.9	91	24.4	0	---	0	---	1010.8	0	0
10/13/2010	3:00 AM	25.9	26.1	25.9	92	24.5	0	N	0.9	N	1010.8	0	0
10/13/2010	3:15 AM	26.1	26.1	25.9	91	24.5	0	---	0	---	1010.8	0	0
10/13/2010	3:30 AM	26.3	26.3	26.2	90	24.5	0	N	0.4	N	1010.8	0	0
10/13/2010	3:45 AM	26.4	26.4	26.3	90	24.7	0	N	0.4	N	1010.9	0	0
10/13/2010	4:00 AM	26.3	26.4	26.3	88	24.2	0	N	0.4	N	1010.9	0	0
10/13/2010	4:15 AM	26.3	26.4	26.3	88	24.2	0	---	0	---	1010.9	0	0
10/13/2010	4:30 AM	26.1	26.4	26.1	89	24.1	0	N	0.9	N	1011	0	0
10/13/2010	4:45 AM	26.1	26.1	26	89	24.1	0	NW	0.9	N	1011.1	0	0
10/13/2010	5:00 AM	26.2	26.2	26.1	89	24.3	0	WNW	1.3	WNW	1011.2	0	0
10/13/2010	5:15 AM	26.4	26.4	26.2	87	24	0	NNW	2.2	NW	1011.3	0	0
10/13/2010	5:30 AM	26.3	26.4	26.3	87	23.9	0	---	0	---	1011.6	0	0
10/13/2010	5:45 AM	26.2	26.3	26.2	87	23.9	0	---	0	---	1011.6	0	0
10/13/2010	6:00 AM	26.2	26.2	26.2	89	24.2	0	NNW	0.4	NNW	1011.8	0	0
10/13/2010	6:15 AM	26.2	26.2	26.2	90	24.4	0	---	0	---	1012	0	0
10/13/2010	6:30 AM	26.1	26.2	26.1	90	24.3	0	NNW	0.9	NNW	1012.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/13/2010	6:45 AM	26.8	26.8	26.1	87	24.4	0	NNW	0.9	NNW	1012.3	0	0
10/13/2010	7:00 AM	27.3	27.3	26.8	83	24.1	0.4	NNW	1.8	NNW	1012.5	0	0
10/13/2010	7:15 AM	28.2	28.2	27.3	81	24.6	0	NW	0.9	NW	1012.8	0	0
10/13/2010	7:30 AM	28.6	28.6	28.2	79	24.6	0.4	NW	2.2	NW	1013	0	0
10/13/2010	7:45 AM	28.9	29	28.6	78	24.7	0.4	NNW	2.2	NNW	1013.3	0	0
10/13/2010	8:00 AM	29.4	29.4	29	78	25.1	0.4	NW	2.2	NNW	1013.3	0	0
10/13/2010	8:15 AM	29.8	29.8	29.4	77	25.4	0.4	NW	1.3	NW	1013.7	0	0
10/13/2010	8:30 AM	30	30.2	29.8	74	24.9	0.4	NW	1.8	NW	1013.9	0	0
10/13/2010	8:45 AM	30.1	30.1	30	76	25.4	0	NW	0.9	NW	1014.1	0	0
10/13/2010	9:00 AM	30	30.2	29.9	77	25.5	0.4	NW	1.8	NW	1014.1	0	0
10/13/2010	9:15 AM	30.7	30.7	30	77	26.2	0.4	NW	1.8	NW	1014.3	0	0
10/13/2010	9:30 AM	30.8	30.8	30.6	76	26.1	0.9	WNW	2.2	NW	1014.4	0	0
10/13/2010	9:45 AM	31.1	31.2	30.8	75	26.2	0.9	WNW	3.1	WNW	1014.5	0	0
10/13/2010	10:00 AM	31.2	31.2	31.1	74	26	0.9	WNW	2.2	WNW	1014.4	0	0
10/13/2010	10:15 AM	31.3	31.4	31.3	72	25.7	0.9	ENE	3.1	NE	1014.3	0	0
10/13/2010	10:30 AM	31.1	31.4	31	74	25.9	1.3	ESE	3.6	SSE	1014.2	0	0
10/13/2010	10:45 AM	31.3	31.3	31.1	75	26.3	1.3	ESE	3.1	SE	1014.1	0	0
10/13/2010	11:00 AM	31.3	31.4	31.1	76	26.6	2.2	SE	5.4	SE	1013.8	0	0
10/13/2010	11:15 AM	31.3	31.3	31.2	73	25.9	4.5	SSE	8	SSE	1013.5	0	0
10/13/2010	11:30 AM	31.2	31.3	31	77	26.7	4.9	SSE	8	SSE	1013.1	0	0
10/13/2010	11:45 AM	31	31.2	30.9	77	26.5	5.4	SSE	7.2	SE	1013	0	0
10/13/2010	12:00 PM	31	31.1	30.9	77	26.5	4.9	SSE	7.2	SSE	1012.8	0	0
10/13/2010	12:15 PM	31	31.1	30.9	77	26.5	4.9	SSE	8.5	SE	1012.7	0	0
10/13/2010	12:30 PM	31.1	31.2	30.9	77	26.5	4.9	SSE	8	ESE	1012.3	0	0
10/13/2010	12:45 PM	31.1	31.1	30.9	77	26.5	5.4	SSE	8.5	SSE	1012.2	0	0
10/13/2010	1:00 PM	31.1	31.1	30.9	78	26.8	5.4	SSE	8.9	SSE	1012	0	0
10/13/2010	1:15 PM	30.9	31.2	30.9	78	26.7	5.4	SSE	8.9	S	1011.6	0	0
10/13/2010	1:30 PM	31	31	30.9	78	26.7	5.8	SSE	8.9	SSE	1011.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/13/2010	1:45 PM	31.1	31.1	30.9	76	26.3	5.4	SSE	9.4	SSE	1011.4	0	0
10/13/2010	2:00 PM	31.1	31.1	30.9	76	26.3	5.4	SSE	9.4	SSE	1011.4	0	0
10/13/2010	2:15 PM	31	31.1	30.9	76	26.3	4.5	SSE	7.2	S	1011.7	0	0
10/13/2010	2:30 PM	30.4	31.1	30.4	69	24.1	0.9	WNW	4.5	SSE	1011.8	0	0
10/13/2010	2:45 PM	29.9	30.4	29.9	71	24.1	0.9	NW	3.1	WNW	1011.7	0	0
10/13/2010	3:00 PM	30.5	30.5	29.9	71	24.6	0.4	SE	2.2	SE	1011.7	0	0
10/13/2010	3:15 PM	30.4	30.7	30.4	79	26.4	1.3	SE	5.8	SE	1011.5	0	0
10/13/2010	3:30 PM	29.8	30.4	29.8	80	26	4.9	SE	8.5	SSE	1011.1	0	0
10/13/2010	3:45 PM	29.8	30.1	29.8	78	25.5	4.5	SE	8	SE	1011.4	0	0
10/13/2010	4:00 PM	29.8	29.8	29.7	79	25.7	4.5	SE	8	SE	1011.4	0	0
10/13/2010	4:15 PM	29.7	30	29.7	80	25.8	3.6	SE	6.7	SE	1011.4	0	0
10/13/2010	4:30 PM	28.8	29.6	28.8	84	25.8	2.7	ENE	4.5	NE	1011.4	0	0
10/13/2010	4:45 PM	29.2	29.2	28.8	82	25.8	0.4	ENE	2.7	ENE	1011.4	0	0
10/13/2010	5:00 PM	29.1	29.2	29.1	82	25.7	0.4	NNW	2.2	NNW	1011.3	0	0
10/13/2010	5:15 PM	29.3	29.3	29	82	25.9	0.4	NNW	1.8	NNW	1011.4	0	0
10/13/2010	5:30 PM	29.2	29.3	29.2	80	25.4	0	NNW	1.3	NNW	1011.4	0	0
10/13/2010	5:45 PM	28.8	29.2	28.8	79	24.8	0	ENE	5.8	N	1011.4	0	0
10/13/2010	6:00 PM	28.6	28.8	28.6	80	24.8	0	ENE	0.9	ENE	1011.5	0	0
10/13/2010	6:15 PM	28.5	28.6	28.3	79	24.5	0.4	ENE	5.4	SSE	1011.6	0	0
10/13/2010	6:30 PM	28.6	28.7	28.6	81	25	0	ENE	0.9	ENE	1011.7	0	0
10/13/2010	6:45 PM	28.2	28.6	28.2	84	25.3	0	WNW	0.9	WNW	1011.8	0	0
10/13/2010	7:00 PM	27.9	28.2	27.8	84	24.9	0	NW	0.9	NW	1012.1	0	0
10/13/2010	7:15 PM	27.7	27.8	27.7	84	24.8	0	NW	0.9	NW	1012.5	0	0
10/13/2010	7:30 PM	27.5	27.7	27.5	83	24.4	0.4	NW	3.6	NNE	1012.8	0	0
10/13/2010	7:45 PM	27.6	27.6	27.5	82	24.2	0.9	NNE	3.1	NE	1013.2	0	0
10/13/2010	8:00 PM	27.6	27.6	27.6	82	24.2	0.9	NNE	2.7	N	1013.4	0	0
10/13/2010	8:15 PM	27.7	27.7	27.6	80	24	0.9	NNE	3.1	NNE	1013.7	0	0
10/13/2010	8:30 PM	27.7	27.7	27.7	81	24.1	0	NNE	0.9	NNE	1013.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/13/2010	8:45 PM	27.7	27.7	27.6	83	24.5	0	NNE	0.9	NNE	1013.7	0	0
10/13/2010	9:00 PM	27.4	27.7	27.4	82	24.1	0	NNE	0.4	NNE	1013.7	0	0
10/13/2010	9:15 PM	27.3	27.5	27.3	82	23.9	0	---	0	---	1013.9	0	0
10/13/2010	9:30 PM	27	27.3	27	84	24.1	0	---	0	---	1013.7	0	0
10/13/2010	9:45 PM	26.7	27.1	26.7	86	24.2	0	---	0	---	1013.7	0	0
10/13/2010	10:00 PM	26.6	26.7	26.6	88	24.4	0	---	0	---	1013.8	0	0
10/13/2010	10:15 PM	26.4	26.6	26.4	88	24.3	0	---	0	---	1013.9	0	0
10/13/2010	10:30 PM	26.5	26.6	26.4	89	24.5	0	---	0	---	1013.9	0	0
10/13/2010	10:45 PM	26.3	26.5	26.3	89	24.3	0	---	0	---	1014	0	0
10/13/2010	11:00 PM	26.3	26.3	26.3	88	24.2	0	NNE	0.4	NNE	1014	0	0
10/13/2010	11:15 PM	26.4	26.4	26.3	86	23.9	0	NNE	0.4	NNE	1013.9	0	0
10/13/2010	11:30 PM	26.6	26.6	26.4	86	24.1	0	NNE	0.4	NNE	1013.7	0	0
10/13/2010	11:45 PM	26.6	26.6	26.6	87	24.2	0	NNE	0.9	NNE	1013.5	0	0
10/14/2010	12:00 AM	26.4	26.6	26.4	86	23.9	0	NNE	0.4	NNE	1013.4	0	0
10/14/2010	12:15 AM	26.3	26.4	26.3	84	23.4	0	NNE	0.9	NNE	1013.3	0	0
10/14/2010	12:30 AM	26.3	26.3	26.3	83	23.2	0	NNE	0.4	NNE	1013.3	0	0
10/14/2010	12:45 AM	26.3	26.4	26.3	83	23.2	0	NNE	0.9	NNE	1013.2	0	0
10/14/2010	1:00 AM	26.3	26.4	26.3	85	23.6	0	NNE	0.9	NNE	1012.9	0	0
10/14/2010	1:15 AM	26.3	26.3	26.3	85	23.6	0	NNE	0.9	NNE	1012.8	0	0
10/14/2010	1:30 AM	26.3	26.4	26.3	84	23.4	0	NNE	0.4	NNE	1012.6	0	0
10/14/2010	1:45 AM	26.3	26.3	26.3	84	23.4	0	---	0	---	1012.5	0	0
10/14/2010	2:00 AM	26.2	26.3	26.2	83	23.1	0	---	0	---	1012.4	0	0
10/14/2010	2:15 AM	26.2	26.3	26.2	84	23.3	0	---	0	---	1012.1	0	0
10/14/2010	2:30 AM	26.3	26.3	26.2	85	23.6	0	NNE	0.9	NNE	1012.2	0	0
10/14/2010	2:45 AM	26.3	26.3	26.2	84	23.4	0	NNE	0.4	NNE	1012.2	0	0
10/14/2010	3:00 AM	26.1	26.3	26.1	84	23.2	0	---	0	---	1011.9	0	0
10/14/2010	3:15 AM	25.9	26.1	25.9	87	23.6	0	---	0	---	1011.7	0	0
10/14/2010	3:30 AM	25.6	25.9	25.6	89	23.7	0	---	0	---	1011.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/14/2010	3:45 AM	25.6	25.6	25.4	91	24	0	---	0	---	1011.7	0	0
10/14/2010	4:00 AM	25.6	25.7	25.6	91	24	0	---	0	---	1011.7	0	0
10/14/2010	4:15 AM	25.4	25.6	25.4	92	24	0	---	0	---	1011.7	0	0
10/14/2010	4:30 AM	25.4	25.5	25.3	93	24.2	0	---	0	---	1011.8	0	0
10/14/2010	4:45 AM	25.7	25.7	25.4	91	24.1	0	NNE	0.4	NNE	1011.4	0	0
10/14/2010	5:00 AM	25.7	25.7	25.6	90	24	0	NNE	0.4	NNE	1011.6	0	0
10/14/2010	5:15 AM	25.7	25.8	25.7	88	23.6	0	NNE	0.4	NNE	1011.7	0	0
10/14/2010	5:30 AM	25.8	25.8	25.7	89	23.8	0	---	0	---	1011.8	0	0
10/14/2010	5:45 AM	25.6	25.8	25.6	89	23.7	0	NNE	0.4	NNE	1011.9	0	0
10/14/2010	6:00 AM	25.6	25.6	25.5	87	23.2	0	NNE	0.4	NNE	1011.9	0	0
10/14/2010	6:15 AM	25.5	25.6	25.4	87	23.2	0	---	0	---	1012.2	0	0
10/14/2010	6:30 AM	25.7	25.7	25.4	85	23	0.4	NNE	1.8	N	1012.4	0	0
10/14/2010	6:45 AM	26.3	26.3	25.7	82	23	0.4	NNE	1.8	NNE	1012.6	0	0
10/14/2010	7:00 AM	26.9	26.9	26.3	79	23	0.4	NNE	2.2	NW	1012.6	0	0
10/14/2010	7:15 AM	27.5	27.5	26.9	77	23.1	0.9	NNW	2.7	NNW	1012.7	0	0
10/14/2010	7:30 AM	27.8	27.8	27.5	78	23.6	0.9	NNE	3.1	NNE	1012.8	0	0
10/14/2010	7:45 AM	28.4	28.4	27.8	76	23.7	0.4	NNE	2.2	NNE	1013	0	0
10/14/2010	8:00 AM	28.7	28.7	28.4	74	23.6	0.9	NNE	2.2	NNE	1013	0	0
10/14/2010	8:15 AM	29.3	29.3	28.7	73	23.9	0.4	NW	2.2	NW	1013.1	0	0
10/14/2010	8:30 AM	29.7	29.7	29.3	75	24.8	0.4	WNW	1.8	WNW	1013.1	0	0
10/14/2010	8:45 AM	29.8	29.8	29.7	69	23.5	0.4	WNW	0.9	WNW	1013.1	0	0
10/14/2010	9:00 AM	30.1	30.1	29.8	70	24	0.4	WNW	1.8	WNW	1013	0	0
10/14/2010	9:15 AM	30.6	30.6	30.1	67	23.8	0.4	WNW	1.8	WNW	1013.1	0	0
10/14/2010	9:30 AM	30.8	30.8	30.6	65	23.5	1.3	WNW	2.7	W	1013.2	0	0
10/14/2010	9:45 AM	31.1	31.1	30.8	64	23.4	0.9	WNW	2.2	WNW	1013.3	0	0
10/14/2010	10:00 AM	31.2	31.3	31.1	66	24.1	0.9	WNW	2.2	WNW	1013.2	0	0
10/14/2010	10:15 AM	31.3	31.5	31.3	65	24	0.9	WNW	2.2	WNW	1013.1	0	0
10/14/2010	10:30 AM	31.4	31.6	31.3	64	23.8	0.9	WNW	2.2	WNW	1013.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/14/2010	10:45 AM	31.8	31.8	31.4	63	23.9	0.9	WSW	2.7	WSW	1012.9	0	0
10/14/2010	11:00 AM	30.8	31.8	30.8	67	23.9	1.8	S	4.9	S	1012.8	0	0
10/14/2010	11:15 AM	30.2	30.9	30.1	71	24.3	2.2	S	4.9	S	1012.7	0	0
10/14/2010	11:30 AM	30.4	30.4	30.2	70	24.3	2.7	S	4.9	S	1012.5	0	0
10/14/2010	11:45 AM	30.7	30.7	30.3	64	23.1	2.2	S	4	SSE	1012.2	0	0
10/14/2010	12:00 PM	30.7	31	30.7	68	24.1	2.2	S	4.5	SSE	1012.1	0	0
10/14/2010	12:15 PM	30.9	30.9	30.5	71	25.1	2.7	S	4.9	S	1012	0	0
10/14/2010	12:30 PM	30.9	31.1	30.9	74	25.7	3.6	SSE	5.4	SE	1011.9	0	0
10/14/2010	12:45 PM	30.8	31.1	30.8	74	25.7	3.6	SSE	5.4	SE	1011.8	0	0
10/14/2010	1:00 PM	29.9	30.8	29.9	79	25.8	4	SSE	6.7	SE	1011.5	0	0
10/14/2010	1:15 PM	27.2	29.9	27.2	87	24.8	4.9	SSE	10.3	SSE	1011.5	0.51	5.1
10/14/2010	1:30 PM	27.1	27.1	26.8	90	25.3	2.7	S	6.3	SSE	1011.6	1.02	7.1
10/14/2010	1:45 PM	26.8	27.3	26.8	91	25.2	3.6	SE	7.2	ESE	1011.2	2.54	60.5
10/14/2010	2:00 PM	27.1	27.1	26.6	89	25.1	3.6	ESE	6.7	ESE	1011	0	0
10/14/2010	2:15 PM	28.2	28.2	27.1	87	25.8	3.1	SE	4.9	SE	1010.7	0.25	0
10/14/2010	2:30 PM	28.1	28.3	27.9	84	25.1	3.1	ESE	5.8	ESE	1010.6	0	0
10/14/2010	2:45 PM	28.7	28.7	28.1	79	24.7	3.1	E	4.9	ESE	1010.7	0	0
10/14/2010	3:00 PM	29.4	29.4	28.8	78	25.1	1.3	E	3.1	E	1010.6	0	0
10/14/2010	3:15 PM	30.2	30.2	29.4	74	25.1	1.3	E	3.1	E	1010.5	0	0
10/14/2010	3:30 PM	30.1	30.4	30.1	73	24.7	1.3	E	3.1	E	1010.7	0	0
10/14/2010	3:45 PM	30.1	30.1	30	74	24.9	0.4	E	2.2	E	1010.6	0	0
10/14/2010	4:00 PM	30.2	30.3	30.1	74	25	1.3	SE	3.1	S	1010.4	0	0
10/14/2010	4:15 PM	30.1	30.2	30.1	75	25.2	1.3	SSE	2.7	SE	1010.6	0	0
10/14/2010	4:30 PM	30.1	30.2	30	77	25.6	1.3	SE	2.7	SSE	1010.5	0	0
10/14/2010	4:45 PM	29.9	30.1	29.9	78	25.6	1.8	SE	2.7	SE	1010.4	0	0
10/14/2010	5:00 PM	29.7	29.9	29.7	78	25.4	1.3	SSE	3.1	SSE	1010.4	0	0
10/14/2010	5:15 PM	29.4	29.7	29.4	79	25.4	1.3	SSE	2.7	SSE	1010.4	0	0
10/14/2010	5:30 PM	29.2	29.4	29.2	80	25.4	0.4	SSE	2.2	SSE	1010.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/14/2010	5:45 PM	28.9	29.2	28.9	81	25.4	0.4	SSE	2.2	SSE	1010.6	0	0
10/14/2010	6:00 PM	28.9	28.9	28.8	82	25.5	0.4	SSE	1.8	SSE	1010.7	0	0
10/14/2010	6:15 PM	28.7	28.9	28.7	82	25.3	0.4	SSE	2.2	SSE	1010.9	0	0
10/14/2010	6:30 PM	28.7	28.7	28.6	82	25.3	0.9	SSE	2.7	SSE	1010.9	0	0
10/14/2010	6:45 PM	28.8	28.8	28.7	82	25.4	1.8	SSE	3.1	SE	1011	0	0
10/14/2010	7:00 PM	28.8	28.8	28.7	84	25.8	1.8	SSE	3.1	SSE	1011.2	0	0
10/14/2010	7:15 PM	28.3	28.8	28.3	85	25.6	0.4	ESE	2.2	ESE	1011.3	0	0
10/14/2010	7:30 PM	28.3	28.4	28.3	85	25.6	0.4	ESE	1.8	ESE	1011.5	0	0
10/14/2010	7:45 PM	28.2	28.3	28.2	86	25.7	0	ESE	0.4	ESE	1011.7	0	0
10/14/2010	8:00 PM	27.8	28.2	27.8	85	25.1	0	ENE	2.2	ENE	1012	0	0
10/14/2010	8:15 PM	27.6	27.8	27.6	83	24.5	0.4	NNW	2.7	NW	1012.3	0	0
10/14/2010	8:30 PM	27.4	27.6	27.4	83	24.2	0.4	NNW	2.7	NNW	1012.6	0	0
10/14/2010	8:45 PM	27.3	27.4	27.3	85	24.5	0.4	NW	2.2	W	1012.5	0	0
10/14/2010	9:00 PM	27.2	27.3	27.2	86	24.7	0.4	NW	2.2	WNW	1012.6	0	0
10/14/2010	9:15 PM	27.2	27.3	27.2	86	24.7	0.4	NNW	1.8	NNW	1012.7	0	0
10/14/2010	9:30 PM	27.2	27.2	27.2	87	24.8	0	NW	1.3	NW	1012.8	0	0
10/14/2010	9:45 PM	27	27.2	27	88	24.8	0	NW	0.4	NW	1013	0	0
10/14/2010	10:00 PM	26.9	27	26.9	89	25	0	NW	0.4	NW	1013.1	0	0
10/14/2010	10:15 PM	27	27	26.9	89	25	0	NW	0.4	NW	1013	0	0
10/14/2010	10:30 PM	27	27	26.9	87	24.6	0	NW	0.9	NW	1013	0	0
10/14/2010	10:45 PM	27.2	27.2	27	87	24.9	0	NW	0.9	NW	1013	0	0
10/14/2010	11:00 PM	27.2	27.3	27.2	87	24.9	0	NW	0.9	NW	1012.8	0	0
10/14/2010	11:15 PM	27.2	27.2	27.2	84	24.2	0	NW	0.9	NW	1012.6	0	0
10/14/2010	11:30 PM	27.1	27.2	27.1	84	24.2	0.4	NW	1.8	NW	1012.5	0	0
10/14/2010	11:45 PM	27.1	27.1	27.1	83	23.9	0.4	NNW	2.7	NNW	1012.5	0	0
10/15/2010	12:00 AM	27.1	27.1	27	83	23.9	0	NW	0.9	NW	1012.2	0	0
10/15/2010	12:15 AM	27.1	27.1	27.1	82	23.7	0	NW	1.8	NW	1012.1	0	0
10/15/2010	12:30 AM	27.2	27.2	27.1	83	24	0.4	NNW	2.2	NW	1011.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/15/2010	12:45 AM	27.1	27.2	27.1	83	23.9	0.4	NW	2.2	NNW	1011.7	0	0
10/15/2010	1:00 AM	26.9	27.1	26.9	83	23.8	0	NW	1.3	NW	1011.6	0	0
10/15/2010	1:15 AM	26.8	26.9	26.8	83	23.7	0	NW	0.9	NW	1011.6	0	0
10/15/2010	1:30 AM	26.7	26.8	26.7	84	23.8	0	---	0	---	1011.5	0	0
10/15/2010	1:45 AM	26.7	26.8	26.7	87	24.3	0	---	0	---	1011.4	0	0
10/15/2010	2:00 AM	26.6	26.7	26.5	88	24.4	0	N	1.3	N	1011.5	0	0
10/15/2010	2:15 AM	26.6	26.6	26.5	87	24.2	0	N	1.3	N	1011.3	0	0
10/15/2010	2:30 AM	26.6	26.6	26.5	88	24.4	0	---	0	---	1011.1	0	0
10/15/2010	2:45 AM	26.2	26.5	26.2	89	24.3	0	---	0	---	1011.1	0	0
10/15/2010	3:00 AM	26.1	26.2	26.1	91	24.5	0	---	0	---	1011.1	0	0
10/15/2010	3:15 AM	25.9	26.1	25.9	91	24.3	0	---	0	---	1010.9	0	0
10/15/2010	3:30 AM	25.8	25.9	25.8	92	24.4	0	---	0	---	1010.7	0	0
10/15/2010	3:45 AM	25.8	26	25.8	92	24.4	0	---	0	---	1010.8	0	0
10/15/2010	4:00 AM	25.9	25.9	25.8	93	24.7	0	---	0	---	1010.8	0	0
10/15/2010	4:15 AM	25.9	25.9	25.9	92	24.5	0	---	0	---	1011	0	0
10/15/2010	4:30 AM	25.9	25.9	25.8	90	24.1	0	N	0.4	N	1011.2	0	0
10/15/2010	4:45 AM	26.1	26.1	25.9	90	24.3	0	N	0.4	N	1011.2	0	0
10/15/2010	5:00 AM	26.1	26.1	26.1	89	24.1	0	---	0	---	1011.4	0	0
10/15/2010	5:15 AM	25.8	26.1	25.8	88	23.7	0	NW	1.8	NNW	1011.5	0	0
10/15/2010	5:30 AM	25.7	25.9	25.7	89	23.8	0	NNW	0.4	NNW	1011.7	0	0
10/15/2010	5:45 AM	25.7	25.8	25.7	88	23.6	0	NNW	0.4	NNW	1011.8	0	0
10/15/2010	6:00 AM	25.9	25.9	25.7	87	23.6	0	NNW	0.4	NNW	1012	0	0
10/15/2010	6:15 AM	26.1	26.1	25.9	88	23.9	0	NNW	0.4	NNW	1012.2	0	0
10/15/2010	6:30 AM	26.1	26.1	25.9	87	23.7	0	---	0	---	1012.5	0	0
10/15/2010	6:45 AM	26.7	26.7	26.1	86	24.2	0	NNW	0.4	NNW	1012.7	0	0
10/15/2010	7:00 AM	27.3	27.3	26.7	84	24.4	0	NNW	0.9	NNW	1012.8	0	0
10/15/2010	7:15 AM	28.4	28.4	27.4	79	24.4	0	NNW	0.4	NNW	1012.9	0	0
10/15/2010	7:30 AM	28.5	28.7	28.5	79	24.5	0.4	NNW	0.9	NNW	1012.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/15/2010	7:45 AM	28.9	28.9	28.4	78	24.7	0.4	NNW	0.9	NNW	1013	0	0
10/15/2010	8:00 AM	29.4	29.4	28.9	76	24.7	0.4	NW	1.8	NW	1013	0	0
10/15/2010	8:15 AM	29.8	29.8	29.4	73	24.4	0	NW	1.8	NW	1013	0	0
10/15/2010	8:30 AM	30.2	30.2	29.7	71	24.3	0	NW	1.3	NW	1013	0	0
10/15/2010	8:45 AM	30.3	30.3	30.1	69	24	0	NW	0.9	NW	1013	0	0
10/15/2010	9:00 AM	30.7	30.7	30.3	70	24.6	0	NW	0.9	NW	1012.9	0	0
10/15/2010	9:15 AM	31.1	31.1	30.7	71	25.2	0.4	S	2.2	SSE	1013.1	0	0
10/15/2010	9:30 AM	30.2	31.1	30.2	66	23.1	1.3	SSE	3.1	S	1013.3	0	0
10/15/2010	9:45 AM	30.2	30.3	30.1	73	24.8	1.8	SSE	3.6	SSE	1013.3	0	0
10/15/2010	10:00 AM	30.2	30.2	29.8	70	24.1	1.8	S	3.6	S	1013.4	0	0
10/15/2010	10:15 AM	30.2	30.2	30.1	69	23.8	1.8	SE	3.6	S	1013.2	0	0
10/15/2010	10:30 AM	30.4	30.4	30.2	70	24.4	0.9	S	3.1	S	1013	0	0
10/15/2010	10:45 AM	30.4	30.5	30.4	69	24.1	1.8	SSE	3.6	SE	1013	0	0
10/15/2010	11:00 AM	30.2	30.4	30.2	70	24.1	2.7	SSE	4.5	S	1012.8	0	0
10/15/2010	11:15 AM	30.3	30.3	30	73	24.9	2.2	SSE	4.9	S	1012.7	0	0
10/15/2010	11:30 AM	30.2	30.3	30.2	72	24.6	2.2	SSE	4.9	S	1012.6	0	0
10/15/2010	11:45 AM	30.3	30.3	30.2	74	25.2	2.2	SSE	4.5	SSE	1012.3	0	0
10/15/2010	12:00 PM	30.3	30.4	30.3	74	25.2	2.2	SE	4	SE	1012.2	0	0
10/15/2010	12:15 PM	30.8	30.8	30.3	78	26.5	2.2	SE	4.5	SSE	1011.9	0	0
10/15/2010	12:30 PM	30.5	30.8	30.4	76	25.8	2.7	SSE	4.9	S	1011.7	0	0
10/15/2010	12:45 PM	30.8	30.8	30.5	72	25.2	3.6	SSE	5.4	SE	1011.4	0	0
10/15/2010	1:00 PM	30.6	31	30.6	73	25.2	3.6	SSE	5.4	SSE	1011.2	0	0
10/15/2010	1:15 PM	30.8	30.8	30.6	74	25.7	4	SSE	6.3	SE	1011	0	0
10/15/2010	1:30 PM	30.6	30.9	30.6	77	26.1	3.6	SE	6.3	SE	1010.8	0	0
10/15/2010	1:45 PM	30.4	30.8	30.4	77	26	3.1	SE	4.9	ESE	1010.5	0	0
10/15/2010	2:00 PM	30.7	30.8	30.4	77	26.2	4	SSE	7.2	SSE	1010.3	0	0
10/15/2010	2:15 PM	30.4	30.7	30.1	79	26.3	3.6	SSE	6.3	S	1010.3	0	0
10/15/2010	2:30 PM	30.4	30.6	30.4	80	26.5	3.6	SSE	6.3	S	1010.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/15/2010	2:45 PM	30.5	30.5	30.3	77	26	4	SE	7.2	SSE	1010	0	0
10/15/2010	3:00 PM	30.4	30.5	30.3	79	26.3	4	SE	6.3	ESE	1010	0	0
10/15/2010	3:15 PM	30.3	30.4	30.3	78	26.1	4	SSE	6.3	SSE	1009.6	0	0
10/15/2010	3:30 PM	30.3	30.4	30.2	79	26.2	4	SE	6.7	SE	1009.6	0	0
10/15/2010	3:45 PM	30.1	30.3	30.1	78	25.8	4	SE	6.3	SE	1009.7	0	0
10/15/2010	4:00 PM	30.1	30.1	29.9	80	26.2	3.6	SSE	6.3	SSE	1009.8	0	0
10/15/2010	4:15 PM	29.8	30.1	29.8	79	25.7	4	SSE	5.8	SE	1009.9	0	0
10/15/2010	4:30 PM	29.6	29.8	29.6	82	26.2	3.6	SSE	5.8	SE	1010.1	0	0
10/15/2010	4:45 PM	29.6	29.6	29.5	81	26	3.1	SSE	6.3	SSE	1010.1	0	0
10/15/2010	5:00 PM	29.5	29.7	29.5	79	25.5	3.1	SE	4.9	SE	1010.4	0	0
10/15/2010	5:15 PM	29.4	29.6	29.4	80	25.6	2.7	SE	4.9	SE	1010.6	0	0
10/15/2010	5:30 PM	29.4	29.4	29.3	81	25.8	2.2	SE	4.9	SE	1010.5	0	0
10/15/2010	5:45 PM	28.8	29.4	28.8	80	25	1.3	NNE	4	NE	1010.6	0	0
10/15/2010	6:00 PM	28.7	28.8	28.6	80	24.9	1.8	NNE	3.6	NE	1010.7	0	0
10/15/2010	6:15 PM	28.5	28.7	28.5	82	25.1	1.3	NNE	3.6	NNE	1010.8	0	0
10/15/2010	6:30 PM	28.3	28.5	28.3	81	24.7	1.3	NNE	4	NE	1010.7	0	0
10/15/2010	6:45 PM	28.2	28.3	28.2	82	24.9	0.4	NNE	2.2	N	1011	0	0
10/15/2010	7:00 PM	28.2	28.2	28.2	82	24.8	0.4	NNE	2.2	NNW	1011.3	0	0
10/15/2010	7:15 PM	28.1	28.2	28.1	82	24.7	0.9	NNE	3.1	NE	1011.5	0	0
10/15/2010	7:30 PM	27.9	28.1	27.9	82	24.5	0.9	NNE	2.7	NNE	1011.6	0	0
10/15/2010	7:45 PM	27.8	27.9	27.8	83	24.6	0.4	NNW	3.1	NNW	1011.8	0	0
10/15/2010	8:00 PM	27.7	27.8	27.7	84	24.7	0.4	NNW	2.7	NNW	1012	0	0
10/15/2010	8:15 PM	27.6	27.7	27.6	84	24.7	0	NW	1.3	NW	1012.3	0	0
10/15/2010	8:30 PM	27.7	27.7	27.6	85	24.9	0	NW	0.9	NW	1012.5	0	0
10/15/2010	8:45 PM	27.7	27.7	27.6	85	24.9	0	NW	1.8	NNE	1012.7	0	0
10/15/2010	9:00 PM	27.5	27.7	27.5	85	24.8	0.9	NNE	2.2	NE	1012.9	0	0
10/15/2010	9:15 PM	27.3	27.5	27.3	85	24.6	0.4	NNE	2.2	NNE	1013.1	0	0
10/15/2010	9:30 PM	27.3	27.3	27.3	85	24.5	0	NNE	0.4	NNE	1013.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/15/2010	9:45 PM	27.2	27.3	27.2	85	24.5	0	NNE	0.4	NNE	1013.4	0	0
10/15/2010	10:00 PM	27.2	27.2	27.2	86	24.6	0	NNW	1.8	NNW	1013.5	0	0
10/15/2010	10:15 PM	27.1	27.2	27.1	88	25	0	NW	0.9	NW	1013.5	0	0
10/15/2010	10:30 PM	26.9	27.1	26.9	89	25	0	NW	0.4	NW	1013.5	0	0
10/15/2010	10:45 PM	26.9	26.9	26.9	89	24.9	0	NW	0.4	NW	1013.5	0	0
10/15/2010	11:00 PM	26.8	26.9	26.8	90	25.1	0	---	0	---	1013.4	0	0
10/15/2010	11:15 PM	26.7	26.8	26.7	91	25.1	0	---	0	---	1013.2	0	0
10/15/2010	11:30 PM	26.4	26.7	26.4	91	24.9	0	---	0	---	1013.2	0	0
10/15/2010	11:45 PM	26.4	26.4	26.3	92	25	0	---	0	---	1013.1	0	0
10/16/2010	12:00 AM	26.3	26.4	26.3	91	24.7	0	---	0	---	1013	0	0
10/16/2010	12:15 AM	26.3	26.4	26.3	91	24.7	0	---	0	---	1012.7	0	0
10/16/2010	12:30 AM	26.5	26.5	26.3	92	25.1	0	---	0	---	1012.5	0	0
10/16/2010	12:45 AM	26.4	26.5	26.4	92	25	0	NW	0.4	NW	1012.3	0	0
10/16/2010	1:00 AM	26.3	26.4	26.3	92	24.9	0	---	0.4	NNW	1012.1	0	0
10/16/2010	1:15 AM	26.3	26.4	26.3	92	24.9	0	---	0	---	1012.1	0	0
10/16/2010	1:30 AM	26.3	26.3	26.3	92	24.9	0	NW	0.4	NW	1012	0	0
10/16/2010	1:45 AM	26.3	26.3	26.3	92	24.9	0	NW	0.4	NW	1011.9	0	0
10/16/2010	2:00 AM	26.2	26.3	26.2	92	24.8	0	---	0	---	1011.7	0	0
10/16/2010	2:15 AM	26.2	26.2	26.2	92	24.8	0	---	0	---	1011.6	0	0
10/16/2010	2:30 AM	26.1	26.2	26.1	92	24.7	0	---	0	---	1011.4	0	0
10/16/2010	2:45 AM	26.1	26.1	26.1	91	24.5	0	---	0	---	1011.2	0	0
10/16/2010	3:00 AM	26.1	26.2	26.1	91	24.5	0	NW	0.4	NW	1011.1	0	0
10/16/2010	3:15 AM	26	26.1	25.9	91	24.4	0	NW	0.4	NW	1011.1	0	0
10/16/2010	3:30 AM	25.9	26	25.9	90	24.1	0	---	0	---	1011.2	0	0
10/16/2010	3:45 AM	25.9	25.9	25.8	91	24.4	0	---	0	---	1011.3	0	0
10/16/2010	4:00 AM	25.8	25.9	25.8	92	24.4	0	---	0	---	1011.4	0	0
10/16/2010	4:15 AM	25.6	25.8	25.6	93	24.4	0	---	0	---	1011.6	0	0
10/16/2010	4:30 AM	25.3	25.6	25.3	93	24.1	0	---	0	---	1011.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/16/2010	4:45 AM	25.2	25.3	25.1	93	24	0	---	0	---	1011.7	0	0
10/16/2010	5:00 AM	25.3	25.4	25.2	93	24.1	0	---	0	---	1012	0	0
10/16/2010	5:15 AM	25.4	25.4	25.3	94	24.4	0	---	0	---	1012	0	0
10/16/2010	5:30 AM	25.3	25.4	25.3	94	24.2	0	---	0	---	1012.1	0	0
10/16/2010	5:45 AM	25.2	25.3	25.2	95	24.4	0	---	0	---	1012.4	0	0
10/16/2010	6:00 AM	25.2	25.2	25.2	95	24.4	0	---	0	---	1012.4	0	0
10/16/2010	6:15 AM	25.2	25.3	25.2	94	24.2	0	NW	0.4	NW	1012.6	0	0
10/16/2010	6:30 AM	25.6	25.6	25.2	94	24.5	0	---	0	---	1012.7	0	0
10/16/2010	6:45 AM	26.2	26.2	25.6	93	24.9	0	---	0	---	1012.9	0	0
10/16/2010	7:00 AM	26.9	26.9	26.2	90	25.1	0	---	0	---	1013	0	0
10/16/2010	7:15 AM	28.1	28.1	26.9	87	25.7	0	---	0	---	1013	0	0
10/16/2010	7:30 AM	29	29	28.1	83	25.8	0	---	0	---	1013.1	0	0
10/16/2010	7:45 AM	28.7	29	28.7	83	25.5	0	NW	0.9	NW	1013.2	0	0
10/16/2010	8:00 AM	28.6	28.7	28.6	83	25.4	0.4	NW	0.9	NW	1013.3	0	0
10/16/2010	8:15 AM	28.9	28.9	28.6	81	25.4	0.4	NW	1.3	WNW	1013.5	0	0
10/16/2010	8:30 AM	29	29	28.8	80	25.2	0.4	NW	1.8	NW	1013.7	0	0
10/16/2010	8:45 AM	29.3	29.3	29	77	24.8	0.4	WNW	1.8	NW	1013.9	0	0
10/16/2010	9:00 AM	29.4	29.4	29.3	78	25.2	0.9	NW	2.2	NW	1013.8	0	0
10/16/2010	9:15 AM	29.8	29.8	29.4	74	24.7	0.4	WNW	2.2	WNW	1013.8	0	0
10/16/2010	9:30 AM	30.2	30.3	29.8	72	24.6	0.4	NW	1.8	NW	1013.8	0	0
10/16/2010	9:45 AM	30.5	30.7	30.2	69	24.2	0.4	SSE	2.7	SE	1013.8	0	0
10/16/2010	10:00 AM	30.7	30.7	30.3	72	25.1	0.4	SSE	2.2	SSE	1013.8	0	0
10/16/2010	10:15 AM	30.6	31.1	30.6	70	24.5	0.4	SW	2.7	S	1013.8	0	0
10/16/2010	10:30 AM	30.2	30.6	30.2	73	24.8	0.4	SE	2.7	SSE	1013.6	0	0
10/16/2010	10:45 AM	29.9	30.2	29.9	74	24.7	1.3	S	3.6	S	1013.5	0	0
10/16/2010	11:00 AM	30.1	30.1	29.8	76	25.4	2.2	S	4	SSE	1013.3	0	0
10/16/2010	11:15 AM	30.6	30.6	30.1	75	25.7	2.7	SSE	4	SSE	1013.2	0	0
10/16/2010	11:30 AM	30.7	30.7	30.4	74	25.6	3.1	S	5.4	SSE	1013.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/16/2010	11:45 AM	30.8	30.8	30.4	74	25.6	3.6	S	5.8	S	1013	0	0
10/16/2010	12:00 PM	30.8	30.8	30.5	75	25.8	3.6	S	5.8	S	1012.7	0	0
10/16/2010	12:15 PM	30.9	30.9	30.8	76	26.2	3.1	S	5.4	S	1012.6	0	0
10/16/2010	12:30 PM	30.8	30.9	30.6	74	25.6	3.1	SSE	5.4	S	1012.7	0	0
10/16/2010	12:45 PM	30.4	30.8	30.4	75	25.5	3.1	SSE	4.9	SSE	1012.4	0	0
10/16/2010	1:00 PM	29.8	30.4	29.8	79	25.8	3.1	SSE	4.5	SE	1012.1	0	0
10/16/2010	1:15 PM	29.7	29.8	29.7	79	25.7	2.7	SSE	4.5	S	1012.1	0	0
10/16/2010	1:30 PM	29.6	29.8	29.6	80	25.8	2.7	SSE	5.4	S	1012	0	0
10/16/2010	1:45 PM	29.6	29.7	29.5	80	25.8	2.2	SSE	4	S	1011.8	0	0
10/16/2010	2:00 PM	29.7	29.7	29.6	78	25.4	2.2	SSE	4	S	1011.6	0	0
10/16/2010	2:15 PM	29.7	29.7	29.6	79	25.7	2.2	SSE	4	SSE	1011.4	0	0
10/16/2010	2:30 PM	29.5	29.7	29.4	80	25.7	1.8	S	3.6	S	1011.4	0	0
10/16/2010	2:45 PM	29.6	29.6	29.5	80	25.7	1.3	SSE	3.1	S	1011.4	0	0
10/16/2010	3:00 PM	29.6	29.6	29.5	80	25.7	1.3	SSE	2.7	SSE	1011.4	0	0
10/16/2010	3:15 PM	28.7	29.6	28.7	82	25.3	1.8	NNE	4.9	NNW	1011.4	0	0
10/16/2010	3:30 PM	27.9	28.7	27.9	86	25.4	2.7	NNE	4.5	N	1011.4	0	0
10/16/2010	3:45 PM	28.2	28.3	27.9	85	25.4	2.2	NNE	4	N	1011.4	0	0
10/16/2010	4:00 PM	27.8	28.2	27.8	84	24.8	1.8	NNE	3.6	NNE	1011.5	0	0
10/16/2010	4:15 PM	27.4	27.8	27.4	89	25.5	1.8	NNE	3.1	NNE	1011.6	0.25	0
10/16/2010	4:30 PM	27.6	27.6	27.4	83	24.5	1.3	NNE	3.6	ENE	1011.7	0	0
10/16/2010	4:45 PM	27.7	27.7	27.6	82	24.4	1.3	NE	4	ENE	1011.8	0	0
10/16/2010	5:00 PM	27.8	27.8	27.7	82	24.5	0.4	NE	1.8	NE	1012	0	0
10/16/2010	5:15 PM	27.7	27.9	27.7	85	24.9	0.4	NNE	2.7	NE	1012	0	0
10/16/2010	5:30 PM	27.6	27.7	27.5	84	24.6	0.4	NNE	2.7	NE	1012.1	0	0
10/16/2010	5:45 PM	27.4	27.6	27.4	86	24.8	0.4	NE	2.7	NE	1012.2	0	0
10/16/2010	6:00 PM	27.3	27.4	27.3	86	24.7	1.3	NNE	3.1	N	1012.4	0	0
10/16/2010	6:15 PM	27.4	27.4	27.2	82	24.1	0.9	NNE	3.6	NNE	1012.2	0	0
10/16/2010	6:30 PM	27.4	27.4	27.4	83	24.2	0.9	NNE	3.1	NNE	1012.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/16/2010	6:45 PM	27.3	27.4	27.3	82	24	0.9	NNE	3.1	NNE	1012.3	0	0
10/16/2010	7:00 PM	27.3	27.4	27.3	81	23.8	0.9	NNE	3.6	NNE	1012.6	0	0
10/16/2010	7:15 PM	27.3	27.3	27.2	82	23.9	0.9	NNE	4	NNE	1012.7	0	0
10/16/2010	7:30 PM	27.2	27.3	27.2	82	23.9	0.9	NNE	3.6	NE	1012.9	0	0
10/16/2010	7:45 PM	27.1	27.2	27.1	83	23.9	0.4	NW	2.2	NE	1013	0	0
10/16/2010	8:00 PM	27.2	27.2	27.1	83	24	0.4	NW	2.7	NNW	1013.2	0	0
10/16/2010	8:15 PM	27.2	27.3	27.1	83	24	0.9	NNE	3.1	NE	1013.4	0	0
10/16/2010	8:30 PM	26.7	27.2	26.7	84	23.8	0.4	NNE	2.2	NNE	1013.5	0	0
10/16/2010	8:45 PM	26.6	26.7	26.4	85	23.8	0.4	NNE	2.7	N	1013.7	0	0
10/16/2010	9:00 PM	26.8	26.8	26.6	84	23.9	0.9	NNE	3.1	NNE	1013.8	0	0
10/16/2010	9:15 PM	26.9	26.9	26.8	84	24	0.4	NNE	2.2	NNE	1013.8	0	0
10/16/2010	9:30 PM	26.9	26.9	26.9	84	24	0.4	NNE	0.9	NNE	1013.8	0	0
10/16/2010	9:45 PM	26.8	26.9	26.8	85	24.1	0	---	0	---	1013.8	0	0
10/16/2010	10:00 PM	26.7	26.8	26.7	85	23.9	0	NNE	0.4	NNE	1014	0	0
10/16/2010	10:15 PM	26.6	26.7	26.6	85	23.8	0	NNE	0.4	NNE	1014.1	0	0
10/16/2010	10:30 PM	26.5	26.6	26.4	84	23.6	0.4	NNE	3.1	NNE	1014	0	0
10/16/2010	10:45 PM	26.7	26.7	26.5	83	23.5	0.9	NNE	3.1	N	1013.9	0	0
10/16/2010	11:00 PM	26.8	26.8	26.7	83	23.6	1.3	NNE	4.5	NNE	1013.7	0	0
10/16/2010	11:15 PM	26.8	26.8	26.8	82	23.5	0.9	NNE	3.6	NNE	1013.5	0	0
10/16/2010	11:30 PM	26.8	26.9	26.8	82	23.4	0.9	NNE	3.1	NNE	1013.3	0	0
10/16/2010	11:45 PM	26.7	26.8	26.7	82	23.4	0.4	NNE	2.7	NNE	1013.4	0	0
10/17/2010	12:00 AM	26.8	26.8	26.7	83	23.6	0.4	NE	3.1	NE	1013.3	0	0
10/17/2010	12:15 AM	26.8	26.8	26.8	83	23.7	1.3	NNE	3.1	NNE	1013.1	0	0
10/17/2010	12:30 AM	26.7	26.8	26.7	86	24.2	1.8	NNE	4	NE	1013	0	0
10/17/2010	12:45 AM	26.7	26.7	26.7	85	24	1.3	NNE	3.6	NNE	1012.7	0	0
10/17/2010	1:00 AM	26.7	26.7	26.7	85	23.9	1.3	NNE	4.5	NNE	1012.6	0	0
10/17/2010	1:15 AM	26.7	26.7	26.7	84	23.8	0.9	NNE	3.1	NNE	1012.5	0	0
10/17/2010	1:30 AM	26.7	26.8	26.7	83	23.6	0.9	NNE	3.1	NNE	1012.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/17/2010	1:45 AM	26.5	26.7	26.5	83	23.4	0	NNE	1.8	NNE	1012.3	0	0
10/17/2010	2:00 AM	26.3	26.5	26.3	84	23.4	0	NNE	0.9	NNE	1012.2	0	0
10/17/2010	2:15 AM	26.3	26.4	26.3	84	23.4	0.4	NNE	1.8	NNE	1012.2	0	0
10/17/2010	2:30 AM	26.3	26.4	26.3	84	23.4	0	---	0	---	1012	0	0
10/17/2010	2:45 AM	26.2	26.3	26.2	86	23.7	0	NNE	0.4	NNE	1011.9	0	0
10/17/2010	3:00 AM	26.2	26.3	26.2	87	23.9	0	NNE	0.4	NNE	1012	0	0
10/17/2010	3:15 AM	26.2	26.2	26.2	88	24.1	0	NNE	0.4	NNE	1011.9	0	0
10/17/2010	3:30 AM	26.1	26.2	26.1	88	23.9	0	---	0	---	1011.8	0	0
10/17/2010	3:45 AM	25.9	26.1	25.9	88	23.8	0	---	0	---	1011.9	0	0
10/17/2010	4:00 AM	25.9	25.9	25.8	87	23.6	0	NNE	0.4	NNE	1012.1	0	0
10/17/2010	4:15 AM	25.9	26	25.8	87	23.6	0	NNE	0.4	NNE	1012.1	0	0
10/17/2010	4:30 AM	26	26.1	25.9	86	23.5	0	NNE	0.4	NNE	1012.1	0	0
10/17/2010	4:45 AM	26.1	26.1	26	85	23.4	0	NNE	0.9	NNE	1012.2	0	0
10/17/2010	5:00 AM	26.3	26.3	26.1	84	23.4	0.4	NNE	1.8	NNE	1012.2	0	0
10/17/2010	5:15 AM	26.3	26.3	26.2	84	23.4	0	NNE	0.4	NNE	1012.4	0	0
10/17/2010	5:30 AM	26.1	26.3	26.1	87	23.7	0	---	0	---	1012.5	0	0
10/17/2010	5:45 AM	25.8	26.1	25.7	89	23.8	0	---	0	---	1012.7	0	0
10/17/2010	6:00 AM	25.6	25.8	25.6	90	23.8	0	---	0	---	1012.9	0	0
10/17/2010	6:15 AM	25.7	25.7	25.5	92	24.3	0	---	0	---	1012.9	0	0
10/17/2010	6:30 AM	25.8	25.8	25.7	92	24.4	0	---	0	---	1013.2	0	0
10/17/2010	6:45 AM	25.8	25.8	25.8	92	24.4	0	NNE	0.9	NNE	1013.3	0	0
10/17/2010	7:00 AM	26.1	26.1	25.8	92	24.7	0	---	0	---	1013.6	0	0
10/17/2010	7:15 AM	26.6	26.6	26.1	91	25	0	---	0	---	1013.9	0	0
10/17/2010	7:30 AM	27.1	27.1	26.6	89	25.1	0	---	0	---	1014.1	0	0
10/17/2010	7:45 AM	27.7	27.7	27.1	86	25.1	0	NNE	0.9	NNE	1014.2	0	0
10/17/2010	8:00 AM	28.1	28.1	27.7	83	24.9	0	NNE	0.9	NNE	1014.2	0	0
10/17/2010	8:15 AM	28.5	28.5	28.1	82	25.1	0	NNE	0.9	NNE	1014.5	0	0
10/17/2010	8:30 AM	28.9	28.9	28.5	80	25.1	0.4	WNW	1.8	WNW	1014.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/17/2010	8:45 AM	29.5	29.5	28.9	76	24.8	0.4	NW	1.8	NW	1014.7	0	0
10/17/2010	9:00 AM	29.8	29.8	29.5	72	24.2	0	NW	0.9	NW	1014.8	0	0
10/17/2010	9:15 AM	30.3	30.3	29.8	72	24.7	0.4	NW	1.3	NW	1014.9	0	0
10/17/2010	9:30 AM	30.4	30.4	30.3	71	24.5	0.4	NW	0.9	NW	1014.9	0	0
10/17/2010	9:45 AM	30.2	30.4	30.2	73	24.8	0.4	WNW	1.8	WNW	1014.8	0	0
10/17/2010	10:00 AM	30	30.2	29.9	74	24.9	0.9	WNW	2.2	WNW	1014.6	0	0
10/17/2010	10:15 AM	30.3	30.3	30.1	73	24.9	0.9	WNW	2.7	WNW	1014.4	0	0
10/17/2010	10:30 AM	30.8	30.8	30.3	71	24.9	0.9	W	2.2	WNW	1014.3	0	0
10/17/2010	10:45 AM	30.9	30.9	30.8	70	24.8	0.9	WNW	2.2	NW	1014.1	0	0
10/17/2010	11:00 AM	31	31	30.9	72	25.4	0.9	WNW	2.2	WNW	1014	0	0
10/17/2010	11:15 AM	31	31	30.9	72	25.4	1.3	WNW	2.7	WNW	1013.9	0	0
10/17/2010	11:30 AM	31.2	31.2	31	71	25.3	1.3	WSW	2.7	WSW	1013.5	0	0
10/17/2010	11:45 AM	30.7	31.2	30.7	72	25.1	1.8	S	4.5	SSE	1013.2	0	0
10/17/2010	12:00 PM	30.3	30.8	30.3	72	24.7	2.7	S	4.5	S	1013	0	0
10/17/2010	12:15 PM	30.3	30.6	30.3	71	24.4	2.7	S	4.5	S	1012.8	0	0
10/17/2010	12:30 PM	30.7	30.7	30.3	69	24.3	2.2	S	4	S	1012.6	0	0
10/17/2010	12:45 PM	30.8	30.8	30.6	69	24.4	2.2	SE	4	SSE	1012.4	0	0
10/17/2010	1:00 PM	30.9	30.9	30.7	70	24.8	2.2	SE	4.9	S	1012.2	0	0
10/17/2010	1:15 PM	30.8	31.1	30.8	71	24.9	2.2	S	4.5	ESE	1011.9	0	0
10/17/2010	1:30 PM	30.6	30.8	30.6	74	25.4	2.7	SE	5.4	SSE	1011.6	0	0
10/17/2010	1:45 PM	30.7	30.8	30.5	74	25.6	2.2	SSE	4	S	1011.3	0	0
10/17/2010	2:00 PM	30.6	30.7	30.4	75	25.6	2.7	SSE	4.5	SE	1011.3	0	0
10/17/2010	2:15 PM	30.8	30.8	30.5	75	25.8	2.7	S	4.9	S	1011	0	0
10/17/2010	2:30 PM	30.4	30.8	30.4	76	25.7	3.1	SSE	5.4	S	1010.9	0	0
10/17/2010	2:45 PM	30.3	30.4	30.3	74	25.2	3.1	SSE	4.9	S	1010.8	0	0
10/17/2010	3:00 PM	30.2	30.3	30.2	76	25.5	3.1	SSE	4.9	SE	1010.6	0	0
10/17/2010	3:15 PM	29.9	30.2	29.9	76	25.3	3.1	SSE	5.4	SSE	1010.8	0	0
10/17/2010	3:30 PM	29.9	30	29.9	76	25.3	2.7	SSE	4.9	SSE	1010.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/17/2010	3:45 PM	29.9	30	29.9	76	25.3	1.8	SE	3.6	SSE	1011	0	0
10/17/2010	4:00 PM	29.3	29.9	29.3	79	25.3	0.9	ESE	3.1	NNE	1010.8	0	0
10/17/2010	4:15 PM	28.3	29.3	28.3	83	25.2	1.8	NNE	5.4	N	1011.1	0	0
10/17/2010	4:30 PM	28.1	28.3	27.9	83	24.9	1.3	NNE	4.5	NNE	1011	0	0
10/17/2010	4:45 PM	28.8	28.8	28.1	81	25.2	0.4	NW	1.8	NNW	1011	0	0
10/17/2010	5:00 PM	28.8	28.9	28.8	80	25	0.4	NNE	2.2	NNE	1011.1	0	0
10/17/2010	5:15 PM	28.8	28.8	28.8	82	25.4	0.4	NNE	2.2	NNE	1010.9	0	0
10/17/2010	5:30 PM	28.6	28.8	28.6	84	25.6	0.4	SSE	1.8	SE	1011.1	0	0
10/17/2010	5:45 PM	28.2	28.7	28.2	85	25.5	0	NNE	1.8	NNE	1011.2	0	0
10/17/2010	6:00 PM	28	28.2	27.9	86	25.4	0	NNW	1.8	NNW	1011.5	0	0
10/17/2010	6:15 PM	27.9	28.1	27.9	86	25.4	0	NW	1.8	NW	1011.9	0	0
10/17/2010	6:30 PM	27.8	27.9	27.8	87	25.5	0	NW	1.8	NW	1012	0	0
10/17/2010	6:45 PM	27.5	27.8	27.4	87	25.1	0.4	NNE	3.1	NNE	1012.1	0	0
10/17/2010	7:00 PM	27.4	27.5	27.3	85	24.7	0.9	NNE	3.1	N	1012.2	0	0
10/17/2010	7:15 PM	27.4	27.5	27.4	84	24.5	0.9	NNE	2.7	N	1012.5	0	0
10/17/2010	7:30 PM	27.4	27.4	27.4	85	24.6	0.4	N	2.2	NNE	1012.6	0	0
10/17/2010	7:45 PM	27.4	27.4	27.4	85	24.7	0	NNE	1.8	NNE	1012.8	0	0
10/17/2010	8:00 PM	27.4	27.4	27.4	85	24.7	0	NNE	1.3	NNE	1013.1	0	0
10/17/2010	8:15 PM	27.5	27.5	27.4	85	24.8	0	NNE	1.8	NNE	1013.2	0	0
10/17/2010	8:30 PM	27.4	27.5	27.4	84	24.5	0.4	NNE	2.2	NNE	1013.3	0	0
10/17/2010	8:45 PM	27.6	27.6	27.4	83	24.4	0.9	NNE	2.7	NNE	1013.3	0	0
10/17/2010	9:00 PM	27.4	27.6	27.4	83	24.2	1.3	NNE	2.7	NNE	1013.3	0	0
10/17/2010	9:15 PM	27.4	27.4	27.3	82	24	0.9	NNE	3.1	NNE	1013.3	0	0
10/17/2010	9:30 PM	27.3	27.4	27.3	83	24.2	0.4	NNE	2.7	NNE	1013.3	0	0
10/17/2010	9:45 PM	27.3	27.3	27.3	83	24.1	0	NNE	0.9	NNE	1013.3	0	0
10/17/2010	10:00 PM	27.2	27.3	27.2	83	24	0	NNE	1.3	NNE	1013.3	0	0
10/17/2010	10:15 PM	27.1	27.2	27.1	83	24	0	NNE	0.4	NNE	1013.2	0	0
10/17/2010	10:30 PM	27.1	27.1	27.1	84	24.2	0	NNE	0.4	NNE	1013.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/17/2010	10:45 PM	27.2	27.2	27.1	85	24.4	0	NNE	0.4	NNE	1013.3	0	0
10/17/2010	11:00 PM	27.1	27.2	27.1	86	24.5	0	---	0	---	1013.1	0	0
10/17/2010	11:15 PM	26.8	27.1	26.8	88	24.7	0	---	0	---	1013	0	0
10/17/2010	11:30 PM	26.6	26.8	26.6	88	24.4	0	---	0	---	1012.9	0	0
10/17/2010	11:45 PM	26.3	26.6	26.3	89	24.4	0	---	0	---	1012.7	0	0
10/18/2010	12:00 AM	26.4	26.4	26.3	89	24.4	0	---	0	---	1012.6	0	0
10/18/2010	12:15 AM	26.3	26.4	26.3	89	24.3	0	---	0	---	1012.4	0	0
10/18/2010	12:30 AM	26.2	26.3	26.2	89	24.3	0	NNE	0.4	NNE	1012.3	0	0
10/18/2010	12:45 AM	26.1	26.2	26.1	89	24.2	0	---	0	---	1012.1	0	0
10/18/2010	1:00 AM	26	26.1	26	90	24.2	0	---	0	---	1011.9	0	0
10/18/2010	1:15 AM	25.9	26	25.8	90	24.2	0	---	0	---	1011.6	0	0
10/18/2010	1:30 AM	25.9	25.9	25.9	92	24.5	0	---	0	---	1011.3	0	0
10/18/2010	1:45 AM	25.8	25.9	25.8	92	24.4	0	---	0	---	1011.1	0	0
10/18/2010	2:00 AM	25.7	25.8	25.7	93	24.5	0	---	0	---	1010.9	0	0
10/18/2010	2:15 AM	25.8	25.8	25.7	93	24.6	0	---	0	---	1011	0	0
10/18/2010	2:30 AM	25.8	25.8	25.8	94	24.8	0	---	0	---	1011	0	0
10/18/2010	2:45 AM	25.8	25.8	25.8	94	24.7	0	---	0	---	1011	0	0
10/18/2010	3:00 AM	25.7	25.8	25.6	94	24.6	0	---	0	---	1011	0	0
10/18/2010	3:15 AM	25.8	25.8	25.7	94	24.7	0	---	0	---	1011.3	0	0
10/18/2010	3:30 AM	25.9	25.9	25.8	93	24.7	0	NNE	0.9	NNE	1011.2	0	0
10/18/2010	3:45 AM	25.9	26.1	25.9	92	24.5	0	NNE	0.9	NNE	1011.2	0	0
10/18/2010	4:00 AM	25.9	25.9	25.8	92	24.5	0	NNE	0.9	NNE	1011.3	0	0
10/18/2010	4:15 AM	25.9	25.9	25.8	90	24.1	0	NNE	0.9	NNE	1011.7	0	0
10/18/2010	4:30 AM	25.9	26	25.9	90	24.2	0	NNE	0.4	NNE	1011.7	0	0
10/18/2010	4:45 AM	25.8	25.9	25.8	89	23.9	0	NNE	0.4	NNE	1011.8	0	0
10/18/2010	5:00 AM	25.7	25.8	25.7	89	23.7	0	---	0	---	1012.1	0	0
10/18/2010	5:15 AM	25.6	25.7	25.6	89	23.7	0	---	0	---	1012.1	0	0
10/18/2010	5:30 AM	25.5	25.6	25.5	88	23.4	0	NNE	0.4	NNE	1012.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/18/2010	5:45 AM	25.7	25.7	25.5	88	23.6	0.4	NNE	1.8	NNE	1012.4	0	0
10/18/2010	6:00 AM	25.7	25.8	25.7	89	23.7	0	---	0	---	1012.7	0	0
10/18/2010	6:15 AM	25.6	25.7	25.6	89	23.6	0	---	0	---	1012.7	0	0
10/18/2010	6:30 AM	25.6	25.6	25.6	90	23.8	0	---	0	---	1012.6	0	0
10/18/2010	6:45 AM	25.9	25.9	25.6	92	24.5	0	---	0	---	1013.1	0	0
10/18/2010	7:00 AM	26.6	26.6	25.9	89	24.6	0	NNE	0.4	NNE	1013.4	0	0
10/18/2010	7:15 AM	27.3	27.3	26.6	85	24.5	0	NNE	0.9	NNE	1013.4	0	0
10/18/2010	7:30 AM	28	28	27.3	80	24.2	0	---	0	---	1013.7	0	0
10/18/2010	7:45 AM	28.6	28.6	28.1	78	24.3	0	NNE	0.4	NNE	1013.7	0	0
10/18/2010	8:00 AM	28.9	28.9	28.6	76	24.3	0	NNE	0.9	NNE	1013.9	0	0
10/18/2010	8:15 AM	29.3	29.3	28.9	76	24.7	0	NNE	0.9	NNE	1014	0	0
10/18/2010	8:30 AM	30	30	29.3	73	24.6	0	NNE	0.9	NNE	1014.3	0	0
10/18/2010	8:45 AM	29.8	30.2	29.8	71	24	0.9	SE	2.2	SE	1014.3	0	0
10/18/2010	9:00 AM	29.5	29.8	29.4	74	24.4	0.9	S	3.1	S	1014.4	0	0
10/18/2010	9:15 AM	29.6	29.7	29.5	71	23.7	1.3	SSE	2.7	SE	1014.4	0	0
10/18/2010	9:30 AM	29.8	29.8	29.6	70	23.7	1.3	SE	3.1	SE	1014.5	0	0
10/18/2010	9:45 AM	29.6	29.7	29.6	71	23.7	1.3	SSE	2.7	S	1014.6	0	0
10/18/2010	10:00 AM	29.8	29.8	29.6	72	24.2	1.8	SSE	4	S	1014.4	0	0
10/18/2010	10:15 AM	29.8	29.8	29.6	75	24.9	2.7	SSE	4.5	SE	1014.3	0	0
10/18/2010	10:30 AM	30.1	30.1	29.8	75	25.1	2.7	S	4.9	S	1014.3	0	0
10/18/2010	10:45 AM	30.3	30.3	30.1	74	25.1	3.6	S	5.8	SSE	1014	0	0
10/18/2010	11:00 AM	30.3	30.4	30.2	73	24.9	3.6	S	5.8	SSE	1013.7	0	0
10/18/2010	11:15 AM	30.5	30.5	30.3	73	25.1	3.6	S	5.4	S	1013.8	0	0
10/18/2010	11:30 AM	30.7	30.7	30.5	73	25.3	3.1	S	5.8	S	1013.5	0	0
10/18/2010	11:45 AM	30.7	30.7	30.3	73	25.3	3.6	S	5.4	SSE	1013.1	0	0
10/18/2010	12:00 PM	30.6	30.8	30.6	73	25.2	3.1	S	5.4	SSE	1013	0	0
10/18/2010	12:15 PM	30.7	30.8	30.5	73	25.3	3.6	S	5.4	SSE	1013	0	0
10/18/2010	12:30 PM	30.2	30.7	30.2	75	25.2	3.6	S	5.4	SSE	1012.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/18/2010	12:45 PM	30.1	30.2	30.1	77	25.6	3.1	SSE	5.4	SSE	1012.4	0	0
10/18/2010	1:00 PM	30.1	30.1	29.8	78	25.8	3.1	SSE	4.9	SSE	1012.3	0	0
10/18/2010	1:15 PM	29.9	30.1	29.8	77	25.4	3.1	SSE	4.9	S	1012.1	0	0
10/18/2010	1:30 PM	30.1	30.1	29.9	77	25.6	2.7	SE	4	SE	1011.8	0	0
10/18/2010	1:45 PM	29.9	30.1	29.9	78	25.7	2.7	SE	4	SE	1011.5	0	0
10/18/2010	2:00 PM	30.1	30.1	30	78	25.8	2.7	SSE	4.9	SE	1011	0	0
10/18/2010	2:15 PM	30.1	30.2	30.1	77	25.6	3.1	SSE	5.4	SSE	1010.7	0	0
10/18/2010	2:30 PM	30.3	30.3	30.1	77	25.8	3.1	SSE	4.9	SSE	1010.5	0	0
10/18/2010	2:45 PM	29.8	30.3	29.8	77	25.4	3.1	SSE	4.9	S	1010.4	0	0
10/18/2010	3:00 PM	29.6	29.9	29.6	78	25.3	3.1	SSE	4.9	SSE	1010.2	0	0
10/18/2010	3:15 PM	29.4	29.6	29.4	82	26	3.1	SSE	4.5	S	1010.3	0	0
10/18/2010	3:30 PM	29.3	29.4	29.3	81	25.7	3.1	SSE	4.9	S	1010.6	0	0
10/18/2010	3:45 PM	29.2	29.3	29.2	81	25.6	3.1	SSE	5.4	SSE	1010.5	0	0
10/18/2010	4:00 PM	29.3	29.4	29.2	82	25.9	3.1	SSE	4.5	SSE	1010.5	0	0
10/18/2010	4:15 PM	29.1	29.3	29.1	82	25.7	3.1	S	4.9	S	1010.6	0	0
10/18/2010	4:30 PM	28.9	29.2	28.9	82	25.6	2.7	SSE	4.5	S	1010.5	0	0
10/18/2010	4:45 PM	29	29.1	28.8	81	25.4	2.7	SSE	4	SSE	1010.5	0	0
10/18/2010	5:00 PM	28.8	29.1	28.8	82	25.5	2.7	SSE	3.6	SSE	1010.5	0	0
10/18/2010	5:15 PM	28.6	28.8	28.6	83	25.4	2.2	SE	3.6	ESE	1010.4	0	0
10/18/2010	5:30 PM	28.6	28.7	28.6	84	25.6	2.7	SSE	4	SE	1010.4	0	0
10/18/2010	5:45 PM	28.4	28.6	28.4	84	25.5	2.2	SSE	4	SSE	1010.6	0	0
10/18/2010	6:00 PM	28.3	28.4	28.3	84	25.4	1.8	S	3.1	SSE	1010.9	0	0
10/18/2010	6:15 PM	28.3	28.4	28.3	85	25.5	0.9	S	2.7	S	1011.1	0	0
10/18/2010	6:30 PM	28.3	28.3	28.3	85	25.6	1.3	SSE	2.7	S	1011.2	0	0
10/18/2010	6:45 PM	28.4	28.4	28.3	80	24.6	2.2	SE	4.5	ESE	1011.3	0	0
10/18/2010	7:00 PM	28.4	28.4	28.4	81	24.8	1.8	ESE	3.6	SE	1011.4	0	0
10/18/2010	7:15 PM	28.3	28.4	28.3	81	24.7	0.4	ESE	2.2	ESE	1011.8	0	0
10/18/2010	7:30 PM	28.2	28.3	28.2	82	24.8	0	ESE	0.4	ESE	1011.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/18/2010	7:45 PM	27.9	28.2	27.9	80	24.1	0	ESE	0.4	ESE	1012.3	0	0
10/18/2010	8:00 PM	27.8	27.9	27.8	81	24.3	0	ESE	0.9	ESE	1012.4	0	0
10/18/2010	8:15 PM	27.9	27.9	27.8	81	24.4	0.4	SSE	2.2	SE	1012.4	0	0
10/18/2010	8:30 PM	27.9	27.9	27.9	81	24.4	0.4	SE	2.2	SSE	1012.6	0	0
10/18/2010	8:45 PM	27.7	27.9	27.7	81	24.2	0	SE	1.3	SE	1012.9	0	0
10/18/2010	9:00 PM	27.6	27.7	27.6	83	24.5	0	SE	0.9	SE	1013	0	0
10/18/2010	9:15 PM	27.5	27.7	27.5	83	24.4	0	SE	0.9	SE	1013	0	0
10/18/2010	9:30 PM	27.3	27.5	27.3	84	24.4	0	SE	0.4	SE	1013.2	0	0
10/18/2010	9:45 PM	27	27.3	27	83	23.9	0	SE	0.9	SE	1013	0	0
10/18/2010	10:00 PM	27.2	27.2	27	82	23.8	0.4	SE	0.9	SE	1013.1	0	0
10/18/2010	10:15 PM	27.1	27.2	27.1	82	23.7	0	SE	0.9	SE	1013.1	0	0
10/18/2010	10:30 PM	26.9	27.2	26.9	81	23.4	0	SE	0.9	SE	1013.1	0	0
10/18/2010	10:45 PM	27	27	26.9	80	23.3	0.9	SE	1.8	SE	1012.9	0	0
10/18/2010	11:00 PM	27.1	27.1	27	80	23.3	0.4	ESE	1.8	SE	1012.7	0	0
10/18/2010	11:15 PM	27.2	27.2	27.1	81	23.7	0.4	ESE	1.8	ESE	1012.6	0	0
10/18/2010	11:30 PM	27.1	27.2	27	80	23.3	0.4	ESE	1.8	ESE	1012.4	0	0
10/18/2010	11:45 PM	26.9	27.1	26.9	82	23.6	0	ESE	0.9	ESE	1012.4	0	0
10/19/2010	12:00 AM	27	27	26.9	84	24.1	0	ESE	0.9	ESE	1012.5	0	0
10/19/2010	12:15 AM	26.8	27	26.8	83	23.7	0.4	ESE	0.9	ESE	1012.3	0	0
10/19/2010	12:30 AM	26.8	26.9	26.8	84	23.8	0	ESE	1.8	ESE	1012.2	0	0
10/19/2010	12:45 AM	26.6	26.8	26.6	84	23.6	0	---	0	---	1012.2	0	0
10/19/2010	1:00 AM	26.6	26.6	26.5	85	23.8	0	---	0	---	1012.3	0	0
10/19/2010	1:15 AM	26.4	26.6	26.4	85	23.7	0	ESE	0.4	ESE	1012.2	0	0
10/19/2010	1:30 AM	26.4	26.5	26.4	83	23.3	0	NW	1.8	NW	1012.1	0	0
10/19/2010	1:45 AM	26.5	26.5	26.4	84	23.6	0.4	NNW	2.7	NNW	1012	0	0
10/19/2010	2:00 AM	26.2	26.6	26.2	87	23.8	0.9	SW	3.1	W	1012	0.25	0
10/19/2010	2:15 AM	25.9	26.2	25.8	90	24.1	0.4	WSW	1.8	NW	1011.7	0.25	1
10/19/2010	2:30 AM	25.8	25.9	25.8	91	24.2	0.4	NW	1.8	NNW	1011.4	0	1

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/19/2010	2:45 AM	25.6	25.8	25.6	91	24	0.4	NNE	2.7	NNE	1011.3	0	0
10/19/2010	3:00 AM	25.5	25.6	25.5	89	23.6	0.4	NNE	2.2	NNE	1011	0	0
10/19/2010	3:15 AM	25.6	25.6	25.5	89	23.6	0	NNE	0.4	NNE	1010.9	0	0
10/19/2010	3:30 AM	25.7	25.7	25.6	89	23.7	0	NNE	0.4	NNE	1011	0	0
10/19/2010	3:45 AM	25.6	25.8	25.6	91	24	0	---	0	---	1011	0	0
10/19/2010	4:00 AM	25.3	25.6	25.3	92	23.9	0	---	0	---	1011.1	0	0
10/19/2010	4:15 AM	25.3	25.3	25.3	93	24.1	0	NNE	2.7	SSE	1011	0	0
10/19/2010	4:30 AM	25.5	25.5	25.3	92	24.1	0	SSE	0.4	SSE	1011.1	0	0
10/19/2010	4:45 AM	25.5	25.6	25.5	92	24.1	0	---	0	---	1011	0	0
10/19/2010	5:00 AM	25.3	25.6	25.3	92	23.9	0	---	0	---	1011.2	0	0
10/19/2010	5:15 AM	25.6	25.6	25.3	93	24.3	0	SSE	0.4	SSE	1011.3	0	0
10/19/2010	5:30 AM	25.4	25.5	25.4	92	24	0	SSE	0.9	SSE	1011.4	0	0
10/19/2010	5:45 AM	25.5	25.5	25.4	91	23.9	0	SSE	0.9	SSE	1011.3	0	0
10/19/2010	6:00 AM	25.7	25.7	25.5	90	23.9	0.4	NNE	2.2	NNE	1011.4	0	0
10/19/2010	6:15 AM	25.7	25.7	25.6	91	24.1	0	---	0	---	1011.7	0	0
10/19/2010	6:30 AM	25.8	25.8	25.6	92	24.4	0	---	0	---	1012	0	0
10/19/2010	6:45 AM	26.3	26.3	25.8	91	24.7	0	NNE	0.4	NNE	1012.4	0	0
10/19/2010	7:00 AM	27.1	27.1	26.3	88	24.9	0	NNE	0.9	NNE	1012.5	0	0
10/19/2010	7:15 AM	27.9	27.9	27.1	85	25.2	0	NNE	0.4	NNE	1012.5	0	0
10/19/2010	7:30 AM	28.3	28.3	27.9	82	24.9	0	NNE	0.4	NNE	1012.9	0	0
10/19/2010	7:45 AM	28.4	28.6	28.2	80	24.7	0	NNE	0.9	NNE	1013	0	0
10/19/2010	8:00 AM	28.7	28.8	28.4	79	24.7	0	NNE	0.9	NNE	1013.1	0	0
10/19/2010	8:15 AM	29.4	29.4	28.7	76	24.7	0	NNE	1.8	ENE	1013.1	0	0
10/19/2010	8:30 AM	29.3	29.5	29.2	77	24.9	1.3	SSE	3.1	SSE	1013.3	0	0
10/19/2010	8:45 AM	29.5	29.6	29.3	76	24.8	2.2	SSE	4.9	SSE	1013.6	0	0
10/19/2010	9:00 AM	29.3	29.7	29.3	76	24.7	2.7	SSE	5.4	S	1013.7	0	0
10/19/2010	9:15 AM	30	30	29.3	76	25.3	2.7	SSE	4.5	SSE	1013.6	0	0
10/19/2010	9:30 AM	29.7	30.1	29.7	76	25	3.1	SE	4.9	SSE	1013.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/19/2010	9:45 AM	28.9	29.7	28.9	81	25.4	3.1	SE	5.8	SSE	1013.9	0	0
10/19/2010	10:00 AM	28.5	28.9	28.4	80	24.7	3.6	SSE	5.8	SSE	1013.9	0	0
10/19/2010	10:15 AM	28.6	28.6	28.5	83	25.4	2.7	SSE	4.9	SSE	1013.7	0	0
10/19/2010	10:30 AM	28.7	28.7	28.6	83	25.5	3.1	SSE	4.9	SSE	1013.4	0	0
10/19/2010	10:45 AM	28.9	28.9	28.7	82	25.5	3.6	SSE	5.8	SE	1013.3	0	0
10/19/2010	11:00 AM	29.2	29.2	28.8	77	24.8	4	ESE	5.8	SE	1013.2	0	0
10/19/2010	11:15 AM	29.6	29.7	29.2	75	24.7	3.6	SE	5.4	SE	1013	0	0
10/19/2010	11:30 AM	29.8	29.8	29.6	74	24.6	3.6	SE	5.8	SE	1012.8	0	0
10/19/2010	11:45 AM	29.7	29.8	29.7	78	25.4	3.6	SE	5.8	ESE	1012.6	0	0
10/19/2010	12:00 PM	29.9	29.9	29.7	76	25.3	3.1	SE	5.4	SE	1012.3	0	0
10/19/2010	12:15 PM	30.4	30.5	29.9	77	26	3.1	SE	6.3	SSE	1012.1	0	0
10/19/2010	12:30 PM	29.8	30.4	29.8	77	25.3	4	SE	6.3	SSE	1011.9	0	0
10/19/2010	12:45 PM	29.1	29.8	29.1	77	24.7	4	SE	6.3	SE	1011.4	0	0
10/19/2010	1:00 PM	28.8	29.1	28.8	79	24.8	3.1	SE	5.4	SSE	1011.5	0	0
10/19/2010	1:15 PM	28.8	28.9	28.7	82	25.5	3.1	SE	4.9	SE	1011.3	0	0
10/19/2010	1:30 PM	28.9	28.9	28.8	79	24.9	3.1	SE	4.9	SSE	1011.3	0	0
10/19/2010	1:45 PM	29	29.1	28.8	81	25.4	3.1	SE	5.4	S	1011.1	0	0
10/19/2010	2:00 PM	29.3	29.3	29	80	25.5	3.1	SSE	5.4	SE	1011.2	0	0
10/19/2010	2:15 PM	29.1	29.5	29.1	82	25.7	2.7	SSE	4.9	SSE	1011.1	0	0
10/19/2010	2:30 PM	28.8	29.1	28.8	83	25.6	3.1	SSE	4.5	S	1011	0	0
10/19/2010	2:45 PM	27.3	28.8	27.3	87	25	4	S	7.2	S	1011	0	0
10/19/2010	3:00 PM	26.9	27.3	26.8	85	24.2	2.7	SSE	4.9	S	1011.1	0	0
10/19/2010	3:15 PM	27.3	27.3	26.9	82	23.9	0.9	ESE	4	SSE	1011.2	0	0
10/19/2010	3:30 PM	27.7	27.7	27.3	76	23.1	0.4	SSE	2.2	SSE	1011.1	0	0
10/19/2010	3:45 PM	27.7	27.8	27.7	77	23.3	0	SSE	0.9	SSE	1010.8	0	0
10/19/2010	4:00 PM	27.2	27.7	27.2	82	23.8	0.9	SSE	4.9	S	1010.9	0	0
10/19/2010	4:15 PM	26.6	27.2	26.6	87	24.3	1.3	SSW	4	SSW	1011.1	0	0
10/19/2010	4:30 PM	26.1	26.6	26.1	90	24.3	0.4	SW	2.2	WSW	1011.3	0.25	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/19/2010	4:45 PM	26	26.1	26	91	24.4	0.4	SW	2.2	SW	1011.4	0	0
10/19/2010	5:00 PM	25.9	26.1	25.9	92	24.5	0	---	0	---	1011.7	0	0
10/19/2010	5:15 PM	25.9	25.9	25.9	92	24.5	0	SW	0.9	SW	1011.8	0.25	0
10/19/2010	5:30 PM	25.7	25.9	25.7	92	24.3	0.4	WNW	1.8	WNW	1011.8	0	0
10/19/2010	5:45 PM	25.8	25.8	25.7	93	24.6	0.9	WNW	2.2	WNW	1012.2	0.25	0
10/19/2010	6:00 PM	25.7	25.8	25.7	93	24.4	0.9	WNW	2.2	WNW	1012.3	0	0
10/19/2010	6:15 PM	25.4	25.7	25.4	94	24.4	0.9	NNW	2.7	N	1012.3	0	0
10/19/2010	6:30 PM	25.3	25.4	25.3	94	24.2	0.4	NNW	2.2	NNW	1012.5	0	0
10/19/2010	6:45 PM	25.2	25.3	25.2	94	24.2	0.4	NNW	3.1	WNW	1012.3	0.25	0
10/19/2010	7:00 PM	25.2	25.3	25.2	94	24.1	1.3	WNW	2.7	WNW	1012.4	0.25	1.3
10/19/2010	7:15 PM	25	25.2	24.9	94	24	0.9	WNW	2.7	W	1012.5	0.25	1.5
10/19/2010	7:30 PM	24.8	25	24.8	95	23.9	1.3	WNW	3.1	WNW	1012.5	0.25	1.5
10/19/2010	7:45 PM	24.9	24.9	24.8	95	24	1.3	WNW	3.1	WNW	1012.6	0	0
10/19/2010	8:00 PM	25	25	24.9	95	24.1	1.3	WNW	3.1	W	1012.7	0	0
10/19/2010	8:15 PM	24.8	25.1	24.8	94	23.8	0.9	NW	2.7	WNW	1012.9	0	0
10/19/2010	8:30 PM	24.8	24.9	24.8	94	23.7	0.9	NW	3.1	NW	1012.9	0	0
10/19/2010	8:45 PM	24.8	24.8	24.8	94	23.7	0.4	NNW	2.2	NNW	1013	0	0
10/19/2010	9:00 PM	24.9	24.9	24.8	94	23.9	0.4	NW	2.2	NNW	1013.1	0	0
10/19/2010	9:15 PM	24.9	24.9	24.8	93	23.7	0.9	WNW	2.7	WNW	1013.3	0	0
10/19/2010	9:30 PM	25.1	25.1	24.9	92	23.7	0.9	NNW	2.2	NNW	1013.3	0	0
10/19/2010	9:45 PM	25.1	25.2	25.1	92	23.7	0.4	NW	2.2	NNW	1013.2	0	0
10/19/2010	10:00 PM	25.1	25.2	25.1	92	23.7	0.4	NW	2.2	NW	1013.1	0	0
10/19/2010	10:15 PM	25.2	25.2	25.1	92	23.8	0.4	WNW	2.2	WNW	1013.1	0	0
10/19/2010	10:30 PM	25.3	25.3	25.2	92	23.9	0	WNW	1.8	NW	1013.1	0	0
10/19/2010	10:45 PM	25.5	25.5	25.3	92	24.1	0.4	WNW	1.8	WNW	1012.9	0	0
10/19/2010	11:00 PM	25.7	25.7	25.5	92	24.3	0.4	WNW	1.8	NW	1012.9	0	0
10/19/2010	11:15 PM	25.1	25.7	25.1	93	23.8	0.9	WSW	2.2	W	1012.8	3.81	32.8
10/19/2010	11:30 PM	24.8	25.1	24.8	94	23.7	0	NW	2.7	NNW	1012.5	0	1

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/19/2010	11:45 PM	25.1	25.1	24.8	94	24	0.9	NNE	3.6	NE	1012.4	0	0
10/20/2010	12:00 AM	24.9	25.1	24.9	94	23.9	0.4	NNE	2.7	NE	1012.4	0	0
10/20/2010	12:15 AM	24.9	24.9	24.9	94	23.9	0.4	WNW	1.8	NW	1012.3	0	0
10/20/2010	12:30 AM	24.9	25	24.9	94	23.9	0	WNW	0.9	NW	1012.1	0	0
10/20/2010	12:45 AM	24.8	24.9	24.8	93	23.6	0	N	1.8	N	1011.8	0	0
10/20/2010	1:00 AM	25	25	24.8	93	23.8	0	N	0.9	N	1011.5	0	0
10/20/2010	1:15 AM	25.2	25.3	25	93	24	0	N	0.9	N	1011.5	0	0
10/20/2010	1:30 AM	25.2	25.2	25.1	94	24.2	0	N	0.4	N	1011.4	0	0
10/20/2010	1:45 AM	25.4	25.5	25.2	95	24.6	0	N	0.9	N	1011.2	0	0
10/20/2010	2:00 AM	25.5	25.5	25.4	93	24.3	0	SE	1.8	SE	1011.3	0	0
10/20/2010	2:15 AM	25.7	25.7	25.6	92	24.3	0	SE	0.9	SE	1011.2	0	0
10/20/2010	2:30 AM	25.8	25.8	25.7	92	24.4	0.4	SE	1.8	SE	1011.2	0	0
10/20/2010	2:45 AM	26.1	26.1	25.8	90	24.3	0.9	SE	3.1	SE	1011	0	0
10/20/2010	3:00 AM	25.9	26.2	25.8	93	24.7	3.1	SSE	5.4	SSE	1010.9	1.02	8.1
10/20/2010	3:15 AM	25.9	25.9	25.9	93	24.7	3.6	SSE	8	SE	1010.7	0	0
10/20/2010	3:30 AM	25.8	25.9	25.8	91	24.3	3.6	SSE	5.8	SE	1010.8	0	0
10/20/2010	3:45 AM	25.9	25.9	25.8	92	24.5	4	SE	6.3	SE	1010.8	0	0
10/20/2010	4:00 AM	26.1	26.1	25.9	90	24.3	4	SE	6.7	SE	1010.9	0	0
10/20/2010	4:15 AM	26	26.1	26	91	24.4	4.5	SE	7.2	SE	1010.8	0	0
10/20/2010	4:30 AM	25.9	26.1	25.9	91	24.4	3.6	SE	5.8	SSE	1010.9	0	0
10/20/2010	4:45 AM	26	26.1	25.9	91	24.4	2.2	ESE	4.9	SE	1011.2	0	0
10/20/2010	5:00 AM	25.6	26	25.6	90	23.8	1.8	E	4	NNE	1011.2	0	0
10/20/2010	5:15 AM	25.5	25.6	25.4	90	23.7	0.9	NNE	3.6	NNE	1011.2	0	0
10/20/2010	5:30 AM	25.5	25.6	25.5	91	23.9	0	NNE	0.9	NNE	1011.2	0	0
10/20/2010	5:45 AM	25.2	25.5	25.2	93	24	0	---	0	---	1011.3	0	0
10/20/2010	6:00 AM	25.1	25.2	25.1	93	23.9	0	NNE	0.4	NNE	1011.4	0.25	0
10/20/2010	6:15 AM	25.2	25.2	25.1	94	24.1	0	NNE	0.9	NNE	1011.6	0	0
10/20/2010	6:30 AM	25.2	25.3	25.2	94	24.1	0.4	NW	1.8	WNW	1011.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/20/2010	6:45 AM	25.2	25.2	25.2	94	24.1	0	NNW	0.9	NW	1011.9	0	0
10/20/2010	7:00 AM	25.4	25.4	25.2	94	24.4	0	NNW	1.3	NNW	1012	0	0
10/20/2010	7:15 AM	25.7	25.7	25.4	94	24.6	0	NNW	0.4	NNW	1012.3	0	0
10/20/2010	7:30 AM	25.8	25.8	25.7	94	24.7	0	NNW	0.4	NNW	1012.6	0	0
10/20/2010	7:45 AM	26.4	26.4	25.8	87	24.1	0.9	SE	4	SE	1012.5	0	0
10/20/2010	8:00 AM	27.3	27.3	26.5	82	23.9	2.2	SE	4.5	SE	1012.5	0	0
10/20/2010	8:15 AM	27.8	27.8	27.3	82	24.4	1.8	SE	3.1	SE	1012.6	0	0
10/20/2010	8:30 AM	28	28	27.8	79	24	1.8	SE	3.1	SE	1012.8	0	0
10/20/2010	8:45 AM	28.3	28.3	28	80	24.5	2.2	SE	3.1	SSE	1012.9	0	0
10/20/2010	9:00 AM	28.6	28.6	28.3	80	24.8	2.7	SE	4.5	SE	1013	0	0
10/20/2010	9:15 AM	28.7	28.7	28.6	78	24.4	3.1	SE	5.8	SSE	1013.1	0	0
10/20/2010	9:30 AM	29.3	29.3	28.7	76	24.6	3.1	SE	5.4	ESE	1013	0	0
10/20/2010	9:45 AM	29.3	29.3	29.1	78	25.1	3.6	SE	5.8	ESE	1013.1	0	0
10/20/2010	10:00 AM	29.6	29.6	29.3	75	24.7	4	SE	7.2	SE	1013	0	0
10/20/2010	10:15 AM	29.8	29.8	29.6	76	25.1	4	SE	6.3	SSE	1013.1	0	0
10/20/2010	10:30 AM	29.5	29.8	29.5	76	24.8	4	SE	6.3	SE	1013	0	0
10/20/2010	10:45 AM	29.4	29.6	29.4	71	23.6	4	SSE	6.3	SSE	1012.8	0	0
10/20/2010	11:00 AM	29.4	29.4	29.3	68	22.9	4	SE	6.7	SE	1012.8	0	0
10/20/2010	11:15 AM	29.3	29.4	29.3	69	23	3.6	SE	6.7	SE	1012.5	0	0
10/20/2010	11:30 AM	29.3	29.3	29.2	71	23.5	3.6	SE	5.8	SE	1012.5	0	0
10/20/2010	11:45 AM	29.9	29.9	29.3	69	23.6	3.6	SE	5.8	SE	1012.3	0	0
10/20/2010	12:00 PM	29.8	29.8	29.7	70	23.8	4	SE	6.7	SSE	1012	0	0
10/20/2010	12:15 PM	29.5	29.8	29.4	73	24.1	3.6	SSE	5.8	SSE	1012	0	0
10/20/2010	12:30 PM	29.1	29.5	29.1	75	24.2	3.6	SSE	5.8	SE	1011.8	0	0
10/20/2010	12:45 PM	29.1	29.1	28.9	76	24.4	3.1	SE	4.9	SE	1011.5	0	0
10/20/2010	1:00 PM	28.9	29.1	28.9	75	24.1	3.1	SSE	4.9	ESE	1011.1	0	0
10/20/2010	1:15 PM	29.1	29.1	28.9	77	24.6	2.7	SSE	4.9	SE	1010.8	0	0
10/20/2010	1:30 PM	29.1	29.1	29.1	77	24.6	2.7	SSE	4.5	S	1010.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/20/2010	1:45 PM	28.9	29.1	28.9	77	24.5	2.7	SSE	4.5	SE	1010.4	0	0
10/20/2010	2:00 PM	28.8	28.9	28.8	78	24.6	2.2	SSE	4	S	1010.3	0	0
10/20/2010	2:15 PM	28.7	28.8	28.7	79	24.7	3.1	SSE	4.9	S	1010.1	0	0
10/20/2010	2:30 PM	28.7	28.8	28.7	79	24.7	2.7	SSE	4.5	SSE	1010	0	0
10/20/2010	2:45 PM	28.7	28.8	28.7	80	24.9	2.7	SSE	4.5	SSE	1010	0	0
10/20/2010	3:00 PM	28.7	28.7	28.6	80	24.9	3.1	SSE	5.4	SSE	1010	0	0
10/20/2010	3:15 PM	28.7	28.7	28.6	78	24.4	3.1	SSE	5.8	SSE	1009.9	0	0
10/20/2010	3:30 PM	28.7	28.7	28.6	78	24.4	3.1	SSE	4.5	SE	1009.7	0	0
10/20/2010	3:45 PM	28.7	28.7	28.6	80	24.9	2.7	SSE	4.5	SE	1009.7	0	0
10/20/2010	4:00 PM	28.7	28.7	28.6	77	24.3	2.7	SSE	4.9	SSE	1009.8	0	0
10/20/2010	4:15 PM	28.7	28.7	28.6	77	24.2	3.1	SSE	5.4	SSE	1009.7	0	0
10/20/2010	4:30 PM	28.6	28.7	28.6	78	24.3	3.1	SSE	5.8	S	1009.8	0	0
10/20/2010	4:45 PM	28.6	28.6	28.5	77	24.1	3.1	SSE	5.8	SSE	1010	0	0
10/20/2010	5:00 PM	28.4	28.6	28.4	78	24.2	2.7	SSE	4.5	SSE	1010.1	0	0
10/20/2010	5:15 PM	28.4	28.4	28.4	79	24.4	2.7	SSE	4.9	S	1010.3	0	0
10/20/2010	5:30 PM	28.3	28.4	28.3	79	24.3	2.7	SSE	4.9	SSE	1010.5	0	0
10/20/2010	5:45 PM	28.2	28.3	28.2	79	24.2	2.2	SSE	4	SSE	1010.4	0	0
10/20/2010	6:00 PM	28.2	28.2	28.2	80	24.4	2.2	SE	3.6	SE	1010.3	0	0
10/20/2010	6:15 PM	28.2	28.2	28.2	80	24.4	2.2	ESE	3.6	SE	1010.5	0	0
10/20/2010	6:30 PM	27.9	28.2	27.9	79	23.9	1.8	ESE	3.1	ESE	1010.6	0	0
10/20/2010	6:45 PM	27.7	27.9	27.7	78	23.5	1.3	ESE	3.1	ESE	1010.6	0	0
10/20/2010	7:00 PM	27.7	27.7	27.6	79	23.7	1.3	ESE	3.1	ESE	1010.7	0	0
10/20/2010	7:15 PM	27.7	27.7	27.6	77	23.3	0.4	ESE	2.2	ESE	1010.8	0	0
10/20/2010	7:30 PM	27.6	27.7	27.5	78	23.4	0.4	ESE	1.8	ESE	1011	0	0
10/20/2010	7:45 PM	27.5	27.6	27.5	79	23.5	0.9	ESE	2.7	ESE	1011.3	0	0
10/20/2010	8:00 PM	27.7	27.7	27.5	80	24	0.4	SSE	2.7	SSE	1011.6	0	0
10/20/2010	8:15 PM	27.8	27.8	27.7	79	23.8	1.8	SSE	3.6	SSE	1011.9	0	0
10/20/2010	8:30 PM	27.5	27.8	27.5	78	23.3	1.3	SE	2.7	SE	1012	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/20/2010	8:45 PM	27.3	27.5	27.3	77	22.9	0.9	SE	2.7	SE	1012.2	0	0
10/20/2010	9:00 PM	27.3	27.4	27.3	82	24	2.7	SE	6.3	SE	1012.2	0	0
10/20/2010	9:15 PM	27.1	27.3	27.1	80	23.4	3.6	SE	5.8	SE	1012.2	0	0
10/20/2010	9:30 PM	27.1	27.2	27.1	83	24	1.8	SE	3.6	SE	1012.2	0	0
10/20/2010	9:45 PM	26.9	27.1	26.9	85	24.2	1.8	ESE	3.1	ESE	1012.3	0	0
10/20/2010	10:00 PM	26.8	26.9	26.8	86	24.3	0.4	ESE	0.9	ESE	1012.4	0	0
10/20/2010	10:15 PM	26.8	26.8	26.8	84	23.8	0	ESE	1.3	ESE	1012.5	0	0
10/20/2010	10:30 PM	26.8	26.8	26.7	84	23.8	0	ESE	0.4	ESE	1012.6	0	0
10/20/2010	10:45 PM	26.8	26.8	26.8	82	23.5	0.4	ESE	2.2	ESE	1012.5	0	0
10/20/2010	11:00 PM	26.9	26.9	26.8	82	23.6	0.4	ESE	2.2	ESE	1012.3	0	0
10/20/2010	11:15 PM	26.8	26.9	26.8	83	23.7	0	ESE	0.9	ESE	1012.1	0	0
10/20/2010	11:30 PM	26.5	26.8	26.5	83	23.4	0.4	N	2.7	NNE	1011.8	0	0
10/20/2010	11:45 PM	26.6	26.6	26.4	81	23.1	0	NE	0.9	N	1011.6	0	0
10/21/2010	12:00 AM	26.7	26.8	26.6	81	23.2	0	NE	1.8	NE	1011.6	0	0
10/21/2010	12:15 AM	26.9	26.9	26.7	80	23.1	0.4	ENE	0.9	ENE	1011.2	0	0
10/21/2010	12:30 AM	26.8	26.8	26.8	80	23	0.4	SSE	2.2	SSE	1011.2	0	0
10/21/2010	12:45 AM	26.9	26.9	26.8	78	22.7	0.9	ESE	2.7	ESE	1011.2	0	0
10/21/2010	1:00 AM	26.9	26.9	26.9	80	23.1	0.4	SE	2.7	SE	1011.1	0	0
10/21/2010	1:15 AM	26.7	26.9	26.7	79	22.7	0.4	SE	0.9	SE	1011	0	0
10/21/2010	1:30 AM	26.8	26.8	26.7	81	23.2	0.4	SE	2.7	SE	1010.8	0	0
10/21/2010	1:45 AM	26.7	26.8	26.7	79	22.8	0.9	ESE	2.2	ESE	1010.8	0	0
10/21/2010	2:00 AM	26.6	26.7	26.6	79	22.7	0	ESE	0.4	ESE	1010.8	0	0
10/21/2010	2:15 AM	26.3	26.6	26.3	81	22.8	0	ESE	0.9	ESE	1010.7	0	0
10/21/2010	2:30 AM	26.1	26.3	26.1	83	23	0	ESE	0.4	ESE	1010.3	0	0
10/21/2010	2:45 AM	25.8	26.1	25.8	83	22.7	0	ESE	0.4	ESE	1010.2	0	0
10/21/2010	3:00 AM	25.9	25.9	25.7	85	23.2	0	---	0	---	1010.3	0	0
10/21/2010	3:15 AM	25.5	25.9	25.5	88	23.4	0	---	0	---	1010.2	0	0
10/21/2010	3:30 AM	25.2	25.5	25.2	88	23	0	---	0	---	1010.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/21/2010	3:45 AM	24.9	25.2	24.9	87	22.6	0	ESE	0.4	ESE	1010	0	0
10/21/2010	4:00 AM	25.4	25.5	24.9	88	23.3	0	ESE	0.4	ESE	1010	0	0
10/21/2010	4:15 AM	25.4	25.4	25.3	88	23.3	0	---	0	---	1009.9	0	0
10/21/2010	4:30 AM	25.6	25.6	25.4	85	22.8	0	ESE	0.4	ESE	1009.8	0	0
10/21/2010	4:45 AM	25.6	25.7	25.6	84	22.7	0	---	0	---	1009.7	0	0
10/21/2010	5:00 AM	25.5	25.6	25.5	83	22.4	0	---	0	---	1009.8	0	0
10/21/2010	5:15 AM	25.6	25.6	25.4	85	22.9	0	ESE	0.4	ESE	1010	0	0
10/21/2010	5:30 AM	25.9	25.9	25.6	81	22.4	0	ESE	0.9	ESE	1010.2	0	0
10/21/2010	5:45 AM	25.9	26	25.9	82	22.6	0	ESE	0.4	ESE	1010.4	0	0
10/21/2010	6:00 AM	25.6	26	25.6	85	22.9	0	---	0	---	1010.5	0	0
10/21/2010	6:15 AM	25.4	25.6	25.3	85	22.7	0	ESE	0.4	ESE	1011	0	0
10/21/2010	6:30 AM	25.8	25.8	25.4	82	22.5	0	ESE	0.4	ESE	1011.2	0	0
10/21/2010	6:45 AM	26.1	26.1	25.8	81	22.6	0	ESE	0.4	ESE	1011.3	0	0
10/21/2010	7:00 AM	26.6	26.6	26.1	82	23.2	0	---	0	---	1011.2	0	0
10/21/2010	7:15 AM	27.3	27.3	26.6	79	23.4	0	ESE	0.4	ESE	1011.3	0	0
10/21/2010	7:30 AM	27.6	27.6	27.3	78	23.4	0	ESE	0.9	ESE	1011.4	0	0
10/21/2010	7:45 AM	27.5	27.6	27.5	79	23.5	0.4	ESE	0.9	ESE	1011.4	0	0
10/21/2010	8:00 AM	27.8	27.8	27.5	77	23.4	0.4	SSE	2.7	ESE	1011.5	0	0
10/21/2010	8:15 AM	28.1	28.1	27.8	78	23.9	2.2	SE	3.6	SSE	1011.6	0	0
10/21/2010	8:30 AM	28.4	28.4	28.1	78	24.2	2.7	SE	4	ESE	1011.8	0	0
10/21/2010	8:45 AM	28.7	28.7	28.5	78	24.4	2.2	SE	4.5	SE	1011.9	0	0
10/21/2010	9:00 AM	28.7	28.7	28.6	78	24.5	2.2	SSE	4	SSE	1011.8	0	0
10/21/2010	9:15 AM	28.8	28.8	28.7	77	24.3	2.7	SE	4.5	SE	1011.7	0	0
10/21/2010	9:30 AM	28.9	28.9	28.8	76	24.3	2.7	SE	4.9	S	1011.6	0	0
10/21/2010	9:45 AM	29.4	29.4	28.9	76	24.8	2.7	SE	5.4	SSE	1011.8	0	0
10/21/2010	10:00 AM	29.7	29.8	29.4	75	24.8	3.1	SSE	5.4	SSE	1011.7	0	0
10/21/2010	10:15 AM	29.4	29.8	29.4	75	24.5	3.6	SSE	5.8	SE	1011.7	0	0
10/21/2010	10:30 AM	29.4	29.4	29.3	79	25.4	3.6	SSE	5.4	SSE	1011.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/21/2010	10:45 AM	29.7	29.7	29.4	78	25.5	3.6	SSE	5.8	SSE	1011.7	0	0
10/21/2010	11:00 AM	29.7	29.8	29.7	77	25.2	4	SSE	6.3	SSE	1011.7	0	0
10/21/2010	11:15 AM	29.7	29.7	29.6	77	25.2	3.6	SSE	5.8	S	1011.6	0	0
10/21/2010	11:30 AM	29.5	29.7	29.5	77	25	4	SSE	6.7	S	1011.3	0	0
10/21/2010	11:45 AM	29.6	29.6	29.4	79	25.5	4	SSE	6.3	SE	1011.1	0	0
10/21/2010	12:00 PM	29.2	29.6	29.2	79	25.2	4	SSE	6.3	SE	1010.8	0	0
10/21/2010	12:15 PM	29	29.3	29	81	25.4	4	SSE	6.3	SE	1010.9	0	0
10/21/2010	12:30 PM	28.4	28.9	28.3	85	25.7	3.6	SSE	7.2	SSE	1010.6	0	0
10/21/2010	12:45 PM	28.9	28.9	28.4	81	25.3	3.6	SSE	5.8	SSE	1010.4	0	0
10/21/2010	1:00 PM	29.4	29.4	28.9	77	25	4	SSE	7.2	SE	1010.4	0	0
10/21/2010	1:15 PM	29.8	29.8	29.4	77	25.3	4	SSE	6.7	SSE	1010.3	0	0
10/21/2010	1:30 PM	29.6	29.8	29.6	80	25.7	4	SSE	6.3	SSE	1009.9	0	0
10/21/2010	1:45 PM	29.1	29.6	29.1	80	25.3	4	SE	5.8	SE	1009.6	0	0
10/21/2010	2:00 PM	28.6	29.1	28.6	80	24.8	4.5	SE	7.2	SE	1009.5	0	0
10/21/2010	2:15 PM	28.7	28.7	28.4	78	24.4	3.6	SE	5.8	SE	1009.6	0	0
10/21/2010	2:30 PM	28.7	28.7	28.7	81	25.1	3.1	SE	5.4	ESE	1009.6	0	0
10/21/2010	2:45 PM	28.6	28.7	28.6	81	25	3.6	SE	6.3	SSE	1009.7	0	0
10/21/2010	3:00 PM	28.4	28.6	28.4	78	24.2	3.1	ESE	5.4	ESE	1009.5	0	0
10/21/2010	3:15 PM	28.5	28.5	28.4	79	24.5	2.7	SE	4.5	SE	1009.5	0	0
10/21/2010	3:30 PM	28.6	28.6	28.5	78	24.3	2.2	ESE	4	ESE	1009.2	0	0
10/21/2010	3:45 PM	28.5	28.6	28.5	79	24.5	1.8	SE	3.1	SE	1009.4	0	0
10/21/2010	4:00 PM	28.5	28.6	28.4	80	24.7	2.2	ESE	3.6	ESE	1009.2	0	0
10/21/2010	4:15 PM	28.4	28.5	28.4	82	25	2.2	ESE	3.6	SE	1009.2	0	0
10/21/2010	4:30 PM	28.3	28.4	28.3	82	24.9	2.7	SE	4.5	SE	1009.2	0	0
10/21/2010	4:45 PM	27.4	28.3	27.4	83	24.3	4	SE	8	S	1009	0	0
10/21/2010	5:00 PM	26.7	27.4	26.6	85	23.9	3.1	ESE	6.3	ESE	1009.1	0	0
10/21/2010	5:15 PM	27.3	27.3	26.6	85	24.5	2.2	ESE	4	SE	1009.2	0	0
10/21/2010	5:30 PM	27.4	27.5	27.3	84	24.5	2.2	SE	3.6	SSE	1009.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/21/2010	5:45 PM	27.7	27.7	27.4	82	24.3	2.2	ESE	4	ESE	1009.8	0	0
10/21/2010	6:00 PM	27.8	27.8	27.6	79	23.8	2.2	ESE	4	ESE	1010	0	0
10/21/2010	6:15 PM	27.7	27.8	27.7	79	23.7	2.2	ESE	3.6	ESE	1010	0	0
10/21/2010	6:30 PM	27.8	27.8	27.7	80	24	1.8	ESE	3.6	SE	1010	0	0
10/21/2010	6:45 PM	27.8	27.8	27.8	80	24	0.4	SE	2.2	SE	1010.2	0	0
10/21/2010	7:00 PM	27.6	27.8	27.6	80	23.8	0.4	ESE	2.2	ESE	1010.4	0	0
10/21/2010	7:15 PM	27.6	27.6	27.5	80	23.8	1.3	ESE	2.7	ESE	1010.4	0	0
10/21/2010	7:30 PM	27.6	27.6	27.6	79	23.6	1.3	ESE	2.7	E	1010.5	0	0
10/21/2010	7:45 PM	27.8	27.8	27.6	78	23.6	1.3	SE	3.1	SE	1010.6	0	0
10/21/2010	8:00 PM	27.7	27.8	27.7	80	23.9	1.3	SSE	2.7	SE	1010.9	0	0
10/21/2010	8:15 PM	27.8	27.8	27.7	80	24	1.8	SE	3.6	SSE	1011	0	0
10/21/2010	8:30 PM	27.6	27.8	27.6	79	23.6	1.8	ESE	3.1	ESE	1011.1	0	0
10/21/2010	8:45 PM	27.6	27.6	27.5	79	23.6	1.8	SE	3.1	SSE	1011.2	0	0
10/21/2010	9:00 PM	27.7	27.7	27.6	79	23.7	1.8	SE	3.6	ESE	1011.3	0	0
10/21/2010	9:15 PM	27.7	27.7	27.6	79	23.7	1.8	SE	3.1	SE	1011.4	0	0
10/21/2010	9:30 PM	27.7	27.8	27.7	79	23.7	1.8	SE	3.6	SE	1011.6	0	0
10/21/2010	9:45 PM	27.7	27.7	27.7	81	24.1	0.9	SE	2.7	SSE	1011.6	0	0
10/21/2010	10:00 PM	27.6	27.7	27.6	80	23.8	0.9	SE	2.2	SE	1011.7	0	0
10/21/2010	10:15 PM	27.6	27.6	27.6	82	24.2	0.9	SE	2.2	ESE	1011.6	0	0
10/21/2010	10:30 PM	27.3	27.6	27.3	82	24	0	SE	0.9	SE	1011.5	0	0
10/21/2010	10:45 PM	26.9	27.3	26.9	83	23.8	0.4	NE	2.2	ENE	1011.3	0	0
10/21/2010	11:00 PM	26.7	26.9	26.7	82	23.4	0	NW	0.9	WNW	1011.3	0	0
10/21/2010	11:15 PM	26.6	26.7	26.6	81	23.1	0	NW	0.4	NW	1011.1	0	0
10/21/2010	11:30 PM	26.6	26.7	26.6	83	23.5	0	NW	0.4	NW	1010.9	0	0
10/21/2010	11:45 PM	26.3	26.6	26.3	85	23.6	0	NW	0.4	NW	1010.8	0	0
10/22/2010	12:00 AM	26.1	26.3	26.1	85	23.3	0	NW	0.4	NW	1010.7	0	0
10/22/2010	12:15 AM	26	26.1	25.9	85	23.3	0	---	0	---	1010.6	0	0
10/22/2010	12:30 AM	25.9	26.1	25.9	86	23.4	0	---	0	---	1010.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/22/2010	12:45 AM	25.7	25.9	25.7	87	23.4	0	---	0	---	1010.2	0	0
10/22/2010	1:00 AM	25.8	25.8	25.7	85	23.1	0	NW	0.9	NW	1010.2	0	0
10/22/2010	1:15 AM	25.7	25.8	25.7	85	23	0	NW	0.9	NW	1010	0	0
10/22/2010	1:30 AM	25.8	25.8	25.7	85	23.1	0	NW	0.9	NW	1010	0	0
10/22/2010	1:45 AM	25.7	25.8	25.7	85	23	0	WNW	0.9	WNW	1010.1	0	0
10/22/2010	2:00 AM	25.7	25.7	25.7	83	22.6	0	WNW	0.4	WNW	1010	0	0
10/22/2010	2:15 AM	25.7	25.7	25.7	84	22.8	0	WNW	0.4	WNW	1009.9	0	0
10/22/2010	2:30 AM	25.9	25.9	25.7	84	23	0	NNW	0.9	WNW	1009.8	0	0
10/22/2010	2:45 AM	26	26	25.9	84	23.1	0	NNW	0.9	NNW	1009.9	0	0
10/22/2010	3:00 AM	25.8	25.9	25.8	85	23.1	0	NNW	0.4	NNW	1009.7	0	0
10/22/2010	3:15 AM	25.7	25.8	25.7	86	23.1	0	---	0	---	1009.8	0	0
10/22/2010	3:30 AM	25.6	25.7	25.4	87	23.2	0	---	0	---	1009.7	0	0
10/22/2010	3:45 AM	25.4	25.7	25.4	88	23.3	0	NNW	0.4	NNW	1009.8	0	0
10/22/2010	4:00 AM	25.1	25.5	25.1	90	23.4	0	NNW	0.4	NNW	1009.7	0	0
10/22/2010	4:15 AM	25	25.1	25	90	23.2	0	---	0	---	1009.8	0	0
10/22/2010	4:30 AM	24.9	25	24.9	91	23.4	0	NNW	0.4	NNW	1009.9	0	0
10/22/2010	4:45 AM	24.9	24.9	24.8	91	23.4	0	---	0	---	1009.9	0	0
10/22/2010	5:00 AM	24.9	24.9	24.8	91	23.3	0	NNW	0.4	NNW	1010	0	0
10/22/2010	5:15 AM	25.3	25.3	24.9	89	23.4	0	NNW	0.4	NNW	1010.3	0	0
10/22/2010	5:30 AM	25.4	25.4	25.3	89	23.5	0	NNW	1.8	NNW	1010.5	0	0
10/22/2010	5:45 AM	25.8	25.8	25.4	87	23.4	0.4	NNW	0.9	NNW	1010.7	0	0
10/22/2010	6:00 AM	25.8	25.9	25.8	87	23.5	0	NNW	0.9	NNW	1010.8	0	0
10/22/2010	6:15 AM	26.1	26.1	25.7	85	23.4	0.9	SSE	2.7	S	1011.2	0	0
10/22/2010	6:30 AM	26.3	26.3	26.1	83	23.2	0.4	SE	1.8	SE	1011.3	0	0
10/22/2010	6:45 AM	26.6	26.6	26.3	83	23.4	0	SE	1.8	SE	1011.7	0	0
10/22/2010	7:00 AM	26.6	26.7	26.6	85	23.9	0.4	WNW	2.2	WNW	1011.6	0	0
10/22/2010	7:15 AM	26.5	26.6	26.5	86	24	0.4	NW	2.2	WNW	1011.8	0	0
10/22/2010	7:30 AM	26.2	26.5	26.2	87	23.9	0.9	WNW	2.2	WNW	1012.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/22/2010	7:45 AM	26.3	26.3	26.2	87	24	0.4	WNW	1.8	NW	1012.4	0	0
10/22/2010	8:00 AM	26.9	26.9	26.3	86	24.3	0.4	WNW	1.3	WNW	1012.6	0	0
10/22/2010	8:15 AM	27.5	27.5	26.9	83	24.4	0	WNW	0.9	WNW	1012.7	0	0
10/22/2010	8:30 AM	28.3	28.3	27.5	80	24.5	0.4	WNW	1.8	WNW	1012.8	0	0
10/22/2010	8:45 AM	28.7	28.7	28.3	80	24.9	0.4	WNW	2.2	WNW	1013	0	0
10/22/2010	9:00 AM	28.8	28.8	28.6	77	24.4	1.8	ESE	3.6	SE	1013.1	0	0
10/22/2010	9:15 AM	28.8	28.9	28.8	77	24.3	3.1	SE	4.9	ESE	1013.3	0	0
10/22/2010	9:30 AM	29.4	29.4	28.8	74	24.3	2.7	SE	4.9	SE	1013.3	0	0
10/22/2010	9:45 AM	29.6	29.6	29.4	76	24.9	2.7	SE	4.9	SSE	1013.4	0	0
10/22/2010	10:00 AM	29.7	29.7	29.6	75	24.8	3.6	SE	5.4	SSE	1013.6	0	0
10/22/2010	10:15 AM	29.8	29.8	29.7	77	25.4	3.1	SE	5.4	SE	1013.5	0	0
10/22/2010	10:30 AM	30.1	30.1	29.8	76	25.4	3.6	SSE	5.4	SSE	1013.1	0	0
10/22/2010	10:45 AM	30.1	30.2	30	74	24.9	4	SE	6.3	ESE	1012.9	0	0
10/22/2010	11:00 AM	30.1	30.2	30	73	24.7	4	SSE	6.3	SSE	1012.8	0	0
10/22/2010	11:15 AM	30.3	30.3	30	73	24.9	4	SE	5.8	SE	1012.7	0	0
10/22/2010	11:30 AM	30.4	30.4	30.2	72	24.8	4	SSE	6.7	SE	1012.4	0	0
10/22/2010	11:45 AM	30.2	30.4	30.2	72	24.6	4.5	SSE	6.7	ESE	1012.1	0	0
10/22/2010	12:00 PM	30.6	30.7	30.2	70	24.5	4	SSE	6.7	SSE	1011.9	0	0
10/22/2010	12:15 PM	30.6	30.7	30.6	71	24.7	4	SSE	7.2	SE	1011.7	0	0
10/22/2010	12:30 PM	30.7	30.7	30.5	72	25	4	SSE	6.7	SSE	1011.5	0	0
10/22/2010	12:45 PM	30.8	30.8	30.6	74	25.6	3.6	SSE	5.8	SSE	1011.3	0	0
10/22/2010	1:00 PM	30.1	30.8	30.1	78	25.8	4.5	SSE	6.7	S	1011.1	0	0
10/22/2010	1:15 PM	30.3	30.3	30.1	78	26	4.5	SSE	7.2	SSE	1011	0	0
10/22/2010	1:30 PM	30.4	30.4	30.3	76	25.7	4.5	SSE	6.7	SE	1010.9	0	0
10/22/2010	1:45 PM	30.1	30.4	30.1	77	25.6	4.9	SSE	8.5	SSE	1010.9	0	0
10/22/2010	2:00 PM	29.9	30.2	29.9	78	25.7	4.9	SSE	8.5	SSE	1010.6	0	0
10/22/2010	2:15 PM	29.4	29.9	29.4	80	25.6	5.4	SSE	9.4	ESE	1010.4	0	0
10/22/2010	2:30 PM	29.4	29.4	29.1	78	25.2	5.4	SSE	10.3	SSE	1010.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/22/2010	2:45 PM	29.4	29.5	29.4	79	25.4	5.4	SSE	8.9	SSE	1010.1	0	0
10/22/2010	3:00 PM	29.6	29.6	29.4	78	25.3	4.9	SSE	8.5	SSE	1010	0	0
10/22/2010	3:15 PM	29.8	29.9	29.6	79	25.7	4.9	SSE	9.4	SE	1010	0	0
10/22/2010	3:30 PM	29.7	29.8	29.6	76	25	5.4	SE	8.9	SSE	1010.1	0	0
10/22/2010	3:45 PM	29.4	29.7	29.4	79	25.4	4.9	SE	8.9	SE	1010	0	0
10/22/2010	4:00 PM	29.3	29.4	29.3	79	25.3	4.9	SSE	8	SE	1009.9	0	0
10/22/2010	4:15 PM	29.1	29.3	29.1	81	25.5	5.4	SSE	9.4	SSE	1010.2	0	0
10/22/2010	4:30 PM	28.3	29	28.2	80	24.5	6.3	SE	10.3	SE	1010.2	0	0
10/22/2010	4:45 PM	28.7	28.7	28.3	78	24.5	5.4	SE	9.4	SE	1010.2	0	0
10/22/2010	5:00 PM	28.6	28.8	28.6	77	24.2	4	SE	7.2	SE	1010.4	0	0
10/22/2010	5:15 PM	28.4	28.6	28.4	78	24.2	4	SE	6.7	SE	1010.7	0	0
10/22/2010	5:30 PM	28.4	28.4	28.3	77	24	4.5	ESE	6.7	SE	1010.9	0	0
10/22/2010	5:45 PM	28.5	28.5	28.4	77	24.1	4.5	ESE	7.2	SE	1010.9	0	0
10/22/2010	6:00 PM	28.5	28.6	28.4	78	24.3	3.6	ESE	6.3	ESE	1011.2	0	0
10/22/2010	6:15 PM	28.4	28.5	28.4	77	24	3.6	SE	6.7	SSE	1011.4	0	0
10/22/2010	6:30 PM	28	28.4	28	81	24.4	3.6	SE	6.3	SE	1011.4	0	0
10/22/2010	6:45 PM	28.1	28.1	27.9	81	24.5	3.1	SE	5.4	SSE	1011.6	0	0
10/22/2010	7:00 PM	28.3	28.3	28.1	78	24.1	3.1	SE	5.4	ESE	1011.7	0	0
10/22/2010	7:15 PM	28.3	28.3	28.3	77	23.9	3.6	ESE	5.8	SE	1011.7	0	0
10/22/2010	7:30 PM	28.4	28.4	28.3	76	23.7	3.6	ESE	6.3	SE	1011.6	0	0
10/22/2010	7:45 PM	28.4	28.4	28.4	76	23.7	3.6	ESE	6.7	SE	1011.8	0	0
10/22/2010	8:00 PM	28.3	28.4	28.3	77	23.9	2.7	ESE	5.8	SE	1011.9	0	0
10/22/2010	8:15 PM	28.3	28.3	28.2	77	23.9	2.7	ESE	4.5	ESE	1011.9	0	0
10/22/2010	8:30 PM	28.4	28.4	28.2	77	24	2.7	ESE	4.9	SE	1012.1	0	0
10/22/2010	8:45 PM	28.5	28.5	28.3	76	23.9	3.1	ESE	5.8	ESE	1012.2	0	0
10/22/2010	9:00 PM	28.5	28.5	28.4	76	23.9	3.1	ESE	5.4	SE	1012.5	0	0
10/22/2010	9:15 PM	28.4	28.5	28.4	76	23.8	3.1	SE	4.9	ESE	1012.7	0	0
10/22/2010	9:30 PM	28.3	28.4	28.3	77	23.9	3.6	ESE	6.7	ESE	1012.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/22/2010	9:45 PM	28.2	28.3	28.2	77	23.8	3.1	ESE	5.8	ESE	1012.8	0	0
10/22/2010	10:00 PM	28.1	28.2	28.1	77	23.6	2.7	ESE	5.4	ESE	1013.1	0	0
10/22/2010	10:15 PM	27.9	28.1	27.9	76	23.3	1.8	ESE	3.6	E	1013.1	0	0
10/22/2010	10:30 PM	28.2	28.2	27.9	74	23.1	1.8	ESE	4	E	1013	0	0
10/22/2010	10:45 PM	28.3	28.3	28.2	73	23	1.3	ESE	3.1	SE	1013.1	0	0
10/22/2010	11:00 PM	28.2	28.3	28.2	73	22.9	2.2	ESE	4	ESE	1013.1	0	0
10/22/2010	11:15 PM	28.4	28.4	28.2	73	23.1	2.7	ESE	5.8	S	1013.1	0	0
10/22/2010	11:30 PM	27	28.4	27	86	24.5	4	SSE	7.2	SE	1013.1	0	0
10/22/2010	11:45 PM	26.2	27	26.2	87	23.8	3.6	SSE	5.8	SSE	1012.7	0	0
10/23/2010	12:00 AM	25.6	26.2	25.6	88	23.5	0.4	SE	2.7	SE	1012.6	0.25	0
10/23/2010	12:15 AM	25.8	25.8	25.5	91	24.2	0.9	SE	5.4	SSE	1012.9	0	0
10/23/2010	12:30 AM	25.8	26.2	25.8	71	20.1	5.4	SE	9.8	SE	1012.6	0	0
10/23/2010	12:45 AM	24.7	25.8	24.7	84	21.8	1.8	SSE	9.8	SE	1012.5	0.51	1.3
10/23/2010	1:00 AM	24.3	24.7	24.3	87	22	0.4	S	2.7	S	1012.1	0	0
10/23/2010	1:15 AM	24.4	24.4	24.2	91	22.9	0	SSW	0.4	SSW	1012.1	0	0
10/23/2010	1:30 AM	24.7	24.7	24.4	93	23.5	0	SSW	0.9	SSW	1011.9	0	0
10/23/2010	1:45 AM	25	25	24.7	92	23.6	0	NE	2.2	NE	1011.6	0	0
10/23/2010	2:00 AM	25.4	25.4	25	91	23.8	0	NW	2.2	NNW	1011.6	0	0
10/23/2010	2:15 AM	25.3	25.4	25.3	92	23.9	0	WNW	0.9	WNW	1011.7	0	0
10/23/2010	2:30 AM	25.2	25.3	25.2	90	23.5	0.4	S	2.2	S	1011.5	0	0
10/23/2010	2:45 AM	25.2	25.3	25.2	91	23.6	0	SSE	0.4	SSE	1011.6	0	0
10/23/2010	3:00 AM	25.2	25.3	25.2	90	23.5	0	SSE	0.9	SSE	1011.6	0	0
10/23/2010	3:15 AM	25.4	25.4	25.2	89	23.5	0	SSE	0.9	SSE	1011.6	0	0
10/23/2010	3:30 AM	25.3	25.4	25.3	90	23.6	0	WNW	0.9	WNW	1011.1	0.25	0
10/23/2010	3:45 AM	25.2	25.3	25.2	90	23.5	0	NW	1.8	NW	1010.9	0	0
10/23/2010	4:00 AM	25.2	25.2	25.1	91	23.6	0	---	0	---	1011.1	0	0
10/23/2010	4:15 AM	25.2	25.3	25.2	92	23.8	0	---	0	---	1011.1	0	0
10/23/2010	4:30 AM	25	25.1	25	93	23.8	0	NW	0.4	NW	1011	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/23/2010	4:45 AM	25	25.1	25	92	23.6	0	NW	0.9	NW	1011.2	0	0
10/23/2010	5:00 AM	25.1	25.1	25	92	23.7	0	NW	0.4	NW	1011.4	0	0
10/23/2010	5:15 AM	25.1	25.1	25	92	23.7	0.4	NW	1.8	NW	1011.9	0	0
10/23/2010	5:30 AM	24.9	25.1	24.9	91	23.4	0	NW	0.9	NW	1012.1	0	0
10/23/2010	5:45 AM	25.2	25.2	24.9	90	23.4	0	NW	0.9	WNW	1012.1	0	0
10/23/2010	6:00 AM	25.4	25.4	25.2	89	23.4	0	N	1.8	NNW	1012.3	0	0
10/23/2010	6:15 AM	25.6	25.6	25.4	88	23.4	0	N	2.2	N	1012.6	0	0
10/23/2010	6:30 AM	25.7	25.7	25.6	87	23.4	0	N	0.9	N	1012.9	0	0
10/23/2010	6:45 AM	25.9	25.9	25.7	87	23.6	0.4	N	2.2	WNW	1012.7	0	0
10/23/2010	7:00 AM	26.1	26.1	25.9	88	24	0.4	WNW	1.8	WNW	1012.6	0	0
10/23/2010	7:15 AM	26.1	26.1	26.1	88	24	0.4	NW	1.8	WNW	1012.7	0	0
10/23/2010	7:30 AM	26.3	26.3	26.1	88	24.2	0.4	NW	1.8	NW	1012.7	0	0
10/23/2010	7:45 AM	27.1	27.1	26.3	85	24.3	0.4	WNW	2.2	NW	1012.6	0	0
10/23/2010	8:00 AM	27.4	27.4	27.1	82	24	0.4	WNW	2.2	W	1012.9	0	0
10/23/2010	8:15 AM	27.8	27.8	27.4	79	23.8	0	WNW	1.8	WNW	1012.9	0	0
10/23/2010	8:30 AM	28.2	28.2	27.8	79	24.2	0.4	WNW	1.3	WNW	1013.3	0	0
10/23/2010	8:45 AM	28.4	28.5	28.2	82	25	0.4	WNW	2.2	WNW	1013.9	0	0
10/23/2010	9:00 AM	28.2	28.4	28.2	82	24.9	0.4	WNW	1.8	WNW	1014	0	0
10/23/2010	9:15 AM	28.3	28.3	28.2	81	24.7	0.4	WNW	1.8	WNW	1013.9	0	0
10/23/2010	9:30 AM	28.3	28.3	28.2	81	24.8	0	WNW	0.9	WNW	1014.1	0	0
10/23/2010	9:45 AM	29.2	29.2	28.3	78	25	0.4	WNW	2.2	NW	1014.1	0	0
10/23/2010	10:00 AM	29.8	29.8	29.1	73	24.4	0.9	NE	2.7	NNE	1014.1	0	0
10/23/2010	10:15 AM	30.1	30.1	29.8	71	24.2	0.9	ENE	2.2	NE	1014.3	0	0
10/23/2010	10:30 AM	30.6	30.6	30.1	68	24	0.4	ENE	1.8	ENE	1014.1	0	0
10/23/2010	10:45 AM	30.7	30.9	30.6	70	24.6	0.4	NNE	2.7	NNE	1014	0.25	0
10/23/2010	11:00 AM	30.4	30.7	30.4	75	25.5	1.3	S	4	SSE	1013.8	0	0
10/23/2010	11:15 AM	30.2	30.6	30.2	77	25.7	4	SSE	6.7	SE	1013.4	0	0
10/23/2010	11:30 AM	30.3	30.4	30.2	76	25.6	4	SE	6.7	SE	1013.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/23/2010	11:45 AM	30.3	30.3	30.1	78	26	4.5	SE	8	SE	1013.1	0	0
10/23/2010	12:00 PM	30.3	30.4	30.3	73	24.9	4	SE	7.2	ESE	1013.1	0	0
10/23/2010	12:15 PM	29.7	30.3	29.7	78	25.5	4.5	SSE	6.3	SSE	1012.9	0	0
10/23/2010	12:30 PM	29.7	29.7	29.6	78	25.4	3.6	SSE	5.8	SSE	1012.9	0	0
10/23/2010	12:45 PM	29.6	29.7	29.6	77	25.1	3.6	SSE	5.8	SSE	1012.4	0	0
10/23/2010	1:00 PM	29.7	29.7	29.6	78	25.4	3.6	SSE	5.4	SE	1012.2	0	0
10/23/2010	1:15 PM	29.8	29.8	29.7	77	25.4	3.6	SSE	5.4	SE	1012.4	0	0
10/23/2010	1:30 PM	30	30	29.8	79	26	3.1	SSE	5.4	SE	1012	0	0
10/23/2010	1:45 PM	29.8	30.2	29.8	78	25.5	4.5	SSE	7.2	SE	1012	0	0
10/23/2010	2:00 PM	29.3	29.8	29.3	76	24.6	4	SSE	7.2	E	1011.8	0	0
10/23/2010	2:15 PM	29	29.3	29	78	24.8	4	SSE	8	SE	1011.6	0	0
10/23/2010	2:30 PM	28.6	29.1	28.6	78	24.4	4	SE	6.7	SE	1011.4	0	0
10/23/2010	2:45 PM	28.9	28.9	28.6	76	24.3	3.1	SE	5.8	SE	1011.4	0	0
10/23/2010	3:00 PM	29.2	29.2	28.9	76	24.5	2.2	ESE	3.6	ESE	1011.3	0	0
10/23/2010	3:15 PM	29.2	29.3	29.2	75	24.3	1.8	SE	3.6	SE	1011.5	0	0
10/23/2010	3:30 PM	29.2	29.2	29.2	77	24.8	2.7	SE	4.9	ESE	1011.6	0	0
10/23/2010	3:45 PM	29.2	29.2	29.2	77	24.7	2.2	ESE	3.6	ESE	1011.6	0	0
10/23/2010	4:00 PM	29.3	29.3	29.2	74	24.2	0.9	ESE	2.7	ESE	1011.7	0	0
10/23/2010	4:15 PM	29.5	29.5	29.3	72	23.9	0.4	ESE	1.8	ESE	1011.8	0	0
10/23/2010	4:30 PM	29.7	29.7	29.5	72	24.1	0	ESE	0.4	ESE	1012	0	0
10/23/2010	4:45 PM	29.8	29.9	29.7	75	24.9	0	ESE	0.4	ESE	1012.1	0	0
10/23/2010	5:00 PM	29.5	29.8	29.5	76	24.8	0	ESE	0.4	ESE	1012.1	0	0
10/23/2010	5:15 PM	29.1	29.5	29.1	80	25.3	0.4	WNW	2.2	WNW	1012.4	0	0
10/23/2010	5:30 PM	28.7	29.1	28.7	81	25.1	0	WNW	1.8	NNW	1012.7	0	0
10/23/2010	5:45 PM	28.4	28.8	28.4	81	24.9	0.4	WNW	2.2	WNW	1012.8	0	0
10/23/2010	6:00 PM	28.3	28.4	28.3	82	24.9	0	WNW	1.8	WNW	1012.7	0	0
10/23/2010	6:15 PM	28.2	28.3	28.2	82	24.8	0	W	2.2	W	1012.9	0	0
10/23/2010	6:30 PM	28	28.2	28	82	24.6	0.4	NW	2.2	NW	1013	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/23/2010	6:45 PM	27.9	28	27.9	83	24.8	0.4	NNW	2.2	NNW	1013.2	0	0
10/23/2010	7:00 PM	27.8	27.9	27.8	84	24.9	0	NW	0.9	NW	1013.3	0	0
10/23/2010	7:15 PM	27.7	27.8	27.7	84	24.8	0	NW	0.4	NW	1013.5	0	0
10/23/2010	7:30 PM	27.7	27.7	27.7	84	24.7	0	NW	0.4	NW	1013.6	0	0
10/23/2010	7:45 PM	27.7	27.7	27.7	84	24.7	0	NW	0.4	NW	1013.9	0	0
10/23/2010	8:00 PM	27.7	27.7	27.7	84	24.7	0	NW	0.4	NW	1013.8	0	0
10/23/2010	8:15 PM	27.6	27.7	27.6	86	25	0	---	0	---	1013.8	0	0
10/23/2010	8:30 PM	27.3	27.6	27.3	86	24.7	0	NW	0.4	NW	1014	0	0
10/23/2010	8:45 PM	27.4	27.4	27.3	86	24.8	0.9	WNW	2.2	WNW	1014.1	0	0
10/23/2010	9:00 PM	27.3	27.4	27.3	85	24.6	0.4	WNW	2.2	NW	1014.1	0	0
10/23/2010	9:15 PM	27.3	27.4	27.3	84	24.3	0	NW	1.8	NW	1014	0	0
10/23/2010	9:30 PM	27.2	27.3	27.2	85	24.5	0	NW	1.3	NW	1014	0	0
10/23/2010	9:45 PM	27.2	27.2	27.2	85	24.4	0	---	0	---	1014	0	0
10/23/2010	10:00 PM	26.8	27.2	26.8	88	24.6	0	---	0	---	1014	0	0
10/23/2010	10:15 PM	26.4	26.8	26.4	89	24.4	0	NW	0.9	NW	1013.9	0	0
10/23/2010	10:30 PM	26.5	26.6	26.3	89	24.5	0	WNW	0.9	NW	1013.9	0	0
10/23/2010	10:45 PM	26.3	26.5	26.3	89	24.4	0	---	0	---	1013.7	0	0
10/23/2010	11:00 PM	26.2	26.4	26.2	90	24.5	0	WNW	0.4	WNW	1013.5	0	0
10/23/2010	11:15 PM	26	26.2	26	91	24.4	0	WNW	0.9	WNW	1013.5	0	0
10/23/2010	11:30 PM	26	26	25.9	89	24	0	SSE	2.2	SSE	1013.2	0	0
10/23/2010	11:45 PM	25.9	26	25.9	90	24.2	0	WSW	0.9	WSW	1013.1	0	0
10/24/2010	12:00 AM	25.9	26	25.9	89	24	0	WSW	0.4	WSW	1012.7	0	0
10/24/2010	12:15 AM	25.9	25.9	25.9	86	23.4	0	WSW	0.9	WSW	1012.3	0	0
10/24/2010	12:30 AM	26.1	26.1	25.9	87	23.7	0	W	0.9	W	1012.2	0	0
10/24/2010	12:45 AM	25.9	26.1	25.9	84	23	0	W	1.8	W	1012.2	0	0
10/24/2010	1:00 AM	25.9	25.9	25.9	84	23	0	W	0.4	W	1012	0	0
10/24/2010	1:15 AM	26.1	26.1	25.9	84	23.2	0	WNW	1.8	WNW	1011.9	0	0
10/24/2010	1:30 AM	26.3	26.3	26.1	83	23.2	0	NNE	1.8	NNE	1012	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/24/2010	1:45 AM	26.3	26.4	26.3	84	23.4	0	NNE	0.4	NNE	1012	0	0
10/24/2010	2:00 AM	25.8	26.3	25.8	86	23.3	0	NNE	0.9	NNE	1012	0	0
10/24/2010	2:15 AM	25.3	25.8	25.3	88	23.2	0	NNE	0.4	NNE	1012.1	0	0
10/24/2010	2:30 AM	25.3	25.3	25.2	88	23.1	0	NNE	0.4	NNE	1012	0	0
10/24/2010	2:45 AM	25.3	25.3	25.3	89	23.3	0	---	0	---	1011.7	0	0
10/24/2010	3:00 AM	25.2	25.3	25.1	87	22.8	0	NNE	1.8	NNE	1011.4	0	0
10/24/2010	3:15 AM	25.3	25.3	25.2	87	23	0	NNE	0.9	NNE	1011.6	0	0
10/24/2010	3:30 AM	25.6	25.6	25.3	88	23.4	0	NNE	0.4	NNE	1011.7	0	0
10/24/2010	3:45 AM	25.5	25.6	25.5	85	22.8	0	NNE	0.4	NNE	1011.5	0	0
10/24/2010	4:00 AM	25.5	25.6	25.4	85	22.8	0	NNE	0.4	NNE	1011.4	0	0
10/24/2010	4:15 AM	25.5	25.6	25.4	82	22.2	0	NNE	1.3	NNE	1011.6	0	0
10/24/2010	4:30 AM	25.6	25.6	25.5	82	22.3	0	NNE	0.4	NNE	1011.4	0	0
10/24/2010	4:45 AM	25.7	25.7	25.6	81	22.2	0	NNE	1.8	NNE	1011.6	0	0
10/24/2010	5:00 AM	25.6	25.7	25.5	80	21.8	0	NNE	2.2	NNE	1011.3	0	0
10/24/2010	5:15 AM	25.8	25.8	25.6	78	21.7	0	NNW	1.3	NNW	1011.3	0	0
10/24/2010	5:30 AM	25.8	25.8	25.8	78	21.7	0	NNW	2.7	NE	1011.7	0	0
10/24/2010	5:45 AM	25.8	25.8	25.7	77	21.4	0.4	NE	2.7	NNE	1011.7	0	0
10/24/2010	6:00 AM	25.8	25.9	25.8	78	21.7	0	NNE	0.9	NNE	1011.8	0	0
10/24/2010	6:15 AM	25.8	25.8	25.8	78	21.7	0.4	NNE	2.2	NNE	1011.8	0	0
10/24/2010	6:30 AM	25.9	25.9	25.8	79	22	0	NNE	0.4	NNE	1012.1	0	0
10/24/2010	6:45 AM	26.1	26.1	25.9	78	22	0	NNE	0.9	N	1012.3	0	0
10/24/2010	7:00 AM	27.1	27.1	26.2	76	22.5	0	N	0.9	N	1012.6	0	0
10/24/2010	7:15 AM	27.7	27.7	27.1	73	22.4	0.4	N	2.2	N	1012.6	0	0
10/24/2010	7:30 AM	28.4	28.4	27.7	71	22.7	0	N	0.9	N	1012.8	0	0
10/24/2010	7:45 AM	28.8	28.8	28.4	70	22.8	0.4	NW	1.8	NW	1013	0	0
10/24/2010	8:00 AM	29.1	29.1	28.8	71	23.3	0.4	NW	1.8	NW	1013	0	0
10/24/2010	8:15 AM	29.7	29.7	29.1	67	22.9	0.4	NW	1.8	NW	1013.2	0	0
10/24/2010	8:30 AM	29.8	29.9	29.7	73	24.5	0.9	WNW	2.7	W	1013.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/24/2010	8:45 AM	29.6	29.8	29.6	73	24.2	0.9	WNW	2.7	NW	1013.6	0	0
10/24/2010	9:00 AM	29.8	29.8	29.6	72	24.2	0.9	WNW	2.2	WNW	1013.5	0	0
10/24/2010	9:15 AM	30.3	30.3	29.8	66	23.3	0.4	WNW	2.2	W	1013.6	0	0
10/24/2010	9:30 AM	31	31	30.4	68	24.4	0.9	WNW	3.1	WNW	1013.7	0	0
10/24/2010	9:45 AM	31.1	31.1	30.9	64	23.5	0.9	WNW	3.1	WNW	1013.8	0	0
10/24/2010	10:00 AM	30.6	31.3	30.6	67	23.7	1.8	S	4.5	SSW	1014	0	0
10/24/2010	10:15 AM	30.2	30.6	30.2	68	23.6	2.2	S	4	SSE	1014	0	0
10/24/2010	10:30 AM	30.2	30.3	30	73	24.8	2.7	S	4	S	1014.1	0	0
10/24/2010	10:45 AM	30.4	30.4	30.1	76	25.7	2.2	S	4.9	SSE	1013.9	0	0
10/24/2010	11:00 AM	30.4	30.6	30.2	76	25.7	1.3	SSE	3.6	SSE	1013.7	0	0
10/24/2010	11:15 AM	30	30.6	30	78	25.7	1.8	S	4.5	SSE	1013.5	0	0
10/24/2010	11:30 AM	30.1	30.2	29.6	79	26.1	2.7	SSE	5.4	SSE	1013.2	0	0
10/24/2010	11:45 AM	30.4	30.5	30.1	81	26.8	3.6	SSE	5.8	SSE	1013	0	0
10/24/2010	12:00 PM	30.5	30.5	30.3	80	26.7	3.6	SSE	6.7	S	1013	0	0
10/24/2010	12:15 PM	30.6	30.6	30.3	80	26.7	4	SSE	6.3	SSE	1012.8	0	0
10/24/2010	12:30 PM	30.6	30.6	30.4	80	26.8	4.5	SSE	8	SSE	1012.4	0	0
10/24/2010	12:45 PM	30.6	30.7	30.6	78	26.3	4.5	SSE	8	SSE	1012.1	0	0
10/24/2010	1:00 PM	30.4	30.7	30.3	74	25.3	4.5	SE	8.9	SE	1011.6	0	0
10/24/2010	1:15 PM	30.6	30.7	30.4	75	25.6	4.9	SE	8.9	SSE	1011	0	0
10/24/2010	1:30 PM	30.1	30.6	30.1	79	26.1	5.4	SSE	8	SE	1011.1	0	0
10/24/2010	1:45 PM	29.2	30.2	29.2	82	25.8	5.4	SSE	9.8	SE	1010.7	0	0
10/24/2010	2:00 PM	28.9	29.2	28.9	78	24.7	5.4	SSE	9.4	SSE	1010.7	0	0
10/24/2010	2:15 PM	28.9	28.9	28.9	81	25.3	5.4	SSE	8.9	SE	1010.6	0	0
10/24/2010	2:30 PM	28.9	28.9	28.9	79	24.9	4.9	SSE	8.9	SSE	1010.6	0	0
10/24/2010	2:45 PM	29	29	28.9	77	24.6	4.9	SSE	8.5	SSE	1010.4	0	0
10/24/2010	3:00 PM	29	29.1	29	79	25	5.4	SSE	8	SSE	1010.6	0	0
10/24/2010	3:15 PM	28.9	29	28.9	81	25.3	4.9	SSE	8.5	SE	1010.5	0	0
10/24/2010	3:30 PM	28.8	28.9	28.8	81	25.2	5.4	SSE	8.9	SSE	1010.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/24/2010	3:45 PM	28.9	28.9	28.8	79	24.9	4.5	SSE	8	SE	1010.5	0	0
10/24/2010	4:00 PM	28.8	28.9	28.8	79	24.8	4.9	SSE	8.9	ESE	1010.7	0	0
10/24/2010	4:15 PM	28.5	28.8	28.5	83	25.3	4	SE	6.7	SE	1011.1	0	0
10/24/2010	4:30 PM	27.4	28.5	27.4	87	25.1	3.1	ESE	5.4	ESE	1011.3	0.25	0
10/24/2010	4:45 PM	27.9	27.9	27.4	85	25.2	3.1	SE	5.4	SE	1011.4	0.25	1
10/24/2010	5:00 PM	27.9	28.1	27.9	84	25	2.7	ESE	5.4	SSE	1011.4	0	0
10/24/2010	5:15 PM	26.6	27.9	26.6	86	24	1.3	NNE	4	N	1011.7	0	0
10/24/2010	5:30 PM	25.9	26.5	25.9	85	23.2	0.9	NNE	3.1	NNE	1011.8	0	0
10/24/2010	5:45 PM	25.9	25.9	25.9	87	23.6	0.4	NNE	2.2	NNW	1011.9	0	0
10/24/2010	6:00 PM	25.8	25.9	25.8	86	23.3	0.4	NW	2.7	NW	1012.1	0	0
10/24/2010	6:15 PM	26.1	26.1	25.8	85	23.4	0.4	NW	3.1	NNW	1012.3	0	0
10/24/2010	6:30 PM	26.2	26.2	26.1	88	24	0.9	NW	2.7	NW	1012.5	0	0
10/24/2010	6:45 PM	26.1	26.2	26.1	90	24.3	0.4	NW	2.2	NNW	1012.5	0	0
10/24/2010	7:00 PM	26.1	26.1	26.1	91	24.5	0.4	NW	1.3	WNW	1012.7	0	0
10/24/2010	7:15 PM	25.9	26.1	25.9	90	24.2	0.4	NW	2.7	NW	1012.8	0	0
10/24/2010	7:30 PM	25.9	25.9	25.9	89	24	0.4	NW	2.7	NNW	1013	0	0
10/24/2010	7:45 PM	25.9	25.9	25.9	90	24.2	0.4	NW	1.8	NW	1013.1	0	0
10/24/2010	8:00 PM	26	26	25.9	90	24.2	0	NW	1.8	NW	1013.3	0	0
10/24/2010	8:15 PM	25.9	26	25.9	89	24	0.4	NNE	2.7	NNE	1013.4	0	0
10/24/2010	8:30 PM	26.2	26.2	25.9	87	23.9	0.4	NNE	2.7	NNE	1013.4	0	0
10/24/2010	8:45 PM	26.2	26.3	26.2	87	23.9	0	NNE	1.3	NNE	1013.4	0	0
10/24/2010	9:00 PM	26.2	26.2	26.2	86	23.7	0	NNE	1.3	NNE	1013.5	0	0
10/24/2010	9:15 PM	26.2	26.3	26.2	86	23.7	0.4	NNE	1.3	NNE	1013.3	0	0
10/24/2010	9:30 PM	26.2	26.3	26.2	86	23.7	0	NNE	0.9	NNE	1013.2	0	0
10/24/2010	9:45 PM	26	26.2	26	87	23.7	0	NNE	1.8	NNE	1013.1	0	0
10/24/2010	10:00 PM	25.8	26	25.8	87	23.4	0	NNE	0.9	NNE	1013	0	0
10/24/2010	10:15 PM	25.7	25.8	25.7	86	23.2	0	N	1.8	NW	1013	0	0
10/24/2010	10:30 PM	25.8	25.8	25.7	84	22.9	0.4	NNW	1.8	NNW	1013.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/24/2010	10:45 PM	26	26	25.8	83	22.9	0.4	NW	2.2	NW	1013.1	0	0
10/24/2010	11:00 PM	26	26.1	26	84	23.1	0	NW	0.9	NW	1013.1	0	0
10/24/2010	11:15 PM	25.9	26	25.8	84	23	0	WNW	1.3	WNW	1012.9	0	0
10/24/2010	11:30 PM	25.7	25.9	25.7	84	22.8	0	WNW	0.9	WNW	1012.8	0	0
10/24/2010	11:45 PM	25.7	25.8	25.6	83	22.6	0	WNW	0.9	WNW	1012.8	0	0
10/25/2010	12:00 AM	25.7	25.7	25.6	85	23	0	NW	1.3	NW	1012.6	0	0
10/25/2010	12:15 AM	25.6	25.7	25.6	88	23.4	0	NW	0.9	NW	1012.4	0	0
10/25/2010	12:30 AM	25.3	25.6	25.3	89	23.4	0.4	NW	1.8	NW	1012.2	0	0
10/25/2010	12:45 AM	25.1	25.3	25.1	90	23.3	0	---	0	---	1011.9	0	0
10/25/2010	1:00 AM	24.9	25.1	24.9	91	23.3	0	---	0	---	1011.6	0	0
10/25/2010	1:15 AM	24.8	24.9	24.8	92	23.4	0	---	0	---	1011.4	0	0
10/25/2010	1:30 AM	24.7	24.8	24.7	92	23.3	0	---	0	---	1011.2	0	0
10/25/2010	1:45 AM	24.6	24.7	24.6	93	23.3	0	---	0	---	1011	0	0
10/25/2010	2:00 AM	24.4	24.6	24.4	94	23.4	0	---	0	---	1010.9	0	0
10/25/2010	2:15 AM	24.3	24.5	24.3	94	23.3	0	---	0	---	1010.8	0	0
10/25/2010	2:30 AM	24.3	24.4	24.3	95	23.5	0	---	0	---	1010.8	0	0
10/25/2010	2:45 AM	24.1	24.3	24.1	94	23	0	---	0	---	1010.5	0	0
10/25/2010	3:00 AM	24.3	24.3	24	94	23.3	0	NW	0.9	NW	1010.2	0	0
10/25/2010	3:15 AM	24.4	24.5	24.3	92	23.1	0.4	NW	1.8	NW	1010.2	0	0
10/25/2010	3:30 AM	24.6	24.6	24.4	91	23	0.4	NW	2.2	NNW	1010.3	0	0
10/25/2010	3:45 AM	24.3	24.6	24.3	86	21.8	0	WNW	0.9	WNW	1010.3	0	0
10/25/2010	4:00 AM	24.7	24.7	24.3	81	21.2	0.4	NNW	2.2	NW	1010.3	0	0
10/25/2010	4:15 AM	24.9	25	24.7	81	21.5	0.4	WNW	2.2	NW	1010.2	0	0
10/25/2010	4:30 AM	24.8	24.9	24.8	82	21.5	0.4	WNW	2.2	S	1010.3	0	0
10/25/2010	4:45 AM	24.9	24.9	24.7	81	21.5	0.4	WNW	2.2	SSW	1010.5	0	0
10/25/2010	5:00 AM	24.8	25	24.8	84	21.9	0	WNW	0.4	WNW	1010.6	0	0
10/25/2010	5:15 AM	24.2	24.8	24.2	86	21.7	0	---	0	---	1010.9	0	0
10/25/2010	5:30 AM	24.1	24.2	24	87	21.8	0	N	1.3	N	1011	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/25/2010	5:45 AM	24.3	24.3	24.1	84	21.5	0.4	N	1.8	N	1011.1	0	0
10/25/2010	6:00 AM	24.4	24.4	24.3	84	21.6	0	N	0.9	N	1011.2	0	0
10/25/2010	6:15 AM	24.7	24.7	24.4	83	21.6	0	N	0.9	N	1011.4	0	0
10/25/2010	6:30 AM	25.3	25.3	24.7	78	21.2	0	N	1.8	ESE	1011.6	0	0
10/25/2010	6:45 AM	25.9	25.9	25.3	76	21.4	0	ESE	0.9	ESE	1011.8	0	0
10/25/2010	7:00 AM	26.7	26.7	25.9	74	21.6	0	E	0.9	E	1011.9	0	0
10/25/2010	7:15 AM	27.3	27.3	26.7	74	22.2	0.4	N	2.2	N	1012	0	0
10/25/2010	7:30 AM	27.6	27.6	27.3	74	22.5	0.4	N	1.8	N	1012.2	0	0
10/25/2010	7:45 AM	28.4	28.4	27.6	70	22.4	0	N	0.9	N	1012.3	0	0
10/25/2010	8:00 AM	28.9	28.9	28.4	66	21.9	0.4	NW	0.9	NW	1012.5	0	0
10/25/2010	8:15 AM	29.3	29.3	28.9	67	22.5	0.4	NW	1.8	N	1012.6	0	0
10/25/2010	8:30 AM	29.3	29.3	29.2	65	22	0.4	NNE	2.2	NNE	1012.8	0	0
10/25/2010	8:45 AM	29.8	29.8	29.3	65	22.5	0.4	NNE	1.8	NNE	1012.7	0	0
10/25/2010	9:00 AM	29.8	30.2	29.8	65	22.5	0.9	NNE	2.7	NNE	1012.9	0	0
10/25/2010	9:15 AM	29.9	29.9	29.7	66	22.9	0.9	NE	2.7	NE	1013	0	0
10/25/2010	9:30 AM	30.1	30.1	29.9	66	23	1.8	ENE	4	SE	1012.9	0	0
10/25/2010	9:45 AM	30.7	30.7	30.1	66	23.6	0.9	ENE	4.5	SE	1013	0	0
10/25/2010	10:00 AM	30.6	30.7	30.5	69	24.2	3.1	SE	5.4	SSE	1012.8	0	0
10/25/2010	10:15 AM	30.6	30.7	30.5	68	24	3.1	SE	5.8	SE	1012.9	0	0
10/25/2010	10:30 AM	30.8	30.8	30.6	72	25.2	3.1	SSE	6.3	SE	1012.8	0	0
10/25/2010	10:45 AM	30.6	30.8	30.4	74	25.4	4	SSE	6.7	SSE	1012.6	0	0
10/25/2010	11:00 AM	30.1	30.7	30.1	75	25.1	4.9	SSE	9.4	ESE	1012.5	0	0
10/25/2010	11:15 AM	29.6	30.1	29.6	73	24.3	5.8	SE	9.4	ESE	1012.3	0	0
10/25/2010	11:30 AM	29.6	29.6	29.2	71	23.7	5.4	ESE	8.9	ESE	1012	0	0
10/25/2010	11:45 AM	29.7	29.8	29.6	68	23.1	4	ESE	6.7	ESE	1011.9	0	0
10/25/2010	12:00 PM	29.5	29.7	29.4	72	23.9	2.7	SE	5.4	SE	1011.8	0	0
10/25/2010	12:15 PM	29.4	29.5	29.4	72	23.9	3.1	SE	4.9	SE	1011.7	0	0
10/25/2010	12:30 PM	29.5	29.6	29.4	74	24.4	3.6	SSE	5.8	SE	1011.5	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/25/2010	12:45 PM	29.8	29.8	29.5	74	24.7	3.6	SE	5.8	SE	1011.2	0	0
10/25/2010	1:00 PM	30.1	30.1	29.8	72	24.5	4.5	SE	8	SE	1010.9	0	0
10/25/2010	1:15 PM	30.3	30.3	29.9	74	25.1	4.5	SE	8	SE	1010.8	0	0
10/25/2010	1:30 PM	30.9	31	30.3	72	25.3	4	SE	7.2	SSE	1010.7	0	0
10/25/2010	1:45 PM	30.5	30.9	30.5	74	25.3	4.9	SSE	8	SSE	1010.5	0	0
10/25/2010	2:00 PM	29.9	30.4	29.9	74	24.8	4.5	SE	7.2	SSE	1010.3	0	0
10/25/2010	2:15 PM	29.6	29.9	29.6	72	24	3.6	SE	5.8	ESE	1010.2	0	0
10/25/2010	2:30 PM	29.5	29.6	29.4	75	24.6	3.6	SE	6.3	SE	1009.9	0	0
10/25/2010	2:45 PM	30.1	30.1	29.5	73	24.7	4	SE	6.3	SE	1009.9	0	0
10/25/2010	3:00 PM	29.8	30.1	29.8	76	25.1	3.6	SE	5.8	SE	1010.1	0	0
10/25/2010	3:15 PM	29.9	29.9	29.8	76	25.3	3.6	SSE	5.8	SE	1010.2	0	0
10/25/2010	3:30 PM	29.8	29.9	29.8	77	25.4	3.1	SE	5.4	SE	1010.1	0	0
10/25/2010	3:45 PM	29.4	29.8	29.4	76	24.7	3.1	SE	6.3	SSE	1010.2	0	0
10/25/2010	4:00 PM	29.3	29.4	29.2	76	24.6	4	SE	7.2	SE	1010.1	0	0
10/25/2010	4:15 PM	29.2	29.3	29.2	76	24.5	3.6	SE	6.3	SE	1009.9	0	0
10/25/2010	4:30 PM	29	29.2	29	77	24.6	3.1	SE	5.4	SE	1009.9	0	0
10/25/2010	4:45 PM	28.9	29	28.8	76	24.2	3.6	SE	5.8	SE	1010	0	0
10/25/2010	5:00 PM	28.8	28.9	28.8	78	24.6	3.6	SE	6.3	SE	1010.1	0	0
10/25/2010	5:15 PM	28.8	28.8	28.8	80	25	3.6	SE	5.4	SE	1010.3	0	0
10/25/2010	5:30 PM	28.8	28.8	28.8	80	25	3.1	ESE	4.5	ESE	1010.5	0	0
10/25/2010	5:45 PM	28.6	28.7	28.6	77	24.1	2.2	E	3.6	E	1010.6	0	0
10/25/2010	6:00 PM	28.3	28.6	28.3	76	23.7	2.2	NNE	3.6	NE	1010.7	0	0
10/25/2010	6:15 PM	28.1	28.3	28.1	76	23.4	1.3	NNE	4	NNE	1010.8	0	0
10/25/2010	6:30 PM	27.9	28.1	27.9	77	23.5	0.9	NNE	2.7	N	1010.9	0	0
10/25/2010	6:45 PM	27.8	27.9	27.8	79	23.8	0.4	NNE	1.8	NNE	1011	0	0
10/25/2010	7:00 PM	27.4	27.8	27.4	81	23.8	0	NNE	0.4	NNE	1011.1	0	0
10/25/2010	7:15 PM	27.1	27.4	27.1	82	23.7	0	NNE	0.4	NNE	1011.3	0	0
10/25/2010	7:30 PM	26.9	27	26.9	83	23.8	0	NNE	0.9	NNE	1011.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/25/2010	7:45 PM	27.5	27.5	26.9	81	23.9	0	NNE	0.9	NNE	1011.6	0	0
10/25/2010	8:00 PM	27.2	27.5	27.2	80	23.5	0	NNE	0.4	NNE	1011.8	0	0
10/25/2010	8:15 PM	27	27.2	26.9	82	23.7	0	NNE	0.4	NNE	1011.9	0	0
10/25/2010	8:30 PM	26.8	27	26.8	83	23.7	0	NNE	0.4	NNE	1011.9	0	0
10/25/2010	8:45 PM	26.8	26.8	26.8	84	23.8	0	NNE	0.9	NNE	1012	0	0
10/25/2010	9:00 PM	26.6	26.8	26.6	83	23.5	0	NNE	0.4	NNE	1012.1	0	0
10/25/2010	9:15 PM	26.7	26.7	26.6	84	23.7	0	NNE	0.4	NNE	1012	0	0
10/25/2010	9:30 PM	26.4	26.6	26.4	85	23.7	0	---	0	---	1012.1	0	0
10/25/2010	9:45 PM	26.3	26.4	26.3	85	23.6	0	---	0	---	1012.1	0	0
10/25/2010	10:00 PM	26.1	26.3	26.1	85	23.4	0	---	0	---	1012.2	0	0
10/25/2010	10:15 PM	26	26.1	26	84	23.1	0	NNE	0.4	NNE	1012.1	0	0
10/25/2010	10:30 PM	25.9	26	25.8	85	23.2	0	NNE	0.4	NNE	1012.1	0	0
10/25/2010	10:45 PM	25.9	25.9	25.9	85	23.2	0	---	0	---	1012.1	0	0
10/25/2010	11:00 PM	25.8	25.9	25.8	85	23.1	0	---	0	---	1012.1	0	0
10/25/2010	11:15 PM	25.8	25.8	25.8	84	22.9	0	---	0	---	1012	0	0
10/25/2010	11:30 PM	25.9	25.9	25.8	85	23.2	0	NNE	0.9	NNE	1012	0	0
10/25/2010	11:45 PM	25.9	25.9	25.9	85	23.2	0	NNE	0.4	NNE	1012	0	0
10/26/2010	12:00 AM	25.9	25.9	25.9	84	23	0	NNE	0.4	NNE	1012	0	0
10/26/2010	12:15 AM	25.9	26	25.9	84	23	0	NNE	0.4	NNE	1012	0	0
10/26/2010	12:30 AM	25.9	25.9	25.8	86	23.4	0	---	0	---	1011.9	0	0
10/26/2010	12:45 AM	25.6	25.9	25.6	88	23.4	0	NNE	0.4	NNE	1011.8	0	0
10/26/2010	1:00 AM	25.1	25.6	25.1	89	23.1	0	NNE	0.4	NNE	1011.7	0	0
10/26/2010	1:15 AM	24.8	25.1	24.8	91	23.2	0	---	0	---	1011.6	0	0
10/26/2010	1:30 AM	24.6	24.8	24.6	91	23	0	---	0	---	1011.5	0	0
10/26/2010	1:45 AM	24.7	24.7	24.6	92	23.3	0	---	0	---	1011.3	0	0
10/26/2010	2:00 AM	24.6	24.7	24.6	92	23.2	0	---	0	---	1011.1	0	0
10/26/2010	2:15 AM	24.6	24.6	24.6	92	23.2	0	---	0	---	1011	0	0
10/26/2010	2:30 AM	24.7	24.7	24.6	93	23.5	0	---	0	---	1011	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/26/2010	2:45 AM	24.7	24.7	24.6	92	23.3	0	---	0	---	1010.9	0	0
10/26/2010	3:00 AM	24.9	24.9	24.7	91	23.3	0	NNE	0.9	NNE	1010.8	0	0
10/26/2010	3:15 AM	24.9	24.9	24.9	91	23.4	0	---	0	---	1010.8	0	0
10/26/2010	3:30 AM	24.8	25	24.8	91	23.3	0	---	0	---	1010.7	0	0
10/26/2010	3:45 AM	24.9	24.9	24.8	91	23.3	0	NNE	0.4	NNE	1010.8	0	0
10/26/2010	4:00 AM	24.7	25.1	24.7	90	22.9	0	NNE	1.8	NNE	1010.9	0	0
10/26/2010	4:15 AM	24.4	24.7	24.4	91	22.9	0	NNE	0.4	NNE	1010.9	0	0
10/26/2010	4:30 AM	24.3	24.4	24.3	92	22.9	0	NNE	0.9	NNE	1010.8	0	0
10/26/2010	4:45 AM	24.2	24.3	24.2	92	22.8	0	---	0	---	1010.9	0	0
10/26/2010	5:00 AM	24.1	24.2	24.1	93	22.9	0	NNE	0.4	NNE	1011	0	0
10/26/2010	5:15 AM	24.3	24.3	24.1	92	22.9	0	NNE	1.3	NNE	1011.1	0	0
10/26/2010	5:30 AM	24.8	24.8	24.3	90	23	0	NNE	0.9	NNE	1011.2	0	0
10/26/2010	5:45 AM	24.8	24.9	24.8	89	22.8	0	NNE	0.4	NNE	1011.4	0	0
10/26/2010	6:00 AM	24.7	24.8	24.7	87	22.4	0	NNE	0.9	NNE	1011.6	0	0
10/26/2010	6:15 AM	24.9	24.9	24.7	85	22.2	0	NNE	0.9	NNE	1011.8	0	0
10/26/2010	6:30 AM	25.6	25.6	24.9	83	22.5	0	NNE	0.9	NNE	1011.9	0	0
10/26/2010	6:45 AM	26.2	26.2	25.6	82	22.8	0	NNE	1.8	NNE	1012.1	0	0
10/26/2010	7:00 AM	26.7	26.7	26.2	82	23.3	0	---	0	---	1012.2	0	0
10/26/2010	7:15 AM	27.2	27.2	26.7	78	23	0	NNE	0.4	NNE	1012.3	0	0
10/26/2010	7:30 AM	27.7	27.7	27.2	75	22.8	0.4	NNE	0.9	NNE	1012.5	0	0
10/26/2010	7:45 AM	28.3	28.3	27.7	73	23	0.4	NNE	0.9	NNE	1012.7	0	0
10/26/2010	8:00 AM	28.9	28.9	28.3	68	22.4	0	NNE	0.9	NNE	1012.9	0	0
10/26/2010	8:15 AM	29.4	29.4	28.9	66	22.4	0.4	NNE	0.9	NNE	1013	0	0
10/26/2010	8:30 AM	30.1	30.1	29.4	64	22.5	0	NNE	0.9	NNE	1013.2	0	0
10/26/2010	8:45 AM	30.3	30.3	30.1	66	23.2	0.4	W	2.2	S	1013.3	0	0
10/26/2010	9:00 AM	30.7	30.7	30.3	65	23.3	0.4	NW	2.2	W	1013.4	0	0
10/26/2010	9:15 AM	30.8	30.8	30.7	67	23.9	0.4	SE	2.7	SE	1013.5	0	0
10/26/2010	9:30 AM	30.3	30.7	30.2	70	24.2	1.8	SSE	4	S	1013.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/26/2010	9:45 AM	30.6	30.6	30.2	69	24.2	3.1	SE	4.9	SSE	1013.7	0	0
10/26/2010	10:00 AM	30.5	30.6	30.4	72	24.9	3.6	SSE	5.8	SSE	1013.7	0	0
10/26/2010	10:15 AM	30.8	30.8	30.4	68	24.2	3.1	SE	5.4	SSE	1013.5	0	0
10/26/2010	10:30 AM	30.9	30.9	30.7	65	23.6	4	SSE	5.4	SE	1013.6	0	0
10/26/2010	10:45 AM	30.9	31.1	30.9	65	23.6	4	SSE	6.7	S	1013.5	0	0
10/26/2010	11:00 AM	30.8	31	30.8	69	24.5	4.5	SSE	7.2	SE	1013.2	0	0
10/26/2010	11:15 AM	30.8	30.9	30.8	71	25	4.5	SSE	7.2	SSE	1013.2	0	0
10/26/2010	11:30 AM	30.7	30.8	30.7	72	25.1	4.9	SSE	8	SE	1013	0	0
10/26/2010	11:45 AM	30.9	30.9	30.7	72	25.3	4.9	SSE	8	SE	1012.8	0	0
10/26/2010	12:00 PM	30.5	30.9	30.5	73	25.1	4.9	SSE	8.5	SSE	1012.6	0	0
10/26/2010	12:15 PM	29.7	30.4	29.7	76	25	5.4	SSE	8.5	SSE	1012.4	0	0
10/26/2010	12:30 PM	30.1	30.2	29.7	77	25.6	4.9	SSE	8.9	SSE	1012.2	0	0
10/26/2010	12:45 PM	30.3	30.4	29.9	74	25.2	4.9	SSE	8.9	SSE	1012.1	0	0
10/26/2010	1:00 PM	30.6	30.6	30.3	74	25.4	5.4	SSE	8.5	SSE	1012	0	0
10/26/2010	1:15 PM	30.7	30.7	30.5	73	25.3	4.9	SSE	8.9	SE	1011.6	0	0
10/26/2010	1:30 PM	30.7	30.7	30.6	73	25.3	5.4	SSE	9.4	SSE	1011.4	0	0
10/26/2010	1:45 PM	30.6	30.6	30.4	76	25.8	5.4	SSE	8.5	SSE	1011.4	0	0
10/26/2010	2:00 PM	30.5	30.6	30.3	74	25.3	5.4	SSE	8.9	SSE	1011.2	0	0
10/26/2010	2:15 PM	30.6	30.7	30.5	71	24.7	4.9	SSE	9.8	SE	1011	0	0
10/26/2010	2:30 PM	30.7	30.7	30.4	69	24.3	5.4	SSE	8.5	SSE	1010.9	0	0
10/26/2010	2:45 PM	30.5	30.7	30.4	73	25.1	4.9	SSE	8.5	SE	1011	0	0
10/26/2010	3:00 PM	30.7	30.7	30.4	73	25.3	4.5	SSE	7.2	SSE	1010.9	0	0
10/26/2010	3:15 PM	30.2	30.7	30.2	74	25.1	4.5	SSE	8	SSE	1010.8	0	0
10/26/2010	3:30 PM	30.3	30.4	30.2	73	24.9	4.5	SSE	7.2	SSE	1010.7	0	0
10/26/2010	3:45 PM	30.1	30.3	29.9	75	25.1	4.5	SSE	8	S	1010.7	0	0
10/26/2010	4:00 PM	30.1	30.2	30.1	74	25	4.5	SSE	8	SE	1010.6	0	0
10/26/2010	4:15 PM	30.1	30.2	30.1	74	24.9	4.5	SE	7.2	SSE	1010.6	0	0
10/26/2010	4:30 PM	29.9	30.1	29.9	76	25.2	3.6	SE	5.8	SE	1010.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/26/2010	4:45 PM	29.7	29.9	29.7	76	25	3.1	ESE	5.8	SSE	1010.8	0	0
10/26/2010	5:00 PM	29.4	29.7	29.4	76	24.7	1.3	NNE	4	NE	1010.9	0	0
10/26/2010	5:15 PM	29.3	29.4	29.3	76	24.6	0.9	N	2.7	NNE	1011	0	0
10/26/2010	5:30 PM	29.2	29.3	29.2	76	24.5	1.3	NNE	3.1	NE	1011.1	0	0
10/26/2010	5:45 PM	28.9	29.2	28.9	77	24.4	1.3	NNE	3.6	NNE	1011.2	0	0
10/26/2010	6:00 PM	28.7	28.9	28.7	78	24.4	0.9	NNE	3.1	NE	1011.3	0	0
10/26/2010	6:15 PM	28.5	28.7	28.5	79	24.5	0.4	NNE	2.2	NNE	1011.6	0	0
10/26/2010	6:30 PM	28.4	28.5	28.4	80	24.6	0	NNE	0.9	NNE	1011.7	0	0
10/26/2010	6:45 PM	28.2	28.4	28.2	81	24.6	0	NNE	0.9	NNE	1011.9	0	0
10/26/2010	7:00 PM	28.1	28.2	28.1	81	24.5	0.4	NNW	1.8	N	1012	0	0
10/26/2010	7:15 PM	28	28.1	28	82	24.6	0	NW	1.8	NW	1012.3	0	0
10/26/2010	7:30 PM	27.9	28	27.9	83	24.7	0	NW	0.9	NW	1012.5	0	0
10/26/2010	7:45 PM	27.8	27.9	27.8	83	24.6	0	NW	0.4	NW	1012.7	0	0
10/26/2010	8:00 PM	27.7	27.8	27.7	84	24.7	0	NW	0.9	NW	1012.9	0	0
10/26/2010	8:15 PM	27.5	27.7	27.5	84	24.6	0	NW	0.4	NW	1013	0	0
10/26/2010	8:30 PM	27.3	27.5	27.3	85	24.6	0	---	0	---	1013.1	0	0
10/26/2010	8:45 PM	27.2	27.3	27.2	86	24.7	0	NW	0.4	NW	1013.3	0	0
10/26/2010	9:00 PM	27.1	27.3	27.1	87	24.8	0	---	0	---	1013.3	0	0
10/26/2010	9:15 PM	27.1	27.1	26.9	87	24.7	0	NW	0.4	NW	1013.3	0	0
10/26/2010	9:30 PM	27.1	27.1	27	86	24.5	0	NW	0.9	NW	1013.3	0	0
10/26/2010	9:45 PM	27.1	27.1	27.1	86	24.5	0	NW	0.4	NW	1013.3	0	0
10/26/2010	10:00 PM	26.9	27.1	26.9	86	24.3	0	NW	0.4	NW	1013.3	0	0
10/26/2010	10:15 PM	26.8	26.9	26.8	87	24.5	0	NW	0.4	NW	1013.3	0	0
10/26/2010	10:30 PM	26.6	26.9	26.6	88	24.4	0	---	0	---	1013.3	0	0
10/26/2010	10:45 PM	26.4	26.6	26.4	89	24.5	0	---	0	---	1013.3	0	0
10/26/2010	11:00 PM	26.4	26.5	26.4	90	24.7	0	---	0	---	1013.5	0	0
10/26/2010	11:15 PM	26.3	26.5	26.3	90	24.6	0	---	0	---	1013.3	0	0
10/26/2010	11:30 PM	26.3	26.3	26.2	91	24.7	0	---	0	---	1013.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/26/2010	11:45 PM	26	26.3	26	90	24.2	0	---	0	---	1013.4	0	0
10/27/2010	12:00 AM	25.9	26	25.9	90	24.2	0	---	0	---	1013.3	0	0
10/27/2010	12:15 AM	26.1	26.3	25.9	90	24.3	0	---	0	---	1013.2	0	0
10/27/2010	12:30 AM	26.2	26.2	26	92	24.8	0	NW	0.4	NW	1013.1	0	0
10/27/2010	12:45 AM	25.9	26.2	25.9	91	24.4	0	---	0	---	1012.9	0	0
10/27/2010	1:00 AM	25.9	26.1	25.9	92	24.5	0	---	0	---	1012.8	0	0
10/27/2010	1:15 AM	25.7	25.9	25.7	92	24.3	0	---	0	---	1012.7	0	0
10/27/2010	1:30 AM	25.8	25.8	25.7	92	24.4	0	---	0	---	1012.6	0	0
10/27/2010	1:45 AM	25.9	25.9	25.8	92	24.5	0	---	0	---	1012.5	0	0
10/27/2010	2:00 AM	25.8	25.9	25.8	92	24.4	0	---	0	---	1012.4	0	0
10/27/2010	2:15 AM	26.1	26.1	25.8	92	24.7	0	NW	0.4	NW	1012.2	0	0
10/27/2010	2:30 AM	26.2	26.2	26.1	91	24.6	0	NW	0.4	NW	1012.1	0	0
10/27/2010	2:45 AM	26.3	26.3	26.1	91	24.7	0	---	0	---	1012.1	0	0
10/27/2010	3:00 AM	26.1	26.3	26.1	91	24.5	0	---	0	---	1011.9	0	0
10/27/2010	3:15 AM	25.8	26.1	25.8	90	24.1	0	NW	0.4	NW	1011.8	0	0
10/27/2010	3:30 AM	25.9	25.9	25.8	90	24.2	0	---	0	---	1011.8	0	0
10/27/2010	3:45 AM	25.7	26	25.7	89	23.8	0	---	0	---	1012	0	0
10/27/2010	4:00 AM	25.7	25.8	25.7	90	23.9	0	NW	0.4	NW	1012.1	0	0
10/27/2010	4:15 AM	25.3	25.6	25.3	90	23.6	0	NW	0.4	NW	1012.1	0	0
10/27/2010	4:30 AM	25.7	25.7	25.3	88	23.5	0	NW	0.4	NW	1012.2	0	0
10/27/2010	4:45 AM	25.9	25.9	25.7	88	23.7	0	N	1.8	N	1012.2	0	0
10/27/2010	5:00 AM	25.8	25.9	25.8	87	23.5	0	NW	1.3	NW	1012.3	0	0
10/27/2010	5:15 AM	25.8	25.8	25.8	86	23.3	0	NW	0.4	NW	1012.3	0	0
10/27/2010	5:30 AM	25.8	25.9	25.8	85	23.1	0	NW	0.9	NW	1012.4	0	0
10/27/2010	5:45 AM	25.6	25.9	25.6	87	23.2	0	---	0	---	1012.8	0	0
10/27/2010	6:00 AM	25.6	25.6	25.5	89	23.7	0	NW	1.8	SSE	1013.2	0	0
10/27/2010	6:15 AM	26.3	26.3	25.6	86	23.7	1.3	SE	4.5	SE	1013.3	0	0
10/27/2010	6:30 AM	26.4	26.4	26.3	85	23.7	0.4	ESE	2.7	ESE	1013.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/27/2010	6:45 AM	26.3	26.4	26.3	84	23.4	0.4	ESE	2.2	ESE	1013.6	0	0
10/27/2010	7:00 AM	26.4	26.4	26.3	81	22.9	0.4	E	2.2	ESE	1013.5	0	0
10/27/2010	7:15 AM	26.6	26.7	26.4	83	23.5	0	SSE	2.2	SSE	1013.8	0	0
10/27/2010	7:30 AM	26.6	26.6	26.4	85	23.9	0	NE	1.8	NE	1014.1	0	0
10/27/2010	7:45 AM	26.9	26.9	26.6	85	24.2	0	NNE	2.2	NE	1014.3	0	0
10/27/2010	8:00 AM	27.9	27.9	26.9	81	24.3	0.4	NNE	1.8	NNE	1014.4	0	0
10/27/2010	8:15 AM	29	29	27.9	76	24.3	0.4	NW	1.8	W	1014.5	0	0
10/27/2010	8:30 AM	29.6	29.6	29	71	23.8	0.4	NW	1.3	NW	1014.6	0	0
10/27/2010	8:45 AM	29.9	30.1	29.6	69	23.6	0	NW	0.9	NW	1014.7	0	0
10/27/2010	9:00 AM	29.9	30	29.9	70	23.9	0	WNW	1.3	WNW	1014.9	0	0
10/27/2010	9:15 AM	29.9	30.2	29.9	71	24.1	0.9	SSE	3.1	S	1014.9	0	0
10/27/2010	9:30 AM	29.4	29.9	29.3	74	24.3	1.3	SE	2.7	SE	1015	0	0
10/27/2010	9:45 AM	29.6	29.6	29.4	76	24.9	1.3	SE	3.1	SE	1015	0	0
10/27/2010	10:00 AM	29.4	29.6	29.3	74	24.3	1.8	SE	3.6	SE	1015	0	0
10/27/2010	10:15 AM	29.5	29.5	29.3	76	24.8	1.8	SE	3.1	SE	1015	0	0
10/27/2010	10:30 AM	30.3	30.3	29.5	70	24.2	2.7	SSE	4.5	S	1015	0	0
10/27/2010	10:45 AM	30.4	30.6	30.3	69	24.1	2.2	SSE	3.6	ESE	1014.8	0	0
10/27/2010	11:00 AM	30.5	30.6	30.4	69	24.2	1.8	SSE	4	SE	1014.7	0	0
10/27/2010	11:15 AM	30.4	30.4	30.3	73	25	2.7	SSE	4.5	ESE	1014.5	0	0
10/27/2010	11:30 AM	30.6	30.6	30.2	72	25	3.6	SSE	5.4	SE	1014.2	0	0
10/27/2010	11:45 AM	30.8	30.8	30.5	71	25	3.1	SSE	5.8	S	1014.1	0	0
10/27/2010	12:00 PM	30.7	30.9	30.6	73	25.3	3.6	SSE	5.8	SSE	1013.9	0	0
10/27/2010	12:15 PM	30.8	30.8	30.4	71	25	4	SSE	7.2	S	1013.7	0	0
10/27/2010	12:30 PM	30.4	30.8	30.4	73	25.1	4	SSE	6.7	SSE	1013.6	0	0
10/27/2010	12:45 PM	29.5	30.5	29.5	80	25.7	4	SSE	8	SE	1013.3	0	0
10/27/2010	1:00 PM	29.5	29.5	29.3	78	25.3	4.9	SSE	8	SE	1013.1	0	0
10/27/2010	1:15 PM	29.6	29.8	29.5	77	25.1	4.5	SSE	8.5	SE	1012.9	0	0
10/27/2010	1:30 PM	30.2	30.2	29.6	77	25.7	4	SSE	6.3	SSE	1012.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/27/2010	1:45 PM	30.1	30.3	30	76	25.4	4	SSE	6.3	S	1012.5	0	0
10/27/2010	2:00 PM	30.1	30.2	29.9	75	25.2	4	SE	6.7	ESE	1012.2	0	0
10/27/2010	2:15 PM	29.2	30.2	29.2	76	24.6	4	SSE	6.3	SE	1012	0	0
10/27/2010	2:30 PM	29.7	29.8	29.2	77	25.2	4	SSE	6.7	SSE	1011.9	0	0
10/27/2010	2:45 PM	29.4	29.7	29.3	80	25.6	4	SSE	6.7	SSE	1011.6	0	0
10/27/2010	3:00 PM	29.3	29.4	29.3	79	25.3	3.6	SSE	5.8	SE	1011.6	0	0
10/27/2010	3:15 PM	29.3	29.4	29.3	80	25.5	3.6	SSE	5.8	SSE	1011.7	0	0
10/27/2010	3:30 PM	28.9	29.3	28.9	80	25.1	3.6	SE	5.8	ESE	1011.5	0	0
10/27/2010	3:45 PM	29.1	29.1	28.8	81	25.5	3.1	SSE	4.9	SSE	1011.5	0	0
10/27/2010	4:00 PM	29.1	29.2	29.1	81	25.5	3.1	SE	4.5	SSE	1011.5	0	0
10/27/2010	4:15 PM	29.1	29.1	29.1	80	25.3	2.2	SSE	4.5	SSE	1011.7	0	0
10/27/2010	4:30 PM	29.1	29.1	29.1	79	25.1	1.8	SSE	4	SE	1011.7	0	0
10/27/2010	4:45 PM	29.1	29.2	29.1	79	25.1	1.3	SE	3.1	NNE	1011.7	0	0
10/27/2010	5:00 PM	29	29.1	28.9	81	25.4	0.4	NNW	3.6	NW	1011.6	0	0
10/27/2010	5:15 PM	28.6	28.9	28.6	82	25.2	1.3	NNW	4	NNW	1011.6	0	0
10/27/2010	5:30 PM	28.6	28.6	28.6	82	25.2	0.9	NNW	2.7	NW	1011.7	0	0
10/27/2010	5:45 PM	28.4	28.6	28.4	82	25.1	0.9	NW	3.6	NW	1011.7	0	0
10/27/2010	6:00 PM	28.3	28.4	28.3	82	25	0.9	WNW	2.7	NW	1011.8	0	0
10/27/2010	6:15 PM	28.2	28.3	28.2	81	24.6	0.4	NW	2.7	NNW	1011.9	0	0
10/27/2010	6:30 PM	28.1	28.2	28.1	82	24.7	0.4	WNW	2.7	WNW	1012.1	0	0
10/27/2010	6:45 PM	28.1	28.1	28.1	82	24.7	0.9	WNW	2.7	NW	1012	0	0
10/27/2010	7:00 PM	27.9	28.1	27.9	82	24.5	0.4	WNW	2.2	WNW	1012	0	0
10/27/2010	7:15 PM	27.6	27.9	27.6	82	24.3	0	NW	0.9	NNW	1012.2	0	0
10/27/2010	7:30 PM	27.5	27.6	27.5	83	24.4	0.4	NW	1.8	NNW	1012.2	0	0
10/27/2010	7:45 PM	27.4	27.6	27.4	83	24.2	0.4	WNW	1.8	WNW	1012.3	0	0
10/27/2010	8:00 PM	27.2	27.4	27.2	80	23.4	0.4	NW	1.3	NNW	1012.6	0	0
10/27/2010	8:15 PM	27.1	27.2	27.1	83	23.9	0	NW	1.3	NW	1012.8	0	0
10/27/2010	8:30 PM	26.7	27.1	26.7	84	23.7	0	NW	0.4	NW	1013.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/27/2010	8:45 PM	26.7	26.8	26.6	85	24	0.9	ESE	2.7	ESE	1013.2	0	0
10/27/2010	9:00 PM	27	27	26.7	81	23.5	1.8	ESE	3.1	ESE	1013.3	0	0
10/27/2010	9:15 PM	27.1	27.1	26.9	82	23.7	0.9	ESE	2.2	ESE	1013.3	0	0
10/27/2010	9:30 PM	27	27.1	27	83	23.9	0.4	ESE	0.9	ESE	1013.2	0	0
10/27/2010	9:45 PM	26.9	27	26.9	83	23.8	0	ESE	0.4	ESE	1013.4	0	0
10/27/2010	10:00 PM	26.8	26.9	26.7	84	23.9	0.4	ESE	1.8	ESE	1013.6	0	0
10/27/2010	10:15 PM	26.8	26.9	26.8	83	23.7	0	ESE	1.3	ESE	1013.5	0	0
10/27/2010	10:30 PM	26.8	26.9	26.8	84	23.9	0	ESE	0.9	ESE	1013.3	0	0
10/27/2010	10:45 PM	26.6	26.8	26.5	89	24.6	0	ESE	0.4	ESE	1013.3	0	0
10/27/2010	11:00 PM	26.4	26.6	26.4	88	24.3	0	ESE	0.4	ESE	1013.2	0	0
10/27/2010	11:15 PM	26.2	26.4	26.2	88	24	0	ESE	0.4	ESE	1013	0	0
10/27/2010	11:30 PM	26	26.2	25.9	87	23.7	0	ESE	0.4	ESE	1012.8	0	0
10/27/2010	11:45 PM	26.2	26.2	26	88	24	0	---	0	---	1012.6	0	0
10/28/2010	12:00 AM	26.1	26.2	26.1	89	24.2	0	---	0	---	1012.5	0	0
10/28/2010	12:15 AM	26.2	26.2	26.1	88	24	0	ESE	0.4	ESE	1012.5	0	0
10/28/2010	12:30 AM	26.2	26.2	26.2	86	23.7	0	ESE	0.9	ESE	1012.2	0	0
10/28/2010	12:45 AM	26.3	26.3	26.2	84	23.4	0	ESE	0.9	ESE	1012.1	0	0
10/28/2010	1:00 AM	26.2	26.3	26.2	85	23.5	0	---	0	---	1011.8	0	0
10/28/2010	1:15 AM	26.1	26.2	26.1	86	23.6	0	---	0	---	1011.8	0	0
10/28/2010	1:30 AM	26.1	26.2	26.1	89	24.1	0	---	0	---	1011.5	0	0
10/28/2010	1:45 AM	25.8	26.1	25.8	90	24	0	---	0	---	1011.4	0	0
10/28/2010	2:00 AM	25.6	25.8	25.6	90	23.8	0	---	0	---	1011.4	0	0
10/28/2010	2:15 AM	25.5	25.7	25.5	90	23.7	0	---	0	---	1011.2	0	0
10/28/2010	2:30 AM	25.5	25.5	25.4	91	23.9	0	---	0	---	1011.2	0	0
10/28/2010	2:45 AM	25.6	25.7	25.5	90	23.8	0	ESE	0.4	ESE	1011.1	0	0
10/28/2010	3:00 AM	25.7	25.7	25.6	89	23.7	0	ESE	0.9	ESE	1011	0	0
10/28/2010	3:15 AM	25.7	25.8	25.7	89	23.8	0	ESE	1.8	ESE	1010.9	0	0
10/28/2010	3:30 AM	25.7	25.8	25.7	89	23.8	0	ESE	0.4	ESE	1011	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/28/2010	3:45 AM	25.7	25.7	25.6	90	23.9	0	ESE	0.9	ESE	1011.2	0	0
10/28/2010	4:00 AM	25.6	25.7	25.6	90	23.8	0	ESE	0.4	ESE	1011.2	0	0
10/28/2010	4:15 AM	25.6	25.6	25.5	90	23.8	0	---	0	---	1011.2	0	0
10/28/2010	4:30 AM	25.7	25.7	25.6	90	23.9	0	ESE	0.4	ESE	1011.2	0	0
10/28/2010	4:45 AM	25.8	25.8	25.7	89	23.9	0	NNE	0.9	NNE	1011.1	0	0
10/28/2010	5:00 AM	25.9	25.9	25.8	88	23.8	0	NNE	0.9	NNE	1011.3	0	0
10/28/2010	5:15 AM	26.2	26.2	26	88	24	0	NNE	0.9	NNE	1011.1	0	0
10/28/2010	5:30 AM	26.2	26.2	26.2	87	23.8	0	NNE	1.8	NNE	1011.6	0	0
10/28/2010	5:45 AM	26.1	26.2	26.1	85	23.3	0	NNW	2.2	NNW	1011.5	0	0
10/28/2010	6:00 AM	25.9	26.1	25.9	86	23.4	1.3	NNE	4	NE	1011.7	0	0
10/28/2010	6:15 AM	25.9	25.9	25.8	86	23.4	0.9	NNE	2.7	NNE	1011.9	0	0
10/28/2010	6:30 AM	26	26.1	25.9	86	23.5	0	NNE	1.8	NNE	1011.9	0	0
10/28/2010	6:45 AM	26.1	26.1	26	87	23.7	0	NNE	0.4	NNE	1012.2	0	0
10/28/2010	7:00 AM	26.1	26.1	26	88	23.9	0	NNE	0.9	NNE	1012.4	0	0
10/28/2010	7:15 AM	26.4	26.4	26	88	24.2	0	NNE	0.4	NNE	1012.6	0	0
10/28/2010	7:30 AM	27.2	27.2	26.4	85	24.5	0	NNE	0.9	NNE	1012.6	0	0
10/28/2010	7:45 AM	27.4	27.4	27.2	84	24.4	0	NNE	0.4	NNE	1012.5	0	0
10/28/2010	8:00 AM	27.8	27.8	27.3	82	24.4	0	NNE	0.4	NNE	1012.7	0	0
10/28/2010	8:15 AM	28.6	28.6	27.8	78	24.4	0.4	NNE	0.9	NNE	1012.9	0	0
10/28/2010	8:30 AM	28.8	28.8	28.6	76	24.1	0.4	NNW	1.8	NNW	1012.9	0	0
10/28/2010	8:45 AM	29.4	29.4	28.8	73	24.1	0.4	WNW	1.8	WNW	1012.8	0	0
10/28/2010	9:00 AM	30.1	30.1	29.4	72	24.5	0.4	WNW	1.8	W	1012.9	0	0
10/28/2010	9:15 AM	30.4	30.5	30.1	68	23.9	0.4	WNW	1.8	WNW	1012.9	0	0
10/28/2010	9:30 AM	30.9	30.9	30.4	67	24	0.4	WNW	2.2	WNW	1013.1	0	0
10/28/2010	9:45 AM	31.1	31.1	30.9	64	23.4	0.4	W	2.7	SSE	1013.1	0	0
10/28/2010	10:00 AM	30.9	31.3	30.9	64	23.3	1.3	W	3.6	WSW	1013	0	0
10/28/2010	10:15 AM	30.9	31.1	30.8	68	24.3	1.3	WSW	3.1	WSW	1013.1	0	0
10/28/2010	10:30 AM	30	30.9	29.9	70	23.9	2.2	S	4.5	SSE	1013.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/28/2010	10:45 AM	29.6	29.9	29.4	73	24.2	2.7	S	4.5	S	1012.9	0	0
10/28/2010	11:00 AM	30.2	30.3	29.6	71	24.3	1.8	S	4	S	1012.5	0	0
10/28/2010	11:15 AM	30.3	30.9	30.2	71	24.4	2.2	SSE	4.5	S	1012.4	0	0
10/28/2010	11:30 AM	30.5	30.5	30	70	24.4	1.8	S	3.6	SSE	1012.1	0	0
10/28/2010	11:45 AM	29.9	30.6	29.9	70	23.9	2.2	S	4	S	1012.1	0	0
10/28/2010	12:00 PM	29.9	29.9	29.6	72	24.3	1.8	S	3.6	S	1011.7	0	0
10/28/2010	12:15 PM	30.7	30.9	30	69	24.3	2.2	S	4.9	S	1011.5	0	0
10/28/2010	12:30 PM	30.5	30.7	30.2	69	24.2	2.7	S	5.4	S	1011.3	0	0
10/28/2010	12:45 PM	29.8	30.7	29.8	73	24.5	3.1	S	5.8	SSE	1010.8	0	0
10/28/2010	1:00 PM	29.4	29.8	29.4	77	25	3.6	SSE	6.3	SSE	1010.6	0	0
10/28/2010	1:15 PM	27.4	29.4	27.4	82	24.1	3.1	SE	6.3	ESE	1010.8	1.02	11.7
10/28/2010	1:30 PM	25.8	27.4	25.8	90	24	1.8	NNE	4.5	NNE	1010.9	9.4	115.3
10/28/2010	1:45 PM	25.2	25.8	25.2	93	24	3.1	E	5.4	ENE	1010.8	4.32	82.6
10/28/2010	2:00 PM	24.7	25.3	24.7	93	23.5	1.8	ENE	4.5	ENE	1011.1	2.29	41.1
10/28/2010	2:15 PM	24.5	24.8	24.4	93	23.3	0.4	W	2.7	WNW	1011	0.51	6.6
10/28/2010	2:30 PM	24.6	24.7	24.5	94	23.6	0.4	WNW	2.7	W	1011	0.76	13
10/28/2010	2:45 PM	24.8	24.8	24.6	94	23.7	0.4	WNW	2.7	W	1010.9	0	0
10/28/2010	3:00 PM	24.9	24.9	24.8	94	23.9	0.4	NNE	2.7	N	1010.5	0	0
10/28/2010	3:15 PM	25.2	25.2	24.9	93	24	0.4	NNE	3.1	N	1010.2	0	0
10/28/2010	3:30 PM	25.3	25.3	25.2	91	23.8	0.9	NNE	2.7	N	1010.3	0	0
10/28/2010	3:45 PM	25.4	25.4	25.3	90	23.7	0	NNE	0.9	NNE	1010.2	0	0
10/28/2010	4:00 PM	25.7	25.7	25.4	91	24.1	0	NW	1.3	NNW	1010	0	0
10/28/2010	4:15 PM	25.8	25.8	25.6	91	24.2	0.4	NW	1.8	WNW	1010.1	0	0
10/28/2010	4:30 PM	25.8	25.8	25.7	89	23.8	0.4	NW	1.8	N	1010.2	0	0
10/28/2010	4:45 PM	25.9	25.9	25.8	88	23.7	0.4	N	2.2	N	1010.1	0	0
10/28/2010	5:00 PM	25.9	25.9	25.9	89	23.9	0	N	0.9	N	1010	0	0
10/28/2010	5:15 PM	25.7	25.9	25.7	89	23.8	0	WNW	0.4	WNW	1010.1	0	0
10/28/2010	5:30 PM	25.8	25.8	25.7	90	24	0	NNW	1.3	NNW	1010.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/28/2010	5:45 PM	25.7	25.8	25.7	91	24.1	0	---	0	---	1010.4	0	0
10/28/2010	6:00 PM	25.7	25.8	25.7	92	24.3	0	NNW	0.9	NNW	1010.6	0	0
10/28/2010	6:15 PM	25.4	25.7	25.4	90	23.6	0.9	SSE	2.2	NNW	1010.6	0	0
10/28/2010	6:30 PM	25.3	25.4	25.3	90	23.6	0.9	SSE	2.2	SSE	1010.7	0	0
10/28/2010	6:45 PM	25.3	25.3	25.3	90	23.6	0.4	SSE	0.9	SSE	1010.8	0	0
10/28/2010	7:00 PM	25.4	25.4	25.3	89	23.5	0.4	SSE	1.8	SSE	1010.8	0	0
10/28/2010	7:15 PM	25.2	25.4	25.2	90	23.4	0	---	0	---	1010.9	0	0
10/28/2010	7:30 PM	25.1	25.2	24.9	92	23.7	0	---	0	---	1011.1	0	0
10/28/2010	7:45 PM	24.8	25.1	24.7	93	23.6	0	---	0	---	1011	0	0
10/28/2010	8:00 PM	24.8	24.8	24.7	92	23.4	0	NNE	0.9	NNE	1011	0	0
10/28/2010	8:15 PM	25	25	24.8	92	23.6	0	NNE	1.8	NNE	1011.2	0	0
10/28/2010	8:30 PM	24.9	25	24.9	91	23.4	0	NNE	0.9	NNE	1011.3	0	0
10/28/2010	8:45 PM	24.8	24.9	24.8	90	23.1	0	NNE	2.2	NNE	1011.2	0	0
10/28/2010	9:00 PM	24.8	24.8	24.8	90	23	0	NNE	0.4	NNE	1011.1	0	0
10/28/2010	9:15 PM	24.6	24.8	24.6	92	23.2	0	NNE	0.9	NNE	1011	0	0
10/28/2010	9:30 PM	24.3	24.6	24.3	92	22.9	0	NNE	0.9	NNE	1011.1	0	0
10/28/2010	9:45 PM	24.4	24.4	24.3	93	23.2	0	NNE	0.9	NNE	1011.1	0	0
10/28/2010	10:00 PM	24.3	24.4	24.3	93	23.1	0	NNE	0.9	NNE	1011.2	0	0
10/28/2010	10:15 PM	24.4	24.4	24.3	94	23.4	0	NNE	0.9	NNE	1011.1	0	0
10/28/2010	10:30 PM	24.4	24.4	24.3	93	23.2	0	NNE	0.9	NNE	1011.2	0	0
10/28/2010	10:45 PM	24.4	24.4	24.3	94	23.4	0	NNE	0.4	NNE	1011.2	0	0
10/28/2010	11:00 PM	24.3	24.4	24.3	94	23.3	0	NNE	0.4	NNE	1011.1	0	0
10/28/2010	11:15 PM	24.5	24.5	24.3	94	23.5	0	NNE	0.9	NNE	1011.2	0	0
10/28/2010	11:30 PM	24.7	24.8	24.5	94	23.7	0.4	ENE	1.8	ENE	1011.1	0	0
10/28/2010	11:45 PM	24.7	24.8	24.6	94	23.7	0	ENE	0.4	ENE	1011.1	0	0
10/29/2010	12:00 AM	24.7	24.7	24.6	94	23.7	0	ENE	0.9	ENE	1010.9	0	0
10/29/2010	12:15 AM	24.5	24.7	24.4	93	23.3	0	ENE	0.4	ENE	1010.8	0	0
10/29/2010	12:30 AM	24.7	24.7	24.4	94	23.6	0	ENE	0.4	ENE	1010.7	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/29/2010	12:45 AM	24.5	24.7	24.4	93	23.3	0	ENE	0.9	ENE	1010.6	0	0
10/29/2010	1:00 AM	24.7	24.7	24.5	93	23.5	0	ENE	0.4	ENE	1010.4	0	0
10/29/2010	1:15 AM	24.4	24.7	24.4	92	23.1	0	---	0	---	1010.4	0	0
10/29/2010	1:30 AM	24.3	24.4	24.2	92	22.9	0	---	0	---	1010.2	0	0
10/29/2010	1:45 AM	24.4	24.4	24.3	92	23.1	0	ENE	0.4	ENE	1010.1	0	0
10/29/2010	2:00 AM	24.2	24.4	24.2	91	22.6	0	ENE	0.4	ENE	1010	0	0
10/29/2010	2:15 AM	24.1	24.2	24.1	90	22.4	0	ENE	0.4	ENE	1010	0	0
10/29/2010	2:30 AM	24	24.2	24	92	22.6	0	---	0	---	1009.9	0	0
10/29/2010	2:45 AM	23.8	24	23.8	92	22.4	0	---	0	---	1009.8	0	0
10/29/2010	3:00 AM	23.6	23.8	23.6	93	22.4	0	---	0	---	1009.8	0	0
10/29/2010	3:15 AM	23.5	23.6	23.4	94	22.5	0	---	0	---	1009.9	0	0
10/29/2010	3:30 AM	23.4	23.5	23.3	93	22.2	0	WNW	1.8	ENE	1009.9	0	0
10/29/2010	3:45 AM	23.5	23.5	23.4	93	22.3	0	WNW	0.4	WNW	1009.8	0	0
10/29/2010	4:00 AM	23.8	23.8	23.5	92	22.5	0	WNW	0.9	WNW	1009.8	0	0
10/29/2010	4:15 AM	23.9	23.9	23.8	91	22.3	0	WNW	1.8	NNW	1009.9	0	0
10/29/2010	4:30 AM	23.9	23.9	23.8	90	22.1	0	N	1.3	N	1009.9	0	0
10/29/2010	4:45 AM	23.8	23.9	23.8	90	22.1	0	N	0.4	N	1009.9	0	0
10/29/2010	5:00 AM	23.8	23.8	23.7	87	21.5	0	N	0.9	N	1009.8	0	0
10/29/2010	5:15 AM	24.1	24.1	23.8	84	21.2	0	N	1.8	N	1009.8	0	0
10/29/2010	5:30 AM	24.1	24.1	24.1	84	21.2	0	N	0.9	N	1009.9	0	0
10/29/2010	5:45 AM	23.9	24.1	23.9	84	21.1	0	N	1.8	N	1010.3	0	0
10/29/2010	6:00 AM	24.4	24.4	23.9	81	20.9	0.9	N	2.7	NNE	1010.5	0	0
10/29/2010	6:15 AM	24.4	24.5	24.4	81	21	0	N	1.8	N	1010.7	0	0
10/29/2010	6:30 AM	24.8	24.8	24.4	82	21.5	0	N	0.4	N	1010.8	0	0
10/29/2010	6:45 AM	25.1	25.1	24.8	86	22.6	0	N	0.4	N	1011	0	0
10/29/2010	7:00 AM	25.3	25.3	25	85	22.6	0	N	0.4	N	1011.4	0	0
10/29/2010	7:15 AM	25.9	25.9	25.3	82	22.6	0	N	0.9	N	1011.4	0	0
10/29/2010	7:30 AM	26.6	26.6	25.9	77	22.2	0	N	0.4	N	1011.4	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/29/2010	7:45 AM	27.2	27.2	26.6	77	22.8	0	N	0.4	N	1011.5	0	0
10/29/2010	8:00 AM	27.8	27.8	27.2	77	23.4	0	N	0.9	N	1011.6	0	0
10/29/2010	8:15 AM	27.8	27.9	27.8	75	23	0	N	1.8	N	1011.8	0	0
10/29/2010	8:30 AM	27.9	27.9	27.6	77	23.5	0.4	N	0.9	N	1012	0	0
10/29/2010	8:45 AM	28.1	28.2	27.9	73	22.8	0.4	NNW	1.3	NNW	1012.3	0	0
10/29/2010	9:00 AM	28.6	28.6	28.1	68	22.1	0	NW	0.9	NNW	1012.5	0	0
10/29/2010	9:15 AM	29.1	29.1	28.6	67	22.3	0.4	NW	1.8	NW	1012.7	0	0
10/29/2010	9:30 AM	29.2	29.3	29.1	65	22	0.4	NW	0.9	NW	1012.7	0	0
10/29/2010	9:45 AM	29.4	29.5	29.2	67	22.6	0.4	N	1.8	N	1012.6	0	0
10/29/2010	10:00 AM	30	30	29.4	65	22.7	0	NNW	1.3	N	1012.6	0	0
10/29/2010	10:15 AM	29.7	30.1	29.4	65	22.4	0.9	S	3.1	S	1012.5	0	0
10/29/2010	10:30 AM	30	30.2	29.7	65	22.7	0.4	NNW	2.2	NNW	1012.6	0	0
10/29/2010	10:45 AM	30.6	30.6	30	64	23	0.9	NW	2.2	NW	1012.4	0	0
10/29/2010	11:00 AM	30.6	30.8	30.6	58	21.4	0.4	WNW	2.2	WNW	1012.3	0	0
10/29/2010	11:15 AM	29.8	30.6	29.8	62	21.7	1.3	SSE	3.6	SSE	1012.2	0	0
10/29/2010	11:30 AM	29.7	29.7	29.5	64	22.1	1.8	SSE	3.6	SE	1012.2	0	0
10/29/2010	11:45 AM	29.8	29.8	29.4	62	21.8	1.8	SSE	3.6	S	1012.1	0	0
10/29/2010	12:00 PM	29.9	30.1	29.8	63	22.1	2.2	S	4.5	S	1011.8	0	0
10/29/2010	12:15 PM	29.6	29.9	29.6	64	22.1	2.7	S	4.5	S	1011.6	0	0
10/29/2010	12:30 PM	29.6	29.7	29.6	67	22.8	2.2	S	3.6	S	1011.6	0	0
10/29/2010	12:45 PM	29.4	29.7	29.3	68	22.9	2.2	SSE	4.5	S	1011.4	0	0
10/29/2010	1:00 PM	29.4	29.8	29.4	68	22.9	2.2	S	4.5	SE	1011.2	0	0
10/29/2010	1:15 PM	29.6	29.8	29.3	68	23	2.2	SSE	4	S	1010.9	0	0
10/29/2010	1:30 PM	29.7	29.8	29.6	66	22.6	1.8	SE	3.6	SE	1010.7	0	0
10/29/2010	1:45 PM	29.7	29.9	29.7	67	22.9	2.2	SE	3.6	SE	1010.6	0	0
10/29/2010	2:00 PM	29.8	29.8	29.6	69	23.5	1.8	SSE	3.6	S	1010.3	0	0
10/29/2010	2:15 PM	29.9	29.9	29.6	69	23.6	1.8	SSE	4.5	S	1010.2	0	0
10/29/2010	2:30 PM	29.8	29.9	29.7	68	23.2	1.3	SE	3.1	SE	1010.2	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/29/2010	2:45 PM	29.8	29.8	29.7	69	23.5	1.3	SSE	3.1	SE	1010.2	0	0
10/29/2010	3:00 PM	29.9	29.9	29.8	70	23.9	1.3	SSE	3.1	SSW	1010.1	0	0
10/29/2010	3:15 PM	30.1	30.1	29.9	70	24	2.2	SE	4	SE	1010.1	0	0
10/29/2010	3:30 PM	29.7	30.1	29.7	72	24.1	2.7	SSE	4	SSE	1010.1	0	0
10/29/2010	3:45 PM	29.7	29.9	29.7	74	24.5	2.7	SSE	4.5	SE	1010.2	0	0
10/29/2010	4:00 PM	29.3	29.7	29.3	72	23.8	2.2	SE	3.6	SE	1010.2	0	0
10/29/2010	4:15 PM	29.4	29.5	29.3	73	24.1	2.2	SE	4	SSE	1010.2	0	0
10/29/2010	4:30 PM	29.3	29.4	29.3	75	24.4	2.7	SSE	4.9	SSE	1010.4	0	0
10/29/2010	4:45 PM	29.2	29.3	29.2	74	24.1	2.7	SSE	5.4	SE	1010.5	0	0
10/29/2010	5:00 PM	27.9	29.2	27.9	75	23.1	3.6	ESE	6.3	ESE	1010.5	0	0
10/29/2010	5:15 PM	28.1	28.1	27.8	70	22.1	2.2	ESE	3.6	ESE	1010.6	0	0
10/29/2010	5:30 PM	28	28.1	27.9	75	23.2	1.8	ESE	3.6	ESE	1010.7	0	0
10/29/2010	5:45 PM	28	28.1	28	77	23.6	0.4	ESE	2.2	ESE	1010.8	0	0
10/29/2010	6:00 PM	28	28	27.9	79	24	0	ESE	0.9	ESE	1010.9	0	0
10/29/2010	6:15 PM	27.8	28	27.8	78	23.6	0	ESE	0.9	ESE	1011	0	0
10/29/2010	6:30 PM	27.8	27.8	27.7	80	24	0	---	0	---	1011.2	0	0
10/29/2010	6:45 PM	27.5	27.8	27.5	79	23.5	0	ESE	0.9	ESE	1011.5	0	0
10/29/2010	7:00 PM	27.7	27.7	27.6	77	23.3	1.3	ENE	3.1	NE	1011.8	0	0
10/29/2010	7:15 PM	27.4	27.7	27.4	77	23.1	1.8	NE	4.5	NE	1011.7	0	0
10/29/2010	7:30 PM	27.3	27.4	27.3	77	22.9	1.3	NNE	3.1	NNE	1011.8	0	0
10/29/2010	7:45 PM	27.2	27.3	27.2	77	22.8	0.9	NNE	4	NNE	1011.8	0	0
10/29/2010	8:00 PM	27.1	27.2	27.1	76	22.5	0.4	NNW	2.2	NNW	1011.7	0	0
10/29/2010	8:15 PM	26.9	27.1	26.9	78	22.8	0.9	NNW	3.1	NNW	1011.9	0	0
10/29/2010	8:30 PM	26.8	26.9	26.8	77	22.4	0.4	NNE	3.1	NW	1012.1	0	0
10/29/2010	8:45 PM	26.7	26.8	26.7	77	22.4	0.4	NW	1.8	NNW	1012.4	0	0
10/29/2010	9:00 PM	26.6	26.7	26.6	77	22.2	0	NNE	0.9	NNE	1012.8	0	0
10/29/2010	9:15 PM	26.6	26.6	26.5	77	22.2	0	NNE	1.8	NNE	1012.9	0	0
10/29/2010	9:30 PM	26.6	26.6	26.5	77	22.2	0	NNE	0.4	NNE	1012.9	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/29/2010	9:45 PM	26.6	26.6	26.6	78	22.4	0	NNE	0.4	NNE	1012.9	0	0
10/29/2010	10:00 PM	26.4	26.6	26.4	79	22.5	0	NNE	1.8	NNE	1012.9	0	0
10/29/2010	10:15 PM	26.2	26.4	26.2	82	22.9	0	---	0	---	1012.9	0	0
10/29/2010	10:30 PM	25.9	26.3	25.9	83	22.8	0	---	0	---	1013	0	0
10/29/2010	10:45 PM	25.8	25.9	25.8	86	23.3	0	---	0	---	1013	0	0
10/29/2010	11:00 PM	25.6	25.8	25.6	87	23.3	0	---	0	---	1013	0	0
10/29/2010	11:15 PM	25.6	25.6	25.6	87	23.3	0	---	0	---	1012.8	0	0
10/29/2010	11:30 PM	25.9	25.9	25.6	89	23.9	0	---	0	---	1012.8	0	0
10/29/2010	11:45 PM	25.8	25.9	25.8	89	23.8	0	---	0	---	1012.6	0	0
10/30/2010	12:00 AM	25.4	25.8	25.4	89	23.5	0	---	0	---	1012.4	0	0
10/30/2010	12:15 AM	25.7	25.7	25.5	90	23.9	0	NNE	0.4	NNE	1012.2	0	0
10/30/2010	12:30 AM	25.3	25.7	25.3	88	23.2	0	---	0	---	1012.1	0	0
10/30/2010	12:45 AM	25.6	25.6	25.3	88	23.4	0	---	0	---	1012	0	0
10/30/2010	1:00 AM	25.6	25.7	25.5	89	23.7	0	NNE	0.4	NNE	1011.9	0	0
10/30/2010	1:15 AM	25.5	25.6	25.5	88	23.4	0	NNE	0.4	NNE	1011.7	0	0
10/30/2010	1:30 AM	25.3	25.5	25.3	84	22.4	0	NNW	2.2	NNW	1011.6	0	0
10/30/2010	1:45 AM	25.4	25.4	25.3	84	22.5	0	NNW	1.8	NNW	1011.2	0	0
10/30/2010	2:00 AM	25.5	25.5	25.4	82	22.2	0	NNW	0.4	NNW	1010.9	0	0
10/30/2010	2:15 AM	25.5	25.5	25.5	79	21.6	0	NNW	0.9	NNW	1010.9	0	0
10/30/2010	2:30 AM	25.2	25.5	25.2	84	22.3	0	---	0	---	1010.9	0	0
10/30/2010	2:45 AM	24.9	25.2	24.9	83	21.9	0	NNW	0.4	NNW	1010.8	0	0
10/30/2010	3:00 AM	24.8	24.9	24.8	83	21.7	0	---	0	---	1010.7	0	0
10/30/2010	3:15 AM	24.6	24.9	24.6	87	22.2	0	---	0	---	1011	0	0
10/30/2010	3:30 AM	24.5	24.6	24.4	90	22.8	0	---	0	---	1011	0	0
10/30/2010	3:45 AM	24.1	24.5	24.1	89	22.2	0	---	0	---	1011.1	0	0
10/30/2010	4:00 AM	24.2	24.2	24	89	22.2	0	---	0	---	1010.9	0	0
10/30/2010	4:15 AM	24.2	24.2	24.1	91	22.7	0	---	0	---	1011.1	0	0
10/30/2010	4:30 AM	24.3	24.3	24.1	91	22.7	0	---	0	---	1011.3	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/30/2010	4:45 AM	24.3	24.4	24.3	92	22.9	0	---	0	---	1011.5	0	0
10/30/2010	5:00 AM	24.6	24.6	24.3	92	23.2	0	---	0	---	1011.3	0	0
10/30/2010	5:15 AM	24.6	24.6	24.5	92	23.2	0	NNW	0.4	NNW	1011.4	0	0
10/30/2010	5:30 AM	24.6	24.7	24.6	92	23.2	0	---	0	---	1011.8	0	0
10/30/2010	5:45 AM	24.8	24.8	24.6	91	23.2	0	NNW	0.9	NNW	1011.8	0	0
10/30/2010	6:00 AM	24.8	24.8	24.8	90	23.1	0	NNW	0.4	NNW	1012.1	0	0
10/30/2010	6:15 AM	24.8	24.8	24.8	91	23.2	0	NNW	0.4	NNW	1012.1	0	0
10/30/2010	6:30 AM	24.7	24.8	24.7	91	23.2	0	NNW	0.9	NNW	1012.4	0	0
10/30/2010	6:45 AM	25.3	25.3	24.7	89	23.3	0	NNW	0.4	NNW	1012.4	0	0
10/30/2010	7:00 AM	26.4	26.4	25.3	85	23.7	0	NNW	0.4	NNW	1012.4	0	0
10/30/2010	7:15 AM	27.7	27.7	26.4	80	23.9	0	---	0	---	1012.6	0	0
10/30/2010	7:30 AM	28.1	28.1	27.6	78	23.9	0	NNW	0.4	NNW	1012.6	0	0
10/30/2010	7:45 AM	27.9	28.2	27.9	78	23.7	0	NNW	1.8	NNW	1012.5	0	0
10/30/2010	8:00 AM	28.1	28.1	27.9	77	23.6	0	NNW	1.3	NNW	1012.6	0	0
10/30/2010	8:15 AM	28.6	28.6	28.1	76	24	0.4	NNW	0.9	NNW	1012.8	0	0
10/30/2010	8:30 AM	28.9	28.9	28.6	70	22.9	0.4	NW	0.9	NNW	1013.1	0	0
10/30/2010	8:45 AM	29.3	29.3	28.9	72	23.7	0.4	NW	1.8	NW	1013.4	0	0
10/30/2010	9:00 AM	29.4	29.4	29.3	71	23.6	0.4	NW	1.8	WNW	1013.5	0	0
10/30/2010	9:15 AM	30	30	29.4	70	23.9	0.4	WNW	2.2	NW	1013.8	0	0
10/30/2010	9:30 AM	30.2	30.3	30	68	23.7	0.9	WNW	2.2	WNW	1013.8	0	0
10/30/2010	9:45 AM	30.3	30.3	30.2	67	23.5	0.9	WNW	2.2	WNW	1014	0	0
10/30/2010	10:00 AM	30.5	30.5	30.3	65	23.2	0.9	WNW	2.7	NNW	1013.9	0	0
10/30/2010	10:15 AM	30.8	30.8	30.3	66	23.7	0.9	WNW	2.7	W	1013.7	0	0
10/30/2010	10:30 AM	31.3	31.3	30.8	63	23.4	0.9	WNW	2.7	NW	1013.5	0	0
10/30/2010	10:45 AM	31.3	31.4	31.3	62	23.1	1.3	WNW	3.1	WSW	1013.3	0	0
10/30/2010	11:00 AM	31.3	31.3	31.1	60	22.6	1.3	W	3.1	SW	1013.2	0	0
10/30/2010	11:15 AM	31.6	31.6	31.3	58	22.3	1.3	SW	3.6	WSW	1013	0	0
10/30/2010	11:30 AM	31.8	31.8	31.4	56	21.9	1.3	SW	3.1	S	1012.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/30/2010	11:45 AM	31.9	32.1	31.7	54	21.5	1.3	WSW	3.6	WSW	1012.5	0	0
10/30/2010	12:00 PM	31.1	31.9	31.1	63	23.2	2.2	S	4.5	SE	1012.3	0	0
10/30/2010	12:15 PM	30.2	31.1	30.2	66	23.2	2.7	S	5.4	SE	1012.1	0	0
10/30/2010	12:30 PM	30.7	30.9	30.2	67	23.9	1.8	S	4	S	1011.6	0	0
10/30/2010	12:45 PM	31.2	31.4	30.7	67	24.3	1.8	SSW	3.6	S	1011.3	0	0
10/30/2010	1:00 PM	30.8	31.3	30.8	71	24.9	1.3	S	3.1	SSE	1011.1	0	0
10/30/2010	1:15 PM	30.9	31.2	30.8	70	24.8	1.8	S	4	S	1011	0	0
10/30/2010	1:30 PM	30.8	30.8	30.6	70	24.7	2.7	SSE	4.5	SSE	1010.8	0	0
10/30/2010	1:45 PM	30.3	30.8	30.2	73	24.9	1.8	SE	3.6	ESE	1010.7	0	0
10/30/2010	2:00 PM	30.8	30.8	30.3	71	25	2.2	SSE	4.9	SSE	1010.6	0	0
10/30/2010	2:15 PM	30.9	31.1	30.9	70	24.8	3.1	SE	5.4	ESE	1010.4	0	0
10/30/2010	2:30 PM	30.9	31	30.8	73	25.5	3.6	SSE	5.8	SSE	1010.2	0	0
10/30/2010	2:45 PM	30.8	30.9	30.7	74	25.6	3.6	SSE	6.3	SSE	1010.1	0	0
10/30/2010	3:00 PM	31	31	30.6	75	26	3.6	SSE	5.8	SSE	1010.1	0	0
10/30/2010	3:15 PM	30.8	31.1	30.8	70	24.7	3.1	SSE	5.8	S	1010	0	0
10/30/2010	3:30 PM	31	31	30.8	69	24.6	1.8	SE	4	SE	1010.1	0	0
10/30/2010	3:45 PM	31.2	31.6	31	69	24.8	1.3	WNW	3.6	WNW	1010	0	0
10/30/2010	4:00 PM	30.2	31.2	30.2	72	24.6	1.8	WNW	4	WNW	1010.3	0	0
10/30/2010	4:15 PM	30.3	30.3	30.1	72	24.7	1.3	WNW	3.6	WNW	1010.3	0	0
10/30/2010	4:30 PM	30.2	30.4	30.2	73	24.8	1.8	WNW	4	W	1010.3	0	0
10/30/2010	4:45 PM	29.8	30.2	29.8	73	24.4	1.3	NW	3.6	WNW	1010.4	0	0
10/30/2010	5:00 PM	29.4	29.8	29.4	74	24.3	1.8	WNW	4.5	WNW	1010.3	0	0
10/30/2010	5:15 PM	28.9	29.4	28.9	74	23.8	1.3	NW	3.6	WNW	1010.4	0	0
10/30/2010	5:30 PM	28.6	28.9	28.6	73	23.3	1.3	NNW	3.6	N	1010.2	0	0
10/30/2010	5:45 PM	28.4	28.7	28.4	73	23.1	0.9	NW	3.1	NNW	1010.4	0	0
10/30/2010	6:00 PM	28.3	28.4	28.3	73	23	0.9	NNW	2.7	NW	1010.5	0	0
10/30/2010	6:15 PM	28.1	28.3	28.1	73	22.8	0.4	NNW	3.1	NNW	1010.8	0	0
10/30/2010	6:30 PM	27.8	28.1	27.8	73	22.5	0.9	NNW	3.1	NE	1010.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/30/2010	6:45 PM	27.8	27.8	27.8	73	22.5	0.4	NW	2.7	NW	1011	0	0
10/30/2010	7:00 PM	27.9	27.9	27.8	73	22.6	0.4	NNE	2.7	NNE	1011.2	0	0
10/30/2010	7:15 PM	28.2	28.2	27.9	78	24	1.3	ESE	3.1	SE	1011.4	0	0
10/30/2010	7:30 PM	28.2	28.3	28.2	79	24.2	2.2	ESE	4	ESE	1011.7	0	0
10/30/2010	7:45 PM	28.2	28.2	28.1	79	24.2	1.3	E	3.6	ESE	1011.9	0	0
10/30/2010	8:00 PM	27.9	28.2	27.9	77	23.5	0.9	SE	2.2	SE	1012.1	0	0
10/30/2010	8:15 PM	27.9	28	27.9	77	23.5	0	SE	1.3	SE	1012.3	0	0
10/30/2010	8:30 PM	27.6	27.9	27.6	76	23	0	SE	0.9	SE	1012.3	0	0
10/30/2010	8:45 PM	27.6	27.6	27.5	76	22.9	0	SW	2.2	SW	1012.4	0	0
10/30/2010	9:00 PM	27.4	27.6	27.3	78	23.2	0	---	0	---	1012.4	0	0
10/30/2010	9:15 PM	27.1	27.4	27.1	82	23.7	0	---	0	---	1012.7	0	0
10/30/2010	9:30 PM	26.8	27	26.8	82	23.4	0	SW	0.9	SW	1012.8	0	0
10/30/2010	9:45 PM	26.5	26.7	26.5	80	22.8	0.4	SW	1.8	SSW	1013	0	0
10/30/2010	10:00 PM	26.5	26.5	26.4	79	22.6	0	SW	0.4	SW	1012.9	0	0
10/30/2010	10:15 PM	26.5	26.6	26.5	80	22.8	0	SW	0.4	SW	1012.8	0	0
10/30/2010	10:30 PM	26.5	26.5	26.4	80	22.8	0	WNW	1.8	WNW	1012.7	0	0
10/30/2010	10:45 PM	26.7	26.7	26.5	81	23.2	0.4	WNW	1.8	NW	1012.6	0	0
10/30/2010	11:00 PM	26.6	26.7	26.6	80	22.9	0.4	WNW	2.2	WNW	1012.5	0	0
10/30/2010	11:15 PM	26.4	26.6	26.4	82	23.1	0.4	WNW	1.8	WNW	1012.5	0	0
10/30/2010	11:30 PM	26.3	26.4	26.3	83	23.2	0	NW	0.4	NW	1012.3	0	0
10/30/2010	11:45 PM	26.1	26.3	26.1	83	22.9	0	NW	0.9	NW	1012.3	0	0
10/31/2010	12:00 AM	25.8	26.1	25.8	84	22.9	0	NW	0.4	NW	1012.3	0	0
10/31/2010	12:15 AM	25.7	25.8	25.7	84	22.8	0	NW	0.4	NW	1012.1	0	0
10/31/2010	12:30 AM	25.4	25.7	25.4	84	22.5	0	NW	0.4	NW	1012.1	0	0
10/31/2010	12:45 AM	25.6	25.6	25.4	85	22.8	0	---	0	---	1012	0	0
10/31/2010	1:00 AM	25.4	25.6	25.4	88	23.3	0	---	0	---	1012	0	0
10/31/2010	1:15 AM	25.1	25.4	25.1	88	22.9	0	NW	0.4	NW	1011.8	0	0
10/31/2010	1:30 AM	24.9	25.1	24.9	89	23	0	---	0	---	1011.6	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/31/2010	1:45 AM	24.8	24.9	24.8	88	22.7	0	NW	0.4	NW	1011.6	0	0
10/31/2010	2:00 AM	25.2	25.2	24.8	89	23.2	0	NW	0.4	NW	1011.3	0	0
10/31/2010	2:15 AM	25.2	25.3	25.2	88	23.1	0	---	0	---	1011.3	0	0
10/31/2010	2:30 AM	25.2	25.2	25.2	88	23	0	---	0	---	1011.1	0	0
10/31/2010	2:45 AM	25.4	25.4	25.2	87	23.1	0	NW	0.9	NW	1010.9	0	0
10/31/2010	3:00 AM	25.6	25.6	25.4	87	23.2	0	NW	0.4	NW	1010.8	0	0
10/31/2010	3:15 AM	25.5	25.6	25.5	85	22.8	0	NNW	0.9	NNW	1010.9	0	0
10/31/2010	3:30 AM	25.3	25.5	25.3	86	22.8	0	---	0	---	1011.1	0	0
10/31/2010	3:45 AM	25.2	25.3	25.1	85	22.5	0	NNW	0.4	NNW	1011.1	0	0
10/31/2010	4:00 AM	25.5	25.5	25.2	86	23	0	NNW	0.9	NNW	1011.2	0	0
10/31/2010	4:15 AM	25.6	25.7	25.5	85	22.9	0	NNW	0.9	NNW	1011.1	0	0
10/31/2010	4:30 AM	25.4	25.7	25.4	86	22.9	0	---	0	---	1011.2	0	0
10/31/2010	4:45 AM	25.4	25.4	25.4	87	23.1	0	NNW	0.9	NNW	1011.3	0	0
10/31/2010	5:00 AM	25.4	25.5	25.4	87	23.1	0	---	0	---	1011.4	0	0
10/31/2010	5:15 AM	25.3	25.4	25.3	89	23.4	0	NNW	0.4	NNW	1011.6	0	0
10/31/2010	5:30 AM	24.9	25.3	24.9	90	23.1	0	NNW	0.4	NNW	1011.8	0	0
10/31/2010	5:45 AM	24.9	24.9	24.8	85	22.2	0	NNW	0.4	NNW	1011.7	0	0
10/31/2010	6:00 AM	25.1	25.2	24.9	87	22.7	0	NNW	0.4	NNW	1011.9	0	0
10/31/2010	6:15 AM	24.8	25.1	24.8	88	22.7	0	---	0	---	1011.9	0	0
10/31/2010	6:30 AM	24.7	24.8	24.7	90	23	0	---	0	---	1012.2	0	0
10/31/2010	6:45 AM	25.1	25.1	24.7	91	23.5	0	---	0	---	1012.6	0	0
10/31/2010	7:00 AM	25.1	25.1	24.9	90	23.3	0	---	0	---	1013	0	0
10/31/2010	7:15 AM	25.6	25.6	25.1	88	23.5	0	---	0	---	1013.3	0	0
10/31/2010	7:30 AM	27.1	27.1	25.7	84	24.1	0	NNW	0.4	NNW	1013.3	0	0
10/31/2010	7:45 AM	28	28	27.1	79	24	0.9	SSE	2.2	S	1013.4	0	0
10/31/2010	8:00 AM	28.7	28.7	28	76	24.1	0.4	SE	2.2	SE	1013.5	0	0
10/31/2010	8:15 AM	29	29	28.7	74	23.9	0.9	NE	2.7	ENE	1013.6	0	0
10/31/2010	8:30 AM	29.4	29.4	29	72	23.8	0.4	NW	1.3	NW	1013.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/31/2010	8:45 AM	29.6	29.6	29.4	70	23.6	0.4	NW	0.9	NW	1013.7	0	0
10/31/2010	9:00 AM	30.2	30.2	29.6	70	24.1	0.4	NW	1.8	NW	1013.8	0	0
10/31/2010	9:15 AM	30.3	30.4	30.2	70	24.2	0.9	WNW	2.2	WNW	1014.1	0	0
10/31/2010	9:30 AM	30.8	30.9	30.3	68	24.2	0.9	WNW	2.2	WNW	1014.1	0	0
10/31/2010	9:45 AM	31	31.1	30.8	67	24.2	0.9	WNW	2.2	WNW	1014.2	0	0
10/31/2010	10:00 AM	31.2	31.2	30.9	64	23.6	0.4	W	1.8	WNW	1014	0	0
10/31/2010	10:15 AM	31.4	31.4	31.2	64	23.8	0.4	SE	2.7	WSW	1014	0	0
10/31/2010	10:30 AM	30.8	31.5	30.8	67	24	0.4	ESE	2.7	S	1014	0	0
10/31/2010	10:45 AM	31.4	31.4	30.8	67	24.6	0.4	W	2.7	WSW	1013.7	0	0
10/31/2010	11:00 AM	29	31.4	29	79	25	2.2	SSE	6.7	S	1013.8	0	0
10/31/2010	11:15 AM	28.5	28.9	28.4	82	25.1	3.6	SSE	6.7	S	1013.7	0	0
10/31/2010	11:30 AM	28.7	28.8	28.5	82	25.3	3.6	SSE	6.3	SE	1013.4	0	0
10/31/2010	11:45 AM	28.7	28.8	28.6	84	25.7	4.5	SSE	7.2	SSE	1013.1	0	0
10/31/2010	12:00 PM	29.3	29.3	28.7	81	25.7	3.6	SE	5.8	SE	1012.7	0	0
10/31/2010	12:15 PM	29.4	29.5	29.3	82	26	3.6	SSE	5.8	SSE	1012.2	0	0
10/31/2010	12:30 PM	29.3	29.4	29.3	81	25.7	4	SSE	6.7	SSE	1012.1	0	0
10/31/2010	12:45 PM	29.4	29.5	29.3	80	25.6	4	SSE	6.7	SE	1012.1	0	0
10/31/2010	1:00 PM	29.7	29.7	29.4	79	25.6	3.6	SE	6.3	SSE	1011.6	0	0
10/31/2010	1:15 PM	29.8	29.8	29.6	78	25.5	3.6	SE	5.8	ESE	1011.5	0	0
10/31/2010	1:30 PM	30.3	30.4	29.8	77	25.8	3.6	SE	6.3	SE	1011.4	0	0
10/31/2010	1:45 PM	30.3	30.3	30.1	79	26.3	4	SSE	6.7	SSE	1011.3	0	0
10/31/2010	2:00 PM	30.4	30.4	30.2	75	25.5	4.9	SSE	7.2	SSE	1011.1	0	0
10/31/2010	2:15 PM	30.4	30.5	30.3	76	25.7	4.9	SSE	8	SSE	1011	0	0
10/31/2010	2:30 PM	30.6	30.6	30.1	76	25.8	4.5	SSE	8.5	SSE	1010.9	0	0
10/31/2010	2:45 PM	28.9	30.6	28.9	75	24.1	2.7	SSE	6.7	SE	1011.3	0	0
10/31/2010	3:00 PM	28.6	28.9	27.8	77	24.1	2.2	WNW	6.3	NW	1011.6	0	0
10/31/2010	3:15 PM	29.8	29.8	28.6	75	24.9	1.8	NW	3.6	NW	1011.9	0	0
10/31/2010	3:30 PM	29.6	29.9	29.6	72	24	0.9	WNW	3.1	WNW	1011.8	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010

American Airlines 331 Accident Site and Landfarm

Date	Time	Temp Out	Hi Temp	Low Temp	Out Hum	Dew Pt.	Wind Speed	Wind Dir	Hi Speed	Hi Dir	Bar	Rain	Rain Rate
10/31/2010	3:45 PM	28.7	29.7	28.7	79	24.7	1.8	NW	4.5	NW	1011.9	0	0
10/31/2010	4:00 PM	28.5	28.8	28.4	82	25.1	1.3	NW	3.1	NW	1011.9	0	0
10/31/2010	4:15 PM	28.5	28.8	28.5	82	25.1	0.9	NW	3.1	NNW	1012	0	0
10/31/2010	4:30 PM	28.3	28.5	28.3	81	24.7	1.3	NW	3.1	NW	1012.2	0	0
10/31/2010	4:45 PM	28	28.3	28	83	24.8	1.8	WNW	3.6	W	1012.3	0	0
10/31/2010	5:00 PM	27.6	28	27.6	84	24.6	1.3	WNW	3.6	NW	1012.5	0	0
10/31/2010	5:15 PM	26.9	27.6	26.9	81	23.4	1.8	WNW	4.5	WNW	1012.7	0	0
10/31/2010	5:30 PM	26.6	26.9	26.6	83	23.4	1.3	WNW	4	WNW	1012.8	0	0
10/31/2010	5:45 PM	26.4	26.6	26.4	85	23.7	1.3	WNW	3.1	W	1012.9	0	0
10/31/2010	6:00 PM	26.4	26.4	26.4	87	24.1	0.4	WNW	2.2	WNW	1012.8	0	0
10/31/2010	6:15 PM	26.4	26.5	26.4	88	24.3	0.4	WNW	2.2	WNW	1012.9	0	0
10/31/2010	6:30 PM	26.5	26.5	26.4	89	24.5	0.4	WNW	2.2	WNW	1013	0	0
10/31/2010	6:45 PM	26.9	26.9	26.5	88	24.7	0.4	NW	3.1	NNW	1013.1	0	0
10/31/2010	7:00 PM	27.1	27.1	26.9	87	24.8	0.4	NNW	3.1	NE	1013.3	0	0
10/31/2010	7:15 PM	27.2	27.2	27.1	86	24.6	0.4	NNE	2.7	NE	1013.3	0	0
10/31/2010	7:30 PM	27.2	27.2	27.1	86	24.6	0.4	NNE	2.7	NNE	1013.5	0	0
10/31/2010	7:45 PM	27.1	27.2	27.1	85	24.4	0	N	1.3	NNW	1013.7	0	0
10/31/2010	8:00 PM	27.1	27.1	27.1	85	24.3	0.4	N	2.2	N	1013.9	0	0
10/31/2010	8:15 PM	26.9	27.1	26.9	84	24	0	NNE	0.9	NNE	1014.2	0	0
10/31/2010	8:30 PM	26.9	26.9	26.9	85	24.2	0	NNE	0.4	NNE	1014.4	0	0
10/31/2010	8:45 PM	26.9	26.9	26.9	88	24.8	0	NNE	0.9	NNE	1014.8	0	0
10/31/2010	9:00 PM	26.9	27	26.9	87	24.6	0	NNE	0.4	NNE	1014.8	0	0
10/31/2010	9:15 PM	26.9	26.9	26.8	85	24.2	0.4	ENE	2.2	ENE	1015	0	0
10/31/2010	9:30 PM	26.9	27	26.9	84	24	0	ENE	1.3	ENE	1014.9	0	0
10/31/2010	9:45 PM	26.8	26.9	26.8	86	24.2	0	ENE	0.9	ENE	1015	0	0
10/31/2010	10:00 PM	26.8	26.8	26.7	87	24.4	0	ENE	0.9	ENE	1015	0	0
10/31/2010	10:15 PM	26.7	26.8	26.7	87	24.4	0.4	ENE	1.8	ENE	1015.1	0	0
10/31/2010	10:30 PM	26.8	26.8	26.7	86	24.2	0	ENE	1.8	ENE	1015.1	0	0

Submitted to: American Airlines
Prepared by: CL Environmental

Monitoring Report
OCTOBER 2010



American Airlines 331 Accident Site and Landfarm



		Temp	Hi	Low	Out	Dew	Wind	Wind	Hi	Hi			Rain
Date	Time	Out	Temp	Temp	Hum	Pt.	Speed	Dir	Speed	Dir	Bar	Rain	Rate
10/31/2010	10:45 PM	26.7	26.8	26.7	86	24.2	0	ENE	0.4	ENE	1015.1	0	0
10/31/2010	11:00 PM	26.4	26.7	26.4	86	23.9	0	ENE	0.9	ENE	1015	0	0
10/31/2010	11:15 PM	26.2	26.4	26.2	83	23.1	0.4	NNE	3.1	NNE	1014.8	0	0
10/31/2010	11:30 PM	26.7	26.7	26.2	81	23.1	0.9	NNE	3.1	NNE	1014.8	0	0
10/31/2010	11:45 PM	26.6	26.7	26.6	81	23.1	0	NNE	2.7	NNE	1014.7	0	0
11/1/2010	12:00 AM	26.6	26.6	26.5	80	22.8	0	NNE	0.9	NNE	1014.6	0	0



*Submitted to: American Airlines
Prepared by: CL Environmental*



Appendix 4 Water quality graphs showing trends from March - October, 2010


Accident Site











Land Farm

